



435 FM 1092
Stafford, Texas 77477
Phone: (713) 443-6862
Fax: (713) 481-8209
rhandler@inspecthouston.com
www.inspecthouston.com

Insight Property Inspection

It has been a pleasure to provide your inspection service and we truly appreciate your patronage. We worked hard to research your real estate investment and report back to you in a comprehensive way to answer all of your questions as thoroughly as possible. Remember that we have your best interests in mind throughout this process and we are happy to answer any questions that you might have about the inspection. Please feel free to call us directly with any of your questions.



REPORT PREPARED FOR:
Cyle Hepburn

INSPECTED PROPERTY ADDRESS:
6200 W. Tidwell Rd. #205
Houston Texas 77092

[Texas Real Estate Commission Professional Inspector License # 6803](#)

[Certified Master Inspector, CMI](#)

Certified Thermal Imaging Specialist

[Certified HUD/FHA Inspector # S668](#)

[Certified HUD/FHA 203\(k\) Consultant # D0828](#)

Certified Pool Operator # 77-262081, National Swimming Pool Foundation

Certified Pool Inspector # 77-262081, National Swimming Pool Foundation

[Certified Mold Consultant, Cert. # IAC2-01-5402](#)

PROPERTY INSPECTION REPORT

Prepared For:	Cyle Hepburn	
	(Name of Client)	
Concerning:	6200 W. Tidwell Rd. #205, Houston, Texas 77092	
	(Address or Other Identification of Inspected Property)	
By:	Richard Chandler #6803 / Insight Property Inspections	3/30/2019
	(Name and License Number of Inspector)	(Date)
	(Name, License Number of Sponsoring Inspector)	

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standard for inspections by TREC Licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers.

Promulgated by the Texas Real Estate Commission(TREC) P.O. Box 12188, Austin, TX 78711-2188 (512)936-3000
<http://www.trec.state.tx.us>.

You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods.

Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathrooms, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms require a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT

REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR:

In Attendance:

Vacant (inspector only)

Type of building:

Condominium

Approximate age of building:

Over 25 Years

Temperature:

78

Weather:

Cloudy

Ground/Soil surface condition:

Dry

Rain in last 3 days:

No

Radon Test:

No

Water Test:

No

Building Status:

Vacant

Utilities on::

Yes

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

I NI NP D

I. Structural Systems

The structure of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

A. Foundations

Comments:

Performance Opinion:

Note: *Weather conditions, leakage and other adverse factors are able to effect structures, and differential movements are likely to occur. The inspectors opinion is based on visual observations of accessible and unobstructed areas of the structure at the time of the inspection. Future performance of the structure cannot be predicted or warranted.*

Note: It is not uncommon for foundations to reveal some symptoms of differential movement. At the time of the inspection, this inspector did not observe any evidences or consequences that would indicate the presence of a significantly deflected foundation nor any evidences or consequences indicating the foundation is not providing adequate support for the structure. Therefore, in my opinion, the foundation is performing its intended function and re-leveling repairs would not be currently necessary. However, differential movement can occur rapidly under certain conditions and the future performance or stability of the foundation cannot be predicted.

Because the Texas Real Estate Commission has not provided exact specifications or selected other available criteria as a guideline for the inspectors Standards of Practice on what constitutes a failed foundation the performance opinion rendered by this inspector is based on personal opinion. Opinions may vary greatly on the performance of a foundation.

SUGGESTED FOUNDATION MAINTENANCE & CARE - Proper drainage and moisture maintenance to all types of foundations due to the expansive nature of the area load bearing soils. Drainage must be directed away from all sides of the foundation with grade slopes. In most cases, floor coverings and/or stored articles prevent recognition of signs of settlement - cracking in all but the most severe cases. It is important to note, this was not a structural engineering survey nor was any specialized testing done of any sub-slab plumbing systems during this limited visual inspection, as these are specialized processes requiring excavation. In the event that structural movement is noted, client is advised to consult with a Structural Engineer who can isolate and identify causes, and determine what corrective steps, if any, should be considered to either correct and/or stop structural movement.

Recommendation: visit the following website: www.houston-slab-foundations.info. This website will provide you with general information about slab on ground foundations in the Greater Houston Area that is not readily available elsewhere. The website was published specifically to help buyers and others understand the foundation inspections with reference to real estate transactions.

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

I NI NP D

B. Grading and Drainage

Comments:

C. Roof Covering Materials

Comments:

D. Roof Structures and Attics

Comments:

E. Walls (Interior and Exterior)


Comments:

F. Ceilings and Floors

Comments:

G. Doors (Interior and Exterior)

Comments:

 The sliding patio door does not open and close smoothly and does not latch properly.

H. Windows

Comments:

 Window screens are missing.



H. Item 1(Picture)

I. Stairways (Interior and Exterior)

Comments:

J. Fireplaces and Chimneys


Comments:

K. Porches, Balconies, Decks and Carports

Comments:

L. Other

Comments:

 (1) Cabinets have damaged shelves and cabinet doors do not shut completely in both bathrooms.

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

I NI NP D



L. Item 1(Picture)



L. Item 2(Picture)

 (2) Some kitchen cabinet doors do not close properly.




L. Item 3(Picture)

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

I NI NP D

II. Electrical Systems

The electrical system of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Outlets were not removed and the inspection was only visual. Any outlet not accessible (behind the refrigerator for example) was not inspected or accessible. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.




A. Service Entrance and Panels

Electrical Service Conductors: Below ground


Panel Capacity: 100 AMP

Panel Type: Circuit breakers

Comments:

 (1) AFCI devices were not observed in the panel box. AFCI (Arc Fault Circuit Interrupt) device protection, as required by current building standards, for all: family rooms, dining rooms, living rooms, parlors, libraries, dens, bedrooms, sunrooms, recreations rooms, closets, hallways, or similar rooms or areas. AFCI devices are intended to protect against fires caused by electrical arcing faults in the home's wiring. Arc faults are a common cause of residential electrical fires. Arc faults can be created by damaged, deteriorated, or worn electrical plugs, cords, and/or branch circuit conductors. As of September 1, 2008, the State of Texas has adopted the 2005 NEC, which includes this requirement, as the "minimum standard" for all non-exempt electrical work. Homes built prior to 2002, generally were not required to have arc fault protection. However, the current TREC standard of practice requires inspectors to indicate that a hazardous or deficient condition exists if any home does not have this protection, regardless of date the home was constructed.


Note: At the time this home was built AFCI devices were not required


 (2) The Panel box dead front cover is missing. Repair is needed.

B. Branch Circuits, Connected Devices and Fixtures

Type of wiring: Copper

Comments:

 (1) The light fixture does not work at the Kitchen. Electrical issues are considered a hazard until repaired. A qualified licensed electrical contractor should perform repairs that involve wiring.

 (2) Several electrical outlets are not working in the kitchen. Electrical issues are considered a hazard until repaired. A qualified licensed electrical contractor should perform repairs that involve wiring.

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

I NI NP D



B. Item 1(Picture)

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

I NI NP D



B. Item 1(Picture)

(2) The AC condenser (outside unit) is not level. This can cause damage to the unit or shorten its life span. .

C. Duct Systems, Chases and Vents

Ductwork: Insulated

Comments:

No furnace air filter was installed at the time of the inspection. A filter should be installed to improve indoor air quality.



C. Item 1(Picture)

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

I NI NP D

IV. Plumbing System

The plumbing in the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Washing machine drain line for example cannot be checked for leaks or the ability to handle the volume during drain cycle. Older homes with galvanized supply lines or cast iron drain lines can be obstructed and barely working during an inspection but then fails under heavy use. If the water is turned off or not used for periods of time (like a vacant home waiting for closing) rust or deposits within the pipes can further clog the piping system. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

A. Plumbing Supply, Distribution System and Fixtures

Comments:

 Rust and peeling paint was observed at both bath tubs.




A. Item 1(Picture)



A. Item 2(Picture)

B. Drains, Waste and Vents

Comments:

 The toilet flush mechanism does not work properly in the half bathroom.

C. Water Heating Equipment

Comments:

D. Hydro-Massage Therapy Equipment

Comments:

E. Other

Comments:


I = Inspected NI = Not Inspected NP = Not Present D = Deficient

I NI NP D

V. Appliances


A. Dishwasher

Comments:


 Dishwasher should be equipped with an "air gap" or a "loop" high in the drain line. The purpose of these items is to prevent wastewater from backing up into the washer.

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

I NI NP D



A. Item 1(Picture) I1



A. Item 2(Picture) I2




A. Item 3(Picture)

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

I NI NP D

B. Food Waste Disposers

Comments:

 The food disposer would not operate or non functional. I recommend repair as needed.

C. Range Hood and Exhaust System

Comments:

D. Ranges, Cooktops and Ovens

Comments:

E. Microwave Ovens

Comments:

F. Mechanical Exhaust Vents and bathroom Heaters

Comments:

G. Garage Door Operator(s)

Comments:

H. Dryer Exhaust System

Comments:

I. Other

Comments:

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

I NI NP D

VI. Optional Systems

A. Landscape Irrigation (Sprinkler) Systems

Comments:

B. Swimming Pools, Spas, Hot Tubs and Equipment

Comments:

C. Out Buildings

Comments:

D. Private Water Wells (a coliform analysis is recommended)

Comments:

E. Private Sewage Disposal (Septic) System

Comments:

F. Other

Comments:

General Summary



Insight Property Inspection

Insight Property Inspections

435 FM 1092 #B1-132
Stafford, Texas 77477
(713) 443-6862

Customer
Cyle Hepburn

Address
6200 W. Tidwell Rd. #205
Houston Texas 77092


The following items or discoveries indicate that these systems or components **do not function as intended** or **adversely affects the habitability of the dwelling**; or **warrants further investigation by a specialist**, or **requires subsequent observation**. This summary shall not contain recommendations for routine upkeep of a system or component to keep it in proper functioning condition or recommendations to upgrade or enhance the function or efficiency of the home. This Summary is not the entire report. The complete report may include additional information of concern to the customer. It is recommended that the customer read the complete report.

I. Structural Systems




Doors (Interior and Exterior)

Inspected, Deficient

-  1 The sliding patio door does not open and close smoothly and does not latch properly.



Windows

Inspected, Deficient

-  2 Window screens are missing.

Other


Inspected, Deficient

-  3 (1) Cabinets have damaged shelves and cabinet doors do not shut completely in both bathrooms.
-  4 (2) Some kitchen cabinet doors do not close properly.


II. Electrical Systems

Service Entrance and Panels

Inspected, Deficient



-  5 (1) AFCI devices were not observed in the panel box. AFCI (Arc Fault Circuit Interrupt) device protection, as required by current building standards, for all: family rooms, dining rooms, living rooms, parlors, libraries, dens, bedrooms, sunrooms, recreations rooms, closets, hallways, or similar rooms or areas. AFCI devices are intended to protect against fires caused by electrical arcing faults in the home's wiring. Arc faults are a common cause of residential electrical fires. Arc faults can be created by damaged, deteriorated, or worn electrical plugs, cords, and/or branch circuit conductors. As of September 1, 2008, the State of Texas has adopted the 2005 NEC, which includes this requirement, as the "minimum standard" for all non-exempt electrical work. Homes built prior to 2002, generally were not required to have arc fault protection. However, the current TREC standard of practice requires inspectors to indicate that a hazardous or deficient condition exists if any home does not have this protection, regardless of date the home was constructed.

Note: At the time this home was built AFCI devices were not required

-  6 (2) The Panel box dead front cover is missing. Repair is needed.

Branch Circuits, Connected Devices and Fixtures



Inspected, Deficient

-  7 (1) The light fixture does not work at the Kitchen. Electrical issues are considered a hazard until repaired. A qualified licensed electrical contractor should perform repairs that involve wiring.
-  8 (2) Several electrical outlets are not working in the kitchen. Electrical issues are considered a hazard until repaired. A qualified licensed electrical contractor should perform repairs that involve wiring.

III. Heating, Ventilation and Air Conditioning Systems


Cooling Equipment

Inspected, Deficient

-  9 (1) The foam sleeve on suction line is missing in area(s) at outside unit. Missing foam on suction line can cause energy loss and condensation. I recommend service or repair as needed.
-  10 (2) The AC condenser (outside unit) is not level. This can cause damage to the unit or shorten its life span. .

Duct Systems, Chases and Vents


Inspected, Deficient

-  11 No furnace air filter was installed at the time of the inspection. A filter should be installed to improve indoor air quality.

IV. Plumbing System


Plumbing Supply, Distribution System and Fixtures

Inspected, Deficient

-  12 Rust and peeling paint was observed at both bath tubs.

Drains, Waste and Vents


Inspected, Deficient

-  13 The toilet flush mechanism does not work properly in the half bathroom.


V. Appliances

Dishwasher

Inspected, Deficient

-  14 Dishwasher should be equipped with an "air gap" or a "loop" high in the drain line. The purpose of these items is to prevent wastewater from backing up into the washer.

Food Waste Disposers**Inspected, Deficient**

-  15 The food disposer would not operate or non functional. I recommend repair as needed.

Home inspectors are not required to report on the following: Life expectancy of any component or system; The causes of the need for a repair; The methods, materials, and costs of corrections; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; Any component or system that was not observed; The presence or absence of pests such as wood damaging organisms, rodents, or insects; or Cosmetic items, underground items, or items not permanently installed. Home inspectors are not required to: Offer warranties or guarantees of any kind; Calculate the strength, adequacy, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility; Determine the presence or absence of any suspected adverse environmental condition or hazardous substance, including but not limited to mold, toxins, carcinogens, noise, contaminants in the building or in soil, water, and air; Determine the effectiveness of any system installed to control or remove suspected hazardous substances; Predict future condition, including but not limited to failure of components; Since this report is provided for the specific benefit of the customer(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

Prepared Using HomeGauge <http://www.HomeGauge.com> : Licensed To Richard Chandler #6803



Insight Property Inspection

Upon Taking Ownership

After taking possession of a new home, there are some maintenance and safety issues that should be addressed immediately. The following checklist should help you undertake these improvements:

1. Complete all of the improvements recommended in this inspection report.
2. Change all the locks on the exterior entrances, for improved security.
3. Check that all windows and doors are secure. Improve windows hardware as necessary. Security rods can be added to sliding windows and doors. Consideration could also be given to a security system.
4. Install smoke detectors on each level of the home. Ensure that there is a smoke detector outside all sleeping areas. Replace batteries on any existing smoke detectors and test them. Make a note to replace batteries again in one year.
5. Create a plan of action in the event of a fire in your home. Ensure that there is an operable window or door in every room of the house. Consult with your local fire department regarding fire safety issues and what to do in the event of a fire.
6. Examine driveways and walkways for trip hazards. Undertake repairs where necessary.
7. Examine the interior of the home for trip hazards. Loose or torn carpeting and flooring should be repaired.
8. Undertake improvements to all stairways, decks, porches and landings where there is a risk of falling or stumbling.
9. Review your home inspection report for any items that require immediate improvement or further investigation. Address these areas immediately.
10. Install rain caps and vermin screens on all chimney flues, as necessary.
11. Investigate the location of the main shut-offs for the plumbing, heating and electrical systems. Regular Maintenance

Every Week

1. Check that the soil around the perimeter of the house is clinging tightly to the edge of the foundation. If there is any space between the soil and the concrete, the soil is too dry and you should increase the frequency with which you water. The foremost cause of foundation failure in the Houston metro area is lack of soil moisture control and maintenance by homeowners. Periods of dry weather occur in all seasons. Inspect this item weekly.

Every Month

1. Check that fire extinguishers are fully charged. Re-charge if necessary.
2. Replace heating/cooling air filters.
3. Inspect and clean humidifiers and electronic air cleaners.
4. Test the Temperature and Pressure Relief Valve on the Water Heater(s) for proper operation. Replace if defective.
5. Clean gutters and downspouts. Ensure that downspouts are secure, and that the discharge of the downspouts is appropriate. Remove debris from window wells.
6. Carefully inspect the condition of shower enclosures. Repair or replace deteriorated grout and caulk. Ensure that water is not escaping the enclosure during showering. Check below all plumbing fixtures for evidence of leakage.
7. Repair or replace leaking faucets or shower heads.

8. Secure loose toilets, or repair flush mechanisms that become troublesome.
9. Operate all of the doors in the house to ensure that none are sticking or binding at the jambs. Door frames out of square is an indication of excessive foundation movement.
10. Test all ground fault circuit interrupter (GFCI) and arc fault circuit interrupter (AFCI) devices, as identified in the inspection report. If these devices do not trip or reset properly, they should be replaced immediately.

Spring and Fall

1. Examine the roof for evidence of damage to roof coverings, flashings and chimneys.
2. Look in the attic (if accessible) to insure that roof vents are not obstructed. Check for evidence of leakage, condensation or vermin activity. Level out insulation if needed.
3. Trim back tree branches and shrubs to insure that they are not in contact with the house.
4. Inspect the exterior walls and foundation for evidence of damage, cracking or movement. Watch for bird nests or other vermin or insect activity.