



October 29, 2019

Wedgewood Inc.
10311 Meadow Lake Lane
Houston, Texas 77042

RE: Foundation Inspection
Job #18607

Dear Mr. Conar Cabucio:

Enclosed is the report of the foundation inspection performed at 10311 Meadow Lake Lane in Houston, Texas. This inspection was conducted for you on October 28, 2019, at the agreed upon fee.

We appreciate the opportunity to assist you in performing the inspection. If we can be of any further service, please let us know.

Respectively Submitted,

Jeff Burkman, P.E. 63505
Champions Engineering & Inspections
Registered Engineering Firm - 5832

9595 Six Pines Drive • Suite 8210 • The Woodlands, Texas 77380

INTRODUCTION

The purpose of this report is to document the results of a visual inspection that was conducted on the residential building described below and to document our agreement regarding the services provided to you. The information contained in this report takes precedence over any information or understandings that may have occurred during verbal communications.

This inspection was conducted for you, as our Client, to provide you with opinions regarding the performance of the primary load-bearing structural components of the foundation and to assess if these components are performing the function for which they were intended or are in need of immediate repair. No assessments were made for driveways, patios, sidewalks, fences, gutters, insulation, carpeting, toxic materials, paint, out buildings, cosmetic damage, etc. An investigation was not conducted to determine the existence of geological faults relative to the structure inspected.

This inspection was limited, in accordance with our agreements, to a visual examination of those portions of the structure that were accessible. Thus, hidden items such as damaged wood inside of walls, leak paths through ceilings and walls, interior slab cracks, etc., that are not amenable to visual inspection cannot be reported. Champions Engineering assumes no responsibility should such defects be discovered in the future.

Compliance with any government or industry code or standard or with any legal requirements is not within the scope of this inspection. By law, inspections to determine the presence of and the extent of damage created by wood infesting organisms, which includes all rotted wood, can only be performed by individuals who are so licensed by the state for that purpose and will not, therefore, be considered to be part of this inspection.

In the conduct of this work, Champions Engineering has acted as an engineering consultant to provide visual observations and opinions with regard to the visible condition of the load-bearing structure of this building. Recognizing that latent defects could exist which inherently may not be detected during an inspection of this type, Champions Engineering, does not represent that the observations described herein and their analysis thereof represent every structural condition that may exist. Any recommendations for repair that may be contained in this report should be completed, since such repairs may result in the discovery of additional defects that may not have been discovered during the original inspection.

To protect the foundation it is advised to maintain a consistent moisture level at all points around the perimeter of the foundation, especially during dry weather periods.

Champions Engineering does not assume responsibility whatsoever for any action that may or may not be done as the result of the information provided during this inspection. The involvement of Champions Engineering in any activities associated with this inspection will terminate at the time this report has been submitted. Finally, this report was written to satisfy the specific objectives of you, as the Client. Neither the author of this report nor Champions Engineering, authorizes or assumes any responsibility whatsoever for the use of this report by any third person, except the Veterans Administration (V.A.) and/or the Federal Housing Administration (F.H.A.) and/or mortgage company.

DESCRIPTION:

The residence inspected was located at 10311 Meadow Lake Lane in Houston, Texas.

This was a foundation inspection, based on physical observation. The following are the results obtained from the visual structural evaluation. This residence is a thirty eight year, one story with attached garage, single family wood frame dwelling with a brick veneer. The structure has what appears to be a poured concrete rebar reinforced monolithic slab foundation.

FOUNDATION INSPECTION:

The foundation inspection includes a physical non-destructive observation of the existing foundation condition and functionality.

The intention of this report is to inform you of the foundations current status, i.e. whether it is performing as intended or in need of repair. The scope of this evaluation is limited to structural components that are readily observable and does not include damage in inaccessible areas, such as between walls. It also does not predict potential performance after the inspection or damage detected after inaccessible areas are uncovered.

Houston, as well as many parts of Texas soil is an active clay type, structures have experienced significant differential movement or settlement with slabs on grade. More often than not, this movement has resulted in little if any serious structural damage. However, some unsightly sheetrock and brick veneer cracks do appear along with annoying sticky doors and cabinets. It should be noted that more than 70% of the houses in Houston have some differential movement including minor cracks in the slab.

Hairline cracks were observed in the front entry hall floor tile and 1/16" cracks in the garage slab floor. Typically during construction cracks in the slab floor do occur due to the normal concrete curing process and these cracks create a very minor weakness in the slab and when thermal expansion or contraction occurs the stresses target these cracked areas. When brittle construction materials (tile) are bonded to the slab surface they will eventually crack during slab flexing or thermal changes in the slab. The proper repair is to remove cracked tiles and place a rubber membrane across the cracks in the floor slab (so that the tile does not bond to the slab) and replace tiles.

Cracks in the foundation and symptoms of settlement will usually be noted in this report for your information. Unless there are significant functional problems or structural defects requiring correction, we will not recommend foundation or structural restoration.

The slab elevations were measured using an electronic manometer level measuring the surface of the floor coverings.

FYI: Apparently there has been previous foundation repair, per the breaks observed in the rear porch flatwork. No documentation was available for review to verify or determine extent of repairs.

The foundation inspection did reveal the existence of a marginally non-functioning slab, as evidenced by floor elevations, window frame separations, uneven front bedrooms door clearances, sheetrock cracks in front bedroom, bubble levels, cracks in the floor tile of front entry and brick veneer cracks. Rafters observed in the attic were relatively construction tight at the ridge board.

Spreadsheet calculations were performed utilizing the FPA (Foundation Performance Association's SC-13-1 Calculation Spreadsheet) resulting in a deflection ratio of L/120 and tilt ratio 28% of 1% which is excessive and will require foundation repair with piers. This spreadsheet and report was reviewed and this engineer has taken into consideration the recommendations and guidelines of the TBPE (Texas Board of Professional Engineers), ASCE (American Society of Civil Engineers), ACI (American Concrete Institute), and TRCC (Texas Residential Construction Commission).

FYI: It is suggested to have a Hydro-Static plumbing test prior to foundation repair and after completion of foundation repairs. Leaks in water and sewer lines will change the soil equilibrium under a foundation and can lead to differential movement/damage.

RECOMMENDATION FOR PIERS:

Approximately nine exterior piers will need to be installed along the *front section* of the house, as depicted on the attached diagram. The reasonable placement is based on the opinions and engineering judgment of this engineer. The piers should be of either *driven piles* or a *bell bottom design* and described as follows:

- set on approximately 7 foot centers – Average Lift 1.5”
- drilled to load bearing soils between 16 to 22 feet
- shaft diameters 8 to 10 inches, using 3 #3 steel rebar tied in a triangle
- bell diameter 20 to 24 inches, 8” shaft diameter minimum
- pier top reinforced with 6 #3 rebar, minimum dimensions are 20” x 24” and 12” deep
- minimum 5 sx mix or at least 3000 psi compressive strength
- shim with 3000 psi compressive strength precast blocks and steel.

This report is to assist our client with soliciting bids for repairs from a qualified foundation contractor. Qualified contractors arrangement of piers may vary due to their specific experience and the fact that they provide the warranty for their work. *This house may not be able to be completely restored to original elevation, however, significant elevation differentials can be reduced and the slab stabilized.*

To protect the integrity of the foundation it is advised to maintain a consistent moisture level at all points around the perimeter of the foundation (not too wet or too dry) even after piers have been installed. Consistent watering is essential, especially during dry weather periods.

CERTIFICATION:

I hereby certify that I performed the inspection of the residence located at 10311 Meadow Lake Lane in Houston, Texas and that I have reported my opinions and findings based upon my observations. I further certify that the information contained in this report is based upon visible evidence and is a level “B” engineering inspection, as per the Texas

Board of Professional Engineers, and that no attempt was made to investigate those latent defects not readily detectable from visual observations. No responsibility is assumed for events that occur subsequent to this inspection and no warranty, either expressed or implied, is hereby made. The inspector and inspection company's liability is limited to twice the amount of the inspection fee paid, which also includes consequential damages. A second opinion is always a prudent and a recommended course of action. Foundation Inspection - 10311 Meadow Lake Lane in Houston, Texas. October 28, 2019.



A handwritten signature in red ink that reads "Jeff Burkman".

Jeffrey C. Burkman
Registered Professional Engineer – 63505
Champions Engineering & Inspections
Registered Engineering Firm – F-5832



CHAMPIONS ENGINEERING

Engineering Designs & Inspections
281.537.5522

9595 Six Pines Dr, Suite 8210
The Woodlands, Tx 77380

10311 Meadow Lake Lane

THIS SKETCH IS TO BE USED ONLY AS A REFERENCE OF THE FLOOR PLAN REPRESENTING AREAS THAT WERE MEASURED. APPROXIMATE SCALE 1" = 10'

BM-Benchmark

● Pier

Average Lift = Approximately 1.5"

