



713-730-3151

www.a-actionhouston.com

info@a-action.com



INSPECTED FOR

Prasad Ivaturi
2719 Newman St
Houston, TX 77098

April 21, 2018

PROPERTY INSPECTION REPORT

Prepared For: Prasad Ivaturi
(Name of Client)

Concerning: 2719 Newman St, Houston, TX 77098
(Address or Other Identification of Inspected Property)

By: Brendan Hirshey, Lic #22135 04/21/2018
(Name and License Number of Inspector) (Date)

(Name, License Number of Sponsoring Inspector)

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, ***THIS IS NOT A CODE COMPLIANCE INSPECTION*** and does NOT verify compliance with manufacturer's installation instructions. ***THE INSPECTION DOES NOT IMPLY INSURABILITY OR WARRANTABILITY OF THE STRUCTURE OR ITS COMPONENTS.*** Although some safety issues may be addressed in this report, ***THIS REPORT IS NOT A SAFETY / CODE INSPECTION***, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. THE INSPECTION MAY NOT REVEAL ALL DEFICIENCIES. A REAL ESTATE INSPECTION HELPS TO REDUCE SOME OF THE RISK INVOLVED IN PURCHASING A HOME, BUT IT CANNOT ELIMINATE THESE RISKS, NOR CAN THE INSPECTION ANTICIPATE FUTURE EVENTS OR CHANGES IN PERFORMANCE DUE TO CHANGES IN USE OR OCCUPANCY. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions

expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. *When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods. Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs.* Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. ***This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information.*** Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathroom, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- the lack of fire safety features, such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "**grandfathered**" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. ***Neither the Standards of Practice nor the TREC contract forms requires a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.***

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

This confidential report is prepared exclusively for Prasad Ivaturi on 04/21/2018.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Inspection Time In: **9 am** Time Out: **12 pm** Property was: **Vacant**
Building Orientation (For Purpose Of This Report Front Faces): **South**
Weather Conditions During Inspection: **Cloudy Overcast**
Outside temperature during inspection: **70 ° to 80 ° Degrees**
Parties present at inspection: **Buyer**

THIS REPORT IS PAID AND PREPARED FOR THE EXCLUSIVE USE BY Prasad Ivaturi. THIS COPYRIGHTED REPORT IS NOT VALID WITHOUT THE SIGNED INSPECTION AGREEMENT.

THIS REPORT IS NOT TRANSFERABLE FROM CLIENT NAMED ABOVE.

SCOPE OF INSPECTION

These standards of practice define the minimum levels of inspection required for substantially completed residential improvements to real property up to four dwelling units. A real estate inspection is a non-technically exhaustive, limited visual survey and basic performance evaluation of the systems and components of a building using normal controls and does not require the use of specialized equipment or procedures. The purpose of the inspection is to provide the client with information regarding the general condition of the residence at the time of inspection. The inspector may provide a higher level of inspection performance than required by these standards of practice and may inspect components and systems in addition to those described by the standards of practice.

GENERAL LIMITATIONS

The inspector is not required to:

(A) inspect:

- (i) items other than those listed within these standards of practice;
- (ii) elevators;
- (iii) detached buildings, decks, docks, fences, or waterfront structures or equipment;
- (iv) anything buried, hidden, latent, or concealed;
- (v) sub-surface drainage systems;
- (vi) automated or programmable control systems, automatic shut-off, photoelectric sensors, timers, clocks, metering devices, signal lights, lightning arrestor system, remote controls, security or data distribution systems, solar panels, outdoor kitchens, gas grills (built-in or free standing), refrigerators (built-in or free standing), wine coolers, ice makers or smart home automation components; or
- (vii) concrete flatwork such as; driveways, sidewalks, walkways, paving stones or patios;

(B) report:

- (i) past repairs that appear to be effective and workmanlike except as specifically required by these standards;
- (ii) cosmetic or aesthetic conditions; or
- (iii) wear and tear from ordinary use;

(C) determine:

- (i) insurability, warrantability, suitability, adequacy, compatibility, capacity, reliability, marketability, operating costs, recalls, counterfeit products, product lawsuits, life expectancy, age, energy efficiency, vapor barriers, thermostatic performance, compliance with any code, listing, testing or protocol authority, utility sources, or manufacturer or regulatory requirements except as specifically required by these standards;
- (ii) the presence or absence of pests, termites, or other wood-destroying insects or organisms;
- (iii) the presence, absence, or risk of asbestos, lead-based paint, **MOLD**, mildew, corrosive or contaminated drywall "Chinese Drywall" or any other environmental hazard, environmental pathogen, carcinogen, toxin, mycotoxin, pollutant, fungal presence or activity, or poison;
- (iv) types of wood or preservative treatment and fastener compatibility; or
- (v) the cause or source of a conditions;

(D) anticipate future events or conditions, including but not limited to:

- (i) decay, deterioration, or damage that may occur after the inspection;
 - (ii) deficiencies from abuse, misuse or lack of use;
 - (iii) changes in performance of any component or system due to changes in use or occupancy;
 - (iv) the consequences of the inspection or its effects on current or future buyers and sellers;
 - (v) common household accidents, personal injury, or death;
 - (vi) the presence of water penetrations; or
 - (vii) future performance of any item;
- (E) operate shut-off, safety, stop, pressure or pressure-regulating valves or items requiring the use of codes, keys, combinations, or similar devices;
- (F) designate conditions as safe;
- (G) recommend or provide engineering, architectural, appraisal, mitigation, physical surveying, realty, or other specialist services;
- (H) review historical records, installation instructions, repair plans, cost estimates, disclosure documents, or other reports;
- (I) verify sizing, efficiency, or adequacy of the ground surface drainage system;
- (J) verify sizing, efficiency, or adequacy of the gutter and downspout system;
- (K) operate recirculation or sump pumps;
- (L) remedy conditions preventing inspection of any item;
- (M) apply open flame or light a pilot to operate any appliance;
- (N) turn on decommissioned equipment, systems or utility services; or
- (O) provide repair cost estimates, recommendations, or re-inspection services.

THE CLIENT, BY ACCEPTING THIS PROPERTY INSPECTION REPORT OR RELYING UPON IT IN ANY WAY, EXPRESSLY AGREES TO THE SCOPE OF INSPECTION, GENERAL LIMITATIONS AND INSPECTION AGREEMENT INCLUDED IN THIS INSPECTION REPORT.

This inspection report is made for the sole purpose of assisting the purchaser to determine his and/or her own opinion of feasibility of purchasing the inspected property and does not warrant or guarantee all defects to be found. If you have any questions or are unclear regarding our findings, please call our office prior to the expiration of any time limitations such as option periods.

This report contains technical information. If you were not present during this inspection, please call the office to arrange for a consultation with your inspector. If you choose not to consult with the inspector, this inspection company cannot be held liable for your understanding or misunderstanding of the reports content.

The contents of this report are for the sole use of the client named above and no other person or party may rely on this report for any reason or purpose whatsoever without the prior written consent of the inspector who authored the report. Any person or party who chooses to rely on this report for any reason or purpose whatsoever without the express written consent of the inspector does so at their own risk and by doing so without the prior written consent of the inspector waives any claim of error or deficiency in this report.

This report is not intended to be used for determining insurability or warrantability of the structure and may not conform to the Texas Department of Insurance guidelines for property insurability. *This report is not to be used by or for any property and/or home warranty company.*

The digital pictures within this report are a representative sample of inaccessible areas, deficiencies or damages in place and should not be considered to show all of the inaccessible areas, deficiencies or damages observed. There will be inaccessible areas, deficiencies or damages not represented with digital imaging.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

I. STRUCTURAL SYSTEMS

A. Foundations

Type of Foundation(s): Slab on Ground

Comments:

Foundation Is Performing Adequately

In my opinion, the foundation appears to be providing adequate support for the structure at the time of this inspection. I did not observe any apparent evidence that would indicate the presence of adverse performance or significant deficiencies in the foundation. The interior and exterior stress indicators showed little affects of adverse performance and I perceived the foundation to contain no significant unlevelness after walking the 1st level floors.

Notice: This inspection is one of first impression and the inspector was not provided with any historical information pertaining to the structural integrity of the inspected real property. This is a limited cursory and visual survey of the accessible general conditions and circumstances present at the time of this inspection. Opinions are based on general observations made without the use of specialized tools or procedures. Therefore, the opinions expressed are one of apparent conditions and not of absolute fact and are only good for the date and time of this inspection.

The inspection of the foundation may show it to be providing adequate support for the structure or having movement typical to this region, at the time of the inspection. This does not guarantee the future life or failure of the foundation. **The Inspector is not a structural engineer. This inspection is not an engineering report or evaluation and should not be considered one, either expressed or implied.** If any cause of concern is noted on this report, or if you want further evaluation, you should consider an evaluation by an engineer of your choice.

B. Grading and Drainage

Comments:


Grading & Drainage

All components were found to be performing and in satisfactory condition on the day of the inspection.

Gutter & Downspout System

- Some of the guttering is pulling loose on the west side of the roof structure.

Note: The gutter downspouts should discharge water at least thirty-six inches (36") away from the foundation perimeter beam. Storm water should be encouraged to flow away from the structure at the points of discharge.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

C. Roof Covering Materials

Type(s) of Roof Covering: Composition

Viewed From: Drone

Comments:

Roof Covering

You are strongly encouraged to have a properly certified roofing contractor to physically inspect the roof, prior to the expiration of any time limitations such as option or warranty periods, to fully evaluate the condition of the roofing material. The observation made to support the rendering of this opinion are listed but not limited to the following:

- Damaged shingles were observed on the north side, south side of the roof structure.
- The composition roofing material has experienced considerable granular loss in various locations throughout the roof.

Note: Some discoloration of the roofing material was observed.

Note: The tree and shrub branches should be trimmed away from the roofing material at all times.



Flashing Details

The flashing details needs to be checked, reset or repaired as necessary. The observations made to support the rendering of this opinion are listed but may not be limited to:

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

- Some of the metal flashing details were observed to be rusted and should be corrected as necessary.
- One or more of the flashing detail flanges are not properly set into the roofing material. This condition needs to be corrected to help prevent water intrusion at this points.
- The storm collar(s) at the roof level gas equipment vent pipe(s) need to be properly sealed to help prevent water intrusion into the structure.



Skylight(s)

- The exterior surface (lens) of the skylight has some damage.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

Notice: Life expectancy of the roofing material is not covered by this property inspection report. If any concerns exist about the roof covering life expectancy or potential for future problems, a roofing specialist should be consulted. The Inspector cannot offer an opinion or warranty as to whether the roof has leaked in the past, leaks now, or may be subject to future leaks, either expressed or implied.

The inspection of this roof may show it to be functioning as intended or in need of minor repairs. This inspection does not determine the insurability of the roof. You are strongly encouraged to have your Insurance Company physically inspect the roof, prior to the expiration of any time limitations such as option or warranty periods, to fully evaluate the insurability of the roof.

D. Roof Structures and Attics

Viewed From: From Interior of Attic

Approximate Average Depth of Insulation: 13+”

(**Note:** Generally recommended depth of attic floor insulation is approximately 10+ inches to achieve a R30 rating.)

Insulation Type: Loose Filled, Batt or Blanket

Description of Roof Structure: Rafter Assembly

Attic Accessibility: Partial

Comments:

Roof Structure

- There are visible water stains/damage on a hip rafter in one or more locations.
- The fascia board material is pulling loose on the north side of the roof structure.



Attic Ventilation

All components were found to be performing and in satisfactory condition on the day of the inspection.

Attic Insulation

- The sidewall insulation was observed to be pulling loose in the attic area and should be corrected as necessary.

I=Inspected

NI=Not Inspected

NP=Not Present



D=Deficient

I	NI	NP	D
---	----	----	---



Attic Ladder

- One or more of the attic ladder components were observed to be damaged. This condition should be corrected for reasons of safety.



E. Walls (Interior and Exterior)

Comments:

Description of Exterior Cladding: Hard Coat Stucco

Interior Walls & Surfaces

- The baseboards were observed to be water stained and/or damaged in the laundry room, master bathroom. The cause and remedy should be further evaluated and corrected as necessary.
- Interior wall joint cracks were observed in the various locations throughout the house.
- The tape lines are pulling and/or twisting in the wall intersections in the front corner bedroom. This condition is sometimes related to adverse foundation performance and should be further evaluated.

Note: There is evidence of painting and patching to the interior finish and prior interior finish repairs. This condition could limit the Inspectors visual observations and ability to render accurate opinions as to the performance of the structure.

Note: Nail heads were observed to be pushing through the interior finish in one or more locations.


I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



Exterior Walls & Surfaces

- The area between the exterior cladding / veneer and all of the wall penetrations / openings need to be properly sealed. Areas such as utility connections, downspouts, hose bibbs, lighting fixtures, receptacles etc. It is recommended to use an elastomeric caulking / sealant.

Stucco (Hard Coat or EIFS) Observation and Opinions

There is a stucco type product installed as the exterior veneer / cladding for this structure. Due to the known general misapplication of residential stucco products, associated deficiencies and water intrusion problems; full evaluation of this product requires a specialty inspection from a Properly Certified Third Party Stucco Inspector.

At this time a general limited visually based survey of the accessible exterior stucco veneer / cladding will be performed without the use of any specialized tools or procedures. The Inspectors findings will be listed below but all possible deficiencies will not be limited to the following:

- Cracking of the stucco type veneer/cladding was observed on the north side of the structure. This condition should be further evaluated and corrected as necessary.
- There is visible evidence of water intrusion through the stucco cladding system on the west side of the structure. This condition has caused some visible damage to the stucco cladding. This condition should be further evaluated and corrected as necessary.
- The stucco finish was observed to be installed over the window weepholes at several of the windows on all sides of the structure.
- There is no visible through wall flashing (head flashing) above the windows. Under current stucco installation standards, there should be through wall flashing continuously above all windows to help prevent water intrusion at these locations.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

- The exterior stucco type veneer/cladding has inadequate clearance from the finished grade (ground). Most manufacturers require a minimum of 4- to 6-inches of clearance from the finished grade (ground).
- Some discoloration and/or staining of the stucco type veneer/cladding was observed on the west side of the structure.
- Some deterioration and/or damage to the stucco type veneer/cladding was observed on the west side of the structure.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



F. Ceilings and Floors

Comments:

Ceilings

- There was an unknown dark mold like substance observed in the guest bathroom. Evaluation of this substance is beyond the scope of this inspection. If any concerns exist on the type and/or nature of this substance, we recommend further evaluation by a professional in the Air Quality sampling field.

Note: There is evidence of painting and patching to the interior finish and prior interior finish repairs. This condition could limit the Inspectors visual observations and ability to render accurate opinions as to the performance of the structure.

Note: Nail heads were observed to be pushing through the interior finish in one or more locations.



Floors

- The floor covering was observed to be damaged in the master bedroom.
- The floor tile(s) were observed to be cracked and/or damaged in guest bathroom.

Note: The upstairs sub-floors (flooring) observed to squeak when walked over.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



G. Doors (Interior and Exterior)


Comments:

Interior Doors

All components were found to be performing and in satisfactory condition on the day of the inspection.

Exterior Doors

- Double cylinder locks were observed on one or more of the exterior exit (egress) doors. All exterior egress doors should be readily operable from the side from which egress is to be made without the use of a key or special knowledge or effort.



Overhead Garage Door

All components were found to be performing and in satisfactory condition on the day of the inspection.

H. Windows

Comments:

Window Screens

- One or more of the window screens were observed to be missing.

Windows

- The window is damaged in the front corner bedroom.

This confidential report is prepared exclusively for Prasad Ivaturi on 04/21/2018.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Note: I was unable to visually inspect or operate of some of the windows due to height, window treatments, personal effects, large, heavy or fragile storage and/or furniture.



I. Stairways (Interior and Exterior)

Comments:

All components were found to be performing and in satisfactory condition on the day of the inspection.

J. Fireplaces and Chimneys

Comments:

- The gas log assembly appears to be inoperative at the time of this inspection. I was unable to get the gas logs to respond to the pilot assembly / controls. This condition needs to be further evaluated and corrected as necessary.
- The fireplace chimney / vent pipe has inadequate clearance from combustible materials. Fireplace chimneys should have a minimum 2-inch of clearance (air space) from combustible material.



K. Porches, Balconies, Decks, and Carports

Comments:

Porches / Patio

All components were found to be performing and in satisfactory condition on the day of the inspection.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Driveway

All components were found to be performing and in satisfactory condition on the day of the inspection.

-

L. Other

Comments:



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

II. ELECTRICAL SYSTEMS

A. Service Entrance and Panels

Comments:

Panel Box



Box Rating and/or Main Disconnect Rating: 200 amps

Box Location: West Exterior Wall

Cabinet Manufacturer: Square D

Branch Circuit Wire Type: Copper

- One or more of the cabinet cover plate screws are missing and need to be replaced.
- There was no anti-oxidant gel observed on the exposed aluminum conductor terminations.
- The wires entering the electrical cabinet are not properly secured or protected from the sharp edges of the cabinet.



Distribution Wiring

- Electrical flex extension cords should not be used for permanent wiring or pass through walls or ceilings. The improper use of extension cord was observed in or around the attic area.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



Grounding / Bonding

- The bonding wire connection to the ground electrode rod has pulled loose and needs to be repaired as necessary.



B. Branch Circuits, Connected Devices, and Fixtures

Type of Wiring: Copper

Comments:

Receptacle Outlets

- One or more of the receptacles were observed to be loose at the wall mount in the various locations throughout the house.
- Not all of the laundry room receptacles appear to be connected to a ground fault circuit interrupter (GFCI) device. Under current electrical standards, all of the receptacles in the laundry room should have GFCI protection.
- Not all of the garage receptacles appear to be connected to a ground fault circuit interrupter (GFCI) device. Under current electrical standards, all of the garage receptacles should have GFCI protection. There New National Electrical (NEC) Code no longer has an exception for “non-appliance dedicated”.
- One or more of the receptacles were observed to be damaged in the front corner bedroom.
- One of the ground fault circuit interrupter (GFCI) devices does not appear to be functioning properly at the time of this inspection. The device in question is located in the north exterior wall.

Note: Some of the receptacles in the home were inaccessible and could not be reached for inspection due

I=Inspected


NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

to height, personal effects, heavy storage, furniture or conditions outside the control of the inspector.



Switches

All components were found to be performing and in satisfactory condition on the day of the inspection.

Note: I was unable to determine the operation end of one or more of the switches.

Fixtures

- One or more of the closet light fixtures appear to be installed without globes and/or covers. Safety precautions should be taken around these light fixtures.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
----------	-----------	-----------	----------



Smoke Alarms

All components were found to be performing and in satisfactory condition on the day of the inspection.

Note: It is recommended to replace the batteries in all of the smoke detectors once a year for reasons of safety.

Note: Due to location, height or conditions outside the control of the inspector, one or more of the smoke alarms were inaccessible and could not be tested at the time of this inspection.

Carbon Monoxide Alarms

All components were found to be performing and in satisfactory condition on the day of the inspection.

Doorbell / Chime

All components were found to be performing and in satisfactory condition on the day of the inspection.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS

A. Heating Equipment

Type of Systems:

Energy Sources:




Comments:

Downstairs Central Heating System – Energy Source: Gas

Brand Name: Unable To Determine

- The heater gas supply line is not equipped with a sediment trap just before the gas appliance connector. This condition does not meet current installation requirements and should be corrected.

Samples of correct sediment trap installation.



Central Heating System – Energy Source: Gas

Brand Name: Unable To Determine

I=Inspected


NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

- The heater gas supply line is not equipped with a sediment trap just before the gas appliance connector. This condition does not meet current installation requirements and should be corrected.
- The roof level flue storm collar needs to be properly sealed to help prevent water intrusion into the structure.
- The heating unit flue (vent pipe) has inadequate clearance from combustibile materials. Double walled vent pipes should have at least 1-inch of clearance and single walled vent pipes should have at least 6-inches of clearance from combustibile material.



B. Cooling Equipment

Type of Systems:

Comments:

Downstairs Central Cooling System

Today's Temperature Differential (Delta-T): 18

Approximate System Age: **2014**

Approximate System SEER: **14**

Approximate System Size: **4 ton**

Brand Name: Trane

- The dirty air filter should be replaced.
- The auxiliary/secondary drain pan under the coil housing is rusted through and should be replaced.
- The electrical service disconnect is installed behind the outside condenser/coil. This does not meet the clearance requirements of the National Electrical Code or the International Residential Code and should be corrected as necessary.

Note: The heavy foliage at and around the outside condenser/coils should be trimmed back a minimum of 18-inches to help improve air circulation.


I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



Upstairs Central Cooling System

Today's Temperature Differential (Delta-T): 17

Approximate System Age: 2013

Approximate System SEER: 14

Approximate System Size: 3 ton

Brand Name: Trane

- The auxiliary/secondary drain pan under the coil housing is rusted through and should be replaced.

Note: Previous water leakage was observed from around the base of the indoor coil housing. This condition should be closely monitored.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



Notice: Temperature differential readings (Delta-T) are an accepted industry standard of practice for testing the proper operation of the cooling system. Our company policy normal acceptable range is considered approximately **between 15 to 20 degrees °F** total difference (Delta-T) measured between the return air and supply air within close proximity of the related coils of the system being evaluated. Conditions such as but not limited to; excessive humidity, high or low outdoor temperatures or restricted airflow may indicate abnormal operation even through the equipment is functioning basically as designed and occasionally may indicate normal operation in spite of an equipment malfunction. *The inspector will not be able to anticipate future events, conditions or changes in performance of any component or system due to changes in use or occupancy. The inspector makes no guarantee or warranty, express or implied, as to future performance of any item, system or component.*

C. Duct Systems, Chases, and Vents

Comments:

- The duct work in the attic area does not appear to be properly suspended and separated to help prevent condensation from developing. It is recommended to separate and suspend the duct work with supports in minimum intervals of 4-feet that have a minimum width of 1.5-inches.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

IV. PLUMBING SYSTEM

A. Plumbing Supply, Distribution Systems and Fixtures

Location of water meter: Within 5-feet of Front Curb

Location of main water supply valve: Garage Area

Static water pressure reading: 50 to 60 psi

Comments:

Water Supply System

All components were found to be performing and in satisfactory condition on the day of the inspection.



Exterior Faucets/Fixtures

All components were found to be performing and in satisfactory condition on the day of the inspection.

Laundry Sink

All components were found to be performing and in satisfactory condition on the day of the inspection.

Wet Bar Sink

All components were found to be performing and in satisfactory condition on the day of the inspection.



Laundry Connections

- Some rust and/or corrosion was observed at the laundry connection hose bibbs.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



Kitchen Sink

All components were found to be performing and in satisfactory condition on the day of the inspection.

Note: Previous water leaks were observed at and/or around the drain connections under the sink. This would indicate previous problems and should be closely monitored and corrected when necessary.



Guest Bath

Bathtub

- The bathtub shower head diverter is not functioning properly.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



Shower

- The faucet assembly is not sealed at the wall. This condition has the potential to allow water to leak back into the wall cavity.



Master Bathroom

Shower

- The faucet assembly is not sealed at the wall. This condition has the potential to allow water to leak back into the wall cavity.
- Cracked, deteriorated and/or missing shower stall grout and/or caulking should be repaired or replaced as necessary.


I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



Downstairs Guest Bathroom

Shower

- The faucet assembly is not sealed at the wall. This condition has the potential to allow water to leak back into the wall cavity.
- The faucet has a slow leak when off.
- Cracked, deteriorated and/or missing shower stall grout and/or caulking should be repaired or replaced as necessary.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

Half Bath

All components were found to be performing and in satisfactory condition on the day of the inspection.

Notice: The Inspector has attempted to discover and report conditions requiring further evaluation or repair. However; determining the condition of any component that is not visible and/or accessible, such as plumbing components that are buried, beneath the foundation, located within construction voids or otherwise concealed, and reporting any deficiency that does not appear or become evident during our limited cursory and visual survey is outside the scope of this inspection. **The inspector will not be able to anticipate future events, conditions or changes in performance of any component or system due to changes in use or occupancy. The inspector makes no guarantee or warranty, express or implied, as to future performance of any item, system or component.**

B. Drains, Wastes, and Vents

Comments:

The plumbing cleanout cover(s) located in the yard were observed to be missing on the north side of the structure.



Notice: Reporting the condition of drains, wastes and vent piping that is not completely visible and/or accessible or; reporting any defect or deficiency that requires extended use of the system to develop or does not become evident during our limited cursory and visual survey is outside the scope of the inspection. This is a limited cursory and visual survey of the accessible general conditions and circumstances present at the time of this inspection. Opinions are based on general observations made without the use of specialized tools or procedures. Therefore, the opinions expressed are one of apparent conditions and not of absolute fact and are only good for the date and time of this inspection. **The inspector will not be able to anticipate future events, conditions or changes in performance of any component or system due to changes in use or occupancy. The inspector makes no guarantee or warranty, express or implied, as to future performance of any item, system or component.**

C. Water Heating Equipment

Energy Sources:

Capacity:

Comments:

Water Heater –Energy Source: **Gas**

Location: **Attic**

Approximate Capacity: **40 Gallons**

Approximate Age: **1998**

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



Brand Name: A.O. Smith

The buyer should have the water heater checked by a Qualified Licensed Plumber. The observations made to support the rendering of this opinion are listed but not limited to the following:

The water heater appears to be reaching the end of its serviceable life expectancy.

- The water heater is making a rumbling noise when operated. This is a good indicator that there is a lot of sediment in the bottom of the water heater tank. Cleaning and servicing is recommended.
- The water heater gas supply line is not equipped with a sediment trap just before the gas appliance connector. This condition does not meet current installation requirements and should be corrected.
- The roof level flue storm collar needs to be properly sealed to help prevent water intrusion into the structure.
- There is a surface damage on the water. This condition needs to be further evaluated and corrected.

Samples of correct sediment trap installations





I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



D. Hydro-Massage Therapy Equipment

Comments:

Location of GFCI: Unable to locate a GFCI for equipment.

- I was unable to locate a ground fault circuit interrupter (GFCI) receptacle or breaker for the hydro-massage therapy equipment. The homeowner should be consulted on the location of this GFCI device. If there is no GFCI device installed on the hydro-massage therapy equipment circuit, a GFCI receptacle or breaker should be installed for reasons of safety.
- The hydro-massage therapy equipment appears to be inoperative at the time of this inspection. This condition should be further evaluated and corrected as necessary.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



E. Gas Distribution System

Comments:

- All unused gas valve ends should be capped off for safety purposes.



Notice: The Inspector will use a combustible gas leak detector on accessible gas lines, joints, unions and connectors and report visible deficiencies found at the time and date of the inspection. The inspector inspects the gas lines from the point they enter the structure and will complete the inspection without digging, damaging property, permanent construction or building finish. When performing the inspection, the inspector will keep in consideration the age of the system and normal wear and tear from ordinary use when rendering opinions.

The inspector is not required to and will not inspect sacrificial anode bonding or for its existence. The Inspector is not licensed to and will not perform a pressure test on the gas line system. The Inspector cannot detect gas leaks below the finished grade (underground), construction voids, between the walls or behind fireplace hearths. Propane tanks will not be inspected. If any further concerns exist about possible gas line failure and/or deficiencies or code compliance, we recommend the buyer have the gas system further evaluated by the local controlling gas supplier and/or a qualified licensed master plumber prior to the expiration of any time limitations such as option or warranty periods.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

V. APPLIANCES

-

A. Dishwashers

Comments:

Brand Name: Frigidaire


This component appears to be performing adequately at the time of this inspection.

-

B. Food Waste Disposers

Comments:

- The food waste disposer is leaking water into the cabinet area. This condition should be further evaluated and corrected as necessary.
- The electrical wiring to the disposal is exposed and should be enclosed in conduit.
- The disposer housing is corroded.



-

C. Range Hood and Exhaust Systems

Comments:

This component appears to be performing adequately at the time of this inspection.

-

D. Ranges, Cooktops, and Ovens

Comments:

Cooktop Brand Name: Frigidaire

This component appears to be performing adequately at the time of this inspection.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



Built-in Oven Brand Name: Frigidaire

This component appears to be performing adequately at the time of this inspection.

E. Microwave Ovens

Comments:


Brand Name: Frigidaire

This component appears to be performing adequately at the time of this inspection.

F. Mechanical Exhaust Vents and Bathroom Heaters

Comments:

- The mechanical exhaust vents were observed to be venting into the attic area. Under current building standards, all mechanical exhaust vents should vent to the exterior of the structure. This is an “**as-built**” condition.
- The ducting to one of the mechanical exhaust fans was observed to be damaged in the attic area over the bedroom hallway.



G. Garage Door Operators

Comments:

- When an automatic garage door opener is in use, the manual lock should be disabled or removed.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
----------	-----------	-----------	----------

- The manual release (emergency release) cord is missing at the garage door opener connection.

H. Dryer Exhaust Systems

Comments:

This component appears to be performing adequately at the time of this inspection.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

VI. OPTIONAL SYSTEMS

A. Landscape Irrigation (Sprinkler) Systems

Comments:

When the system is operational, all of the sprinkler system associated components are inspected and operated in the manual settings only.

Note: Some municipalities now require moisture (rain/freeze) sensors to be installed on all new installation and existing sprinkler systems. Our company does not maintain a list of municipalities that require the installation of a moisture sensor. Please check with your municipality for moisture sensor requirements. Sprinkler system equipped with a moisture (rain/freeze) sensor Yes or No.

Total Number of Zones Wired: 3

Sprinkler System and Associated Components

The sprinkler system and associated components should be further evaluated and/or serviced by a Licensed Irrigation Technician. The observations made to support the rendering of this opinion are listed but not limited to the following:

- One or more of the sprinkler heads need to be adjusted so not to spray water onto the exterior walls, surfaces or windows in stations; **1, 2, 3.**
- I was unable to locate a moisture (rain / freeze) sensor device for the sprinkler system. This is an **“as-built” condition**, but Per TREC standards of practice we are required to report this condition as a deficiency.
- There appears to be a sub-surface leak or damaged water lines in station(s); **2, 3.** The cause and remedy should be further evaluated and corrected as necessary.
- One or more of the sprinkler heads need to be adjusted so not to spray water into the pool in stations **3.**



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



INSPECTION AGREEMENT
PLEASE READ THIS AGREEMENT CAREFULLY BEFORE SIGNING

This Inspection Agreement (herein after known as the Agreement) is entered into on this day, 04/21/2018, between Prasad Ivaturi (herein known as the Client) and A-Action Home Inspection Group (herein known as the Inspector) for the purpose of performing a general property condition inspection concerning 2719 Newman St (herein known as the property).

I. SCOPE OF SERVICES

- A. A real estate inspection is a non-technically exhaustive, limited visual survey and basic performance evaluation of the systems and components of a building using normal controls and does not require the use of specialized equipment or procedures. The purpose of the inspection is to provide the Client with information regarding the general condition of the Property at the time of inspection.
- B. In exchange for the inspection fee (**\$\$639.00**) paid by the Client, the Inspector agrees to provide the Client with an Inspection Report setting out the Inspector's professional opinions concerning the condition of the Property further described in the report. The inspection will be performed in accordance with the Standards of Practice promulgated by the Texas Real Estate Commission. Inspector will attempt to identify major defects and problems with the Property. However, Client acknowledges that the Inspection Report may not identify all defects or problems.
- C. The inspection is limited to those items which are easily accessible, seen, viewed or capable of being approached, entered and/or operated by the Inspector at the time of the inspection as set out in the Inspection Report. The Inspector will not climb over obstacles, move furnishings or large, heavy, or fragile objects, remove walls, floors, wall coverings, floor coverings and other obstructions in order to inspect concealed items. The inspector will not turn on decommissioned equipment, systems, utility services. Systems, components and conditions which are not specifically addressed in the Inspection Report are excluded.
- D. The Inspection Report may indicate one of the following opinions of the Inspector regarding a particular item:
 - 1. The item is performing its intended function, achieving an operation, function or configuration relative to accepted industry standard practices with consideration of age and normal wear and tear from ordinary use at the time of the inspection;
 - 2. The item is in need of replacement, maintenance or repair; or
 - 3. Further evaluation by an expert is recommended.

II. INSPECTION REPORT

- A. The Inspection Report provided by the Inspector will contain the Inspector's professional, good-faith opinions concerning the need for repair or replacement of certain observable items. All statements in the report are the Inspector's opinions and should not be construed as statements of fact or factual representations concerning the Property. **By signing this Agreement, the Client understands that the services provided by the Inspector fall within the Professional Services Exemption of the Texas Deceptive Trade Practices Act ("DTPA") and agrees that no cause of action exists under the DTPA related to the services provided.**
- B. **Unless specifically stated, the report WILL NOT INCLUDE and should not be read to indicate OPINIONS AS TO:**
 - 1. the presence, absence, or risk of environmental conditions such as asbestos, lead-based paint, **MOLD**, mildew, corrosive or contaminated drywall "Chinese Drywall" or any other environmental hazard, environmental pathogen, carcinogen, toxin, mycotoxin, pollutant, fungal presence or activity, poison, presence of toxic or hazardous waste or substances;
 - 2. presence or absence of pests, termites, or other wood-destroying insects or organisms;
 - 3. **COMPLIANCE WITH compliance with any ordinances, statutes or restrictions, CODE, listing, testing or protocol authority, utility sources, property association guidelines or requirements, manufacturer or regulatory requirements;**
 - 4. insurability, efficiency warrantability, suitability, adequacy, compatibility, capacity, durability, quality reliability, marketability, operating costs, recalls, counterfeit products, product lawsuits, age, energy efficiency; or
 - 5. anticipate future life or future events or changes in performance of any item inspected.
- C. The Inspection Report is not a substitute for disclosures by sellers and real estate agents. Said disclosure statements should be carefully investigated for any material facts that may influence or effect the desirability and/or market value of the Property.
- D. As noted above, the Inspection Report may state that further evaluation of certain items is needed by an expert in the field of the item inspected. By signing this Agreement, Client acknowledges that qualified experts may be needed to further evaluate such items as structural systems, foundations, grading, drainage, roofing, plumbing, electrical systems, HVAC, appliances, sprinkler systems pool system and components, fire/smoke detection systems, septic systems and other observable items as noted in the report. Any such follow-up should take place prior to the expiration of any time limitations such as option or warranty periods.

This confidential report is prepared exclusively for Prasad Ivaturi on 04/21/2018.

III. DISCLAIMER OF WARRANTIES

The inspector makes no guarantee or warranty, express or implied, as to any of the following:

1. That all defects have been found or that the Inspector will pay for repair of undisclosed defects;
2. That any of the items inspected are designed or constructed in a good and workmanlike manner;
3. That any of the items inspected will continue to perform in the future as they are performing at time of the inspection; and
4. That any of the items inspected are merchantable or fit for any particular purpose.

IV. LIMITATION OF LIABILITY

BY SIGNING THIS AGREEMENT, CLIENT ACKNOWLEDGES THAT THE INSPECTION FEE PAID TO THE INSPECTOR IS NOMINAL GIVEN THE RISK OF LIABILITY ASSOCIATED WITH PERFORMING HOME INSPECTIONS IF LIABILITY COULD NOT BE LIMITED. CLIENT ACKNOWLEDGES THAT WITHOUT THE ABILITY TO LIMIT LIABILITY, THE INSPECTOR WOULD BE FORCED TO CHARGE CLIENT MUCH MORE THAN THE INSPECTION FEE FOR THE INSPECTOR'S SERVICES. CLIENT ACKNOWLEDGES BEING GIVEN THE OPPORTUNITY TO HAVE THIS AGREEMENT REVIEWED BY COUNSEL OF HIS OR HER OWN CHOOSING AND FURTHER ACKNOWLEDGES THE OPPORTUNITY OF HIRING A DIFFERENT INSPECTOR TO PERFORM THE INSPECTION. BY SIGNING THIS AGREEMENT, CLIENT AGREES TO LIABILITY BEING LIMITED TO THE AMOUNT OF THE INSPECTION FEE PAID BY THE CLIENT. \$639.00

V. DISPUTE RESOLUTION

In the event a dispute arises regarding an inspection that has been performed under this agreement, the Client agrees to notify the Inspector within ten (10) days of the date the Client discovers the basis for the dispute so as to give the Inspector a reasonable opportunity to reinspect the property. Client agrees to allow reinspection before any corrective action is taken. Client agrees not to disturb or repair or have repaired anything which might constitute evidence relating to a complaint against the Inspector. Client further agrees that the Inspector can either conduct the reinspection himself or can employ others (at Inspector's expense) to reinspect the property, or both. In the event a dispute cannot be resolved by the Client and the Inspector, the parties agree that any dispute or controversy shall be resolved by mandatory and binding arbitration administered by the American Arbitration Association ("AAA") pursuant to Chapter 171 of the Texas Civil Practice & Remedies Code and in accordance with this arbitration agreement and the commercial arbitration rules of the AAA.

VI. ATTORNEY'S FEES

The Inspector and the Client agree that in the event any dispute or controversy arises as a result of this Agreement, and the services provided hereunder, the prevailing party in that dispute shall be entitled to recover all of the prevailing party's reasonable and necessary attorneys' fees and costs incurred by that party.

VII. EXCLUSIVITY

The Inspection Report is to be prepared exclusively for the Client and is not transferable to anyone in any form. Client gives permission for the Inspector to discuss report findings with real estate agents, specialists, or repair persons for the sake of clarification. A copy of the Inspection Report may be released to the buyers Real Estate Agent.

BY MY SIGNATURE BELOW, I ACKNOWLEDGE THAT I HAVE READ THIS CONTRACT AND THAT THE INSPECTOR DID NOT COERCE, PRESSURE OR RUSH ME TO EXECUTE THIS CONTRACT WITHOUT OPPORTUNITY TO FULLY REVIEW THE CONTRACT AND IF NECESSARY HAVE THE CONTRACT REVIEWED BY AN ATTORNEY; THAT INSPECTOR AGREED TO RESCHEDULE THE INSPECTION IN THE EVENT I REQUIRED ADDITIONAL TIME TO REVIEW THE CONTRACT; THAT I UNDERSTAND THE TERMS AND CONDITIONS AND THAT I AGREE TO BE BOUND BY THESE TERMS AND CONDITIONS. IF CLIENT IS MARRIED, CLIENT REPRESENTS THAT THIS OBLIGATION IS A FAMILY OBLIGATION INCURRED IN THE INTEREST OF THE FAMILY.

Client Signature: _____

Date: 04/21/2018

Inspector: Brendan Hirshey

Property was Vacant

Client Present during Inspection: Yes

Termite Report is Paid in Full
Termite Warranty Offered: No

(1A.) Name of Inspection Company: Sharpeye Pest Control (1C.) 1305 Edwinstowe Ln Houston Texas 77043
713-730-3151 (1B.) SPCS Business License Number#0773025

4A. Prasad Ivaturi Seller Agent Buyer Management Co. Other
Name of Person Purchasing Inspection
2719 Newman St Houston, TX 77098
Inspected Address Telephone No.

1D. Brendan Hirshey #773025 Name of Inspector (Please Print)
1E. Certified Applicator Technician (check one)

2. Unknown Case Number (VA/FHA/Other)
3. Saturday, April 21, 2018 Inspection Date

4B. Not Determined Owner/Seller

4C. REPORT FORWARDED TO: Title Company or Mortgagee Purchaser of Service Seller Agent Buyer
(Under the Structural Pest Control Service of the Texas Department of Agriculture regulations only the purchaser of the service is required to receive a copy)

SCOPE OF INSPECTION / AGREEMENT

- A. This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guest houses or any other structure will not be included in this inspection report unless specifically noted in Section 5 of this report.
B. This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work.
C. Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment, has rendered the pest(s) inactive.
D. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is present.
E. If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified expert.
F. THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS.
G. If termite treatment (including pesticides, baits or other methods) has been recommended, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticides to be used and complete details of warranty (if any). At a minimum, the warranty must specify which areas of the structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party.
H. There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and renewal options.
I. There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure, (2) there is visible evidence of a previous infestation with no evidence of a prior treatment.
J. If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture.

Sharpeye Pest Control Additional Statements Included in the Scope of Inspection / Agreement that are not Promulgated by the Structural Pest Control Service

- A. This inspection is only good for the date and time of the inspection. Sharpeye Pest Control, its Inspectors, employees and agents will not guarantee or warrant the absence of any wood destroying insect. Due to the characteristics and behavior of various wood destroying insects, the insects may not be visible or detectable on the date and time of the inspection. Even with the best inspection, termites can remain hidden and unnoticed for a long period of time. Swarming of wood destroying insects can occur in a short amount of time and may by the first signs of the presence of wood destroying insects that were not detectable at the time of the original inspection. If swarming occurs after the date and time of the original inspection and active wood destroying insects were not detectable at the time of the original inspection. Sharpeye Pest Control, its Inspectors, employees and agents cannot be liable for the non-detectable infestation and will not assume any liability for corrective actions needed and will not assume liability for non-detectable wood damage.
B. Sharpeye Pest Control Standard Operational Inspection Procedures: The Inspector will perform a visual inspection of the visible and accessible foundation perimeter beam (slab-on-grade foundation), visual inspection of the visible and accessible exterior perimeter beam and accessible interior perimeter beam and piers (pier-&-beam foundation), probe visible and accessible exterior wood for active or signs of previous activity of a wood destroying insects, visual inspection of the structures accessible interior walls, ceiling, baseboards and cabinetry and visual inspection of the accessible areas of the attic. The inspector will not deface the structure, cut holes, remove panels, pull back carpet, lift floor treatments, cut holes in the floors, wall or ceilings, move boxes, furniture, personal items or effects. The inspector will then complete this WDIR using the SPCS required standards for completing this form. These standards can be provided to you upon request.
C. Additional Information from Sharpeye Pest Control. AREAS OF POTENTIAL NON-VISIBLE WOOD DESTROYING INSECT ACTIVITY AREAS ARE LISTED BUT NOT LIMITED TO THE FOLLOWING: In the wall voids at the bathroom bathtubs and shower stalls/enclosures, plumbing penetrations within the construction wall voids, below high soil lines, behind heavy foliage, non-visible slab joints, non-visible slab cracks, under and/or behind decks and/or raised patios, behind cosmetic repairs of the foundation beam, within sill plates and between sub-floors and any other area that the Inspector marks as inaccessible in section 6B of this report. Sharpeye Pest Control and its Inspectors, employees and agents will not assume any liability for active infestation of a wood destroying insect that is not visible and/or accessible to the Inspector at the time of the original inspection.
D. The Inspector will do his/her best to access and to inspect all accessible and visible areas and/or components of the structure. This inspection is only good for the date and time of this inspection and Sharpeye Pest Control, its Inspectors, employees and agents will not assume any liability for non-accessible areas and non-visible wood destroying insects. If for any reason you are unhappy with the performance of the Inspector, his/her findings or unwilling to accept the scope of this inspection. Sharpeye Pest Control will be more than happy to refund to you the cost of this inspection within ten business day's from the date of the original inspection. The refund is contingent on you surrendering all copies of this inspection report back to Sharpeye Pest Control and you releasing Sharpeye Pest Control, its employee and its agents from all future liabilities to the inspected property. This refund cannot be made if the report has already been used to close on a real estate transaction.

The structure(s) listed below were inspected in accordance with the official inspection procedures adopted by the Texas Structural Pest Control Service. This report is made subject to the conditions listed under the Scope of Inspection. A diagram must be attached including all structures inspected.

5. List structure(s) inspected that may include residence, detached garages and other structures on the property. (Refer to Part A, Scope of Inspection):

- [X] Main House (Excluding all Detached Structures, Sheds, Shrubs, Trees, Barns, Fences and Decks)
[] Main House & Detached Garage (Excluding all other Detached Structures, Sheds, Shrubs, Trees Barns, Fences and Decks)
[] Other Inspected Structures:

6A. Were any areas of the property obstructed or inaccessible? Yes [X] No []
(Refer to Part B & C, Scope of Inspection) If "Yes" specify in 6B.

6B. The obstructed or inaccessible areas include but are not limited to the following:

- Attic [] Plumbing Areas [X] Planter box abutting structure [] Slab Joints [X]
Attic Partially Accessible [X] Bath-trap(s) [X] Below or Behind High Soil Grade [X] Cracks in Slab [X]
Insulated areas of attic [X] Construction Voids [X] Wood Pile in Contact with Structure [] Crawl Space []
Inside Eaves [X] Recent Renovation(s) [] Behind Personal Effects / Furniture [X] Sub Floors []
Deck [] Blocked/Stored Areas [X] Debris Piled Next to Structure [] Weepholes []
Behind Storage in Garage [X] Under Floor Covering [X] Crawl Space Partially Accessible [] Heavy Foilage []
Raised Concrete, Brick and/or Stone at Patio/Porch(s) [] Behind Foundation Beam Cosmetic Repair [X]
Foundation Corner Pops [X] Foundation Plumbing Penetrations [X]

Other [] Specify: _____

7A. Conditions conducive to wood destroying insect infestation? Yes No

7B. Conducive Conditions include but are not limited to:

- Wood to Ground Contact (G) Standing Water in Crawl Space (SW) Wood Pile in Contact with Structure or within Dripline (Q)
Formboards left in place (I) Planter box abutting structure (O) Wooden Fence in Contact with the Structure (R)
Excessive Moisture (J) Debris under or around structure (K) Footing soil line too high (L)
Footing soil line too low (L) Insufficient ventilation (T) Tree Branches in Contact with Roof Structure (TB)
Heavy Foliage (N) Wood Rot (M) Flowerbed Wood Formers within Dripline (F)
Other (C) Specify Other: _____

- Other: Wood Fence within Drip Line (Conducive by Design) (WF)
Other: Wood Deck in Contact with Structure (Conducive by Design) (WD)
Other: Planter Box abutting Structure (Conducive by Design) (OD)
Other: Wood in concrete expansion joints. (Conducive by Design)
Other: Plumbing penetrations (Conducive by Design)

8. Inspection Reveals Visible Evidence in or on the structure: Active Infestation Previous Infestation Previous Treatment
8A. Subterranean Termites Yes No Yes No Yes No
8B. Drywood Termites Yes No Yes No Yes No
8C. Formosan Termites Yes No Yes No Yes No
8D. Carpenter Ants Yes No Yes No Yes No
8E. Other Wood Destroying Insects Yes No Yes No Yes No

8F. Explanation of signs of previous treatment (including pesticides, baits, existing treatment stickers or other methods) identified: N/A

8G. Visible evidence of: N/A has been observed in the following areas:
If there is visible evidence of active or previous infestation, it must be noted. The type of insect(s) must be listed on the first blank and all identified infested areas of the property inspected must be noted in the second blank. (Refer to Part D, E & F, Scope of Inspection)

The conditions conducive to insect infestation reported in 7A & 7B:
9. Will be or has been mechanically corrected by inspecting company: Yes No

If "Yes", specify corrections:
9A. Corrective treatment recommended for active infestation or evidence of previous infestation with no prior treatment as identified in Section 8. (Refer to Part G, H and I, Scope of Inspection) Yes No

9B. A preventive treatment and/or correction of conducive conditions as identified in 7A & 7B is recommended as follows: Yes No
Specify reason: The high soil line(s) need to be corrected. If active wood destroying insects are discovered during the correction process, treatment will be required. The heavy foliage needs to be trimmed at least 18-inches off the exterior walls.
Refer to Scope of Inspection Part J

10A. This company has treated or is treating the structure for the following wood destroying insects: No Treatment Performed at this time.

If treating for subterranean termites, the treatment was: Partial Spot Bait Other
If treating for drywood termites or related insets, the treatment was: Full Limited

10B. N/A Date of Treatment by Inspecting Company N/A Common Name of Insect N/A Name of Pesticide, Bait or Other Method


This company has a contract or warranty in effect for control of the following wood destroying insects:
Yes No List Insects: Sharpeye Pest Control carriers No Warranty on this property expressed or implied.
If "Yes", copy(ies) of warranty and treatment diagram must be attached.

Diagram of Structure(s) Inspected

Foundation Type: **Slab on Ground**

Primary Use: **Residential**

The inspector must draw a diagram including approximate perimeter measurements and indicate active or previous infestation and type of insect by using the following codes:
 (E)=Evidence of infestation; (A)=Active; (P)=Previous; (D)=Drywood Termites; (S)=Subterranean Termites;
 (F)=Formosan Termites; (C)=Conducive Conditions; (B)=Wood Boring Beetles; (H)=Carpenter Ants;
 (X)=Drill Holes; (BS)=Bait Stations; Other(s) - Specify _



Additional Comments There is no visible evidence of active wood destroying insects found at the time of this inspection.

Notice to Client: There is always a possibility of the presence of undetectable activity of wood destroying insects. THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is present, whether visible or non-visible.

Neither I nor the company for which I am acting have had, presently have, or contemplate having any interest in the property. I do further state that neither I nor the company which I am acting is associated in any way with any party to the transaction.

Signatures:

11A. Brendan Hirshey #773025
Inspector

Notice of Inspection Was Posted At or Near

- 12A. Electric Breaker Box
- Water Heater Closet
- Bath Trap Access
- Beneath the Kitchen Sink

Approved:
11B. Chris Murphy #757185 / Saturday, April 21, 2018
Certified Applicator and Certified Applicator License Number

12B. Date Posted 04/21/2018
Date

Statement of Purchaser

I have received the original or a legible copy of this form. I have read and understand any recommendations made. I have also read and understand the "Scope of Inspection." I understand that my inspector may provide additional information as an addendum to this report.

If additional information is attached, list number of pages: Texas Real Estate Inspection Report

Signature of Purchaser of Property or their Designee

Date

The digital pictures within this report are a representative sample of active/previous wood destroying insects, locations of active/previous infestations, inaccessible areas, conducive conditions, deficiencies or damages in place and should not be considered to show all. There will be active/previous wood destroying insects, locations of active/previous infestations, inaccessible areas, conducive conditions, deficiencies or damages not represented with digital imaging.

