# **PROPERTY INSPECTION REPORT**

## 15 Taupewood Place, Conroe, TX, 77384

YEAR BUILT: 2001 SIZE: 3077 Sq Ft sq ft INSPECTION PREPARED FOR: Matt Short INSPECTOR: Robert Saji LICENSE: License # 10287

DATE & TIME OF INSPECTION: 9/7/2020 WEATHER: Clear & Hot





, , ,
 robert.saji@housecheck.com
 832.526.2244

Droporod

	PROPERTY INSPECTION REPORT	
For <sup>.</sup>	Matt Short	

Fiepaleu I UI.					
	(Name of Client)				
Concerning:	15 Taupewood Place, Conroe, TX 77384				
	(Address or Other Identification of Inspected Property)				
By:	Robert Saji, License # 10287	9/7/2020			
	(Name and License Number of Inspector)	(Date)			

### PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods.

Promulgated by the Texas Real Estate Commission (TREC) P.O. Box 12188, Austin, TX 78711-2188 (512) 936-3000 (http://www.trec.texas.gov).

Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

## TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices for electrical
- receptacles in garages, bathrooms, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms require a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

## ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

HouseCheck			15 Taupewood Place, Conroe, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP I	)		
	I. ST	RUCTURAL SYSTEMS	6
x	A. Foundations		
	Type of Foundation(s) • Post - Tension type f Comments: • About Foundations:	: oundation (typical for ho	omes built after 1980)
	Foundations are design components of a dwell ground. Foundation m systems of the house. soil and, during the life that do not operate pro-	ned to provide a base for ling as well as transfer to ovement can have a ne Slab-on-grade foundation the foundation, you ca operly, as well as cracks	e slab or pier and beam. For the framing and structural the weight of the dwelling to the sgative impact on the structural ions are designed to move with the n expect to find doors and windows is to interior/exterior walls. These are dation failure or adverse
	Inspectors' opinions a components. Imperfect coverings, behind wall engineering measurer condition of any found professional for furthe • Note: No signs of set time of the inspection. • Performance of foun	re limited to the visible in stions can be obstructed ls, landscaping and othe nents or perform any tes ation. We recommend f r evaluation and diagnos ttlement were observed dation: It is the profession	on are not visually accessible. Interior and exterior structural or hidden behind wall and floor er items. Inspectors do not take sts that would indicate the exact further evaluation by a qualified sis if there are concerns. to the foundation structure at the onal opinion of the inspector that the ded at the time of the inspection.
		DRIVEWAY OK	

## HouseCheck 15 Taupewood Place, Conroe, TX NP=Not Present D=Deficient I=Inspected NI=Not Inspected NI NP D B. Grading and Drainage Х Comments. About Grading and Drainage: Proper grading and drainage away from the structure is vital to the performance of the foundation. Water intrusion can cause wood rot, attract insects and encourage growth of possible organic materials. As a general rule, the ground should slope 6" within the first 10' away from the house. Clearance to wall siding should be at least 4" for brick, stone, or fiber cement and 6" for any other siding materials. Grading and drainage is inspected visually around the site. Flood plain research, soil and topographical studies are not performed as a part of the inspection. Any deficiencies found could be an indication of a more serious condition and should be evaluated by a qualified professional if there are concerns. Underground drainage was observed at the time of inspection. This is not tested as it is beyond the scope of this inspection. • NOTE: all slopes of the roof should be guttered to ensure that water is adequately diverted away from the structure. Evidence of standing water (ponding) was observed against or near the foundation. Poor grading was noted. This condition should be improved to promote the flow of water away from the structure. • Splash block(s) at the base of the gutter downspouts should be added to prevent erosion of soil from grade. Downspouts should be present to adequately direct water away from the foundation. NO GUTTER SECTIONS NO GUTTER SECTIONS





FRENCH DRAINS PRESENT OK

HouseCheck			15 Taupewood Place, Conroe, T
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
x	C. Roof Covering Mate	rials	
	and/or exterior. If a roc materials which can be Therefore, client is adv	30 Year Rated sually inspected from a of is too high, is too stee damaged if walked up	ccessible points on the interior p, is wet, or is composed of on, the roof is not mounted. d review and a licensed roofer is desired.
	About Roof Covering	s:	
	water from penetrating covering materials, une The roof is inspected v locations of the roof. N guarantee that all dam always recommend co any concerns or a nee	the structure. These sy derlayment, metal flash visually and is limited to lany elements of the ro- age, installation defects nsultation with a qualified to determine insurabi ich may arise. Any defie	yers that come together to keep ystems include the outer roof ings, sheathing, and roof decking. what can be seen at all accessible of are hidden and there is no s, and leaks can be detected. We ed roofing professional if there are lity, life expectancy, or the potential ciencies found could be an
	<ul> <li>This generally consists to-roof intersections.</li> <li>The roof covering wa time of inspection.</li> <li>There is debris from a roof coverings ability to</li> </ul>	s of resealing gaps at th s inspected and show t nearby tree on roof cov	an annual or semi-annual basis. rough-the-roof projections and wall- ypical signs of wear and age at the ering. This debris can impede the aks and premature aging of the roof n debris.

ROOF COVERING; RIGHT

ROOF COVERING; FRONT





DEBRIS AT ROOFTOP

HouseCheck			15 Taupewood Place, Conroe, T>
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP	D		
x	D. Roof Structure and	Attics	
	Viewed From: • Walked deck or safe Approximate Average • Radiant Barrier Prese • Insulation depth is be • Loose Type Insulation Comments: • About the Roof Struc	Depth of Insulation: ent etween 10 and 12 inche n present	S
	The attic of a residence the attic is an essentia in the attic must be of s should also be sufficien home. The overall attic	e is important for severa l element to creating an sufficient depth to achie nt air flow and/or humid c venting ratio should be	al reasons. In warm, moist climates energy-efficient dwelling. Insulation eve proper energy efficiency. There ity control in all confined areas of a e at least 1/150th of the total are taken as a part of the
	can only visibly inspec considered safe to acc remain hidden or inacc defects and leaks can Any deficiencies found	t these components in a ess by the inspector. M cessible. There is no gu be detected. Inspection could be an indication aluation by a qualified p	le decking of the roof. Inspectors areas that are accessible and lany elements of the roof and attic arantee that all damage, installation is are limited to accessible areas. of a more serious condition. We professional for further evaluation
	standards. (R-30)	able insulation is presen ent at the time of inspec	nt in the attic space per today's tion.
	INSULATION OK	Image: Second	

HouseCheck			15 Taupewood Place, Conroe,
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	E. Walls (Interior and E	Exterior)	
	<ul> <li>Wall Materials:</li> <li>Masonry / brick vene siding ( "Hardi-Board") Comments:</li> <li>About Interior and Example.</li> </ul>	)	nstruction, composition cement
	performance. Condition indicate a more seriou	on of wall finishes and co is problem are not noted	etration and general structural osmetic imperfections that do not d within the inspection report. Any ble and cannot be inspected.
	but not limited to: air q inadequate or defectiv regarding environmen professional in these a home inspector to pos environmental factors. (WDI) inspection. The to the dwelling caused	uality, mold, insect intru e drywall, or defective b tal factors arise, the clie areas. Texas law does n itively identify and/or re . This inspection is not a inspector does not assu l by pests or insects. An erious condition and sho	or environmental factors such as, usion points, excessive moisture, puilding materials. If any concerns ent should consult with a certified not allow a licensed professional port the presence of mold or other a pest or wood-destroying insect ume any responsibility for damage by deficiencies found could be an puld be evaluated further by a
	<ul> <li>material abutments and task aids in the prevention</li> <li>All pipes, cables, and penetrate the exterior</li> <li>All deficiencies noted evaluated by a qualifie</li> <li>Seal deterioration / I</li> </ul>	nd all penetrations to the ntion of moisture intrusion d vent lines should be pro- siding throughout the ho d in red OR captioned in the professional. Unsealed areas were no	other sealants at any dissimilar e walls and roof. This inexpensive on and saves on costly repairs. roperly sealed, where they ome. In the pictures should be further oted at one or more exterior siding ealed to help prevent issues and





# HouseCheck 15 Taupewood Place, Conroe, TX NP=Not Present D=Deficient I=Inspected NI=Not Inspected NI NP D F. Ceilings and Floors Х Ceiling and Floor Materials: Floor covering material is carpet Floor covering material is tile Floor covering material is wood Comments: About Ceilings and Floors: Ceilings and floors are visually inspected for moisture penetration and general structural performance. Condition of surface finishes and cosmetic imperfections that do not indicate a more serious problem are not noted in the inspection report. Any area that is enclosed, inaccessible, or not visible cannot be inspected. Any deficiencies noted can be an indication of a more serious condition. We recommend further evaluation by a qualified professional for further evaluation and diagnosis if there are concerns. • The sub-flooring is noisy/loose at the second story in the residence. This is common deficiency for high traffic areas throughout the home. Repairs are recommended. NOISY SUB FLOOR

HouseCheck			15 Taupewood Place, Conroe, TX		
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient		
I NI NP D	)				
	G. Doors (Interior and I	Exterior)			
	Comments: • About Doors:				
	close properly. Locks a noted can potentially b	and latches should funct be an indication of a mor	nctionality. Doors should open and tion as intended. Any deficiencies re serious condition. We rofessional if there are concerns.		
	<ul> <li>Maintenance Tip: Caulk or grout recommended at door - floor junctions, where applicable, to prevent water that is carried in by foot traffic from entering under the flooring.</li> <li>MAINTENANCE: Recommend proper lubrication at the railing and rollers as needed to prevent issues or damage and sticking. CURRENTLY NEEDED</li> <li>All deficiencies noted in red OR captioned in the pictures should be further evaluated by a qualified professional.</li> <li>The hardware on one or more doors was found damaged / inoperable or not properly latching.</li> <li>One or more exterior doors were found incorrectly installed preventing a proper seal at the frame and weatherstripping.</li> <li>Door stops are missing for one or more interior doors throughout the residence. Recommend addition to prevent damage to walls within range of motion of each</li> </ul>				
	<ul> <li>fixture.</li> <li>The weatherstripping weatherstripping is pre</li> <li>Damaged weatherstripting is pre</li> <li>Minimal signs of wood</li> </ul>	is missing at one or mo esent where required. ipping was observed at od rot and deteriotation v	<b>°</b>		

GARAGE DOOR OK

GAP AT DOOR AND WEATHERSTRIPPING











HouseCheck			15 Taupewood Place, Conroe, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
	M=NOL INSpected	INF=INOL FIESEIIL	D=Delicient
I NI NP D			

HouseCheck			15 Taupewood Place, Conroe, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
x	J. Fireplaces and Chim	neys	
	Locations: • Fireplace is located in Types: • Gas-fueled • Prefabricated metal ty Comments: • About Chimneys and	/pe fireplace was noted	l present.
	time of the inspection. I inspection report. Inspe	Any defects observed a ection fireplace compon and hearth extension. I	and fireplace are inspected at the are noted within this section of the nents include the visible firebox, Proper clearance from combustibles is accessible.
	chimney cap and crown tested. We always reco necessary) by a qualifie or any of its accessorie	n. Drafting capability of ommend a complete exa ed and licensed chimne es. Any deficiencies not	nney extension, spark arrestor, the chimney is not measured or amination and cleaning (if ey sweep prior to using the fireplace ed could indicate a more serious ed chimney professional if there are
	<ul> <li>evaluated by a qualified</li> <li>The Damper on the ficlosed multiple times a</li> <li>The fireplace does no combustibles installed.</li> </ul>	d professional. ireplace and chimney s nd found to be in satisfa t have hearth extension The hearth extension r of 8″ on the sides as we	the pictures should be further system was tested / opened and actory condition. In or required clearance from must extend at least 16" from the fell as have at least 6 inches to the



## I=Inspected

NP=Not Present

D=Deficient

NI NP D



PORCH AREA OK



DAMAGE / VOIDS AT PATIO MORTAR



DAMAGE / VOIDS AT PATIO MORTAR

L. Other

Materials:

• Wood type material (typically Pine) Comments:

• Maintenance Tip: When landscaping, keep plants, even at full growth, at least a foot (preferably 18 inches) from house siding and windows. Keep trees away from foundation and roof. Plants in contact or proximity to home can provide pathways for wood destroying insects, as well as abrade and damage siding, screens and roofs.

• No deficiencies present at the time of inspection.

Х



FENCING OK

FENCING OK

II. ELECTRICAL SYSTEMS

HouseCheck			15 Taupewood Place, Conroe, T
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	A. Service Entrance a	nd Panels	
	<ul> <li>150 amp main break</li> <li>60 amp main breake Comments:</li> <li>About Electric Panel</li> <li>Visible and accessible inspection. The electric</li> </ul>	ating: o main breaker is require er was noted preset or was noted present for s: e portions of the electrica ical service system inclu	ed for residential homes. the subpanelas required. al service system are included in the ides components such as the Inspectors will attempt to remove
	the cover when deem Limitation: Much of the walls or other obstruct visible inspection, the conditions that are hid effectiveness or perfo has any concerns with encouraged to consult	ed safe by the inspector e electrical system is no tions. Though some con re may be some underly Iden from view. The insp rmance of any over-curr n the electrical system o t with a licensed electric e serious condition and	
	<ul> <li>the inspection.</li> <li>Missing antioxidant performance panel.</li> <li>Pointed screw(s) observations and screw(s) observations.</li> </ul>	paste for aluminum serv served for the service pa tipped screw to prevent	deficiencies to report at the time of ice entrance conductors at the anel dead front cover. Recommend puncture of electrical wiring and/or





INSIDE PANEL OK

SUB PANEL BREAKER OK

HouseCheck			15 Taupewood Place, Conroe, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	IN	SIDE SUBPANEL OK	
	B. Branch Circuits, Co	nnected Devices, and Fi	ixtures
	Comments:	sheathed cable noted. s, Connected Devices a	and Fixtures:
	fixtures. Much of the e walls or other obstruct visible inspection, ther conditions that are hid inspected and reported sources for smoke ala suitability for the heari	electrical system in not a ions. Though some con- re may be some underly den from view. GFC an d by the inspector. Thou rms are noted, their effe ng impaired are not veri	uch as wiring, switches, outlets and ccessible as it is hidden behind ditions can be discovered by a ing hazardous or damaging ad AFCI protection devices are ugh general locations and power ectiveness, interconnectivity or fied. Low voltage systems and t included in the inspection.
	proper Smoke Alarm o		ing batteries yearly to ensure tion.
	III. HEATING, VENTILA	TION AND AIR CONDIT	FIONING SYSTEMS

HouseCheck			15 Taupewood Place, Conroe, TX		
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient		
I NI NP D					
	A. Heating Equipment				
	<ul> <li>Type of Systems:</li> <li>Direct Port</li> <li>The furnace is located in the attic Energy Sources:</li> <li>The furnace is gas powered. Comments:</li> <li>Limitation: Did not operate the heating equipment due to outside temperature at the time of the inspection. Operating heating equipment when the exterior temperature is above 70 degrees can damage the unit and is not recommended</li> <li>About Heating Equipment:</li> </ul>				
	The heating unit is designed to heat and circulate the inside air. Central heating units often work in conjunction with central cooling systems. The inspector operates the heating equipment if it deemed safe to do so. Inspectors visually inspect the heating unit for general operation and safety issues.				
	Inspectors are not authorized to disassemble heating or cooling components as a part of the home inspection. Inspectors do not verify compatibility of components, accuracy of the thermostat, integrity of the heat exchanger, sizing/tonnage, or uniformity of the air supply. In order to maximize the efficiency of a heating/cooling system, it is advisable to have them serviced annually. Any deficiencies can be an indication of a more serious condition, and further evaluation by a licensed HVAC specialist is advised if there are concerns.				
	<ul> <li>The heating equipment was inspected and no deficiencies were noted at the time of the inspection.</li> </ul>				
	FURNACE OK				

HouseCheck			15 Taupewood Place, Conroe, T≻		
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient		
I NI NP	D				
	X B. Cooling Equipment				
	Type of Systems: • Split-System • Refrigerant: R-22 (The refrigerant is allowable, but R-410A is today's standard for cooling equipment. New production and import of R-22 will be phased out by 2020. As a result, the price will likely increased based on limited supply.) Comments: • About Cooling Equipment:				
	The cooling equipment is designed to cool and circulate the inside air. Central air conditioning units often work in conjunction with central heating systems. The inspector operates the cooling equipment if the outside temperature is above 60 degrees and deemed safe to do so. Inspectors visually inspect the cooling equipment for general operation and safety issues.				
	part of the home inspe accuracy of the thermo order to maximize the have them serviced an	ction. Inspectors do not ostat, sizing/tonnage, or efficiency of a heating/c inually. Any deficiencies	heating or cooling components as a verify compatibility of components, uniformity of the air supply. In cooling system, it is advisable to s can be an indication of a more licensed HVAC specialist is advised		
	evaporator. It is recom as needed to prevent of • Air differential tested: (Standard range is 14 ALWAYS VERIFY THI THE ACTUAL MEASU • First floor air different	mended to clean this lin clogging / water damage Register =53 Return = - 22 degrees for the coo S INFORMATION WITH REMENT	= 69 DELTA = 16 degrees bling equipment.) YOU CAN H THE PROVIDED PICTURE OF 5 Return = 75 DELTA = 20.		
	<ul> <li>the home. (If this pipe cleaning)</li> <li>NOTE: Missing / No for the evaporator. (cu during emergency cau</li> <li>NOTE: According to</li> </ul>	ever drips then the prim overflow pipe OR incorn rrent installation does no sing overflow through th the American Society o	of Heating, Refrigeration, and Air		
	<ul> <li>Is 15 years. The system</li> <li>For more information v</li> <li>Small hole or openin exterior wall.</li> </ul>	m present is at or beyor risit: www.ashrae.org Ig was noted present wh	split system air conditioning system ad the expected life. here the refrigerant lines enter the ty. Recommend having air		
	conditioning system clopurchase, and annually • Deteriorated insulation	eaned and serviced by a y thereafter. on present at refrigerant	a licensed HVAC contractor prior to line located at the exterior / insulated to prevent condensation		
REI 7-5 (05/4	-		Page 30 of 61		



NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

from forming.

Drain pan does not fully cover evaporator. Ensure all areas are protected from water leaks and overflow.



LABEL

**UNSEALED AREAS** 



## HouseCheck

I=Inspected

NP=Not Present

D=Deficient

NI NP D



DRAIN PAN DOES NOT FULLY COVER EVAPORATOR



MISSING OVERFLOW DRAIN PIPE



MISSING / NO ACCESS TO PIPE FOR CLEANING AND MAINTENANCE



THERMOSTAT 2 OK




HouseCheck			15 Taupewood Place, Conroe
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
<u>I NI NP D</u>	)		
	C. Duct Systems, Cha	ses, and Vents	
	throughout the residen system, chases or ver very important for the	nce. Any deficiencies wl nts will be reported. Ven overall performance of	s verified at very accessible register hich can be identified in the duct itilation in the residence and attic is the structure. Proper ventilation can armful combustion gases.
	Texas law does not all presence of mold. Environducted by a traine indicate a more seriou HVAC professional if • MAINTENANCE: Th cleaned or replaced a environment more ple blower and heat excha efficiently. There are (constructed of alumin by soaking in mild det filters that must be RE dirty filters are the mo performance. • The temperature of v registers throughout th • All deficiencies noted evaluated by a qualifie • The return filter(s) for replacement to ensure • The foil/mastic tape	low a home inspector to vironmental and mold in d and state licensed pro- us condition and should there are concerns. e air filter(s) should be is s required. Filters help asant. Filters also clear anger. This helps to kee two types of filters com- num mesh, foam, or rein ergent and rinsing with PLACED before they b st common cause of ina- warm and/or cool air def he residence. d in red OR captioned ir ed professional. r the HVAC unit is exce e proper performance of is missing or not proper	t a mold or air quality assessment. o positively identify or report the ovestigations should be only be ofessional. Any issues noted could be evaluated further by a licensed inspected at least monthly and clean the house air, making the of the air before it passes through the ep the furnace components working monly used: (1) Washable filters, offorced fibers) these may be cleaned water. Or (2) Fiberglass disposable ecome clogged. Remember that adequate heating or cooling tected is consistent at all interior in the pictures should be further essively dirty. Recommend f the HVAC equipment. by sealed at the duct / plenum / unit cie" is used to seal all areas





DUCTING OK

**MISSING / NO FIBER PAINT** 



**MISSING / NO FIBER PAINT** 

**IV. PLUMBING SYSTEMS** 

HouseCheck			15 Taupewood Place, Conroe,
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	A. Plumbing Supply, D	istribution System and I	Fixtures
	Location of Water Met • Front of home. Location of Main Wate • Located inside the G • The main water supp (minimum of 3/4 inch r 3/4 INCH Comments: • About Plumbing Sup	r Supply Valve: ARAGE. Iy line for the home was equired):	s noted of the following size
	plumbing drains, plum not accessible as it is conditions can be disc	bing vents, and fixtures hidden behind walls or o overed by a visible insp	shutoff valve, water supply lines, . Much of the plumbing system is other obstructions. Though some pection, there may be some a that are hidden from view.
	required to inspect (be as pool pumps, under backflow devices. Pota home inspection. Wate there are concerns. Ar	yond a visual inspection ground irrigation lines, fi ability and/or water qual er testing should only be ny deficiencies noted co	perate any shutoff valves and is not n) other mechanical systems such ilter systems, fire sprinklers or lity is not assessed as part of a e done by qualified professionals if buld be an indication of a more vised if there are concerns.
	moisture penetration. A to keep walls sealed c the interior walls and s or accessible to the ins • Plumbing Supply Ma • Static Water Pressur	All missing/damaged gr an cause deterioration a surrounding sub-flooring spector at the time of in terial(s): CPVC e Reading: 75 PSI	be caulked and sealed to prevent outing should be replaced. Failure and extensive moisture damage to g. This damage is not always visible spection.
	<ul> <li>properly sealed water are sealed.</li> <li>The exterior hose bib</li> <li>The hot and cold sup the following locations</li> <li>Water level inside the</li> </ul>	penetration / leaks into ob(s) leak at the followin oply lines are reversed a : master bathroom.	the wall can occur. Ensure all areas ing locations: . at one or more plumbing fixtures in oted too high resulting in continuous

Х



WATER METER LOCATED HERE

HOT WATER OK





HouseCheck			15 Taupewood Place, Conroe,
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D	)		
x	B. Drains, Wastes, and	I Vents	
	Comments: • About Drains and Wa	aste Vents:	
	The inspection of the p water, drain stops, ove throughout the resider	erflow drains, visual drai	em includes basins which hold in pipes, and clean-outs spaced
	is hidden behind walls	, attic spaces, or other c sessed by running pluml	in line system is not accessible and obstructions. Functionality of floor bing supplies within the
	applies maximum pres at the time of the inspe • The A/C condensate	sure to the drain lines. ection.	e completely filled and drained. This The system performed as intended hroom sink. Cleaning this pipe with event clogging is a good
	E K		
SINK / 1	TUB FILLED AND TESTE	ED EVAPOR	ATOR DRAINS INTO THIS SINK

## HouseCheck

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

SINK / TUB FILLED AND TESTED

I NI NP D



EVAPORATOR DRAINS INTO THIS SINK

C. Water Heating Equipment

**Energy Source:** 

- Water heater is gas-fueled
- Water heater is located in the attic

Capacity:

X

Х

• Unit capacity is 50 gallons

Comments:

• About Water Heaters:

Water heaters are designed to heat water throughout designated fixture supplies throughout the home. This report includes the energy source and capacity of the water heating unit (if available or listed). General installation and safety issues are assessed by the inspector. Annual maintenance (or whatever maintenance schedule the manufacturer advises) should be performed to residential water heaters. If the client is not comfortable performing general water heater maintenance, consultation with a qualified professional is advised. Any deficiencies noted could be an indication of a more serious condition, and further evaluation by a licensed plumber is also recommended if there are concerns.

Limitation of scope: Water heaters should be equipped with a temperature and pressure relief valve that is designed to relieve back pressure in the unit if the pressure or temperature exceeds the unit's capacity. This component is not tested as a part of the inspection for each water heating unit, as any failure may result in unforeseen damage to persons or property.

• All deficiencies noted in red OR captioned in the pictures should be further evaluated by a qualified professional.

• The metal "B" vent or flue from the heater was noted incorrectly installed / secured. (not properly secured over the exhaust chamber). Ensure this vent is properly installed as needed to prevent overheating and CO2 buildup.





I=Inspected NI=Not Inspected NP=Not Present D=Deficient	
Image: state of the state	
<text><text><image/></text></text>	
X C. Range Hood and Exhaust Systems	
<ul> <li>Comments:</li> <li>Type: Hood with fan (unit vents to the exterior)</li> <li>Range hood light fixture and all fan speeds were tested (the unit appears to be functional at the time of the inspection).</li> <li>Seal deterioration / Unsealed areas were noted at the exterior brick wall. Although minor recommend properly sealing all areas as needed to prevent issues or vermin intrusion.</li> </ul>	
REI 7-5 (05/4/2015) Page 47 of 6	1

X





## HouseCheck 15 Taupewood Place, Conroe, TX I=Inspected NI=Not Inspected NP=Not Present D=Deficient NI NP D G. Garage Door Operators Х Х Door Type: • Two - single 8', steel panel, sectional doors. Comments: • The overhead garage door(s) operated normally when tested. No deficiencies were observed regarding operation. • The reverse sensors were tested for the overhead garage door and performed as intended. • All deficiencies noted should be evaluated and repaired by an garage door installation professional. • The anchor bolts for the garage door track are not properly installed / secured. GARAGE DOOR OPENER OK LOOSE / UNSECURED GARAGE DOOR RAIL H. Dryer Exhaust Systems Х Comments: • The washer / dryer or appliances were noted present and connected thus the connections and drain line could not be fully verified. Both gas and electrical type supply connections were noted present for the dryer.

HouseCheck			15 Taupewood Place, Conroe, T
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
		PLIANCES PRESENT	
	I. Other		
	<ul> <li>home.</li> <li>The main gas valve not bonded recommer shock.</li> <li>Improper transition r transition. Ensure prop</li> <li>Evidence of gas leak</li> </ul>	and meter for the home nd proper repairs / upda material / Missing sleeve per installation as neede	e did NOT appear to be bonded. If tes as needed to prevent issues or e noted at the wall and gas pipe ed to prevent rust and corrosion. nt at the pool heater and d by the utility district.

GAS METER OK

MISSING BONDING AND PROPER WALL TRANSITION

HouseCheck			15 Taupewood Place, Conroe, T
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
		CE OF GAS SMELL / L OPTIONAL SYSTEMS	FAK
	1		
X X X	A. Landscape Irrigation	ı (Sprinkler) Systems	
	inspection.	e irrigation system perfor s a damaged / unsecure	rmed as intended at the time of the

SPRINKLER BACKFLOW OK DAMAGED / UNSECURED SPRINKLER RAIN SENSOR

Х



D=Deficient

NI NP D



SPRINKLER ZONES OK

SPRINKLER CONTROL OPERATIONAL; 8 ZONES PRESENT



B. Swimming Pools, Spas, Hot Tubs, and Equipment

Type of Construction:

• Disclosure: All pools, spas and related equipment are inspected visually only. The water is not removed from these items to examine the interior surfaces. The pool, spa and plumbing were not inspected for underground leaks. The comments made relate to the condition of visual items at the time of inspection only. No comments regarding the future condition of pools, spas and related equipment are made in this report

- In-Ground
- Plaster Lining
- Comments:

• The pool was inspected and all equipment was operated using normal controls and there were no issues observed regarding operation.

• Water quality was not evaluated at the time of the inspection. Recommend further evaluation by a licensed pool operator/inspector.

• A proper safety fence is not present around the pool. A 3' safety fence with an outward-swinging gate should be installed around the perimeter of the pool.

• Missing / No "drip leg" was noted present on the gas supply line to the heater.

• The backwash for the swimming pool was noted incorrectly draining or routed the old traditional manner. Recommend proper repairs and updates as needed to properly drain pool water into the homes drainage system.

• Missing / No light fixture or electrical outlet was noted present at the pool equipment area. Recommend proper repairs and updates as required to properly service equipment when necessary.





MISSING LIGHT FIXTURE AT POOL EQUIPMENT AREA

POOL CONTROL OPERATIONAL





## Glossary

Term	Definition
A/C	Abbreviation for air conditioner and air conditioning
AFCI	Arc-fault circuit interrupter: A device intended to provide protection from the effects of arc faults by recognizing characteristics unique to arcing and by functioning to de-energize the circuit when an arc fault is detected.
GFCI	A special device that is intended for the protection of personnel by de-energizing a circuit, capable of opening the circuit when even a small amount of current is flowing through the grounding system.

## Report Summary

Page 4 Item: B       Grading and Drainage       • NOTE: all slopes of the roof should be guttered to ensure that water is adequately diverted away from the structure.         • Evidence of standing water (ponding) was observed against or near the foundation. Poor grading was noted. This condition should be improved to promote the flow of water away from the structure.         • Splash block(s) at the base of the gutter downspouts should be added to prevent erosion of soil from grade. Downspouts should be present to adequately direct water away from the foundation.         Page 7 Item: C       Roof Covering Materials       • There is debris from nearby tree on noof covering. This debris can impede the roof coverings ability to shed water causing leaks and premature aging of the roof cover. Roof coverings should remain free from debris.         Page 10 Item: E       Walls (Interior and Exterior)       • Seal deterioration / Unsealed areas were noted at one or more exterior siding intersections. Ensure all areas are properly sealed to help prevent issues and water (causing encort) we sealed to help prevent issues and water (causing encort) we sealed to help prevent issues and water (causing encort) we sealed to help prevent issues and water (causing encort) we sealed to help prevent issues and water (causing encort) we sealed to help prevent issues and water (causing encort) we sealed to help prevent issues and water (causing encort) we sealed to help prevent issues and water (causing encort) we sealed to help prevent issues and water (causing encort) we sealed to help prevent issues and water (causing encort) we sealed to help prevent issues and water (causing encort) we sealed to help prevent issues and water (causing encort) we have therestripping is present where required. • Doer stops are missing for one or more dors. Ensur	STRUCTURAL SYSTEMS		
Materialsdebris can impede the roof coverings ability to shed water causing leaks and premature aging of the roof cover. Roof coverings should remain free from debris.Page 10 Item: EWalls (Interior and Exterior)• Seal deterioration / Unsealed areas were noted at one or more exterior siding intersections. Ensure all areas are properly sealed to help prevent issues and water intrusion.Page 13 Item: FCeilings and Floors ensure the sub-flooring is noisy/loose at the second story in the residence. This is common deficiency for high traffic areas throughout the home. Repairs are recommended.Page 14 Item: GDoors (Interior and Exterior)• The hardware on one or more doors was found damaged / inoperable or not properly latching. • One or more exterior doors were found incorrectly installed preventing a proper seal at the frame and weatherstripping. • Door stops are missing for one or more doors. • The weatherstripping is present where required. • Damaged so doors. • Minimal signs of wood rot and deteriotation were noted at the exterior doors. • Minimal signs of wood or fire-rated door at one or more areas. • Minimal signs of wood or fire-rated door at one or more areas.Page 18 Item: HWindows• Seal deterioration / Unsealed areas were noted around the windows. Maintaining the proper seal around all windows helps prevent issues such as water intrusion, wood rot, and vermin activity. • The windows are stiff or difficult to operate at one or more areas.Page 18 Item	Page 4 Item: B		<ul> <li>that water is adequately diverted away from the structure.</li> <li>Evidence of standing water (ponding) was observed against or near the foundation. Poor grading was noted. This condition should be improved to promote the flow of water away from the structure.</li> <li>Splash block(s) at the base of the gutter downspouts should be added to prevent erosion of soil from grade. Downspouts should be present to adequately direct water away from the</li> </ul>
Exterior)more exterior siding intersections. Ensure all areas are properly sealed to help prevent issues and water intrusion.Page 13 Item: FCeilings and Floors• The sub-flooring is noisy/loose at the second story in the residence. This is common deficiency for high traffic areas throughout the home. Repairs are recommended.Page 14 Item: GDoors (Interior and Exterior)• The hardware on one or more doors was found damaged / inoperable or not properly latching. • One or more exterior doors were found incorrectly installed preventing a proper seal at the frame and weatherstripping. • Door stops are missing for one or more interior doors throughout the residence. Recommend addition to prevent damage to walls within range of motion of each fixture. • The weatherstripping is present where required. • Damaged weatherstripping was observed at one or more exterior doors. • Minimal signs of wood rot and deteriotation were noted at the exterior doors. 	Page 7 Item: C		debris can impede the roof coverings ability to shed water causing leaks and premature aging of the roof cover. Roof
Page 14 Item: GDoors (Interior and Exterior)• The hardware on one or more doors was found damaged / inoperable or not properly latching. • One or more exterior doors were found incorrectly installed preventing a proper seal at the frame and weatherstripping. • Door stops are missing for one or more interior doors throughout the residence. Recommend addition to prevent damage to walls within range of motion of each fixture. • The weatherstripping is present where required. • Damaged weatherstripping was observed at one or more exterior doors. • Minimal signs of wood rot and deteriotation were noted at the exterior doors. • Missing solid wood or fire-rated door at one or more required locations.Page 18 Item: HWindows• Seal deterioration / Unsealed areas were noted around the windows. Maintaining the proper seal around all windows helps prevent issues such as water intrusion, wood rot, and vermin activity. • The windows are stiff or difficult to operate at one or more areas.Page 21 Item: JFireplaces and Chimneys• The fireplace does not have hearth extension or required clearance from combustibles installed. The hearth extension must extend at least 16 from the front of the fireplace and 8" on the sides as well as have at least 6 inches to the sides and top of any combustible material.	Page 10 Item: E		more exterior siding intersections. Ensure all areas are
Exterior)inoperable or not properly latching. • One or more exterior doors were found incorrectly installed preventing a proper seal at the frame and weatherstripping. • Door stops are missing for one or more interior doors throughout the residence. Recommend addition to prevent damage to walls within range of motion of each fixture. • The weatherstripping is missing at one or more doors. Ensure all weatherstripping was observed at one or more exterior doors. • Minimal signs of wood rot and deteriotation were noted at the exterior doors. • Minimal signs of wood rot and deteriotation were noted at the exterior doors. • Missing solid wood or fire-rated door at one or more required locations.Page 18 Item: HWindows• Seal deterioration / Unsealed areas were noted around the windows. Maintaining the proper seal around all windows helps prevent issues such as water intrusion, wood rot, and vermin activity. • The windows are stiff or difficult to operate at one or more areas.Page 21 Item: JFireplaces and Chimneys• The fireplace does not have hearth extension or required clearance from combustibles installed. The hearth extension must extend at least 16" from the front of the fireplace and 8" on the sides as well as have at least 6 inches to the sides and top of any combustible material.	Page 13 Item: F	Ceilings and Floors	residence. This is common deficiency for high traffic areas
windows. Maintaining the proper seal around all windows helps prevent issues such as water intrusion, wood rot, and vermin activity. • The windows are stiff or difficult to operate at one or more areas.Page 21 Item: JFireplaces and Chimneys• The fireplace does not have hearth extension or required clearance from combustibles installed. The hearth extension must extend at least 16" from the front of the fireplace and 8" on the sides as well as have at least 6 inches to the sides and top of any combustible material.	Page 14 Item: G		<ul> <li>inoperable or not properly latching.</li> <li>One or more exterior doors were found incorrectly installed preventing a proper seal at the frame and weatherstripping.</li> <li>Door stops are missing for one or more interior doors throughout the residence. Recommend addition to prevent damage to walls within range of motion of each fixture.</li> <li>The weatherstripping is missing at one or more doors. Ensure all weatherstripping was observed at one or more exterior doors.</li> <li>Minimal signs of wood rot and deteriotation were noted at the exterior doors.</li> <li>Missing solid wood or fire-rated door at one or more required</li> </ul>
Chimneys clearance from combustibles installed. The hearth extension must extend at least 16" from the front of the fireplace and 8" on the sides as well as have at least 6 inches to the sides and top of any combustible material.	Page 18 Item: H	Windows	windows. Maintaining the proper seal around all windows helps prevent issues such as water intrusion, wood rot, and vermin activity. • The windows are stiff or difficult to operate at one or more
ELECTRICAL SYSTEMS	Page 21 Item: J		clearance from combustibles installed. The hearth extension must extend at least 16" from the front of the fireplace and 8" on the sides as well as have at least 6 inches to the sides and
	ELECTRICAL SYSTEMS		

Page 25 Item: A	Service Entrance and Panels	<ul> <li>Missing antioxidant paste for aluminum service entrance conductors at the exterior service panel.</li> <li>Pointed screw(s) observed for the service panel dead front cover. Recommend replacement by a flat-tipped screw to prevent puncture of electrical wiring and/or personal injury from electrocution.</li> </ul>
HEATING, VENTI	LATION AND AIR C	ONDITIONING SYSTEMS
Page 31 Item: B	Cooling Equipment	<ul> <li>NOTE: Missing / No overflow pipe OR incorrectly installed was noted present for the evaporator. (current installation does not allow for condensation drainage during emergency causing overflow through the actual evaporator)</li> <li>NOTE: According to the American Society of Heating, Refrigeration, and Air Conditioning Engineers (ASHRAE). The average life expectancy for a split system air conditioning system is 15 years. The system present is at or beyond the expected life. For more information visit: www.ashrae.org</li> <li>Small hole or opening was noted present where the refrigerant lines enter the exterior wall.</li> <li>The air conditioning system cleaned and serviced by a licensed HVAC contractor prior to purchase, and annually thereafter.</li> <li>Deteriorated insulation present at refrigerant line located at the exterior condenser. Refrigerant line should be properly insulated to prevent condensation from forming.</li> <li>Drain pan does not fully cover evaporator. Ensure all areas are protected from water leaks and overflow.</li> </ul>
Page 36 Item: C	Duct Systems, Chases, and Vents	<ul> <li>The return filter(s) for the HVAC unit is excessively dirty. Recommend replacement to ensure proper performance of the HVAC equipment.</li> <li>The foil/mastic tape is missing or not properly sealed at the duct / plenum / unit transitions. A fiber paint also known as ""pookie" is used to seal all areas preventing air loss.</li> </ul>
PLUMBING SYST	TEMS	
Page 39 Item: A	Plumbing Supply, Distribution System and Fixtures	<ul> <li>Seal deterioration / Unsealed areas were noted at the shower pan. If not properly sealed water penetration / leaks into the wall can occur. Ensure all areas are sealed.</li> <li>The exterior hose bibb(s) leak at the following locations: .</li> <li>The hot and cold supply lines are reversed at one or more plumbing fixtures in the following locations: master bathroom.</li> <li>Water level inside the commode tank was noted too high resulting in continuous water flow. Adjustment / repairs will be needed prior to use.</li> </ul>
Page 45 Item: C	Water Heating Equipment	• The metal "B" vent or flue from the heater was noted incorrectly installed / secured. (not properly secured over the exhaust chamber). Ensure this vent is properly installed as needed to prevent overheating and CO2 buildup.
Page 45 Item: E	Other	<ul> <li>Minimal signs of seal deterioration or Unsealed areas were noted at the kitchen counter-top and wall intersections.</li> <li>Unfinished / Unsealed areas noted present at the kitchen island.</li> </ul>

Page 48 Item: C	Range Hood and Exhaust Systems	• Seal deterioration / Unsealed areas were noted at the exterior brick wall. Although minor recommend properly sealing all areas as needed to prevent issues or vermin intrusion.
Page 50 Item: G	Garage Door Operators	• The anchor bolts for the garage door track are not properly installed / secured.
Page 51 Item: I	Other	<ul> <li>The main gas valve and meter for the home did NOT appear to be bonded. If not bonded recommend proper repairs / updates as needed to prevent issues or shock.</li> <li>Improper transition material / Missing sleeve noted at the wall and gas pipe transition. Ensure proper installation as needed to prevent rust and corrosion.</li> <li>Evidence of gas leak and smell noted present at the pool heater and connections. Further evaluation recommended by the utility district.</li> </ul>
OPTIONAL SYST	EMS	
Page 52 Item: A	Landscape Irrigation (Sprinkler) Systems	<ul> <li>Irrigation system has a damaged / unsecured rain sensor present.</li> </ul>
Page 53 Item: B	Swimming Pools, Spas, Hot Tubs, and Equipment	<ul> <li>A proper safety fence is not present around the pool. A 3' safety fence with an outward-swinging gate should be installed around the perimeter of the pool.</li> <li>Missing / No "drip leg" was noted present on the gas supply line to the heater.</li> <li>The backwash for the swimming pool was noted incorrectly draining or routed the old traditional manner. Recommend proper repairs and updates as needed to properly drain pool water into the homes drainage system.</li> <li>Missing / No light fixture or electrical outlet was noted proper repairs and updates as required to properly service equipment when necessary.</li> </ul>