
Baker Real Estate Inspections

Property Inspection Report
Exclusively Prepared For
Randyl Murrell
Kendra Murrell



31023 Raleigh Creek Tomball, TX 77375



Sandy Baker Master Inspector Texas Real Estate Commission Professional Inspector License #6462



Residential Combination Inspector

Baker Real Estate Inspections 30611 N. Holly Oaks Circle Magnolia, TX 77355

Phone: 281-352-9252 Fax: Email: bakerinspections@att.net

PROPERTY INSPECTION REPORT

Prepared For:	Randyl & Kendra Murrell (Name of Client)		
Concerning:	31023 Raleigh Creek, Tomball, TX 77375 (Address or Other Identification of Inspected Property)		
By:	Sandy Baker, Lic #TREC 6462, ICC 8002272-R5 (Name and License Number of Inspector)	04/04/2018 (Date)	
	(Name, License Number of Sponsoring Inspector)		

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information

obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods. Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathroom, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as, smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms requires a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

Report Identification: Murrell20180404-, 31023 Raleigh Creek, Tomball, TX

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

For inspection purposes the building is considered to face south. Photos are representative of conditions found and not all inclusive of all areas found. New Construction Final Phase Inspection Builder D R Horton

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

I. STRUCTURAL SYSTEMS

A. Foundations

Type of Foundation(s): Post Tension, Slab on Grade *Comments*:

Performing as Intended

All soil compress, and all foundations are subject to some settlement. When settlement is slight and uniform, it is of little concern. When a foundation settles unevenly, (differential settlement), it introduces stresses which can weaken the building. Many installed foundations are out of level, but factors other than an out of level condition are good indicators of foundation movement. These include visible cracks at the foundation's perimeter grade beam, window and door frames out of square, roof rafters pulling away from the ridge board, interior and exterior walls which display signs of stress deflecting or cracking, sloping floors. Evidence found supports the opinion that the foundation performance is satisfactory. That evidence includes the following:

- 1. The absence of cracks at he visible portions of the foundation grade beams faces.
- 2. The absence of significant door frame racking.
- 3. The absence of significant stress deflection in exterior and interior walls.
- 4. The absence of sloping floors.

Departure from dead level of the foundation's horizontal floor plane as measured with a ZipLevel is well within normal range.

This is not an engineering report, but is only an opinion based on observation of conditions known to be related to foundation performance, using the knowledge and experience of the inspector.

Exposed Nails

Exposed nails were noted protruding along the perimeter of the foundation and should be removed.





Hairline Slab Cracks

A hairline slab crack was noted in the following marked locations. The slab floor is in acceptable condition. Small cracks are common and result as a consequence of the curing process, common settling, of the presence of expansive soils, but are not structurally threatening. Also, you may notice some salt crystal formations that are activated by moisture penetrating the slab.

_			
\	ga	ra	ap.

☐ front Porch

☐ back porch

☐ dining room

☐ media room

□ bath

Foundation Elevation Readings taken with a Zip Level

(adjustments were made fro differing floor covering heights)	
Southwest corner of the family room (reference point)	0.0
Southeast corner of the family room	0.0
Northwest corner of the family room	0.0
Northeast corner of the family room	0.0
Southwest corner of the kitchen pantry	0.1
Northwest corner of the dining area	0.0
Northeast corner of the dining area	0.0
Northeast corner of the master bedroom	0.1
Northwest corner of the master bedroom	0.3
Southeast corner of the master bedroom	0.3
Southeast corner of the master closet	-0.1
Southwest corner of the master closet	0.5
Southwest corner of the southwest bedroom closet	-0.3
Southeast corner of the southwest bedroom closet	0.0
Southwest corner of the middle bedroom	-0.3
Southeast corner of the middle bedroom	-0.1
Southeast corner of the southeast bedroom	-0.3
Northeast corner of the laundry	0.1
, 1 × 1 × 1 × 1 × 1 × 1 × 1 × 1	

Post Tension Foundation

Observation of the exposed grade beam surface revealed what appeared to be small "patches". Generally these types of "patches" occur when the concrete void created by the pocket former used with post-tension reinforcement has been sealed. For this reason the foundation is assumed to be post-tension type.

Foundation Maintenance

For a detailed plan or listing of maintenance items important for maintaining foundation performance one should refer to the following online publications: www.foundationperformance.org/Projects/FPA-SC-07-0.pdf

Report Identification: Murrell20180404-, 31023 Raleigh Creek, Tomball, TX **D=Deficient** NP=Not Present NI=Not Inspected I=Inspected I NI NP D B. Grading and Drainage Comments: Grading appears to be adequate on the day of the inspection. C. Roof Covering Materials Types of Roof Covering: Composition Shingles Viewed From: The roof was inspected from the roof level at the eaves where reachable with a twelve foot ladder and from the ground with binoculars. **Buckled Shingles** Buckled shingles were noted on the south and east slope of the roof. According to manufacture installation instructions shingles are to be installed fully flat.




NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



D. Roof Structures and Attics

Viewed From: interior of attic from the service deck Approximate Average Depth of Insulation: 13" + Comments:

Roof Structure

Deflections in Sheathing

Deflections (unevenness between rafters) is visible at the roof service, appears to be cosmetic in nature as the decking material installed is rated for the application. This is most likely caused by rafters not perfectly aligned with one another. east slope

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



Attic Insulation/Ventilation

Type of Exhaust Vents: Static Hock
Type of Intake Vents: soffit
Ceiling Insulation Voids
Voids in the ceiling insulation was noted.



Lack of Insulation on Water Supply Lines

There is a lack of insulation on the water supply lines within the attic space. Improvements should be undertaken to avoid damage to the pipes in freezing weather, which can also result in interior water damage to the home as well.

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D





E. Walls (Interior and Exterior)


Comments:


Interior Walls

Drywall Voids

Voids in drywall coverage was noted around the following receptacles. at refrigerator space

laundry room north end of kitchen bar







Page 9 of 24

NI=Not Inspected


NP=Not Present

D=Deficient

I NI NP D

Drywall/Sealant Void

A void in the drywall and/or sealant was noted in the master bath adjacent to the bathtub.



Minor Cracks

Minor cracks were noted in the following listed room(s). This condition is mainly cosmetic in nature.

under the master bath window



Cabinets

Drawer Missing

A vanity drawer is missing on the west side bath vanity.

NI=Not Inspected

NP=Not Present


D=Deficient


NI NP D



Kitchen Cabinets: Discoloration

Discoloration was noted on all of the upper cabinets on the west wall of the kitchen cabinet doors.





Exterior Walls

Exterior Cladding: brick veneer, stone veneer

Deteriorated Sealant/Caulk: Various Locations

All deteriorated sealant/caulk should be replaced around windows, doors, vents, wall penetrations, exterior lights, ect.

NI=Not Inspected

NP=Not Present


D=Deficient


I NI NP D



Wall/Soffit: Opening

An opening was noted between the junction of the wall and the soffit at the front entry on both sides. These areas need to be properly sealed to avoid the intrusion of and nesting of insects.





F. Ceilings and Floors

Comments:

<u>Ceilings</u>

Functional with no significant problems noted.

NI=Not Inspected

NP=Not Present

D=Deficient


I NI NP D

Floors

Damage Noted

Damage was noted to the wood flooring in several locations.





▼		Ш	Ш	G.	Comments: Interior Doors Functional with no significant problems noted. Exterior Doors Functional with no significant problems noted.
V				н.	Windows Comments: double pane Functional with no significant problems noted.
	$ \sqrt{} $			I.	Stairways (Interior and Exterior) Comments:
	$ \sqrt{} $	Ø		J.	Fireplaces and Chimneys Comments:
				K.	Porches, Balconies, Decks, and Carports Comments: All components of the porch were found to be performing and in satisfactory condition on the day of the inspection.
				L.	Other Comments: Flatwork Functional with no significant problems noted. Fencing Functional with no significant problems noted.

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

II. ELECTRICAL SYSTEMS

A. Service Entrance and Panels

Comments:

Service Entrance

Underground Service Entrance

Main Panel

Cabinet Manufacturer: Square D

Location: Garage

Box and/or Main Disconnect Rating: 150 amps

Branch Circuit Wire Type: Copper Electrical: Unlatched Cover


For electrocution safety the electrician service cover in the utility easement of the back

yard needs to be properly secured and latched.



Improperly Recessed Panel

The panel is improperly recessed in the wall thus when the dead front is installed the panel is not properly sealed closed. Proper installation requires the panel be flush with the drywall so that when the cover is attached it is in full contact with the panel and seals the panel closed. Corrections should be undertaken for *fire safety reasons*.



NI=Not Inspected


NP=Not Present

D=Deficient

NI NP D

Hot White Wires

White wires used to carry electrical current should be clearly marked as hot wires. Improvements should be undertaken for safety.



Concrete Encased Grounding Electrode

There is a concrete encased grounding electrode present which utilizes the steel of the foundation as a grounding means. However this method of grounding should not be used when a moisture barrier is present under the foundation in this area as the grounding is not in direct contact with earth as required. Please see the note published in the 2011 National Electrical Code.

Reference:2011 National Electrical Code Article 250 Section 250.52 Informational Note: Concrete installed with insulation, vapor barriers, films or similar items separating concrete from earth is not considered to be in "direct contact" with the earth".



B. Branch Circuits, Connected Devices, and Fixtures

Type of Wiring: Copper

Comments:

Fixtures: Not Installed

The exterior garage lights were not installed at the time of the inspection.

Report Identif	ication: <u>Mu</u>	rrell20180404-, 31023 F	Raleigh Creek, Tomball, T	X	
I=Inspected		NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP	D				
	III	I. HEATING, VE	NTILATION AND AI	R CONDITIONING SYSTEMS	
	□ A.	Energy Sources: Gas Comments: Heating System Inc	und to be inoperative us and/or repaired. ier	ing normal control devices. This sho	uld be
		Serial # 3817a193 Approximate Manuf	84		
	□ в.	Cooling Equipment Type of Systems: Centra Comments: Inoperative System			
		The air conditioning heating and cooling and the remedies	system was inoperative technician should be cavailable for correction.	e at the time of the inspection. A qua onsulted to further evaluated of this o	alified ondition
		Manufacturer: Carr Model # 58PHB090 Serial # 3817a193 Approximate Manuf Outdoor Unit Manufacturer: Carr Model # 24ACC64: Serial # 3817E153 3 1/2 TON Approximate Manuf	010116 84 facture Date: 2017 rier 2A300 398		
		Indoor Unit Manufacturer: Care Model # CNPHP43 Serial # 2917X898 Approximate Manu	21ALAAAA 68		
		C. Duct Systems, Chases Comments: Ducts Appears to be prop Heating Exhaust Properly installed.	perly Installed		

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

PLUMBING SYSTEMS IV.

A. Plumbing Supply, Distribution Systems and Fixtures

Location of water meter: Southwest corner rof the lot Location of main water supply valve: interior wall of garage Static water pressure reading: 70

Comments:

Sink: Drain Control Defective

The control mechanism for the right side master bath vanity sink(s) drain(s) are not working properly and slow allow the water to seep from the sink.

Lack of Insulation on Water Supply Lines

There is a lack of insulation on the water supply lines within the attic space. Improvements should be undertaken to avoid damage to the pipes in freezing weather, which can also result in interior water damage to the home as well.





B. Drains, Wastes, and Vents

Comments:

Drains/Clean Outs: Lack of Protection

The exposed plumbing drains and/or clean outs should be painted to avoid deterioration of the PVC material from exposure to UV rays.



Report Identification: Murrell20180404-, 31023 Raleigh Creek, Tomball, TX **D**=Deficient NP=Not Present NI=Not Inspected I=Inspected NI NP D C. Water Heating Equipment Energy Sources: Gas Capacity: TANKLESS Comments: Functional with no significant problems noted. Location: Garage Manufacturer: Rinnai Model # V75i Serial # JE CA-058623 Approximate Mfr. Date: 2017 D. Hydro-Massage Therapy Equipment Comments: E. Other Comments: **APPLIANCES** V. A. Dishwashers Comments: Functional with no significant problems noted. Manufacturer: Frigidaire Model # FGCD2444SA2A Serial # TH80260369 **B.** Food Waste Disposers \square \square \square Comments: Functional with no significant problems noted. Manufacturer: In Sink Erator Model # 1-87 Serial # 17111099476 C. Range Hood and Exhaust Systems Comments: Functional with no significant problems noted. Type: Integrated into microwave unit, vented to exterior

Report Identification: Murrell20180404-, 31023 Raleigh Creek, Tomball, TX D=Deficient NP=Not Present NI=Not Inspected I=Inspected NI NP D D. Ranges, Cooktops, and Ovens Comments: Cooktop Functional with no significant problems noted. Manufacturer: Frigidaire Model # data plate not visible Serial # data plate not visible Built in Oven Functional with no significant problems noted. Manufacturer: Frigidaire Model # FFEW3026TSA Serial # AF74301743 E. Microwave Ovens Comments: Functional with the following deficiency noted. Finish Damage Finish damage was noted to the unit on the right side. Manufacturer: Frigidaire Model # FFMV1645TS Serial # KG74900733 F. Mechanical Exhaust Vents and Bathroom Heaters Comments: **Exhaust Fan: Duct** The ducting to one or more of the exhaust fans was observed to be damaged in the attic area.

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



		V	G.	Garage Door Operators Comments:
V			н.	Dryer Exhaust Systems Comments: The dryer vent has been properly vented to the exterior with no significant problems noted.
	V	V	I.	Other Comments: VI. OPTIONAL SYSTEMS
V			A.	Landscape Irrigation (Sprinkler) Systems Comments: Functional with no significant problems noted.
				Manufacturer: Hunter Model # X-Core

ADDENDUM: MAINTENANCE ADVICE

Upon Taking Ownership

After taking possession of a new home, there are some maintenance and safety issues that should be addressed immediately. The following checklist should help you undertake these improvements:

- * Change the locks on all exterior entrances, for improved security.
- * Check that all windows and doors are secure. Improve window hardware as necessary. Security rods can be added to sliding windows and doors. Consideration could also be given to a security system.
- * Install smoke detectors on each level of the home. Ensure that there is a smoke detector outside all sleeping areas. Replace batteries on any existing smoke detectors and test them. Make a note to replace batteries again in one year.
- * Create a plan of action in the event of a fire in your home. Ensure that there is an operable window or door in every room of the house. Consult with your local fire department regarding fire safety issues and what to do in the event of fire.
- Examine driveways and walkways for trip hazards. Undertake repairs where necessary.
- Examine the interior of the home for trip hazards. Loose or torn carpeting and flooring should be repaired.
- * Undertake improvements to all stairways, decks, porches and landings where there is a risk of falling or stumbling.
- * Review your home inspection report for any items that require immediate improvement or further investigation. Address these areas as required.
- * Install rain caps and vermin screens on all chimney flues, as necessary.
- * Investigate the location of the main shut-offs for the plumbing, heating and electrical systems. If you attended the home inspection, these items would have been pointed out to you.

Regular Maintenance

EVERY MONTH

- Check that fire extinguisher(s) are fully charged. Re-charge if necessary.
- Examine heating/cooling air filters and replace or clean as necessary.
- * Inspect and clean humidifiers and electronic air cleaners.
- * If the house has hot water heating, bleed radiator valves.
- * Clean gutters and downspouts. Ensure that downspouts are secure, and that the discharge of the downspouts is appropriate. Remove debris from window wells.
- * Carefully inspect the condition of shower enclosures. Repair or replace deteriorated grout and caulk. Ensure that
 water is not escaping the enclosure during showering. Check below all plumbing fixtures for evidence of leakage.
- * Repair or replace leaking faucets or shower heads.
- Secure loose toilets, or repair flush mechanisms that become troublesome.

SPRING AND FALL

- Examine the roof for evidence of damage to roof coverings, flashings and chimneys.
- * Look in the attic (if accessible) to ensure that roof vents are not obstructed. Check for evidence of leakage, condensation or vermin activity. Level out insulation if needed.
- Trim back tree branches and shrubs to ensure that they are not in contact with the house.
- * Inspect the exterior walls and foundation for evidence of damage, cracking or movement. Watch for bird nests or other vermin or insect activity.
- Survey the basement and/or crawl space walls for evidence of moisture seepage.
- Look at overhead wires coming to the house. They should be secure and clear of trees or other obstructions.

- * Ensure that the grade of the land around the house encourages water to flow away from the foundation.
- * Inspect all driveways, walkways, decks, porches, and landscape components for evidence of deterioration, movement or safety hazards.
- * Clean windows and test their operation. Improve caulking and weather-stripping as necessary. Watch for evidence of rot in wood window frames. Paint and repair window sills and frames as necessary.
- Test all ground fault circuit interrupter (GFCI) devices, as identified in the inspection report.
- * Shut off isolating valves for exterior hose bibs in the fall, if below freezing temperatures are anticipated.
- * Test the Temperature and Pressure Relief (TPR) Valve on water heaters.
- * Inspect for evidence of wood boring insect activity. Eliminate any wood/soil contact around the perimeter of the home.
- * Test the overhead garage door opener, to ensure that the auto-reverse mechanism is responding properly. Clean and lubricate hinges, rollers and tracks on overhead doors.
- * Replace or clean exhaust hood filters.
- Clean, inspect and/or service all appliances as per the manufacturer's recommendations.

ANNUALLY

- * Replace smoke detector batteries.
- * Have the heating, cooling and water heater systems cleaned and serviced.
- * Have chimneys inspected and cleaned. Ensure that rain caps and vermin screens are secure.
- * Examine the electrical panels, wiring and electrical components for evidence of overheating. Ensure that all components are secure. Flip the breakers on and off to ensure that they are not sticky.
- * If the house utilizes a well, check and service the pump and holding tank. Have the water quality tested. If the property has a septic system, have the tank inspected (and pumped as needed).
- * If your home is in an area prone to wood destroying insects (termites, carpenter ants, etc.), have the home inspected by a licensed specialist. Preventative treatments may be recommended in some cases.

Prevention Is The Best Approach

Although we've heard it many times, nothing could be more true than the old cliché "an ounce of prevention is worth a pound of cure." Preventative maintenance is the best way to keep your house in great shape. It also reduces the risk of unexpected repairs and improves the odds of selling your house at fair market value, when the time comes.

Please feel free to contact our office should you have any questions regarding the operation or maintenance of your home.

Enjoy your home!

ADDENDUM: CARBON MONOXIDE INFORMATION

What is carbon monoxide (CO) and how is it produced in the home?

CO is a colorless, odorless, toxic gas. It is produced by the incomplete combustion of solid, liquid and gaseous fuels. Appliances fueled with gas, oil, kerosene, or wood may produce CO. If such appliances ar not installed, maintained, and used properly, CO may accumulate to dangerous levels.

What are the symptoms of CO poisoning and why are these symptoms particularly dangerous?

Breathing CO causes symptoms such as headaches, dizziness, and weakness in healthy people. CO also causes sleepiness, nausea, vomiting, confusion and disorientation. At very high levels, it causes loss of consciousness and death.

This is particularly dangerous because CO effects often are not recognized. CO is odorless and some of the symptoms of CO poisoning are similar to the flu or other common illnesses.

Are some people more affected by exposure to CO than others?

CO exposures especially affect unborn babies, infants, and people with anemia or a history of heart disease. Breathing low levels of the chemical can cause fatigue and increase chest pain in people with chronic heart disease.

How many people die from CO poisoning each year?

In 1989, the most recent year for which statistics are available, thee were about 220 deaths from CO poisoning associated with gasfired appliances, about 30 CO deaths associated with solid-fueled appliances (including charcoal grills), and about 45 CO deaths associated with liquid-fueled heaters.

How many people are poisoned from CO each year?

Nearly 5,000 people in the United States are treated in hospital emergency rooms for CO poisoning; this number is believed to be an underestimate because many people with CO symptoms mistake the symptoms for the flu or are misdiagnosed and never get treated.

How can production of dangerous levels of CO be prevented?

Dangerous levels of CO can be prevented by proper appliance maintenance, installation, and use:

Maintenance:

- A qualified service technician should check your home's central and room heating appliances (including water heaters and gas dryers) annually. The technician should look at the electrical and mechanical components of appliances, such as thermostat controls and automatic safety devices.
- Chimneys and flues should be checked for blockages, corrosion, and loose connections.
- Individual appliances should be serviced regularly. Kerosene and gas space heaters (vented and unvented) should be cleaned and inspected to insure proper operation.
- CPSC recommends finding a reputable service company in the phone book or asking your utility company to suggest a qualified service technician.

Installation:

- Proper installation is critical to the safe operation of combustion appliances. All new appliances have installation instructions that should be followed exactly. Local building codes should be followed as well.
- Vented appliances should be vented properly, according to manufacturer's instructions.
- Adequate combustion air should be provided to assure complete combustion.
- All combustion appliances should be installed by professionals.

Appliance Use:

Follow manufacturer's directions for safe operation.

- Make sure the room where an unvented gas or kerosene space heater is used is well ventilated; doors leading to another room should be open to insure proper ventilation.
- Never use an unvented combustion heater overnight or in a room where you are sleeping.

Are there signs that might indicate improper appliance operation?

Yes, these are:

- Decreasing hot water supply
- Furnace unable to heat house or runs constantly
- Sooting, especially on appliances
- Unfamiliar or burning odor
- Increased condensation inside windows

Are there visible signs that might indicate a CO problem?

Yes, these are:

- Improper connections on vents and chimneys
- Visible rust or stains on vents and chimneys
- An appliance that makes unusual sounds or emits an unusual smell
- An appliance that keeps shutting off (Many new appliances have safety components attached that prevent operation if an unsafe condition exists. If an appliance stops operating, it may be because a safety device is preventing a dangerous condition. Therefore, don't try to operate an appliance that keeps shutting off; call a service person instead.)

Are there other ways to prevent CO poisoning?

Report Identification: Murrell20180404-, 31023 Raleigh Creek, Tomball, TX

Yes, these are:

- * Never use a range or oven to heat the living areas of the home
- * Never use a charcoal grill or hibachi in the home
- * Never keep a car running in an attached garage

Can Carbon Monoxide be detected?

Yes, carbon monoxide can be detected with CO detectors that meet the requirements of Underwriters Laboratories (UL) standard 2034.

Since the toxic effect of CO is dependent upon both CO concentration and length of exposure, long-term exposure to a low concentration can produce effects similar to short term exposure to a high concentration.

Detectors should measure both high CO concentrations over short periods of time and low CO concentrations over long periods of time - the effects of CO can be cumulative over time. The detectors also sound an alarm before the level of CO in a person's blood would become crippling. CO detectors that meet the UL 2034 standard currently cost between \$35 and \$80.

Where should the detector be installed?

CO gases distribute evenly and fairly quickly throughout the house; therefore, a CO detector should be installed on the wall or ceiling in sleeping area/s but outside individual bedrooms to alert occupants who are sleeping.

Aren't there safety devices already on some appliances? And if so, why is a CO detector needed?

Vent safety shutoff systems have been required on furnaces and vented heaters sine the late 1980s. They protect against blocked or disconnected vents or chimneys. Oxygen depletion sensors (ODS) have also been installed on unvented gas space heaters since the 1980s. ODS protect against the production of CO caused by insufficient oxygen for proper combustion. These devices (ODSs and vent safety shutoff systems) are not a substitute for regular professional servicing, and many older, potentially CO-producing appliances may not have such devices. Therefore, a CO detector is still important in any home as another line of defense.

Are there other CO detectors that are less expensive?

There are inexpensive cardboard or plastic detectors that change color and do not sound an alarm and have a limited useful life. They require the occupant to look at the device to determine if CO is present. CO concentrations can build up rapidly while occupants are asleep, and these devices would not sound an alarm to wake them.

For additional information, write to the U.S. Consumer Product Safety Commission, Washington, D.C., 20207, call the toll-free hotline at 1-800-638-2772, or visit the website http://www.cpsc.gov