Your



Report

for the property located at: 229 Cunningham Fir Trail Conroe, Texas 77301





This inspection report is for the exclusive use of:

Uzziel Maldonado

Date of Inspection: December 11, 2019

www.trec.state.tx.us

25725 Moore Lane Montgomery, Tx 77356 (936) 525-0550

Inspector: Chris Guido, TREC #9922
Chris@tandchomeinspection.com

www.tandchomeinspection.com

This real estate inspection and report is intended to meet or exceed the rules and regulations set forth by the Texas Real state Commission (TREC) as well as the International Association of Certified Home Inspectors (InterNACHI) in effect at the date of the inspection.



www.nachi.org

Town and Country H
25725 Moore LN.
Montgomery, TX 77356

Phone: 936-525-0550

Fax: Email:

Chris@TandCHomeInspection.com

PROPERTY INSPECTION REPORT

Prepared For:	: Uzziel Maldonado					
•	(Name of Client)					
Concerning:	229 Cunningham Fir Trail, Conroe, TX 77301 (Address or Other Identification of Inspected Property)	-				
By:	Chris Guido, Lic #9922 12/11/2019 (Name and License Number of Inspector) (Date)	<u>)</u>				
	(Name, License Number of Sponsoring Inspector)	-				

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information

obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods. Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathroom, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as, smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms requires a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

NOTICE: Use of this report by any individual or without written notification by clients name above is subject to theft of service charges and criminal prosecution.

The inspection report is a binding legal contract agreement. By accepting this inspection report or relying on this report in any way the client affirms, understands, and has agreed to be bound by all terms, conditions, disclaimers and limitations contained in this inspection report whether the client has signed this agreement or not.

Important conditions, limitations and disclaimers:

- 1. This inspection report(s) is performed for the person, company or entity named on the report as the client. This report is not transferable to any other person, company or entity without written authorization.
- 2. The client affirms, understands that additional office fees may be included for scheduling of sub-contractors to perform additional inspections at time of scheduled home inspection.
- 3. This inspection report is in no way; a written or implied warranty, guarantee or representation against any conditions latent defects, hidden defects, equipment failure or structural component failure that may occur after the date of the inspection. Absolutely no guarantee, no warranty and no implied warranty is given or maybe construed exist.
- 4. It should be understood that the labeling of pictures does not mean that is the only place items were deficient.
- 5. This visual inspection report has been done on the equipment and structural competence listed only.
- 6. This is a visual inspection only, and does not deal with local/national codes, or any defects that were latent, hidden or not apparent at the time of inspection. This inspection report solely certifies to the apparent visual condition of those items listed at the time and date of inspection.
- 7. No engineering or scientific test were performed during the course of the visual inspection. This inspection <u>does not</u> include asbestos, lead based paint or mold testing.
- 8. This is not a warranty or guarantee of future performance of any mechanical or structural items. No estimates will be given either written or verbal. We recommend that only a licensed repair company in each area of specified expertise repair items and/or give estimates for repairs. Please remember that almost every item in any house, except a new one is in used condition and has ordinary wear and tear. Company does not hold its inspectors out to be specialists for any particular item. We will not make any recommendations regarding the value of the structure or whether or not the structure should be purchased.
- 9. Mold/mildew investigations are <u>NOT</u> included with this report; it is beyond the scope of this inspection at the present time. Any reference of water intrusion is recommended that a licensed professional investigator be obtained for that area of concern. 10. IF WE REMARK ABOUT AN ITEM AS "DEFICIENT' CUSTOMER SHOULD PRIOR TO PURCHASING THE STRUCTURE, HAVE THAT ITEM EXAMINED BY A SPECIALIST NOT EMPLOYED BY TOWN AND COUNTRY HOME INSPECTION. AFTER PROPER REPAIRS HAVE BEEN MADE BY A SPECIALIST, CUSTOMER SHOULD HAVE THAT SPECIALIST PROVIDE DOCUMENTATION OF REPAIRS MADE AND A FULL WRITTEN REPORT OF THE COMPLETE SYSTEM. The Specialist should be trained and qualified persons who are, whenever possible, manufacturer-approved service persons and who are licensed or bonded whenever such license or bond is required bylaw.

Home inspectors are not required to report on the following: Life expectancy of any component or system; The causes of the need for a repair; The methods, materials, and costs of corrections; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; Any component or system that was not observed; The presence or absence of pests such as wood damaging organisms, rodents, or insects; or Cosmetic items, underground items, or items not permanently installed. Home inspectors are not required to: Offer warranties or guarantees of any kind; Calculate the strength, adequacy, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility; Determine the presence or absence of any suspected adverse environmental condition or hazardous substance, including but not limited to mold, toxins, carcinogens, noise, contaminants in the

building or in soil, water, and air; Determine the effectiveness of any system installed to control or remove suspected hazardous substances; Predict future condition, including but not limited to failure of components; Since this report is provided for the specific benefit of the customer(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

Photos are representative of the issue and may not include all instances or locations of the issue.

Note: All directions are from the street facing the house

Present at Inspection: Home Inspector, Buyer,

Building Status: New Construction Type of Building: Single Family (2 Story)

Weather Conditions:Sunny/Fair, Rain in las 3 Days Temperature: 45 Degrees F Humidity: 70 Percent

Square Footage of Structure: 2100 Sq. Ft. Year of Construction: 2019 Direction of Front Door: Southwest

Utilities On: YES

REAL ESTATE AGENT

Brittney Castellon

BrittanyjCastellon@gmail.com

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

NI NP D

I. STRUCTURAL SYSTEMS

 \square \square \square \square A. Foundations

Type of Foundation(s): Post Tension Slab

Special Note: Refer to your online Home Binder for additional information.

All exposed areas of the foundation were examined visually. The grading and drainage around the perimeter of the foundation was examined to evaluate how effectively water is being is being distributed and directed away from the structure. Various structural components of the home were checked for cracks, movement, misalignment or other signs of excessive foundation settling.

Photos are representative of the issue and may not include all instances or locations of the issue.

See TREC Standards of Practice for details (Click here)

Note: Inspector is not required to enter any area where headroom is less than 18 inches, or the access opening is less than 24 inches wide.

OBSERVATIONS:

OPINION: The Inspector's opinion, based on accessible and observable indications, is that the foundation for this home is performing as intended for new construction.

Note: Weather conditions, drainage, leakage, and other adverse factors are able to effect structures, and differential movements are likely to occur. The inspectors opinion is based on visual observations of accessible and unobstructed areas of the structure at the time of the inspection. Future performance of the structure cannot be predicted or warranted.

We recommend that you visit the following website: http://www.houstonslabfoundations.com. This website was published specifically to help buyers and others understand the foundation inspections with reference to real estate transactions.

DEFICIENCIES:



- 1. Observed wood form boards in place at foundation area.
- IRC R408.5 ...All wood forms used for placing concrete shall be removed before a building is occupied or used for any purpose



2. Observed nails extending from the slab in some areas. These could result in injury and should be cut off.

Report Identification: CG20191211-Maldonado, 229 Cunningham Fir Trail, Conroe, TX

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

B. Grading and Drainage

Special Note: Refer to your online Home Binder for additional information.

OBSERVATIONS:

Inspected for proper and adequate grading around the foundation, for evidence of ponding or erosion near the foundation, and for deficiencies in installed rain gutter and downspout systems.

Photos are representative of the issue and may not include all instances or locations of the issue.

Note: Inspector cannot verify the presence or functionality of subterranean drainage systems.

See TREC Standards of Practice for details (Click here)

DEFICIENCIES:



3. Soil levels against the exterior grade beam was noted to be to high. When soil levels are high against the face of the foundation it promotes water penetration of the structure and insect infestation. This item should be corrected so there is some exposure of the foundation face. It is generally accepted that a brick veneer house should have about 6 inches of clearance. Wood siding houses should have more clearance.

☑ □ □ ☑ C. Roof Covering Materials

Type(s) of Roof Covering: Asphalt Shingles Viewed From: From ground with binoculars

Comments: **Note**: Due to height of roof , assessment of roof condition is based on observation through binoculars from ground level. This is an extremely limited examination and should not be considered comprehensive. For an extensive examination, contact a roofing contractor.

Special Note: Refer to your online Home Binder for additional information.

OBSERVATIONS:

Inspected general condition and appearance of roof, for evidence of previous repairs, and for evidence of existing leaks.

Note: It is beyond the scope of this inspection to determine the age or expected life of the roof covering, to determine the number of layers of roof covering, or to identify latent damage.

See TREC Standards of Practice for details (Click here)

Photos are representative of the issue and may not include all instances or locations of the issue.

Note: Installed shingles have an adhesive strip which bonds them together to prevent tear-off by high winds. I attempted to lift the shingles in several locations to examine fasteners, but was unable to do so without potentially damaging the adhesive bond.

NI=Not Inspected

NP=Not Present

D=Deficient


NI NP D

DEFICIENCIES:

4. Observed possible loose shingle(s) on rear roof edge. Recommend having the roofing company that installed the shingles examine the area and repair or ensure there is no damage.







5. Recommend installing kickout flashing where vertical walls extend beyond a lower roof area.



 \square \square \square

D. Roof Structures and Attics

Viewed From: Attic space walked or crawled - Some areas not accessible Approximate Average Depth of Insulation: 14 Inches Approximate Average Thickness of Vertical Insulation: 7 Inches

Special Note: Refer to your online Home Binder for additional information.

OBSERVATIONS:

Inspected the attic for proper ventilation, examined accessible installed framing and decking, checked for consistent distribution of insulation over all living areas, and examined installation of attic access ladder/opening.

Photos are representative of the issue and may not include all instances or locations of the issue.

Note: Some areas of attic spaces may not be accessible, powered vents will not be tested.

See TREC Standards of Practice for details (Click here)

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

DEFICIENCIES:



6. Observed various areas where supply plumbing lines do not appear to be fully insulated in the attic. Recommend having the lines properly insulated to help prevent possible damage to the material.



7. Observed missing insulation markers. Current standards require a marker placed for every 300 Sq. Ft. of the attic and they be facing the attic entrance.



8. Observed no insulating cover or insulation installed on attic access. Recommend Installing a insulation cover over attic ladder. This will help with energy efficiency for the home.



E. Walls (Interior and Exterior)

Special Note: Refer to your online Home Binder for additional information.

OBSERVATIONS:

Observed brick/masonry veneer, concrete fiber on exterior walls, inspected interior and exterior walls for proper structural performance and evidence of water penetration.

Photos are representative of the issue and may not include all instances or locations of the issue.

Note: Inspector is not required to comment on cosmetic deficiencies, awnings or shutters. Inspector can not verify proper mix or composition of applied mortar or other adhesive.

See TREC Standards of Practice for details (Click here)

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

DEFICIENCIES:

Exterior:



9. There is wood in direct contact with the soil around the structure. This condition may result in wood rot and possible wood destroying insect activity.

10. Caulking/sealant is separated or missing in some areas. Seal all gaps, cracks and holes on exterior walls to prevent water damage to the wall structure. This includes areas where different siding materials meet, around windows and doors, and where plumbing or wiring penetrates the exterior wall. Photos are representative of the issue and may not include all instances of the issue.



☑ □ □ F. Ceilings and Floors

OBSERVATIONS:

Inspected ceilings and floors for proper structural performance and evidence of water penetration.

Photos are representative of the issue and may not include all instances or locations of the issue.

Note: Inspector is not required to comment on cosmetic deficiencies.

See TREC Standards of Practice for details (Click here)

DEFICIENCIES:

No deficiencies were observed.

Report Identification: CG20191211-Maldonado, 229 Cunningham Fir Trail, Conroe, TX						
I=Inspected		NI=Not Inspected	NP=Not Present	D=Deficient		
I NI NP D						
	G.		ers should have all locks ch	nanged / re-keyed for safety / security concerns		
		observations:	o move-in.			
			oper structural performance	e and operation, and for evidence of water		
				clude all instances or locations of the issue. metic deficiencies, or on security systems or devices. See TREC Standards of Practice for details (Click here)		
		DEFICIENCIES:				
		No deficiencies were o	bserved.			
	н.	Windows				
		OBSERVATIONS:				
		Inspected windows for proper structural performance and operation, for evidence of water penetration, for deficiencies in glazing and weather stripping, for obvious indications of broken seals on insulated windows, and for safety glass in required areas.				
				clude all instances or locations of the issue. metic deficiencies, or on security systems or devices. See TREC Standards of Practice for details (Click here)		
		DEFICIENCIES:				
		No deficiencies were o	bserved.			
	I.	Stairways (Interior and	l Exterior)			
		OBSERVATIONS:				
		Inspected for proper splandings and rails.	pacing between componen	ts, and for deficiencies in steps, stairways,		
			e of the issue and may not income and required to exhaustively means	clude all instances or locations of the issue. asure every stairway component. See TREC Standards of Practice for details (Click here)		

Report Identification: CG20191211-Maldonado, 229 Cunningham Fir Trail, Conroe, TX					
I=Inspected		NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D					
		DEFICIENCIES:			
		<u>Interior:</u>			
		No deficiencies were o	bserved.		
	J.	Fireplaces and Chimne Special Note: Refer to		er for additional information.	
		OBSERVATIONS:			
		Not Present			
	K.	Porches, Balconies, Dec	ks, and Carports		
		OBSERVATIONS:			
			arports, porches and decks components, materials and	for proper safety railings, and for deficiencies in connection points.	
		Note: Inspector is	not required to exhaustively mea	clude all instances or locations of the issue. sure installed components, or to enter any area where ening is less than 24 inches wide. See TREC Standards of Practice for details (Click here)	
		DEFICIENCIES:			
		No deficiencies were o	bserved.		
	L.	Other			
		OBSERVATIONS:			
		This section is for structure have anything in this section.		't fit in any other category, most homes will not	

Report Identification: CG20191211-Maldonado, 229 Cunningham Fir Trail, Conroe, TX						
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient			
I NI NP D						
	A. Service Entrance and P	anels				
	Special Note: Refer to	o your online Home Bind	er for additional information.			
	OBSERVATIONS:					
	Inspected service entra electrode, and connect		abinets, boxes and boards, breakers, grounding			
	Note: Inspector is calculations, verify when property is c	not required to determine preser accuracy of circuit labeling or op	clude all instances or locations of the issue. In or future sufficiency of capacity, conduct voltage drop In or future sufficiency of capacity, conduct voltage drop In or future sufficiency of capacity, conduct voltage drop In or future is the imerity of the income sufficiency.			
	of inspection.		See TREC Standards of Practice for details (Click here)			
	Main Panel Location Main Panel Size: 150					
	DEFICIENCIES: No deficiencies were o	bserved.				
	B. Branch Circuits, Conne Type of Wiring: Coppe Special Note: Refer to	er Wire	er for additional information.			
	OBSERVATIONS:					
	Inspected installed fixt		ble junction boxes. Looked for GFCI protection Tested accessible smoke detectors by pressing			
	Note: Inspector is	not required to examine low volt	clude all instances or locations of the issue. age wiring, verify the effectiveness or interconnectivity of disassemble mechanical devices. See TREC Standards of Practice for details (Click here)			
	DEFICIENCIES:					
	No deficiencies were o	bserved.				

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	III. HEATING	G, VENTILATION AND AI	R CONDITIONING SYSTEMS
	A. Heating Equipm Type of System: Energy Source:	Central	
	the heat elemen		eating elements/heat exchangers and as a result 100% checked for defects. For a more inclusive g a licensed HVAC technician.
	Special Note: F	Refer to your online Home Bind	ler for additional information.
	OBSERVATION	IS:	
	Verified system	installation and operation.	
	Note: Inspof thermo	pector is not required to program digital o	controls, verify compatibility of components, verify accuracy determine adequacy of the system, or to determine arts of the home. See TREC Standards of Practice for details (Click here)
	DEFICIENCIES		
	No deficiencies	were observed.	
	B. Cooling Equipm Type of Systems	ent Central - Air Conditioner	
	were the coils chany type of cool	necked for leaks. Only licensed F	ecked for the proper freon levels/ pressures nor IVAC technicians are allowed to install gauges or as. For a more extensive cooling system nician.
	Special Note: F	Refer to your online Home Bind	ler for additional information.
	OBSERVATION	IS:	

Verified system installation and operation. Checked for proper access and clearances, adequacy of condensate drain system, insulation on pipes, condition of accessible coils, and condition and installation of window units.

Photos are representative of the issue and may not include all instances or locations of the issue.

Note: Inspector is not required to program digital controls, check pressure or type of refrigerant, verify compatibility of components, verify accuracy of thermostats, determine adequacy of the system, or to determine uniformity of supply of conditioned air to various parts of the home. Inspector should not operate the air conditioning system when the outdoor temperature is less than 60 degrees Fahrenheit.

See TREC Standards of Practice for details (Click here)

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

Delta-T - n/a degrees

Note: A measurement of how well an air conditioning system is operating is called "*Delta-T*" and is the difference in temperature between the air going into the system and the air coming out. The acceptable range is 16 - 21 degrees.

Unit #1 Size Year Condenser 3.5 2019 Coil 3.5 2019 Furnace 88000 2019



DEFICIENCIES

11. Although the unit was visually inspected and was operated due to the exterior ambient air temperature, a proper reading of the Delta T was not able to be taken. If concerns exist we recommend having the unit examined by a licensed HVAC company.

C. Duct Systems, Chases, and Vents

Special Note: Refer to your online Home Binder for additional information.

OBSERVATIONS:

Inspected accessible ducting for condition and proper routing. Checked for air flow at registers. Checked condition of accessible fans, filters, grills and registers.

Photos are representative of the issue and may not include all instances or locations of the issue.

Note: Inspector is not required to program digital controls, verify compatibility of components, verify accuracy of thermostats, determine adequacy of the system, or to determine uniformity of supply of conditioned air to various parts of the home.

See TREC Standards of Practice for details (Click here)

DEFICIENCIES:



12. Observed the door access to the fresh air filter is blocked by the furnace gas line. Recommend having the gas line repositioned so the filter can be properly accessed and replaced as needed. \square \square \square A. Plumbing Supply, Distribution Systems and Fixtures

Location of water meter: Left property line @ front Location of main water supply valve: In garage

Static water pressure reading: 65 psi

Special Note: Refer to your online Home Binder for additional information.

OBSERVATIONS:

Inspected visible and accessible plumbing for presence of active leaks, and for appropriate valves and back-flow devices. Observed accessible supply plumbing, tested fixtures not connected to an appliance, and tested mechanical operation of installed fixtures.

Photos are representative of the issue and may not include all instances or locations of the issue.

Note: Inspector is not required to operate main, branch or shut-off valves, nor to inspect systems or components that have been shut down or secured, circulating pumps, water softening or filtering systems, pressure tanks or sprinkler systems. Inspector is not required to determine quality or volume of water supply, or to verify functionality of back-flow prevention devices.

See TREC Standards of Practice for details (Click here)

DEFICIENCIES:

13. Shower/tub needs caulking. Caulk any gaps that may appear between the hardware and tile of the fixtures or shower enclosures. Most tile surfaces will have gaps in the gout that can also allow for water penetration past the tile work. A leak in any one of these areas can cause concealed structural damage that would not be obvious in a visual inspection.



☑ □ □ □ B. Drains, Wastes, and Vents

Special Note: Refer to your online Home Binder for additional information.

OBSERVATIONS:

Inspected visible and accessible plumbing for presence of active leaks. Observed accessible waste and vent plumbing, checked functional drainage at fixtures, and tested mechanical operation of installed fixtures.

Photos are representative of the issue and may not include all instances or locations of the issue.

Note: Inspector is not required to inspect systems or components that have been shut down or secured. Inspector is not required to verify functionality of floor drains.

See TREC Standards of Practice for details (Click here)

Report 1	Report Identification: CG20191211-Maldonado, 229 Cultillingham Fil Trail, Contoe, TX						
I=Insp	ected	l		NI=Not Inspected	NP=Not Present	D=Deficient	
I NI	NP	D					
d 0			E.	Other			
				OBSERVATIONS:			
				This section is for plumbing system components that don't fit in any other category, some homes will not have anything in this section.			
				inspection. Lines were to		o be in satisfactory condition at the time of the detector. If there are any concerns I recommect the structure.	
				DEFICIENCIES:			
				No deficiencies were ob	servea.		

Report Identification: CG20191211-Maldonado, 229 Cunningham Fir Trail, Conroe, TX I=Inspected NI=Not Inspected **NP=Not Present D=Deficient** NI NP D V. **APPLIANCES** A. Dishwashers Special Note: Refer to your online Home Binder for additional information. **OBSERVATIONS:** Inspected installed appliance for proper installation and operation in normal mode. Photos are representative of the issue and may not include all instances or locations of the issue. Note: Inspector is not required to comment on cosmetic deficiencies. See TREC Standards of Practice for details (Click here) **DEFICIENCIES:** No deficiencies were observed. B. Food Waste Disposers Special Note: Refer to your online Home Binder for additional information. **OBSERVATIONS:** Inspected installed appliance for proper installation and operation. Photos are representative of the issue and may not include all instances or locations of the issue. Note: Inspector is not required to comment on cosmetic deficiencies. See TREC Standards of Practice for details (Click here) **DEFICIENCIES:** No deficiencies were observed. \square C. Range Hood and Exhaust Systems Special Note: Refer to your online Home Binder for additional information. **OBSERVATIONS:** Inspected installed appliance for proper installation and operation at high and low settings. Photos are representative of the issue and may not include all instances or locations of the issue. Note: Inspector is not required to comment on cosmetic deficiencies, or to determine the adequacy of venting systems. See TREC Standards of Practice for details (Click here)

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

DEFICIENCIES:



15. Observed the fan blades are jammed on the side and do not turn. Recommend having a licensed appliance company examine and repair the issue as needed.



16. Bulb missing from fixture. Recommend installing a bulb and testing the unit.

☑ □ □ □ D. Ranges, Cooktops, and Ovens

Special Note: Refer to your online Home Binder for additional information.

Special Note: Checked for proper installation and operation. All burners are operated at low and high settings. The oven is tested at 350 f. and a variance of more than + or - 25 degrees is considered defective. This means that the thermostat is not calibrated properly, is not positioned properly, or is absolutely defective.

Test Result: 365 Degrees

OBSERVATIONS:

Inspected installed appliance for proper installation and operation, burners tested at high and low settings, oven(s) tested at 350 degrees.

Photos are representative of the issue and may not include all instances or locations of the issue.

Note: Inspector is not required to comment on cosmetic deficiencies or to test self-cleaning functions. Did not test broiler

See TREC Standards of Practice for details (Click here)

DEFICIENCIES:

No deficiencies were observed.

Report Identification: CG20191211-Maldonado, 229 Cunningham Fir Trail, Conroe, TX					
I=Inspected		NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D					
	E.	Microwave Ovens Special Note: Refer to OBSERVATIONS:	o your online Home Binde	er for additional information.	
		Not Present			
	F.	Mechanical Exhaust Ve	ents and Bathroom Heaters		
		Special Note: Refer to	o your online Home Binde	er for additional information.	
		OBSERVATIONS:			
		Inspected installed app	bliance for proper installation	n and operation.	
				lude all instances or locations of the issue. netic deficiencies, or to determine the adequacy of venting See TREC Standards of Practice for details (Click here)	
		DEFICIENCIES:			
		No deficiencies were o	bserved.		
	G.	Garage Door Operator			
		Special Note: Refer to	o your online Home Binde	er for additional information.	
		OBSERVATIONS:			
		Not Present			
	Н.	Dryer Exhaust Systems			
		Special Note: Refer to	o your online Home Binde	er for additional information.	
		OBSERVATIONS:			
		Inspected installed app	oliance for proper installation	n.	
			e of the issue and may not inc not required to comment on cosm	dude all instances or locations of the issue. netic deficiencies. See TREC Standards of Practice for details (Click here)	

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

Dryer outlet is a 4 prong There is also a gas connection

DEFICIENCIES:



Example of a dryer exhaust length label

17. Observed the missing required dryer vent length placard.

Length identification. Where the exhaust duct is concealed within the building construction, the equivalent length of the exhaust duct shall be identified on a permanent label or tag. The label or tag shall be located within 6 feet (1829mm) of the exhaust duct connection. IRC 1502.4.5



□ ☑ ☑ □ I. Other

OBSERVATIONS:

This section is for appliances that don't fit in any other category, most homes will not have anything in this section.

Report Summary

This is a listing of significant repair items noted in the report. While every attempt is made to include all pertinent items in this summary, it is possible that some items may be overlooked, or the buyer may feel that there are other items in the report that are of equal or greater significance. In no case should this summary be deemed a substitute for reading the entire report.

FOUNDATIONS

- 1. Observed wood form boards in place at foundation area.
- 2. Observed nails extending from the slab in some areas

GRADING AND DRAINAGE

3. Soil levels against the exterior grade beam was noted to be to high.

ROOF COVERING MATERIALS

- 4. Observed possible loose shingle(s) on rear roof edge.
- 5. Recommend installing kickout flashing where vertical walls extend beyond a lower roof area.

ROOF STRUCTURES AND ATTICS

- 6. Observed various areas where supply plumbing lines do not appear to be fully insulated in the attic
- 7. Observed missing insulation markers
- 8. Observed no insulating cover or insulation installed on attic access.

WALLS (INTERIOR AND EXTERIOR)

Exterior:

- 9. There is wood in direct contact with the soil around the structure.
- 10. Caulking/sealant is separated or missing in some areas.

COOLING EQUIPMENT

11. Although the unit was visually inspected and was operated due to the exterior ambient air temperature, a proper reading of the Delta T was not able to be taken.

DUCT SYSTEMS, CHASES, AND VENTS

12. Observed the door access to the fresh air filter is blocked by the furnace gas line.

PLUMBING SUPPLY, DISTRIBUTION SYSTEMS AND FIXTURES

13. Shower/tub needs caulking.

WATER HEATING EQUIPMENT

14. Observed the condensate drain line is configured into a loop. This may allow for condensate water to sit and become stagnate.

RANGE HOOD AND EXHAUST SYSTEMS

- 15. Observed the fan blades are jammed on the side and do not turn.
- 16. Bulb missing from fixture.

DRYER EXHAUST SYSTEMS

17. Observed the missing required dryer vent length placard.

It is recommended that all repairs should be performed by a qualified and licensed professional in the designated field. A home inspection is a relatively superficial examination of a broad range of items. When a specialist performs a repair it is more likely that any latent defects may be discovered.

All photos in the report are representative of the issue and may not include all instances or locations of the issue of the named deficiency.