

- Real Estate Inspections
- Infrared Thermography
- Stucco Inspections
- Diagnostic Inspections
- Mold Inspections
- Sewer Line Inspections



Providing Peace of Mind,  
One Home at A Time, since  
1989

## INSPECTION GROUP

FIG Services LLC d/b/a FOX INSPECTION GROUP  
Property Inspection Report #210802AD-13822 Senca Park Drive  
8616 Daffodil St. Houston, TX 77063  
(Office)713.723-3330 (Email) [office@foxinspectiongroup.com](mailto:office@foxinspectiongroup.com)

TREC Inspectors # 1718, 3648, 10503, 10524, 10533, 20283, 20719, 20975, 20976, 20994,  
21225, 21326, 21463, 21810, 22072, 22735, 22779, 22780, 22850, 22922  
Mold Assessment Company ACO1129, Mold Assessment Consultant MAC1452  
Mold Assessment Technicians MAT#'s 1197, 1198, 1203, 1224, 1240, 1246, 1256  
SBCCI Registered Building Inspector #5939  
SBCCI Registered Mechanical Inspector # 1739  
Exterior Design Institute (EDI) # TX-113, TX-116, TX-119, TX-121, TX-140, TDTX-001  
ICC Building Inspectors # 1052678-B5, #5294898-B5  
State of Texas Registered Code Enforcement Officer # CE1858  
ICC Residential Combination Inspectors # 1052678-R5, #5294898-R5  
ICC Residential Building Inspectors # 5167093-B1, #5294898-B1  
ICC Mechanical Inspectors # 1052678-M5, #5294898-M5  
Texas Department of Insurance VIP Certificates #20110061045,  
SBCCI Registered One & Two Family Dwelling Code Certified Inspector #1863 & #2185  
ITC Certified Level I Infrared Thermographers #8661, #8662, #8692, #8694, #26034, #26505





8616 Daffodil St  
Houston, TX 77065  
[www.foxinspectiongroup.com](http://www.foxinspectiongroup.com)  
[office@foxinspectiongroup.com](mailto:office@foxinspectiongroup.com)

## ***PROPERTY INSPECTION REPORT***

---

**Prepared For:** Afshin Gazerzadeh  
(Name of Client)

**Concerning:** 13822 Senca Park Drive, Houston, TX 77077  
(Address of Inspected Property)

**By:** Arash Dinyarian, TREC: 22735 08/02/2021  
(Name and License Number of Inspector) (Date)

---

### **PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES**

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules (“Rules”) of the Texas Real Estate Commission (“TREC”), which can be found at [www.trec.texas.gov](http://www.trec.texas.gov).

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer’s installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

**THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS.** The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller’s disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector’s responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

---

---

Promulgated by the Texas Real Estate Commission (TREC) P.O. Box 12188, Austin, TX 78711-2188 (512) 936-3000  
(<http://www.trec.texas.gov>).

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods. Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

### **TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES**

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathroom, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as, smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms requires a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

---

---

**ADDITIONAL INFORMATION PROVIDED BY INSPECTOR**

**How to read and interpret this report:**

All commented items should be reviewed by the client and any questions directed to the inspector for clarification if needed  
**PRIOR TO THE EXPIRATION OF YOUR OPTION PERIOD.**

**Highest Priority Items are printed in bold print and/or are in boxes**

Items that are underlined should be addressed to prevent more extensive damage and should be a priority item or indicate non-compliance with current building standards.

*Comments in italics are generally FYI (for your information) and don't require any action.*

**For reference:** The front of the unit faces North

**Description:** 1 story, wood framed Single family residence ; brick/stucco/cement board/wood exterior; Composition; Attached garage,

**Weather Conditions:** Partly Cloudy,

**Approximate Outside Temperature:** 90's

**Note:** When reviewing the report, the reader should consider photos and citations of specific issues to be representative examples of what was observed rather than a detailed catalog of all instances of that item on the property.

**Need a Bid for Repair?**



[Click Here](#)



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

### I. STRUCTURAL SYSTEMS


**A. Foundations**

*Type of Foundation(s): Slab*

*Comments:*

**Differential movement/settlement observed; indicated by one or more of the following observed conditions; Elevation readings, Cracks in brick veneer and/or foundation, Cracks in sheetrock over doors and windows, doors that are not square in the jamb, etc. In my opinion, the distress patterns observed at the time of inspection indicate that the foundation is not performing its intended function. Acceptance of present and future condition/performance/maintenance rests solely on the buyer.**

A foundation elevation survey was conducted during the inspection. The floorplan below represents data gathered using a Zip Level or similar instrument and adjusting for floor covering height differences. i.e. differences between tile, carpet and wood flooring(except step down to garage). Measurements are listed to the nearest 1/10th of an inch. Greatest variance was 2.9" and -.7"



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

Slab dressing observed at one or more areas of the foundation.

*Spalling (i.e., corner pops) at one or more corner(s), Corner spalling is common to slab foundations and does not affect the structural integrity of the foundation.*

**B. Grading and Drainage**

*Comments:*

No significant deficiencies or anomalies observed at the time of inspection.

*Buyer's note; Eensure flower bed soil does not rise above foundation or bottom of siding to prevent water and wood-destroying insect entry into the house.*

*Underground yard and/ or pool deck drainage system not checked / inspected. Did not verify yard drains operate properly and that there are no collapsed or clogged areas. Inspector (or anyone else) is unable to induce sufficient quantity of water to determine if system will operate properly when needed. Recommend observing performance during heavy rains and ensure system is maintained / cleaned.*

**C. Roof Covering Materials**

*Type(s) of Roof Covering: Composition Asphalt Shingles*

*Viewed From: Roof Level*

*Comments:*

**ROOF SURFACE:**

Exposed staples/nailheads/fasteners observed on the roof are not properly sealed. Water entry possible.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

Observed scuffed/damaged shingles. Scuffing the mineral surface off of a composition shingle exposes the asphalt to ultraviolet light which causes it to deteriorate and can greatly reduce the life of the shingle.

*Observed satellite dishes/antenna on roof - historically satellite dishes have caused damage to roofs due to improper installation techniques. Recommend removal of dishes and sealing all holes caused by the installation, When/if satellite service is discontinued.*


*Buyer's note; Keep leaves from collecting on the roof, especially in the valleys and keep tree limbs away from the roof to prevent damage to shingles.*

**VISIBLE FLASHING:**

No significant deficiencies or anomalies observed at the time of inspection.

**ROOF PENETRATIONS:**

Roof skylight(s) are a likely place for water penetration, make sure flashing and glass edges are maintained.



**EVIDENCE OF ROOF WATER PENETRATION:**

*None observed at the time of inspection.*

**RAIN GUTTERS AND DOWNSPOUTS:**

Recommend addition of rain gutters to help improve drainage and/or prevent wood rot at the following locations; where currently not present.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

- 
- 
- 
- 

**D. Roof Structures and Attics**

*Viewed From: Safely accessible areas as deemed by the inspector*

*Approximate Average Depth of Insulation: 10-12 inches*

*Approximate Average Thickness of Vertical Insulation: 6 inches*

*Comments:*

**ROOF STRUCTURE AND FRAMING:**


Open chases in the attic are not sealing/fire-stopped to the living area below. The current status does not comply with current industry standards, Code. (IRC 602.8).



*Evidence of previous ( possibly current) rodent activity in the attic.*

**ATTIC INSULATION:**

Insulation not properly positioned/missing in areas, etc.





I=Inspected


NI=Not Inspected

NP=Not Present

D=Deficient


I NI NP D

Ensure insulation has maintained a minimum of 3 inches and wood a minimum of 1 inch from around all recessed lights to reduce possible fire hazards.



**ATTIC ACCESS, LADDERS AND SERVICE WALKS:**

Floor decking in the attic is inadequate for service personnel servicing the HVAC system. Code [IRC 1305.1.3] requires a minimum of a 30-inch deep platform in front of the unit.



Attic ladder not cut to fit properly, which puts undue stress on the ladder; there should be no gaps at section ends.

*Not all areas of the attic were accessible for inspection.*

**ATTIC VENTILATION AND SCREENING:**

No significant deficiencies or anomalies observed at the time of inspection.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

**E. Walls (Interior and Exterior)**

*Comments:*

**INTERIOR:**

**Moisture meter registers water stains as active; base of master bedroom back door.**



Hole in the sheetrock where plumbing lines pass through the wall, below the kitchen sink.

Cosmetic cracks and/or previously repaired cracks in the sheetrock observed over some/many doors, windows, and/or corners.

*Water damage /stains to the base of the cabinet below the sink.*

*Buyer's note: Fresh paint observed on interior surfaces can mask distress indicators.*

*Buyer's Note: No moisture, mold and /or indoor air quality (IAQ) tests were performed. The inspector is not qualified / certified for such evaluations / studies. The client should be aware that various fungi, molds and mildew flourish in such an environment provided by water intrusion events, excessively moist conditions and / or water damaged conditions. A growing concern to date includes the adverse effect on indoor air quality and the potential for inherent health hazards. If concerned the client is advised to contact a qualified IAQ Professional for further evaluations of this property.*

**EXTERIOR:**

Caulking missing and/or deficient around windows / vertical trim / joints in siding. May allow wind driven rain entry.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient


I NI NP D



Need sealing/caulking around all holes and exterior siding penetrations on top and both sides, (leave the bottom open) to prevent water entry. Including but not limited to dryer, bath and range top vents, light fixtures, etc.



Possible water entry from cracks and/or penetrations in stucco siding, Recommend sealing/caulking around all cracks and exterior siding penetrations including but not limited to light fixtures, electrical outlets/service panels, dryer, bath vents, etc.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient


I	NI	NP	D
---	----	----	---

Wood rot observed on areas of house/garage. (north side of the house).



Metal lintel(s) over window/door openings are not flashed as required by current building standards. Per IRC R703.7.5 & 703.8.

Cracks in brick veneer and/or repairs, one or more locations, Recommend buyer take photographs of cracks, their location, and width [ruler across the crack] with a high-resolution camera that has a date stamp for future reference.



A limited visual inspection of what appears to be traditional hard coat / cement-based stucco exterior siding did not indicate any specific areas of concern for this inspector; *However, no representation is made regarding the lack of or possibility of unseen / undetected / hidden / latent water damage behind the stucco exterior. If client has any concerns about the possibility of damage behind the stucco, which is specifically excluded from this limited visual inspection, client is encouraged to arrange for a separate stucco intrusive inspection prior to the expiration of any option period.*

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

*Foundation brick ledge does not meet flush with brick veneer around all areas of the house, some areas where foundation extends past brick veneer and some areas where brick veneer extends past foundation.*

*Cracks at the upper corners of windows are typical due to not enough space left at the ends of steel lintel at the time of construction to allow for expansion of the metal.*

**EVIDENCE OF WATER PENETRATION:**

**Water penetration observed at the following location(s): at the base of wall in master bedroom.**

**THERMAL IMAGING:**

No significant deficiencies or anomalies observed at the time of inspection.

*This inspection consisted of using a FLIR or similar infrared camera and walking the interior of the property looking for anomalies that would warrant further investigation using a pin type moisture meter and areas of deficient insulation. Be advised that a thermal scan is not a substitute for indoor air quality testing (IAQ), testing for pollutants and other bio-hazards. If client is concerned about the quality of indoor air or presence of bio-hazards or pollutants, a qualified IAQ specialist should be consulted.*

**F. Ceilings and Floors**

*Comments:*

**CEILINGS:**

No significant deficiencies or anomalies observed at the time of inspection.

**FLOORS:**

Cracked/chipped and/or loose floor tile observed in; guest bathroom in master hall.

Garage floor slopes improperly to rear of the garage. The floor should slope toward the entrance.

**G. Doors (Interior and Exterior)**

*Comments:*

**INTERIOR:**

One or more latching balls on top of door observed to be damaged/ missing / defective; master bedroom bathroom entrance door, closet door in study.

A "ghost door" was observed at one or more locations. The door is self-opening/closing. The door/jamb is not setting level/plumb.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Missing or non-functioning door stop behind one or more doors to prevent damage to sheetrock.

*Striker plate(s) missing on one or more door jambs.*

**EXTERIOR:**

Auto/self-closing device on the door between the house and garage, as required by code, needs adjustment to operate properly, reference CABO 309.1 & UBC 302.4 ex.3

Weather-stripping torn/damaged and/or missing on one or more exterior door(s).

*Prudent buyers replace/rekey exterior locks upon taking possession of property.*

**GARAGE:**

Sticky/noisy operation, recommend adjustment and/or lubrication.

**H. Windows**

*Comments:*

**WINDOWS:**

One or more windows were difficult to open.

**SAFETY GLASS IN HAZARDOUS LOCATIONS:**

Could not confirm the presence of proper/code required safety glass on ALL glass shower enclosure panels, which is a recognized safety hazard. Could not find/observe markings on ALL glass shower enclosure panels to indicate the presence of required tempered / safety glass.

Could not find/observe markings on glass panels of the exterior door(s) to indicate the presence of safety/tempered glass which is a recognized safety hazard and code requirement. Per UBC 2406.4, IRC 308.4.1.

**I. Stairways (Interior and Exterior)**

*Comments:*

**INTERIOR:**

*Not present at the time of inspection.*

**EXTERIOR:**

*Not present at the time of inspection.*

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

**J. Fireplaces and Chimneys**

*Comments:*

Storm collar needs caulking on the chimney.

Soot build-up in the firebox and/or the flue should be cleaned by a qualified chimney sweep.

**K. Porches, Balconies, Decks, and Carports**

*Comments:*

Observed one or more deck boards loose and/or rotted.

*High soil and patio obscures the view of foundation and prevents visual inspection for termite and/or water penetration.*

*Cracks in walkways, driveway and/or garage concrete observed, typical.*

**L. Other**

*Comments:*

*Not checked/inspected.*

**II. ELECTRICAL SYSTEMS**

**A. Service Entrance and Panels**

*Comments:*

**150 AMP ELECTRICAL SERVICE PANEL LOCATED AT SOUTH EXTERIOR.**

One or more breaker(s) were off at the time of inspection. Inspector does not turn on breakers found in off position due to potential short/electrical problem, recommend inquiring seller regarding information regarding any/all breaker(s) found in the off position.



I=Inspected


NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Observed two or more neutral conductors under one screw lug on the neutral bus. Current industry standards and National Electric Code permit one neutral conductor per screw lug.



Ground clamp and/or wire not secured to ground rod below service meter.



Not all breakers are properly identified.

*Did not observe installed AFCI (Arc Fault Circuit Interrupter) device protection, as required by current building standards, for all: family rooms, dining rooms, living rooms, parlors, libraries, dens, bedrooms, sunrooms, recreation rooms, closets, hallways, laundry rooms, or similar rooms or areas. AFCI devices are intended to protect against fires caused by electrical arcing faults in the home's wiring. Arc faults are a common cause of residential electrical fires. Arc faults can be created by damaged, deteriorated, or worn electrical plugs, cords, and/or branch circuit conductors. As of September 1, 2014, the State of Texas has adopted the 2014 NEC, which includes this requirement, as the "minimum standard" for all non-exempt electrical work.*

**SERVICE WIRING:**

*Observed type of service wiring is underground.*



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

No significant deficiencies or anomalies observed at the time of inspection.

**FEEDER WIRING:**

*Observed type of feeder wiring is aluminum.*

No significant deficiencies or anomalies observed at the time of inspection.

**B. Branch Circuits, Connected Devices, and Fixtures**

*Type of Wiring: Observed type of branch wiring is copper.*

*Comments:*

**BRANCH WIRING:**

No significant deficiencies or anomalies observed at the time of inspection.


**FIXTURES:**

Ceiling fan(s) not balanced and/or noisy operation, study.

**OUTLETS:**

**No power to GFCI/outlet(s); in master bathroom closet for spa/tub.**

**GFCI outlet does not operate properly when tested with simulated short; in west wall of garage.**



Did not observe GFCI protection of all outlets in required locations, including but not limited to the location marked below. This condition is a recognized safety hazard and needs repair.

- Not all in kitchen
- Not all exterior locations

- All kitchen countertop outlets
- In garage

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



Outlet(s) found to be worn, does not hold the plug securely, recommend replacement, including but not limited to; in living room, some in master bedroom.



Improperly wired, 3 prong outlet not grounded or polarity reversed, including but not limited to; garage exterior.

*Garage and exterior outlets improperly tied together per September 1st, 2014 NEC Code Change.*

*Outlets located in inaccessible areas (e.g., garage ceilings, exterior soffits, etc.) are not individually tested.*

*All exterior outlets whether in use or not are required to have in use weather proof cover per September 1st 2014 NEC Code Change.*

*GFCI reset locations; 2 -garage, 1 - master bathroom, 1 - guest bathroom in master bathroom hall, 1 - guest bathroom, 1- in kitchen.*

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

**SWITCHES:**

*The use of a voltage detector indicated switch(s) are not grounded as required by current industry standards (code) to reduce the risk of electrical shock. Before 1999, grounding of switches was not required. Recommend grounding all non-grounded switches or replace all metal faceplates and screws with non-conductive plastic faceplates and screws.*

*Unknown control, mystery switch(s) found, probably / possibly for fan light kit.*

**EQUIPMENT DISCONNECTS:**

No significant deficiencies or anomalies observed at the time of inspection.

**SMOKE DETECTORS AND ALARMS:**

Did not observe any CO (carbon monoxide) detectors in the home. We recommend the installation of (CO) detectors per the manufacturer's installation instructions in any home containing fuel-burning appliances.

*Smoke detectors are tested using the manufacturer supplied test button only. This inspection does not include testing units with actual smoke.*

*The installation of smoke alarm(s) is required inside of all bedrooms and in any rooms designated for the purpose of sleeping, and outside within the proximity of the doors to those rooms. Test all alarms and detectors weekly or monthly per manufacture instructions. The installation of carbon monoxide (CO) detector(s) is required in homes with fuel-fired appliances at every floor elevation and any areas where fuel-fired equipment is located. The installation of Type ABC fire extinguisher(s) at the kitchen, laundry, and garage, if applicable, is also advised. Test all of these devices monthly. Install new batteries semi-annually. Initiate and practice plans of escape and protection for all occupants in case any emergencies arise. Failure to repair defective or install absent alarms, detectors, and other safety equipment immediately can result in serious injury or death. For further information about fire safety and CO poisoning, consult your local fire department and your equipment manufacture(s), and read these links: [www.cpsc.gov/CPSCPUB/PUBS/464.pdf](http://www.cpsc.gov/CPSCPUB/PUBS/464.pdf), [www.carbonmonoxidekills.com](http://www.carbonmonoxidekills.com), [www.nfpa.org/index.asp](http://www.nfpa.org/index.asp), and [www.usfa.dhs.gov/downloads/pyfff/inhome.html](http://www.usfa.dhs.gov/downloads/pyfff/inhome.html).*

*Per manufacturer's recommendations, smoke detection equipment should be replaced every 10 years.*

*Smoke detectors are not interconnected. the actuation of one alarm will not actuate all the alarms in the house/unit.*

**DOORBELL & CHIMES:**

No significant deficiencies or anomalies observed at the time of inspection.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

**OTHER ELECTRICAL ITEMS:**

*Not checked/inspected.*

**III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS**

**A. Heating Equipment**

*Type of System: Forced air*

*Energy Source: Natural Gas*



*Comments:*

**HEATING UNIT:**

Make: TRANE

Age: 28 YEARS

*Typical life expectancy: between 15 - 25 years as reported by Nachi [Click here for more information](#)*



**Furnace unit has exceeded its normal serviceable life span, replacement should be expected and budgeted for in the near future. Before use, recommend a qualified/licensed HVAC technician verify the integrity of the heat exchanger. a cracked exchanger allows combustion gasses (carbon monoxide, etc.) to circulate through air ducts.**

**HOUSE HEATER EXHAUST VENT(S):**

No significant deficiencies or anomalies observed at the time of inspection.

**BLOWER(S):**

No significant deficiencies or anomalies observed at the time of inspection.

**THERMOSTAT(S):**

No significant deficiencies or anomalies observed at the time of inspection.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient


I NI NP D

**B. Cooling Equipment**

Type of System: Central

Comments:

CONDENSING UNIT:



Make: ICECO  
Age: 15 YEARS  
Capacity: 5 TON

Typical life expectancy: between 8 - 20 years as reported by Nachi [Click here for more information](#)

Older unit, limited service life remaining.

*Buyer's Note; The HVAC units observed to be labeled for R22 refrigerant (Freon). R22 phased out by 2020. Parts may not be available for any repair, replacement, charge/recharge and/or additional budget may/will be needed. If the client has any concerns, recommend the HVAC license be consulted.*

EVAPORATOR COIL:

Make: AMERICAN STANDARD

Capacity: 5 TON

Temperature Differential:


Return Temp: 76.3

Supply Temp: 60.6

Difference: 15.70

Age: Appeared to be 1993

Typical life expectancy: between 15 - 25 years as reported by Nachi [Click here for more information](#)



**Recommend qualified/licensed HVAC technician service/repair/replace as needed. Not cooling well.**

I=Inspected

NI=Not Inspected


NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

**The unit has exceeded its normal serviceable life span; replacement should be expected and budgeted for in the near future.**

The bottom of the casing has rust pitting, evidence of limited serviceable life.



**CONDENSATION DRAIN PAN/DRAIN LINES:**

The primary drain line should be insulated along the entire length in the attic to prevent warm attic air condensing on the cool drain line and dripping condensation.

Secondary drain pan is very rusted, recommend replacement.



Emergency drain line/elbow observed to be broken over window.

*Buyers Note: Did not observe an overflow protection device installed on the emergency drain pan. The overflow switch will shut your system down if it detects water in the pan to help prevent water damage to your ceiling.*

I=Inspected

NI=Not Inspected

NP=Not Present


D=Deficient

I NI NP D


**C. Duct Systems, Chases, and Vents**

*Comments:*

Observed several/multiple areas in the attic where flex duct mechanical connection zip ties are not snug fit / are loose as required by current industry standards. Appears proper use of a zip tie synching tool was sporadic. Loose mechanical connections increase the chance of duct separation in the future, recommend repair.



Some flex duct observed to be routed improperly, not to manufacturer's installation instructions. Recommend additional support and/or routing ducts to eliminate “snaking” drooping or crimping of flex duct more than 1” per foot which adds unnecessary additional resistance.



*Buyer's Note: This company does not inspect the interior of the HVAC Duct System. We do not inspect for, and are not qualified to render opinions on, any type of environmental or other bio-hazards. If this is a concern or potential concern, Fox Inspection Group recommends contacting a qualified professional of your choice for further information / investigation.*

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

#### IV. PLUMBING SYSTEMS

##### A. Plumbing Supply, Distribution Systems and Fixtures

*Location of water meter: Front of property*

*Location of main water supply valve: below guest bathroom sink*

*Static water pressure reading: 59 psi*

*Comments:*

**WATER SUPPLY PLUMBING:**

*Water supply piping observed to be predominantly copper.*

*Water softener, treatment and filtration type of equipment was not checked/inspected.*

**COMMODES:**

Recommend caulking around the base of all commodes.

*One or more commode seats are loose, need to be secured.*

**SINKS:**

*Drain stopper or pop-up lever assembly of one or more sinks is missing, damaged or needs adjustment.*

**FAUCETS:**

*No significant deficiencies or anomalies observed at the time of inspection.*

**TUBS:**

Grout/caulking needed at vertical tile corners, cracks in tile and/or mortar between tiles, and where tile meets tub to prevent water entry behind the wall.

One or more drain stoppers do not operate properly, needs adjustment, including, but not limited to master bathroom tub.

The overflow cover is loose. The overflow cover holds the overflow drain and gasket tight to the back of the tub. When it's loose, this joint can leak if the water level rises to the overflow. Check the condition of the gasket and tighten the cover. (guest bathroom in hall master bathroom).

**SHOWER(S):**

The shower diverter valve is not fully functional, does not direct all water to shower head during operation, hallway bathroom.

*24 hour shower pan test has been specifically excluded.*



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

**LAUNDRY CONNECTIONS:**

Corrosion observed on the water supply valve(s).

*Recommend use of stainless steel braided "no burst" clothes washer water supply lines to reduce chance of water damage.*

**EXTERIOR HOSE BIBS:**

Exterior hose spigot(s) do not have code approved anti-backflow devices installed.

**GAS SUPPLY SYSTEMS:**

No significant deficiencies or anomalies observed at the time of inspection

*Pressure test of gas lines has been specifically excluded.*

*Gas meter located at the south exterior side of house*

Exposed exterior gas piping not protected from corrosion as required per IRC 2603.3

Unable to determine if above ground gas lines are properly bonded as required by 2006 IRC/G2411.1 (310). Recommend further evaluation by qualified contractor.

**OBSERVED BRANCH LINES:**

No significant deficiencies or anomalies observed at the time of inspection.

*Galvanized and/or black iron*

**APPLIANCE CONNECTIONS:**

Gas Appliance Connectors (GAC's) do not appear to be electrically bonded. Ref NEC 250.104. Gas Appliance Connectors (GAC's) are the short run of yellow corrugated metal gas lines similar in composition to Corrugated Stainless Steel Tubing (CSST) that connects gas appliances such as kitchen appliances, clothes dryers, water heaters, and house heaters to the natural gas piping in the home. Corrugated Stainless Steel Tubing(CSST) which is a similar material as Gas Appliance Connectors (GAC's), has been linked to fires caused by direct and indirect/close proximity lightning strikes. The lightning strikes have been linked to punctures/holes in the thin stainless steel tubing and igniting fires. CSST is now required to be properly bonded in an attempt to make it safer. Because metallic piping may accidentally become energized, the Code requires that anything electrically conductive - such as water piping systems, gas piping systems\*, air duct systems, communication systems, lightning protection systems, exposed structural steel members - that are likely to become energized must also be bonded to the service equipment or other approved location.

*Did not observe gas line drip leg(s) on gas house heater and/or gas water heaters which are called for in the manufacturer's installation instructions.*


I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



**B. Drains, Wastes, and Vents**

*Comments:*

**DRAIN, WASTE, VENT PLUMBING:**

*Type of drain waste vent material observed to be primarily plastic*

*Hydrostatic pressure test of sewer lines was specifically excluded.*

Missing/damaged drain cleanout cap,



Recommend a hydrostatic test of sewer lines. Due to the age of the house and/or amount of settlement, the possibility of damaged/leaking drain lines below the house in this inspector's opinion is significant. The test by licensed plumber costs several hundred dollars and may uncover/find problems that can easily cost 10-20 thousand dollars to fix. Most new homeowner's policy will no longer cover this expense while existing homeowner policyholders may be covered/insured for this expense.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

**C. Water Heating Equipment**

*Energy Source: Natural Gas*

*Capacity: 40 gallons*


*Comments:*

*Recent legislation regarding water heaters installed or replaced by professional plumbers after April 2015 mandates newer energy efficient units that are not only more expensive, they are physically larger which may require additional costs for retrofit. For additional information we recommend consulting a licensed plumber.*

**WATER HEATING UNIT(S):**

Manufactured in: 2010

*Typical life expectancy of a water heater is 6 - 12 years as reported by Nachi-[Click here for more information](#)*



**At or near the end of serviceable life. The client should budget for repair/replacement.**

Drain pan is very rusted, recommend replacement.

**WATER HEATER EXHAUST VENT(S):**

No significant deficiencies or anomalies observed at the time of inspection.

**TEMPERATURE AND PRESSURE RELIEF VALVE(S):**

*Did not check operation due to possible damage to the resident's property if the drain line leaked.*

**D. Hydro-Massage Therapy Equipment**

*Comments:*

**The unit was not operational, not performing its intended function, in need of repair/replacement.**

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

The motor was not accessible for visual inspection. Inaccessibility does not fully comply with the National Electric Code (Reference NEC 680-72. Accessibility. "hydromassage bathtub electrical equipment shall be accessible for repair/replacement without damaging the building structure or building finish".) Should have access panel installed for servicing/access to pump motor IRC 4109.3.

**E. Other**

*Comments:*

*Not checked/inspected.*

**V. APPLIANCES**

**A. Dishwashers**

*Comments:*

No significant deficiencies or anomalies observed at the time of inspection.

**B. Food Waste Disposers**

*Comments:*

The unit has excessive noise/vibration.

**C. Range Hood and Exhaust Systems**

*Comments:*

Vent pipe connection loose in the cabinet below the unit. Air loss observed.

**D. Ranges, Cooktops, and Ovens**

*Comments:*

ELECTRIC RANGE/COOKTOP:

No significant deficiencies or anomalies observed at the time of inspection.

---

ELECTRIC OVEN:

*Older unit, Functioning properly at the time of inspection. Limited service life remaining.*

*Timer and cleaning cycles not checked.*

**E. Microwave Ovens**

*Comments:*

No significant deficiencies or anomalies observed at the time of inspection.

**F. Mechanical Exhaust Vents and Bathroom Heaters**

*Comments:*

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

No significant deficiencies or anomalies observed at the time of inspection.

*Did not confirm/verify proper venting to the exterior.*

**G. Garage Door Operators**

*Comments:*

Unit has excessive vibration / noise level; recommend lubrication.

Missing required safety sticker/decal next to the operator button.

*Remote control hand held units were not checked/inspected.*

**H. Dryer Exhaust Systems**

*Comments:*

Dryer not properly vented to exterior. Does not extend 3/4 of the way into the roof jack.  
Lots of lint observed in attic. Fire hazard.

*Recommend periodic cleaning of the dryer vent ductwork to reduce the risk of fire.*

**I. Other**

*Comments:*

**REFRIGERATOR:**

No significant deficiencies or anomalies observed at the time of inspection.

**WASHER:**

Out of balance, The unit has excessive noise/vibration, which typically indicates the unit having a limited serviceable life remaining.

**DRYER:**

*Older unit, Functioning properly at the time of inspection. Limited service life remaining.*

**VI. OPTIONAL SYSTEMS**

**A. Landscape Irrigation (Sprinkler) Systems**

*Comments:*

Did not observe code require backflow prevention device on sprinkler system Per IRC 2902.5.3.

One or more spray heads need adjustment for proper yard cover and reduced overspray on the house, fence, and paved areas.

Damaged water line, water gusher in the yard; Station(s) # 3

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



*Rain sensor was not checked/inspected.*

*Testing, certifying and / or verifying the proper operation of back-flow device is specifically excluded.*

**2021 FOX INSPECTION GROUP REAL ESTATE INSPECTION SERVICE AGREEMENT**

**THIS IS INTENDED TO BE A LEGALLY BINDING CONTRACT**

**BETWEEN YOU THE CLIENT AND FOX RESIDENTIAL SERVICES GROUP LLC, ITS SUBSIDIARIES, AND ALL  
SUBCONTRACTORS SCHEDULED OR ARRANGED THROUGH US**

**PLEASE READ CAREFULLY**

- 1. SCOPE OF THE INSPECTION:** The inspector will perform a general, non-Invasive limited visual ("eyeball") inspection of the property structure at the address listed below to provide Client(s) with a written opinion as to the apparent general condition of the structure(s) components and systems at the time of the inspection. The inspection will be performed in a manner consistent with the "Standard of Practice" and "Code of Ethics" of "TREC" Texas Real Estate Commission and prepare a written report of the apparent condition of the readily accessible systems and components of the Property unless otherwise indicated existing at the time of the inspection. A copy of these Standards are readily available to the Client(s) at [http://www.trec.state.tx.us/inspector/rules\\_governing\\_inspectors.asp](http://www.trec.state.tx.us/inspector/rules_governing_inspectors.asp) Only systems and components that can be reached, entered, or viewed without difficulty, moving obstructions, or requiring any action which may result in damage to the property or personal injury to the Inspector will be inspected. Latent and concealed defects and deficiencies are excluded from the inspection, and Inspector is not liable for latent and concealed defects and deficiencies. Any area which is not exposed to view, concealed, is inaccessible because of soil, walls, floors, carpets, ceilings, furnishings or other things, or areas/items which have been excluded by "TREC" Texas Real Estate Commission standards and/or by the agreement of the parties is not included in this inspection. The inspection does not include any destructive testing or dismantling. In the event that the property is a part of a condominium unit, such inspection will not include any other connected or external portions of a multi unit building or any common areas covered by a joint use agreement or considered common areas.
- 2. STANDARDS OF PRACTICE:** The parties agree that the Standards of Practice "TREC" Texas Real Estate Commission shall define the standard of duty and the conditions, limitations, scope, and exclusions of the inspection and are incorporated by reference herein.
- 3. CLIENT'S DUTY:** Client agrees to read the entire report when it is received and promptly call the Inspector with any question or concern regarding the inspection or written report. The written report shall be the final exclusive findings of the Inspector. In the event client becomes aware of a reportable condition which was not reported by the Inspector, Client agrees to promptly notify Inspector and allow Inspector and/or Inspector's designated representative(s) to inspect said condition(s) before making any repair, alteration, or replacement.
- 4. FURTHER EVALUATION:** Client acknowledges and agrees that the Inspector is a generalist and that further investigation of a reported condition by an appropriate certified licensed specialist may provide additional information that may affect a Client(s) decision to purchase the home. Client should seek further evaluation from licensed professionals regarding the deficiencies identified in the written report. Inspector is not liable for Client(s) failure to further investigate reported deficiencies.
- 5. CHANGE IN CONDITION(S):** The parties agree and understand that conditions of systems and components may change between the inspection date and the time of closing. It is the Client's responsibility to further investigate before closing and the Inspector is not liable for any changes of conditions.
- 6. NOT A WARRANTY:** The parties agree and understand the Inspector is not an insurer or guarantor against defects in the structure, items, components, or systems inspected. Client(s) understand that the inspection and inspection report does not constitute a guarantee or warranty of merchantability or fitness for a particular purpose, expressed or implied, or insurance policy, nor is it a substitute for real estate transfer disclosures which may be required by law. **INSPECTOR MAKES NO WARRANTY, EXPRESS OR IMPLIED, AS TO THE PRESENT OR FUTURE FITNESS FOR USE, CONDITION, PERFORMANCE OR ADEQUACY OF ANY INSPECTED STRUCTURE, ITEM, COMPONENT, OR SYSTEM, THE PRESENCE OR ABSENCE OF LATENT OR HIDDEN DEFECTS THAT ARE NOT REASONABLY ASCERTAIN IN A COMPETENTLY PERFORMED HOME INSPECTION, OR THE REMAINING USEFUL LIFE OF ANY SYSTEM OR COMPONENT OF THE PROPERTY.**

7. **NOT AN APPRAISAL:** The Inspection will not include an appraisal of the value or a survey of building and/or property lines. This inspection or the inspection report may not be construed as an appraisal or survey and may not be used as such for any purpose.
8. **NOT A COMPLIANCE INSPECTION:** This inspection or inspection report is NOT a code compliance inspection or certification for past or present governmental codes or regulations.
9. **INSURABILITY:** The inspection or inspection report does not determine whether the property is insurable.
10. **THIRD PARTIES AND SUBROGATION:** The inspection and written report are performed and prepared for the sole and exclusive use and possession of the Client. No other person or entity may rely on the report issued pursuant to this Agreement. In the event that any person, not a party to this Agreement, makes any claim against the Inspector, its employees or agents, arising out of the services performed by the Inspector under this Agreement, or claims alleging in whole or part any negligent act or omission of the Inspector, the Client agrees to indemnify, defend, and hold harmless Inspector from any and all damages, expenses, costs, and attorney fees, arising from such a claim.
11. **LIMITATION OF LEGAL ACTION:** The parties agree that any legal action must be brought within one (1) year from the date of the inspection(s), or will be deemed waived and forever banned.
12. **LIABILITY:** The parties agree that the Fox Inspection Group and its employees and its agents assume no liability or responsibility for cost of repairing or replacing any defects specified in the written report, as well as no liability for the costs of further evaluation or investigation of the defects specified in the written report. Further, the parties agree and understand that the Inspector and its employees and its agents assume no liability for the costs of repairing or replacing any of the unreported defects or deficiencies either current or arising in the future or any property damage, consequential damage or bodily injury of any nature. In the event of a claim by the Client that an installed system, or component of the premises which was inspected by the inspector was not in the condition reported by the Inspector, the Client agrees to notify the Inspector at least 72 hours prior to repairing or replacing such system or component. If repairs or replacement are done without giving the Inspector the required notice, the Inspector will have no liability to the client. Client agrees that prior to taking any action, legal or otherwise, Client shall: submit a written claim to Inspection Company within 10 days of the deficiency discovery to 11227 Endicott Lane, Houston TX 77035. The written claim shall describe the suspected deficiency. Allow the Inspection Company, their agent or legal representative to perform a re-inspection of the deficiencies stated in the claim. Agree to not to disturb or repair the disputed item prior to a re-inspection except in cases where injury or subsequent property damage may occur.
13. **DISPUTES AND ARBITRATION** In the event a dispute arises regarding an inspection that has been performed under this service agreement, Client(s) agree to notify Fox Inspection Group within ten (10) days of the time of discovery to give Fox Inspection Group a reasonable opportunity to re-inspect the property and resolved the dispute amicably. Upon the request of either party, all unresolved disputes relating to this agreement shall be submitted for arbitration in accordance with (AAA) American Association of Arbitrators and pursuant to the Federal Arbitration Act then in effect with costs shared equally. This provision shall be specifically enforceable and damages for breach of this provision shall include but not limited to court costs and attorney's fees. Client agrees that Fox Inspection Group and its agents liability, if any, shall be limited to the amount of the inspection fee paid for inspection. This limitation shall apply regardless of the cause of action or the legal theory pled or asserted specifically including, but not limited to, negligence.
14. **SEVERABILITY:** If any court of competent jurisdiction determines that any section, provision or part of this Agreement is void, unenforceable, or contrary to Texas law, the remaining sections of this Agreement shall remain in full force and effect.
15. **DAMAGES:** If the inspection company or any of its employees, agents, providers, officers, members, or shareholders, are found to be liable for any claim or damage due to the alleged negligence or willful misconduct of the Inspection company performing the home inspection or in the reporting on the condition of the property in the inspection report, **THE MAXIMUM DAMAGE THAT THE CLIENT CAN RECOVER SHALL NOT EXCEED THE COST OF THE INSPECTION FEE PAID BY THE CLIENT.** The Inspection Company shall not be liable to the Client for any loss of use of the property, repair or replacement cost, consequential or punitive damages or for attorneys' fees or court costs. The Inspection Company shall not be liable to the Client for any claims, loss or damage if the Client alters, tampers with or repairs or replaces the condition which is the subject matter of the Client's claim before the Inspection Company has had an opportunity to inspect the alleged defective condition.



16. **CLIENT UNDERSTANDS:** The integrity and moisture content of framing and sheathing behind finished wall coverings (exterior siding, stucco, cement stone coverings, fiber cement siding, drywall, interior bath and shower tile walls, etc) is not visible to inspect and beyond the scope of our services and is excluded within our services and is excluded within our inspection and inspection report. The lack of proper detailing and flashing may result in water penetration behind siding resulting in water penetration and structural damage which Fox Inspection Group makes no guarantee, warranty, or implied in the inspection or inspection report.
17. **EXPERT TESTIMONY / LITIGATION FINANCIAL COMPENSATION CLAUSE:** In the event our services are needed at any time in the future as expert testimony or in a litigation case, client agrees at this time / in advance to financially compensate this firm for it's time and services. Terms: Non-refundable retainer of \$2,500.00 upfront, Hourly rate of \$175.00 for any activities on our part for your case, including but not limited to; deposition, phone time, research, court time, travel time portal to portal, review of case prior to court appearance, etc. Balance due invoiced weekly, submitted Friday, payable the next Friday
18. **RE-INSPECTIONS:** Fox Inspection Group does not normally conduct re-inspection services. We are not in the business of certifying the workmanship and/or warranting another company's repair work. Receipts and/or warranty for work performed should be obtained from the company or companies who have provided repairs. In the event a re-inspection is performed it is agreed in advance that Fox Inspection Group does not assume responsibility of any kind for another company's work.
19. **LIMITATION AND EXCLUSION CLAUSE:** The Client expressly acknowledges and agrees that the following are not included in the scope of the inspection and the inspection report and further acknowledges that the Inspector makes no representations or warranties as to them. **THE FOLLOWING SYSTEMS, ITEMS, AND CONDITIONS WHICH ARE NOT WITHIN THE SCOPE OF THE BUILDING INSPECTION INCLUDE BUT ARE NOT LIMITED TO:** recreational, leisure, playground or decorative equipment or appliances including but not limited to pools, hot tubs, saunas, steam baths, landscape lighting, fountains, shrubs, trees, and tennis courts. Cosmetic conditions wallpapering, painting, carpeting, scratches, scrapes, dents, cracks, stains, soiled or faded surfaces on the structure, equipment or component, soiled, faded, torn, or dirty floor, wall or window coverings, etc. Noise pollution or air quality. Earthquake hazard, flood plain certification, liquefaction, soil, retaining walls, slide potential, wave action and hydrological stability, soil and earth measurements and stability, seismic safety, code and zoning, engineer level analysis, under ground utilities, sink hole potential, formaldehyde, lead paint, asbestos, toxic or flammable materials, molds, mildew, fungi, other environmental hazards, pest infestation, security systems, fire protection systems, sump pumps, household appliances, humidifiers, paint, other treatment windows, interior walls, ceilings and floors, water purification systems, (ozone generator/saltwater, etc), under ground storage tanks, energy efficiency measurements, motion or photo electric sensor lighting, concealed or private security systems, water wells, all over flow drains, heating system's accessories, solar heating systems, heat exchangers, wood burning stoves, sprinkler systems, water softener or purification systems, central vacuum systems, telephone intercom or cable TV systems, internet connections and cable connections, antennae, lightning arrestors, load controllers, governing codes, permits, ordinances, statues, and covenants, and manufacturer specifications, recalls, EIFS, Chinese drywall and tainted materials, plasterboard, sheet rock, gypsum board, latent and concealed defects, and manufactured stone veneer, culture stone siding, fiber cement siding, flues or chimneys, coal stoves, water leaks, water intrusion, design and architect problems, circuit breaker operation, fireplace drafting, boundaries egress and ingress, quality of materials, private sewage, wattage and wiring, electromagnetic field, non built in appliances, rodents, ants, birds, or other wood boring organisms, security locks and devices, thermostat and gauges. Client understands that these systems, items, and conditions, are excepted and excluded from this inspection and Inspection report. Any general comments about these systems, items, and conditions of the written report are informal only and **DO NOT REPRESENT AN INSPECTION.**
20. **COMPENSATION BY OTHERS:** Fox Inspection Group may accept a fee from various vendors in this real estate transaction to compensate for administrative / coordinating / scheduling their services. Fox Inspection Group is accepting a fee or other valuable consideration from HomeSwitch LLC., in this real estate transaction. Client(s) acknowledges that they have been informed of this arrangement between Fox Inspection Group and HomeSwitch LLC and authorizes HomeSwitch LLC to call Client at the phone number provided to discuss options regarding setting up TV, Internet, Home Phone, Electricity, Home Security, Pest Control – even municipal utilities at their future home. If client(s) does not want to be contacted just let us know by phone (713-723-3330) or by email ([Office@FoxInspectionGroup.com](mailto:Office@FoxInspectionGroup.com)) .

21. **PERSONAL SAFETY:** We are not responsible for another participant's personal safety during the inspection process. Client, their representative's, or others participation shall be at his/her own risk for falls, injuries, property damage, etc. We reserve the right to refuse service to anyone for any reason.
22. **REGARDING PREVIOUSLY FLOODED HOMES:** Client is hereby put on notice, Caveat emptor / buyer beware; this property inspection and report specifically excludes any representation that the structure has been properly renovated / repaired after being flooded. Ultimate responsibility for proper renovation and repair lies solely with the property owner / seller and their repair contractors (NOT others associated with the transaction such as Realtors, home inspectors, appraisers, surveyors, title companies, lenders, etc.) Client is strongly advised to obtain all mandatory seller disclosure and documentation, including but not limited to photos and video, regarding any past flooding of the structure, as well as repair methods and techniques used by others to restore the property to its pre-flood condition including their contact information for future reference.
23. This Agreement, including the terms and conditions on all pages, represents the entire agreement between the parties and there are no other agreements either written or oral between them. This Agreement shall be amended only by written agreement signed by both parties. **ACKNOWLEDGMENT:** the undersigned has reviewed this document, understands its content and agrees to the terms and conditions contained. The client further represents and warrants that he or she has full and complete authority to execute this contract on behalf of any spouse or significant other, and to fully bind any spouse or significant other to all terms, conditions, exclusions and limitations of this agreement. The report adheres to the "TREC" Texas Real Estate Commission Standards which is readily available ) at

[http://www.trec.state.tx.us/inspector/rules\\_governing\\_inspectors.asp](http://www.trec.state.tx.us/inspector/rules_governing_inspectors.asp).

## **FOX SUMMARY PAGE**

This page represents a condensed (incomplete) summary of the full inspection report to help with prioritizing. This list is not all inclusive. It is the clients personal responsibility to read the full inspection report and call the inspector if you have any questions.

### **FOUNDATIONS**

---

**Differential movement/settlement observed; indicated by one or more of the following observed conditions; Elevation readings, Cracks in brick veneer and/or foundation, Cracks in sheetrock over doors and windows, doors that are not square in the jamb, etc. In my opinion, the distress patterns observed at the time of inspection indicate that the foundation is not performing its intended function. Acceptance of present and future condition/performance/maintenance rests solely on the buyer.**

### **WALLS (INTERIOR AND EXTERIOR)**

---

**Moisture meter registers water stains as active; base of master bedroom back door.**

Wood rot observed on areas of house/garage. (north side of the house).

**Water penetration observed at the following location(s): at the base of wall in master bedroom.**

### **BRANCH CIRCUITS, CONNECTED DEVICES, AND FIXTURES**

---

**No power to GFCI/outlet(s); in master bathroom closet for spa/tub.**

**GFCI outlet does not operate properly when tested with simulated short; in west wall of garage. Improperly wired, 3 prong outlet not grounded or polarity reversed, including but not limited to; garage exterior,**

### **HEATING EQUIPMENT**

---

**Furnace unit has exceeded its normal serviceable life span, replacement should be expected and budgeted for in the near future. Before use, recommend a qualified/licensed HVAC technician verify the integrity of the heat exchanger. a cracked exchanger allows combustion gasses (carbon monoxide, etc.) to circulate through air ducts.**

## **COOLING EQUIPMENT**

---

**Recommend qualified/licensed HVAC technician service/repair/replace as needed. Not cooling well**

**The unit has exceeded its normal serviceable life span; replacement should be expected and budgeted for in the near future.**

Secondary drain pan is very rusted, recommend replacement.

## **WATER HEATING EQUIPMENT**

---

**At or near the end of serviceable life. The client should budget for repair/replacement.**

Drain pan is very rusted, recommend replacement.

## **HYDRO-MASSAGE THERAPY EQUIPMENT**

---

**The unit was not operational, not performing its intended function, in need of repair/replacement.**

## **DRYER EXHAUST SYSTEMS**

---

Dryer not properly vented to exterior. Does not extend 3/4 of the way into the roof jack. Lots of lint observed in attic. Fire hazard.

## **LANDSCAPE IRRIGATION (SPRINKLER) SYSTEMS**

---

Did not observe code require backflow prevention device on sprinkler system Per IRC 2902.5.3.

Damaged water line, water gusher in the yard; Station(s) # 3