Report Summary

Page 5 Item: A	Foundations -	• Unable to see all of the slab due to high soil,decks,porches etc.
r age o nem. A	Touridations	There should be 4 inches of clearance for brick and stone.6 inches for wood and 8 inches for stucco.
Page 5 Item: C	Roof Covering Materials	 Nails exposed and Should be caulked. This is common maintenance. Debris should be removed from the roof covering and/or gutter system. Nails missing from flashing. Cricket flashing needed.
Page 8 Item: D	Roof Structure and Attics	 Insulation is low in one or more spots. Should be replaced. Attic ladder is not insulated or weather stripped at this time. This is an "As Built" condition that does not meet current energy standards. It is recommended to insulate the hatch door after taking ownership of the property. One or more of the attic ladder components were observed to be damaged and should be corrected for safety reasons.
Page 10 Item: E	Walls (Interior and Exterior)	
Page 16 Item: G	Doors (Interior and Exterior)	 Doors between the garage and the residence should be equipped with a solid wood door not less than {1 3/8"} in thickness, solid or honeycomb core steel door not less than {1 3/8"} thick or {20} minute fire rated doors equipped with a self closing device. Garage walk door should be self closing. Some doors were observed to be sticking, not closing properly, out-of-level, frame damage or missing and/or non-functional hardware. Not uncommon in older homes. One or more doors were closing on there on.May need adjusting.Common in older homes.
Page 17 Item: H	Windows	 Window screens were observed to be damaged or missing in one or more locations. Window(s) would not open in one or more locations. One or more of the bedroom windows are inoperable. At least one window in each bedroom should fully open with free access to the outside for safety concerns.

Page 18 Item: J	Chimneys	 Chimney cap and or rain cap is rusty. Mortar cracked.
		 Creosote build up. Creoste build up can cause chimmney fires. Recommend a professional chimney sweep.
ELECTRICAL		
Page 20 Item: A	T T	Panel should be labeled.
	and Panels -	• Double tap on breaker(S) were observed in the service panel. One wire under each screw is recommended.
	-	• Blanks are missing on dead front cover and should be replaced so no sharp objects or insects can enter the breaker area.
		Missing screw to secure dead front cover.
Page 22 Item: B	Branch Circuits, Connected Devices, and Fixtures	• Recommend GFCI protection(If not present) on 15A/20A circuits providing power to kitchens, bathrooms, garages, laundry rooms, exterior receptacles, pools, spas and whirlpool tubs. GFCI receptacles are required in the kitchen within {2'} of the sink and bathroom within {3'} of the sink edge. Also recommended to upgrade smoke and carbon monoxide detectors in home after closing. Homes with attached garages and gas appliances should have carbon monoxide detectors.
	-	 Damaged and/or missing outlet and/or switch covers were observed. This situation creates a Safety Hazard and should be corrected
		 Outlet(s) cover missing or damaged.
	-	• Open ground(s) noticed at one or more locations around the home
		 Spliced and taped wires were observed and should be installed with a covered junction box with approved connectors and is considered a Safety Hazard.
	_	• Light cover(s) missing in one or more locations.
		• Electrical wire not properly secure in one or more locations.
HEATING, VE	NTILATION AND	AIR CONDITIONING SYSTEMS
Page 26 Item: C	Duct Systems,	Ductwork should not be touching.Ductwork is leaking at connections.
PLUMBING S		
Page 28 Item: A	Plumbing Supply, Distribution System and Fixtures	Shower or tub area needs caulking.
Page 30 Item: B	Drains, Wastes, and Vents	• Drain pipes should be painted. They are not UV resistant.
Page 31 Item: C	Water Heating Equipment	 Water heater was not equipped with a corrosion resistant drain pan . No sediment trap on gas line.
APPLIANCES		and any any any
THE DIAMETER	Garage Door	• The garage door sensors should be installed within {6"} of the