```
I=Inspected
```

```
NI=Not Inspected
```

NP=Not Present

D=Deficient

I NI NP D



Damaged/leaking gutters noted, repairs may be necessary to help the runoff of water onto or near the structure.



Roof Cover



Roof Cover

Roof Cover

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D



Roof Cover



Damaged roof shingles noted, repairs to the roofing are recommended. Damaged or missing roofing material should be repaired. All roof penetrations should be examined and sealed as necessary.



The roofing is nearing the end of its life cycle. Minor repairs are recommended in the short term to maintain the weather tightness of the roof. Damaged or missing roofing material should be repaired. All roof penetrations should be examined and sealed as necessary.



Damaged roof shingles noted, repairs to the roofing are recommended. Damaged or missing roofing material should be repaired. All roof penetrations should be examined and sealed as necessary.

```
I=Inspected
```

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



Damaged roof shingles noted, repairs to the roofing are recommended. Damaged or missing roofing material should be repaired. All roof penetrations should be examined and sealed as necessary.



Damaged roof shingles noted, repairs to the roofing are recommended. Damaged or missing roofing material should be repaired. All roof penetrations should be examined and sealed as necessary.



The roofing is nearing the end of its life cycle. Minor repairs are recommended in the short term to maintain the weather tightness of the roof. Damaged or missing roofing material should be repaired. All roof penetrations should be examined and sealed as necessary.



Damaged roof shingles noted, repairs to the roofing are recommended. Damaged or missing roofing material should be repaired. All roof penetrations should be examined and sealed as necessary.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D





Moisture staining was noted on the ceiling of the garage above the water heater, the kitchen, the dining room. The cause for the staining should be dining room. The cause for the staining should be determined, and repairs undertaken, if necessary, determined, and repairs undertaken, if necessary, to prevent structural damage.

Moisture staining was noted on the ceiling of the garage above the water heater, the kitchen, the



The floor covering is damaged and may be in need of repair or replacement.

to prevent structural damage.



The floor covering is damaged and may be in need of repair or replacement.

Cal-Pro Home Inspections Team 5903 Barkaloo Rd., Baytown), Texas I=Inspected NI=Not Inspected NP=Not Present D=Deficient I NI NP D Tile in the was noted to be cracked/damaged.



Evidence of repairs was noted on the ceiling of the dining room and the first bathroom.

Dark Organic growth was observed on the ceiling of the master bathroom, this condition should be investigated further and re-pairs made if needed.





The well psi gauge is not working. It shows pressure even though the well is off.



Even though the well is running, and the valves are open, no water pressure reaches the house.



Even though the well is running, and the valves are open, no water pressure reaches the house.



Even though the well is running, and the valves are open, no water pressure reaches the house.

Cal-Pro Home Inspections Team 5903 Barkaloo Rd., Baytown), Texas I=Inspected NI=Not Inspected NP=Not Present D=Deficient I NI NP D X X X E. Private Sewage Disposal Systems Type of System: • Conventional with drip drain field Location of Drain Field: • The drain field location was not located. Comments: • Recommend inspection by septic tank company

• There appears to be debris in the bottom of the septic tank, recommend having it pumped and debris removed .

• The Liquid level in the tank was noted to be above the drain lines in the tanks into the baffles. Recommendation is to have the tanks pumped out. Septic tank interior was not inspected.

• Recommend having risers and access ports installed to create easier access for maintenance/cleaning(pumping out) and inspecting the underground components of the septic system.



Preinspection



The Liquid level in the tank was noted to be above the drain lines in the tanks into the baffles. Recommendation is to have the tanks pumped out. Septic tank interior was not inspected.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D T



The Liquid level in the tank was noted to be Recommendation is to have the tanks pumped out. Septic tank interior was not inspected.



Checking the sludge level



The Liquid level in the tank was noted to be above the drain lines in the tanks into the baffles. above the drain lines in the tanks into the baffles. Recommendation is to have the tanks pumped out. Septic tank interior was not inspected.



There appears to be debris in the bottom of the septic tank, recommend having it pumped and debris removed.

Cal-Pro Home Inspections Team			5903 Barkaloo Rd., Baytown), Texa
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP	D		
Image: Control of the second secon	With the sludge level.	install	with the second seco
		mainten inspecting t	ance/cleaning(pumping out) and the underground components of the septic system.
	F. Other Built-in Applia		
	Comments:		
	G. Other		
	Comments:		