

# **Inspection Report**

# **Christine Lee**

Property Address: 6315 Settlers Square Lane Katy TX 77449



American Dream Inspections TX, IIc

Kevin Sandel 22389 4634 Kingfisher Dr. Houston, TX 77035 832-566-0973

# **PROPERTY INSPECTION REPORT FORM**

| Christine Lee                             | 5/21/2022          |
|---|--------------------|
| Name of Client                            | Date of Inspection |
| 6315 Settlers Square Lane, Katy, TX 77449 |                    |
| Address of Inspected Property             |                    |
| Kevin Sandel                              | 22389              |
| Name of Inspector                         | TREC License #     |
|   |                    |
| Name of Sponsor (if applicable)           | TREC License #     |

# PURPOSE OF INSPECTION

A real estate inspection is a visual survey of a structure and a basic performance evaluation of the systems and components of a building. It provides information regarding the general condition of a residence at the time the inspection was conducted. It is important that you carefully read ALL of this information. Ask the inspector to clarify any items or comments that are unclear.

# **RESPONSIBILTY OF THE INSPECTOR**

This inspection is governed by the Texas Real Estate Commission (TREC) Standards of Practice (SOPs), which dictates the minimum requirements for a real estate inspection.

The inspector IS required to:

- use this Property Inspection Report form for the inspection;
- inspect only those components and conditions that are present, visible, and accessible at the time of the inspection;
- indicate whether each item was inspected, not inspected, or not present;
- indicate an item as Deficient (D) if a condition exists that adversely and materially affects the performance of a system or component **OR** constitutes a hazard to life, limb or property as specified by the SOPs; and
- explain the inspector's findings in the corresponding section in the body of the report form.

The inspector IS NOT required to:

identify all potential hazards;

- turn on decommissioned equipment, systems, utilities, or apply an open flame or light a pilot to operate any appliance;
- climb over obstacles, move furnishings or stored items;
- prioritize or emphasize the importance of one deficiency over another;
- provide follow-up services to verify that proper repairs have been made; or
- inspect system or component listed under the optional section of the SOPs (22 TAC 535.233).

# **RESPONSIBILTY OF THE CLIENT**

While items identified as Deficient (D) in an inspection report DO NOT obligate any party to make repairs or take other actions, in the event that any further evaluations are needed, it is the responsibility of the client to obtain further evaluations and/or cost estimates from qualified service professionals regarding any items reported as Deficient (D). It is recommended that any further evaluations and/or cost estimates take place prior to the expiration of any contractual time limitations, such as option periods.

**Please Note**: Evaluations performed by service professionals in response to items reported as Deficient (D) on the report may lead to the discovery of additional deficiencies that were not present, visible, or accessible at the time of the inspection. Any repairs made after the date of the inspection may render information contained in this report obsolete or invalid.

## **REPORT LIMITATIONS**

This report is provided for the benefit of the named client and is based on observations made by the named inspector on the date the inspection was performed (indicated above).

ONLY those items specifically noted as being inspected on the report were inspected.

This inspection IS NOT:

- a technically exhaustive inspection of the structure, its systems, or its components and may not reveal all deficiencies;
- an inspection to verify compliance with any building codes;
- an inspection to verify compliance with manufacturer's installation instructions for any system or component and DOES NOT imply insurability or warrantability of the structure or its components.

# NOTICE CONCERNING HAZARDOUS CONDITIONS, DEFICIENCIES, AND CONTRACTUAL AGREEMENTS

<u>Conditions may be present in your home that did not violate building codes or common practices in effect when the home was constructed but are considered hazardous by today's standards. Such conditions that were part of the home prior to the adoption of any current codes prohibiting them may not be required to be updated to meet current code requirements. However, if it can be reasonably determined that they are present at the time of the inspection, the potential for injury or property loss from these conditions is significant enough to require inspectors to report them as Deficient (D). Examples of such hazardous conditions include:</u>

- malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices and arc-fault devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

Please Note: items identified as Deficient (D) in an inspection report DO NOT obligate any party to make repairs or take other actions. The decision to correct a hazard or any deficiency identified in an inspection report is left up to the parties to the contract for the sale or purchase of the home.

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

# **ADDITIONAL INFORMATION PROVIDED BY INSPECTOR:**

| In Attendance:              | <b>Type of building:</b> | Approximate age of building:   |
|-----------------------------|--------------------------|--------------------------------|
| Customer                    | Single Family (2 story)  | Over 10 Years                  |
| <b>Temperature:</b>         | <b>Weather:</b>          | Ground/Soil surface condition: |
| Over 65 (F) = 18 (C)        | Clear                    | Dry                            |
| <b>Rain in last 3 days:</b> | Radon Test:              | <b>Water Test:</b>             |
| No                          | No                       | No                             |

I NI NP D
I. Structural Systems

| I NINP D                                     |  |
|--|--|
|  | THE BELOW MAJOR DEFICIENCIES LISTS ARE TO BE CORRECTED FIRST BY A PROFESSIONAL TRADE. THERE WILL BE<br>OTHER ITEMS IN THE REPORT THAT CAN BE CORRECTED AT A LATER TIME, SO PLEASE COMPLETELY READ THE FULL<br>REPORT!  |
| All<br>repairs<br>are<br>complete            | STRUCTURAL SYSTEMS MAJOR DEFICIENCIES:   |
|  | 1) All foundation penetrations, gaps and cracks should be sealed properly. Conducive to moisture and WDI (Wood Destroying Insect) intrusion.   |
|  | 2) All lifted roof shingles should be corrected and sealed properly by a professional roofer. Conducive to moisture intrusion and causing possible damage. Should have a professional roofer inspect and evaluate roofing.   |
|  | 3) Roofing has wear and tear at time of inspection. Should have a professional roofer further evaluate.  |
|  | <ol> <li>Roof plumbing vent jacks were not installed properly at time of inspection. Should have a professional roofer correct properly.<br/>Conducive to moisture intrusion and causing possible damage.</li> </ol>   |
|  | 5) All lifted roof exhaust vent lifted flashing should be corrected and sealed properly by a professional roofer. Conducive to moisture intrusion and causing possible damage.   |
|  | 6) Roof sheathing has moisture staining from possible roof leak at time of inspection. Should have a professional roofer inspect and correct properly.   |
|  | 7) Attic did not have proper ventilation at time of inspection. Should have a professional roofer correct properly.  |
| F  | 8) All exterior siding seams, penetrations and damage should be sealed and corrected properly. Conducive to moisture and WDI (Wood Destroying Insect) intrusion.   |
|  | 9) Exterior wall trim has moisture damage and rot in several areas at time of inspection. Should have a professional correct properly.   |
| All has<br>been<br>repaired &<br>painted     | 10) Attic wall was leaking daylight into the interior of attic in several areas at time of inspection. Should correct and seal properly.<br>Conducive to moisture intrusion and causing possible damage.   |
|  | 11) Second floor bedroom ceiling has moisture staining in several areas from a possible roof leak at time of inspection. Should have a professional inspect and correct properly.  |
|  | 12) Rear garage door frame has moisture damage and rot at time of inspection. Door frame was leaking daylight into the interior of garage at time of inspection. Should have a professional correct and seal properly. Conducive to moisture intrusion and causing possible damage.    |
| Replaced                                     | 13) Rear garage door handle was loose at time of inspection. Should correct properly.  |
| Door<br>frame<br>repaired                    | 14) Rear exterior garage door was missing sill plate at time of inspection. Should have a professional correct properly Conducive to moisture intrusion and causing possible damage.   |
|  | 15) Rear exterior door frame has moisture damage and rot at time of inspection. Interior door frame has signs of exterior moisture intrusion at time of inspection. Should have a professional correct and seal properly. Conducive to moisture intrusion and causing possible damage. |
|  | 16) Front exterior door was catching door frame at time of inspection. Should have a professional correct properly.  |
| Moisture<br>staining<br>has been<br>mediated | 17) Rear exterior door was not level in door frame, was not seating properly and leaking daylight into the living space at time of inspection. Should have a professional correct properly.  |
|  | 18) All exterior and interior window penetrations should be sealed properly. Interior window sills have moisture staining in several areas from possible exterior moisture intrusion at time of inspection. Conducive to moisture and WDI (Wood Destroying Insects) intrusion.         |
| CL   | 19) Tiles on rear sidewalk are loose in several areas at time of inspection. Should have a professional correct properly.  |

# **ELECTRICAL SYSTEMS MAJOR DEFICIENCIES:**

1) Smoke detectors should be replaced every 10 years and batteries at least every year.

2) All wire sheathing in the breaker box should go all the way to the breaker. No bare wires should be showing. Should have a professional electrician correct.

# I = Inspected NI = Not Inspected NP = Not Present D = Deficient I NI NP D 3) Rear exterior garage electrical box was loose from wall creating large penetration into the interior of garage at time of inspection. Should have a professional electrician correct properly. Conducive to moisture and WDI (Wood Destroying Insect) intrusion.

4) Exterior lighting was loose to structure in several areas at time of inspection. Should be secured and sealed properly to the structure by a professional electrician.

Changed 5) Exterior light was missing bulb at time of inspection. Should replace properly.

6) Several exterior electrical outlets were loose to the wall at time of inspection. Should have a professional electrician secure and seal to the structure.

7) Electrical outlet under kitchen sink should be GFCI protected outlet. Should have a professional electrician correct properly.

8) Several interior electrical outlets were loose to the wall at time of inspection. Should a professional electrician secure properly.

9) Utility light was not operating at time of inspection. Should have a professional electrician inspect and correct properly.

10) All utility room electrical outlets should be GFCI protected. Electrical covers were missing GFCI protected label at time of inspection. Should have a professional inspect and correct.



11) Many lights were not operating at time of inspection. Possible burnt or missing bulbs at time of inspection. Should correct properly.



### **HVAC SYSTEMS MAJOR DEFICIENCIES:**

1) 2021 RUUD 3 ton AC unit was not cooling properly at time of inspection. Electrical conduit from unit was not protruding into the wall properly exposing electrical at time of inspection. Should have a professional AC Tech inspect and service unit properly.

2) RUUD gas furnace in the attic was not working properly in Cool Mode at time of inspection. Did not test in Heat Mode since the outside temperature was over 60 degrees at time of inspection. Should have a professional AC Tech inspect and service unit properly.

3) Return grill was full of debris at time of inspection. Should be cleaned properly.

4) HVAC thermostat has low battery at time of inspection. Should replace batteries properly.

5) HVAC registers were dirty in several areas at time of inspection. Should have a professional correct properly.

|  | PLUMBING SYSTEMS MAJOR DEFICIENCIES:  |
|--|---|
| All of this<br>has been<br>repaired            | 1) Exterior hose bibb was not operating properly at time of inspection. Should have a professional plumber correct properly.  |
|  | 2) 1st floor bathroom sink faucet was loose at time of inspection. Should have a professional plumber correct properly.   |
|  | 3) Bathroom shower diverter was not operating properly at time of inspection. Should have a professional plumber inspect and correct properly.  |
|  | 4) Several bathroom plumbing drains have bowl under them to catch possible moisture at time of inspection. Should have a professional plumber inspect and correct properly.               |
|  | 5) Second floor bathroom sink was not draining properly at time of inspection. Should have a professional plumber inspect and correct properly.   |
|  | 6) Second floor bathtub was not draining properly at time of inspection. Should have a professional plumber inspect and correct properly.   |
|  |   |
| Dishwasher is                                  | APPLIANCES MAJOR DEFICIENCIES:  |
| operating, was<br>plugged in<br>incorrectly at | 1) Whirlpool dishwasher was not operating and could not test or operate unit at time of inspection. Possible defective electrical outlet.<br>Should have a professional correct properly. |
| first.<br>Oven is cleaned                      | 2) Oven is dirty and should be cleaned properly.  |



# Page 6 of 45 Promulgated by the Texas Real Estate Commission • (512) 936-3000 • www.trec.texas.gov

# I = Inspected NI = Not Inspected NP = Not Present D = Deficient I NI NP D 3) Whirlpool built in microwave was working properly at time of inspection. Microwave was loose in compartment at time of inspection. Unit should be secured properly. t) E to be a base of the secure of

4) Exterior exhaust vents are damaged in several areas at time of inspection. Should have a professional correct properly.

5) Utility exhaust fan was not operating properly at time of inspection. Should have a professional inspect and correct properly.

# 🗌 🗌 🔲 🗹 A. Foundations

Currently

working

Type of Foundation(s): Poured concrete Method used to observe Crawlspace: No crawlspace Columns or Piers: No Piers or Columns

# Comments:

Foundation was working as intended at time of inspection. All foundation penetrations, gaps and cracks should be sealed properly. Conducive to moisture and WDI (Wood Destroying Insect) intrusion.



A. Item 1(Picture)

# 🗌 🗌 🔲 🗹 B. Grading and Drainage

# Comments:

(1) All trees should be cut back from the structure. Conducive to WDI (Wood Destroying Insects) and possible damage to structure.



B. Item 1(Picture)

(2) Soil was too high to the foundation and siding in several areas at time of inspection. Soil should be graded 6" in 10' away from the foundation. Soil should be at least 4" from bottom of brick and 6" from bottom of siding.

I NINP D



B. Item 2(Picture)

# □ □ □ **☑** C. Roof Covering Materials

Types of Roof Covering: 3-Tab fiberglass Viewed roof covering from: Ground Comments:

(1) All lifted roof shingles should be corrected and sealed properly by a professional roofer. Conducive to moisture intrusion and causing possible damage. Should have a professional roofer inspect and evaluate roofing.

**Notice:** Life expectancy of the roofing material is not covered by this property inspection report. If any concerns exist about the roof covering life expectancy or potential for future problems, a roofing specialist should be consulted. The Inspector cannot offer an opinion or warranty as to whether the roof has leaked in the past, leaks now, or may be subject to future leaks, either expressed or implied. The inspection of this roof may show it to be functioning as intended or in need of minor repairs. This inspection does not determine the insurability of the roof. You are strongly encouraged to have your Insurance Company physically inspect the roof, prior to the expiration of any time limitations such as option or warranty periods, to fully evaluate the insurability of the roof.

The absolute water-tightness of a roof system can only be determined by observing it during a period of prolonged rainfall and differing weather and wind conditions. These conditions are rarely, if ever, present during the inspection, and if they are, there are almost always some areas of the roof that will not be observable, due to factors such as, but not limited to: construction/ framing design, ductwork, insulation, low headroom, etc. Therefore this report should not be construed as a warranty, or an absolute opinion, of the complete water-tightness of the roof system. We will, however, endeavor to report observable evidence of roof leaks or problems. It is also important to talk to the homeowner about any ceiling stains and leak activity whether past or present. A homeowner is obligated by the seller's disclosure paperwork to truthfully report on any roof leak issues since they have owned the home. Make sure you have reviewed the seller's disclosure statement in its entirety.

I NINP D



C. Item 1(Picture)



C. Item 2(Picture)

(2) Roofing has wear and tear at time of inspection. Should have a professional roofer further evaluate.



C. Item 3(Picture)

# I NINP D

(3) Roof plumbing vent jacks were not installed properly at time of inspection. Should have a professional roofer correct properly. Conducive to moisture intrusion and causing possible damage.



C. Item 4(Picture)

(4) All lifted roof exhaust vent lifted flashing should be corrected and sealed properly by a professional roofer. Conducive to moisture intrusion and causing possible damage.



C. Item 5(Picture)

(5) Roof sheathing has moisture staining from possible roof leak at time of inspection. Should have a professional roofer inspect and correct properly.

I NINP D



C. Item 6(Picture)

# □ □ □ ■ ■ D. Roof Structures and Attics

Roof-Type: Gable Roof Structure Type: 2 X 6 Rafters Method used to observe attic: Walked, Inaccessible Attic info: Scuttle hole Approximate Average Depth of Insulation: 10 inches Comments:

(1) Areas of the attic was not accessible to inspect at time of inspection. These areas were not inspected for any defects or deficiencies at time of inspection.



D. Item 1(Picture)

(2) Attic did not have proper ventilation at time of inspection. Should have a professional roofer correct properly.

I NINP D



D. Item 2(Picture)



D. Item 3(Picture)

# □ □ □ ☑ ☑ E. Walls (Interior and Exterior)

Wall Structure: Wood Siding Style: Lap Siding Material: Cement-Fiber Wall Material: Gypsum Board Cabinetry: Wood Countertop: Granite Comments:

(1) All exterior siding seams, penetrations and damage should be sealed and corrected properly. Conducive to moisture and WDI (Wood Destroying Insect) intrusion.

I NINP D



E. Item 1(Picture)



E. Item 2(Picture)



E. Item 3(Picture)

(2) Exterior wall trim has moisture damage and rot in several areas at time of inspection. Should have a professional correct properly.

I NINP D



E. Item 4(Picture)

(3) Attic wall was leaking daylight into the interior of attic in several areas at time of inspection. Should correct and seal properly. Conducive to moisture intrusion and causing possible damage.



E. Item 5(Picture)



E. Item 6(Picture)

# NI NP D

# □ □ □ ☑ ✓ F. Ceilings and Floors

Ceiling Structure: Not visible Floor Structure: Slab, Wood joists Ceiling Materials: Gypsum Board Floor Covering(s): Carpet, Laminated T&G, Tile Comments:

(1) Second floor bedroom ceiling has moisture staining in several areas from a possible roof leak at time of inspection. Should have a professional inspect and correct properly.



F. Item 1(Picture)



F. Item 2(Picture)

(2) Upstairs subfloor in several areas have soft spots and make noise when walked on. Should have a professional secure subfloor properly.

# I NINP D



F. Item 3(Picture)

# □ □ □ **G**. Doors (Interior and Exterior)

Exterior Entry Doors: Steel Interior Doors: Hollow core Comments:

(1) Rear garage door frame has moisture damage and rot at time of inspection. Door frame was leaking daylight into the interior of garage at time of inspection. Should have a professional correct and seal properly. Conducive to moisture intrusion and causing possible damage.

I NINP D



G. Item 1(Picture)



G. Item 2(Picture)



G. Item 3(Picture)



I NINP D



G. Item 4(Picture)



G. Item 5(Picture)

(2) Rear garage door handle was loose at time of inspection. Should correct properly.



G. Item 6(Picture)

# I NINP D

(3) Rear exterior garage door was missing sill plate at time of inspection. Should have a professional correct properly. . Conducive to moisture intrusion and causing possible damage.



G. Item 7(Picture)

(4) Rear exterior door frame has moisture damage and rot at time of inspection. Interior door frame has signs of exterior moisture intrusion at time of inspection. Should have a professional correct and seal properly. Conducive to moisture intrusion and causing possible damage.

I NINP D



G. Item 8(Picture)



G. Item 9(Picture)

(5) Front exterior door was catching door frame at time of inspection. Should have a professional correct properly.



G. Item 10(Picture)

# I NINP D

(6) Rear exterior door was not level in door frame, was not seating properly and leaking daylight into the living space at time of inspection. Should have a professional correct properly.



G. Item 11(Picture)



G. Item 12(Picture)

# 🗌 🗌 🗖 🗹 H. Windows

Window Types: Thermal/Insulated Window Manufacturer: BFS Comments:

All exterior and interior window penetrations should be sealed properly. Interior window sills have moisture staining in several areas from possible exterior moisture intrusion at time of inspection. Conducive to moisture and WDI (Wood Destroying Insects) intrusion.



I NINP D



H. Item 1(Picture)





| I. Stairways (Interior and Exterior)<br>Comments:   |
|---|
| <ul> <li>□ J. Fireplaces and Chimneys</li> <li>Sky Light(s): None</li> <li>Chimney (exterior): N/A</li> <li>Types of Fireplaces: None</li> <li>Operable Fireplaces: None</li> <li>Number of Woodstoves: None</li> <li>Comments:</li> </ul>  |
| <ul> <li>K. Porches, Balconies, Decks and Carports</li> <li>Appurtenance: Porch, Sidewalk, Patio</li> <li>Driveway: Concrete</li> <li>Comments:         <ul> <li>(1) Front porch columns were touching soil at time of inspection. This is conducive to possible moisture, reand WDI (Wood Destroying Insect).</li> </ul> </li> </ul> |

I NINP D



K. Item 1(Picture)

(2) Tiles on rear sidewalk are loose in several areas at time of inspection. Should have a professional correct properly.



K. Item 2(Picture)

The roof of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Roof coverings and skylights can appear to be leak proof during inspection and weather conditions. Our inspection makes an attempt to find a leak but sometimes cannot. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

### **Disclaimer:**

A general home inspection is a non-invasive, visual examination of the accessible areas of a residential property, performed for a fee, which is designed to identify defects within specific systems and components that are both observed and deemed material by the inspector. It is based on the observations made on the date of the inspection, and not a prediction of future conditions. It is a snapshot in time. A general inspection will not reveal every issue that exists or ever could exist. But only those material defects observed on the date of the inspection. This is not an inspection of cosmetic defects or deficiencies. Several areas of the property were inaccessible at time of inspection due to being blocked, covered or no proper safe pathways to areas. These areas were not inspected at time of inspection.

# ININPD I. Electrical Systems I. Electrical Service Conductors: Below ground Panel Capacity: 100 AMP Panel Type: Circuit breakers, AFCI Breakers Electric Panel Manufacturer: SQUARE D Comments: Square D breaker box and electric meter. Boxes should be sealed properly to siding. Dead front cover was missing fastener at time of inspection. Should have a professional electrician correct properly. Image: Contract of the part of the part

A. Item 1(Picture)



A. Item 3(Picture)





A. Item 4(Picture)

# Image: Image:

Type of wiring: Copper Wiring Methods: Romex Comments:

(1) The smoke detector should be tested at common hallway to bedrooms upon moving in to home. Smoke detectors should be replaced every 10 years and batteries at least every year.



I NINP D



B. Item 1(Picture)

(2) 100 amp main disconnect. (This is for informational purposes only)



B. Item 3(Picture)

(3) All wire sheathing in the breaker box should go all the way to the breaker. No bare wires should be showing. Should have a professional electrician correct.



B. Item 4(Picture)

(4) Rear exterior garage electrical box was loose from wall creating large penetration into the interior of

# I NINP D

garage at time of inspection. Should have a professional electrician correct properly. Conducive to moisture and WDI (Wood Destroying Insect) intrusion.



B. Item 5(Picture)



B. Item 6(Picture)

(5) Exterior lighting was loose to structure in several areas at time of inspection. Should be secured and sealed properly to the structure by a professional electrician.

I NINP D



B. Item 7(Picture)

(6) Exterior light was missing bulb at time of inspection. Should replace properly.



B. Item 8(Picture)

(7) Several exterior electrical outlets were loose to the wall at time of inspection. Should have a professional electrician secure and seal to the structure.

I NINP D



B. Item 9(Picture)

(8) Electrical outlet under kitchen sink should be GFCI protected outlet. Should have a professional electrician correct properly.



B. Item 10(Picture)

(9) Several interior electrical outlets were loose to the wall at time of inspection. Should a professional electrician secure properly.

I NINP D



B. Item 11(Picture)

(10) Utility light was not operating at time of inspection. Should have a professional electrician inspect and correct properly.



B. Item 12(Picture)

(11) All utility room electrical outlets should be GFCI protected. Electrical covers were missing GFCI protected label at time of inspection. Should have a professional inspect and correct.

# I NINP D



B. Item 13(Picture)

(12) Many lights were not operating at time of inspection. Possible burnt or missing bulbs at time of inspection. Should correct properly.



B. Item 14(Picture)

The electrical system of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Outlets were not removed and the inspection was only visual. Any outlet not accessible (behind the refrigerator for example) was not inspected or accessible. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

| I NINP D   |   |
|------------|---|
|            | III. Heating, Ventilation and Air Conditioning Systems  |
| 🗆 🗆 🗖 🗖 A. | . Cooling Equipment   |
|            | Type of Systems (Cooling): Air conditioner unit   |
|            | Cooling Equipment Energy Source: Electricity  |
|            | Number of AC Only Units: One  |
|            | Central Air Brand: RUUD   |
|            | Comments:   |
|            | 2021 RUUD 3 ton AC unit was not cooling properly at time of inspection. Electrical conduit from unit was    |
|            | not protruding into the wall properly exposing electrical at time of inspection. Should have a professional |
|            | AC Tech inspect and service unit properly.  |

I NINP D





A. Item 2(Picture)

A. Item 1(Picture)



A. Item 3(Picture)



A. Item 4(Picture)

🗌 🗌 🗖 🗹 B. Heating Equipment

Type of Systems (Heating): Furnace

I NINP D

# Energy Sources: Gas

Number of Heat Systems (excluding wood): One Heat System Brand: RUUD Comments:

RUUD gas furnace in the attic was not working properly in Cool Mode at time of inspection. Did not test in Heat Mode since the outside temperature was over 60 degrees at time of inspection. Should have a professional AC Tech inspect and service unit properly.



B. Item 1(Picture)

# C. Duct Systems, Chases and Vents

Ductwork:InsulatedFilter Type:DisposableFilter Size:N/AComments:

(1) Return grill was full of debris at time of inspection. Should be cleaned properly.



C. Item 1(Picture)

(2) HVAC thermostat has low battery at time of inspection. Should replace batteries properly.

```
I NINP D
```



C. Item 2(Picture)

(3) HVAC registers were dirty in several areas at time of inspection. Should have a professional correct properly.



C. Item 3(Picture)

The heating and cooling system of this home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection is not meant to be technically exhaustive. The inspection does not involve removal and inspection behind service door or dismantling that would otherwise reveal something only a licensed heat contractor would discover. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

# I NI NP D IV. Plumbing System A. Plumbing Supply, Distribution System and Fixtures Water Source: Public Water Filters: (We do not inspect filtration systems) Plumbing Water Supply (into home): PVC Plumbing Water Distribution (inside home): CPVC Location of water meter: in yard Location of main water supply valve: Side of Structure Static water pressure reading: 58 psi Type of supply piping material: CPVC Type of drain piping material: PVC Comments:

(1) Static water pressure was 58 psi at time of inspection. (This is for informational purposes only)



A. Item 1(Picture)

(2) Exterior hose bibb was not operating properly at time of inspection. Should have a professional plumber correct properly.



A. Item 2(Picture)

(3) Rear exterior faucet was missing hose bibb at time of inspection. Should have a professional plumber correct properly.

I NINP D



A. Item 3(Picture)

(4) 1st floor bathroom sink faucet was loose at time of inspection. Should have a professional plumber correct properly.



A. Item 4(Picture)

(5) Several plumbing fixtures were loose at time of inspection. Should have a professional plumber correct properly.



A. Item 5(Picture)

(6) Bathroom shower diverter was not operating properly at time of inspection. Should have a professional plumber inspect and correct properly.

I NINP D



A. Item 6(Picture)

# B. Drains, Waste and Vents

Washer Drain Size: 2" Diameter Plumbing Waste: PVC

# Comments:

(1) Several bathroom drain stoppers did not operate at time of inspection. Should have a professional plumber correct properly.



B. Item 1(Picture)

(2) Several bathroom plumbing drains have bowl under them to catch possible moisture at time of inspection. Should have a professional plumber inspect and correct properly.

I NINP D



B. Item 2(Picture)

(3) Second floor bathroom sink was not draining properly at time of inspection. Should have a professional plumber inspect and correct properly.



B. Item 3(Picture)

(4) Second floor bathtub was not draining properly at time of inspection. Should have a professional plumber inspect and correct properly.

I NINP D



B. Item 4(Picture)

# ☑ □ □ □ C. Water Heating Equipment

Water Heater energy sources:Gas (quick recovery)Water Heater Capacity:40 Gallon (1-2 people)Water Heater Location:AtticWH Manufacturer:RHEEMComments:2020 Rheem gas 40 gallon hot water heater in the attic was operating properly at time of inspection.

NI NP D





C. Item 5(Picture)

# 🗌 🗌 🗹 🔲 D. Hydro-Massage Therapy Equipment

Comments:

E. Gas Distribution Systems and Gas Appliances Location of gas meter: Exterior Side of Structure Type of gas distribution piping material: Cast Iron Comments:

The plumbing in the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Washing machine drain line for example cannot be checked for leaks or the ability to handle the volume during drain cycle. Older homes with galvanized supply lines or cast iron drain lines can be obstructed and barely working during an inspection but then fails under heavy use. If the water is turned off or not used for periods of time (like a vacant home waiting for closing) rust or deposits within the pipes can further clog the piping system. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.



Dishwasher Brand: WHIRLPOOL

# Comments:

Whirlpool dishwasher was not operating and could not test or operate unit at time of inspection. Possible defective electrical outlet. Should have a professional correct properly.



A. Item 1(Picture)

# 🗹 🗌 🗌 🔲 B. Food Waste Disposers

Disposer Brand: IN SINK ERATOR

Comments:

InSinkErator disposal was working properly at time of inspection.



B. Item 1(Picture)

# Image: Image: Second and Exhaust System

Exhaust/Range hood: WHIRLPOOL

# Comments:

Whirlpool built in microwave exhaust fan and light was working properly at time of inspection.

# I NINP D



C. Item 1(Picture)

# □ □ □ **☑ Ⅰ**. Ranges, Cooktops and Ovens

Range/Oven: WHIRLPOOL

# Comments:

Whirlpool gas cooktop and oven was working properly at time of inspection. Oven is dirty and should be cleaned properly.



D. Item 1(Picture)



D. Item 2(Picture)

# 🗌 🗌 🗖 🗹 E. Microwave Ovens

Built in Microwave: WHIRLPOOL

# Comments:

Whirlpool built in microwave was working properly at time of inspection. Microwave was loose in compartment at time of inspection. Unit should be secured properly.



I NINP D



E. Item 1(Picture)

# □ □ □ ▼ F. Mechanical Exhaust Vents and bathroom Heaters

# Comments:

(1) Exterior exhaust vents are damaged in several areas at time of inspection. Should have a professional correct properly.



F. Item 1(Picture)

(2) Utility exhaust fan was not operating properly at time of inspection. Should have a professional inspect and correct properly.

I NINP D



F. Item 2(Picture)

| 🗆 🗆 🗹 🔲 G. | Garage Door Operator(s)      |    |
|------------|------------------------------|----|
|            | Auto-opener Manufacturer: N/ | A  |
|            | Garage Door Type: One manua  | ıI |
|            | Garage Door Material: Metal  |    |
|            | Comments:                    |    |
| 🗹 🗆 🗆 🗆 н. | Dryer Exhaust System         |    |

Comments:

The built-in appliances of the home were inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

### **Disclaimer:**

A general home inspection is a non-invasive, visual examination of the accessible areas of a residential property, performed for a fee, which is designed to identify defects within specific systems and components that are both observed and deemed material by the inspector. It is based on the observations made on the date of the inspection, and not a prediction of future conditions. It is a snapshot in time. A general inspection will not reveal every issue that exists or ever could exist. But only those material defects observed on the date of the inspection. This is not an inspection of cosmetic defects or deficiencies. Several areas of the property were inaccessible at time of inspection due to being blocked, covered or no proper safe pathways to areas. These areas were not inspected at time of inspection.

If you're reading this report but did not hire me, American Dream Inspections TX LLC to perform the original inspection, please note that it is likely that conditions related to the home have probably changed, even if the report is fairly recent. Just as you cannot rely on an outdated weather report, you should not rely on an outdated inspection report. Minor problems noted may have become worse, recent events may have created new issues, and items may even have been corrected and improved. Don't rely on old information about one of the biggest purchases you'll ever make. Remember that the cost of a home inspection is insignificant compared to the value of the home. Protect your family and your investment, and please call me directly at 832-566-0973 to discuss the report you're reading for this properly so that we can arrange a re-inspection.

Thank you!