



SUMMARY
11120 FM 1484 Rd, Conroe, TX 77303
Linda Jemison
04/28/2023

Weston Brown
TREC# 24165/InterNachi© CPI
iHeart INSPECTIONS®
281-799-7542
iheartinspections@gmail.com



24

MINOR REPAIR
RECOMMENDATIONS

24

RECOMMENDATIONS

2


SAFETY
HAZARD/IMMEDIATE
REPAIR REQUIRED

2.1.1 A. Foundations

POTENTIAL FOUNDATION DAMAGE (TREES)

Minor Repair Recommendations

- Roots from a tree located near the foundation may cause foundation damage as the tree grows and the root system expands. Monitor this area of the foundation during the growing season (usually May through September) for signs of damage. If signs of damage appear (such as cracks) the tree may need to be removed. The potential for damage from tree roots varies with tree species.



2.1.2 A. Foundations

POST-TENSIONED CABLES EXPOSED

Recommendations

- One or more exposed post-tensioned cables were observed at the time of inspection. Exposed cables are subject to water exposure which can cause the cables to rust and potentially snap. **As such, these exposed cable ends should be cleaned and patched with non-shrink concrete to prevent damage.**



Left Exterior




Left Exterior

2.2.1 B. Grading and Drainage
NO GUTTERS

 Minor Repair Recommendations

- The home had no roof drainage system to channel roof drainage away from the foundation. Elevated moisture levels in the soil near the foundation can affect the ability of the soil to support the weight of the structure above and can cause problems related to soil/foundation movement. **The Inspector recommends the installation of a roof drainage system to help protect the home structure.**




Gutter Illustration



2.2.2 B. Grading and Drainage
NEUTRAL OR NEGATIVE GRADE

 Recommendations


- The home had areas of neutral or negative drainage that will route runoff from precipitation toward the foundation. Because the home was in an area that may contain expansive soil, the Inspector recommends re-grading these areas to improve drainage near the foundation and help prevent foundation damage. **The ground should slope away from the home a minimum of 1/4-inch per foot for a distance of at least six feet from the foundation.**



2.2.3 B. Grading and Drainage
POOR FOUNDATION CLEARANCE (GRADE)

 Minor Repair Recommendations

- The top of the foundation wall had inadequate clearance from grade. The top of the foundation wall should be a minimum of six inches above the soil. Inadequate clearance may result in moisture intrusion of the structure. Excessively high moisture levels can result in damage to the home structure or materials from decay or deterioration and may result in conditions that encourage the growth of microbes such as mold fungi. **The Inspector recommends re-grading around the home perimeter to provide increased clearance from grade.**



Correct Foundation Clearance



Front Right Exterior

2.3.1 C. Roof Covering Materials
DEBRIS ON ROOF SURFACE

 Minor Repair Recommendations

- Observed debris on the roof surface. **Recommend removal.**



2.3.2 C. Roof Covering Materials

LIFTED SHINGLES

- One or more shingles are bowing outward and are not flush with the roof surface. This may lead to water intrusion through this shingle. **The Inspector recommends a licensed roofing contractor to evaluate and repair.**



Right Exterior



Right Exterior




Right Exterior

2.4.1 D. Roof Structures and Attics

INADEQUATE INSULATION LEVELS (INSULATION)

- Thermal insulation installed to limit heat gain and loss in the living space did not appear to meet widely-accepted modern standards. To reduce energy consumption and heating/cooling costs, the inspector recommends that additional thermal insulation be added to meet modern standards. **A qualified insulation contractor should be able to advise you capably.**




2.5.1 E. Walls (Interior and Exterior)

CRACKS - MINOR

 Minor Repair Recommendations

- Minor cracking was observed in the wall structure. This is common in homes at this age. ***Recommend monitoring.***



Primary Bedroom

2.5.2 E. Walls (Interior and Exterior)

SEALANT AT EXTERIOR PENETRATIONS

 Minor Repair Recommendations

- All exterior penetration into the exterior veneer should have sealant installed. This condition could lead to moisture intrusion. **The Inspector recommends a licensed contractor to repair the openings.**




Left Exterior



Left Exterior



Left Exterior



Rear Exterior

2.6.1 F. Ceilings and Floors

CRACKED TILE



- One or more tiles are cracked at the time of inspection.



Front Porch


2.7.1 G. Doors (Interior and Exterior)

DOOR DOESN'T LATCH



Minor Repair Recommendations

- Door doesn't latch properly. **Recommend handyman repair latch and/or strike plate.**



Rear Right Bedroom Closet

2.7.2 G. Doors (Interior and Exterior)

DOOR STICKS



Recommendations

- The door sticks and is tough to open. **Recommend sanding down offending sides.**



Laundry Room

2.8.1 H. Windows

DAMAGED

Recommendations

- One or more windows have general damage.



2.8.2 H. Windows

FAILED SEAL

Recommendations

- Observed condensation between the window panes, which indicates a failed seal. **Recommend qualified window contractor evaluate & replace.**

2.8.3 H. Windows

MISSING SCREEN(S)

Minor Repair Recommendations

- One or more windows are missing a screen. **Recommend replacement.**



Front Living Room

2.8.4 H. Windows
OLD WINDOWS

 Minor Repair Recommendations

- The windows appear to be original and are passed their useful time. **The Inspector recommends considering changing out the window for a more energy efficient home.**



2.8.5 H. Windows
WINDOW DIFFICULT TO OPEN

 Recommendations

- Many windows were difficult to open. **The Inspector recommends a licensed window repair company to evaluate the issue or replace the aging window.**



Front Primary Bedroom



Primary Bathroom



Front Living Room




Breakfast Room

2.8.6 H. Windows

**WINDOW BLINDS
INOPERABLE**

Minor Repair Recommendations

- One or more window blind is inoperable.



Front Living Room

2.11.1 K. Porches, Balconies,
Decks, and Carports**DAMAGED CARPORT**

Minor Repair Recommendations

- General damage to the carport was observed at the time of inspection.




2.12.1 L. Other

**CABINET DOESN'T STAY
CLOSED**

Minor Repair Recommendations

- One more cabinet doors do not stay close.



Front Breakfast Room

2.12.2 L. Other


DRAWER STICKS

 Minor Repair Recommendations

- One or more drawers are sticking when operated.



Kitchen



Video
(click here to view on web)

Kitchen

2.12.3 L. Other

PAINT EXTERIOR VENEER

 Minor Repair Recommendations

- Finish painting the exterior veneer in one or more locations.



Left Rear Exterior

3.1.1 A. Service Entrance and Panels

 Safety Hazard/Immediate Repair Required

UNFILLED OPENINGS

- Unfilled holes or knockouts in the electrical service panel may allow persons to come into contact with energized electrical components, may allow insect or rodent entry, or may allow moisture intrusion that can cause corrosion of interior components that can degrade electrical connections. **This condition is a potential fire/shock/electrocution hazard and should be corrected by a qualified electrical contractor.**




Garage

3.2.1 B. Branch Circuits, Connected Devices, and Fixtures


DIFFERENT BRAND BREAKERS (MAIN PANEL)

 Recommendations

- Circuit breakers in the service panel were of a brand different from the main panel brand. Because circuit breakers made by different manufacturers vary in design, panel manufacturers typically require that breakers manufactured by their company be used in their panels. Breakers from one manufacturer used in the panel of another manufacturer may result in poor connections which can create a potential fire or shock/electrocution hazard. **The Inspector recommends correction by a qualified electrical contractor.**



Bedroom




Garage

3.2.2 B. Branch Circuits, Connected Devices, and Fixtures

GROUND & NEUTRALS TERMINATE TOGETHER OK - BUS BAR (MAIN PANEL)

 Recommendations

- Ground and neutral wires in the service panel terminated on the same bus bar. While improper, this is not usually a condition of major concern.



3.2.3 B. Branch Circuits, Connected Devices, and Fixtures



Recommendations

INOPERABLE RECEPTACLES

- An electrical receptacle was inoperable at the time of the inspection. **The Inspector recommends service by a qualified electrical contractor.**



Laundry Room

3.2.4 B. Branch Circuits, Connected Devices, and Fixtures

OPEN GROUND - RECEPTACLES (INTERIOR)




Recommendations

- An electrical receptacle had an open ground. Other receptacles in the home were grounded. **This receptacle should have a functional equipment grounding conductor installed by qualified electrical contractor.**



Rear Primary Bedroom



Rear Primary Bedroom



Primary Bathroom

3.2.5 B. Branch Circuits, Connected Devices, and Fixtures
OPEN NEUTRAL RECEPTACLES (INTERIOR)

Recommendations

- An electrical receptacle had an open neutral which should be corrected by a qualified electrical contractor.



Front Right Bedroom



Front Right Bedroom

3.2.6 B. Branch Circuits, Connected Devices, and Fixtures
LIGHT FIXTURE - NO RESPONSE LIGHTS

Minor Repair Recommendations

3.2.8 B. Branch Circuits, Connected Devices, and Fixtures

AFCI/GFCI BREAKER TEST

- The AFCI/GFCI test button on the "Washer" breaker did not respond when pushed. **Recommend a qualified electrical contractor be contacted to evaluate or replace breaker.**

3.2.9 B. Branch Circuits, Connected Devices, and Fixtures


NON-TAMPER RESISTANT RECEPTACLE

- Any receptacles less than five and a half feet above the floor that are not tamper-resistant are considered deficient per the TREC Standards Of Practice.

3.2.10 B. Branch Circuits, Connected Devices, and Fixtures

NEED MORE RECEPTACLES

- In general living areas, there should be an outlet on the wall every 6 feet (horizontally). Living areas refer to all large areas in your home, including the bedrooms, study, dining room, and hallways. Hallways over 10 feet long require at least one outlet. Walls less than 2 feet long do not require an outlet. **Discuss additional receptacles with a licensed electrician.**



3.3.1 C. Other

RECEPTACLE PLATE LOOSE

Minor Repair Recommendations

- One or more receptacle plates are loose at the time of inspection.



Front Hall Bathroom

3.3.2 C. Other

SWITCH SCREWS MISSING

Minor Repair Recommendations

- One or more switch screws are missing in the plate. **Replace screws.**




4.1.1 A. Heating Equipment

LOW SUPPLY TEMP

Minor Repair Recommendations

- A lower-than-normal temperature was recorded from the supply registers while the furnace was operating. **Recommend a licensed HVAC professional be contacted to evaluate the system.**



4.2.1 B. Cooling Equipment
AGING A/C

 Minor Repair Recommendations



- The A/C is approximately 12 years old. Most condensers or air handlers need replacement between 15-20 years. **Although no obvious deficiencies with the furnace were observed at the time of inspection, the Inspector recommends the client budget in the case of furnace failure.**



4.3.1 C. Duct Systems, Chases, and Vents
DUCT LEAKING

 Recommendations

- The air supply duct was leaking air. **Recommend a qualified HVAC technician or vents & ducts contractor repair.**






5.1.1 A. Plumbing Supply, Distribution Systems, and Fixtures
DISCOLORED HOT WATER

 Recommendations

- Discolored hot water visible at the time of the inspection is seldom caused by tank failure, but may be caused by several non-toxic, iron-reducing bacteria; Crenothrix, Leptothrix, and Gallionella. Bacterial action can lead to early failure of anode rods. Well water, water softeners, and dormant water heaters are conditions that encourage bacterial proliferation. Treatment is possible. **The Inspector recommends service by a qualified water treatment specialist.**



Rear Left Bathroom



Cold Water




Hot Water


5.1.2 A. Plumbing Supply, Distribution Systems, and Fixtures
OBSOLETE TRAPS - "S" TRAP

 Recommendations

- A trap was of a type that is no longer allowed to be installed in new construction for safety reasons. Although this type of trap may have been commonly considered safe when the home was originally constructed, as general knowledge of safe building practices has improved with time, building practices have improved and requirements have become more stringent. Consider replacing this trap with a modern, approved trap. **A qualified plumbing contractor should perform all work.**



Illustration



Under Sink

5.1.3 A. Plumbing Supply, Distribution Systems, and Fixtures FAUCET STOPPERS INOPERABLE




Minor Repair Recommendations

- The water stoppers for the faucet are inoperable. **The Inspector recommends a licensed contractor to repair.**



Primary Bathroom



Rear Left Bathroom

5.1.4 A. Plumbing Supply, Distribution Systems, and Fixtures

SEALANT NEEDED ON FIXTURE

 Minor Repair Recommendations


- The sealant on the tub faucet needs to be added, and resecured to the tile veneer. ***The Inspector recommends a licensed contractor be contacted to make repairs.***



Front Hall Bathroom



Front Hall Bathroom



Front Hall Bathroom

5.1.5 A. Plumbing Supply, Distribution Systems, and Fixtures

TOILET LOOSE

 Minor Repair Recommendations

- The toilet was loose and should be repaired.




Primary Bathroom

5.1.6 A. Plumbing Supply, Distribution Systems, and Fixtures

HOT AND COLD REVERSED

 Recommendations

- The hot and cold water is reversed on the fixture.



Front Hall Bathroom

5.1.7 A. Plumbing Supply, Distribution Systems, and Fixtures
COLD WATER SUPPLY LEAK

Recommendations

- The cold water supply line was leaking at the time of inspection. ***Recommend a licensed plumbing contractor be contacted to evaluate and repair the issue.***




Front Hall Bathroom

Front Hall Bathroom

5.2.1 B. Drains, Wastes, and Vents
POOR/SLOW DRAINAGE

Recommendations

- Poor/slow drainage was observed at the time of inspection. ***Recommend a qualified plumber to evaluate and repair.***



Video
(click here to view on web)

Front Hall Bathroom

5.3.1 C. Water Heating Equipment

FRONT COVER ISSUE

- The front cover for the water heater came off and should be repaired.



Minor Repair Recommendations




6.3.1 C. Range Hood and Exhaust Systems

LOUD NOISE

- Loud noises were observed from the range hood when operated on "High" mode. **Contact an appliance repair specialist to evaluate the issue.**



Recommendations



Video
(click here to view on web)

6.4.1 D. Ranges, Cooktops, and Ovens

RANGE NOT FASTENED



Safety Hazard/Immediate Repair Required

-
- The range was not fastened to the floor. A child standing on the open oven door could overturn the range. This condition is a life-safety issue. ***The Inspector recommends installation of an approved anti-tip device by a qualified appliance contractor.***
-