- Real Estate Inspections
- Infrared Thermography
- Stucco Inspections
- Diagnostic Inspections
- Mold Inspections
- Sewer Line Inspections



Providing Peace of Mind, One Home at A Time, since 1989

INSPECTION GROUP

FIG Services LLC d/b/a FOX INSPECTION GROUP Property Inspection Report #220120CS-2819 Meandering Elm Trail 8616 Daffodil St. Houston, TX 77063

(Office)713.723-3330 (Email) office@foxinspectiongroup.com

TREC Inspectors #1718,364,10913,10524,10533,20283, 20975,20976,20994,21225,21326,21463,21810, Mold Assessment Company ACO1129, Mold Assessment Consultant MAC1452 Mold Assessment Technicians MAT#'s 1197, 1198, 1203, 1224, 1240, 1246, 1256 SBCCI Registered Building Inspector #5939 SBCCI Registered Mechanical Inspector #1739 Exterior Design Institute (EDI) TX-111, TX-116, TX-119 ICC Building Inspectors #1052678-B5, #5294898-B5 State of Texas Registered Code Enforcement Officer # CE1858 ICC Residential Combination Inspectors #1052678-R5, #5294898-B5 ICC Residential Building Inspectors #1052678-B1, #5294898-B1 ICC Mechanical Inspectors #1052678-M5, #5294898-M5, 5230842-M1 Texas Department of Insurance VIP Certificate #20110061045 SBCCI Registered One & Two Family Dwelling Code Certified Inspector #1863 & #2185 Infrared Thermographers



This report # 220120CS-2819 Meandering Elm Trail is the property of FIG Services, LLC d/b/a Fox Inspection Group © 2022, all rights reserved.



PROPERTY INSPECTION REPORT

Prepared For:	Robert & Armi Harper (Name of Client)	
Concerning:	2819 Meandering Elm Trail, Houston, TX 77045 (Address of Inspected Property)	
By:	Cory Simpson, TREC: PI #25086 (Name and License Number of Inspector)	01/20/2022 (Date)

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREClicensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

Promulgated by the Texas Real Estate Commission (TREC) P.O. Box 12188, Austin, TX 78711-2188 (512) 936-3000 (http://www.trec.texas.gov).

Report Identification: 220120CS-2819 Meandering Elm Trail, 2819 Meandering Elm Trail, Houston, TX

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods. Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathroom, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as, smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms requires a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR How to read and interpret this report:

All commented items should be reviewed by the client and any questions directed to the inspector for clarification if needed PRIOR TO THE EXPIRATION OF YOUR OPTION PERIOD.

Highest Priority Items are printed in bold print and/or are in boxes

Items that are underlined should be addressed to prevent more extensive damage and should be a priority item or indicate noncompliance with current building standards.

Comments in italics are generally FYI (for your information) and don't require any action.

For reference: The front of the unit faces North Description: 2 story, wood framed Single family residence; Brick, Wood, Cement board, Exterior; composition roof; Attached garage Weather Conditions: Cloudy

Approximate Outside Temperature: 40's

Note: When reviewing the report, the reader should consider photos and citations of specific issues to be representative examples of what was observed rather than a detailed catalog of all instances of that item on the property.

BE ADVISED: One or more utilities were not on/functioning at time of inspection. Per Buyer's and or Agent's request FIG Inspection Services performed a limited inspection on property as utilities and property were not available or ready for proper inspection. By acceptance of this report buyer assumes all responsibility and liability concerning deficient items and incomplete inspection of property.





I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			


I. STRUCTURAL SYSTEMS

 $\overline{\mathbf{A}} \Box \Box \overline{\mathbf{A}}$

A. Foundations

Type of Foundation(s): Post Tension Comments: Performing intended function. No evidence suggesting significant foundation movement at time of inspection.

A foundation elevation survey was conducted during the inspection. The floor plan below represents data gathered using a Zip Level and adjusting for floor covering height differences. i.e. differences between tile, carpet and wood flooring (except step down to the garage). Measurements are listed to the nearest 1/10th of an inch. The greatest variance was -.2 to 1.4 inches.



I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

Spalling at one or more locations around the house/garage. Generally due to not enough concrete (Minimum 2") coverage over steel in the foundation which causes steel to rust and spall/pop-off the concrete.



$\square \square \square \square \square B. Grading and Drainage$

Comments:

Soil grade and drainage patterns around some areas of the house do not appear to properly direct water away from the foundation to aid in controlling runoff water and could cause differential movement of the foundation or water penetration during heavy rains.



Underground yard and/ or pool deck drainage system not checked / inspected. Did not verify yard drains operate properly and that there are no collapsed or clogged areas. Inspector (or anyone else) is unable to induce sufficient quantity of water to determine if system will operate properly when needed. Recommend observing performance during heavy rains and ensure system is maintained / cleaned.

I=Inspected N	I=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

☑ □ □ ☑ C. Roof Covering Materials

Type(s) of Roof Covering: Composition/Asphalt Shingles Viewed From: Drone due to height at eave and / or pitch of roof. Comments: Due to the lack of safe access to the roof and/or to prevent damage to the roof surface the

inspector did not physically walk on the roof. a drone was used to observe the roof surface for significant issues. The client is advised that aerial observation from a drone will not show all possible deficiencies. If this is a concern, recommend the client retain the services of a qualified roofing specialist at additional cost.

ROOF SURFACE:



No significant deficiencies or anomalies observed at the time of inspection.

Note: Observed staining to shingles at north exterior.



I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

VISIBLE FLASHING:

Flashing missing and/or improperly installed; west exterior above window.



Did not observe head flashing over some windows/doors. Head flashing helps prevent water penetration. Without head flashing, window sealant must be maintained as it is the only defense against water penetration; above garage car door.



ROOF PENETRATIONS: No significant deficiencies or anomalies observed at the time of inspection.

EVIDENCE OF ROOF WATER PENETRATION:

No significant deficiencies or anomalies observed at the time of inspection.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient		
I NI NP D					
	RAIN GUTTERS AND DOWNSPOUTS: Recommend the addition of rain gutters to help improve drainage. Houses located in areas with known expansive or collapsible soils are required to have a roof drainage system (most commonly rain gutters installed completely around the perimeter of the house) that will disperse / discharge water a minimum of 5 feet from the perimeter of t structure, or to an approved drainage system. <i>Ref: IRC 801.3</i>				
	Approximate Average Approximate Average Comments: ROOF STRUCTUR No significant defici Limited visual inspec	v accessible areas as dee ge Depth of Insulation: 1 ge Thickness of Vertical 1 E AND FRAMING: encies or anomalies obse	· ·		
	ATTIC ACCESS, L Not all areas of attic No significant defici ATTIC VENTILAT	encies or anomalies obse ADDERS AND SERVIC were accessible for insp encies or anomalies obse ION AND SCREENINC	<i>pection</i> . erved at the time of inspection.		
	The inspector is not be aware that variou by water intrusion e conditions. A growin and the potential for	oisture, mold and /or ind qualified / certified for s us fungi, molds and milde vents, excessively moist o ng concern to date includ	por air quality (IAQ) tests were such evaluations / studies. The ew flourish in such an environn conditions and / or water dama les the adverse effect on indoon . If concerned the client is advi- uations of this property.	e client should nent provided ged r air quality	

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

Buyer's note: Fresh paint observed on interior surfaces can mask distress indicators.


No significant deficiencies or anomalies observed at the time of inspection.

EXTERIOR:

Gaps at joints in building components are potential pest / rodent entry points.



Observed one or more areas of damaged / cracked / chipped cement board siding.





I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

Trim / siding observed to be not secured down at one or more areas of house/garage.



Need sealing/caulking around all holes and exterior siding penetrations on top and both sides, (*leave the bottom open*) to prevent water entry. Including but not limited to dryer, bath and range top vents, light fixtures, etc.





Caulking missing and/or deficient around windows / doors / vertical trim / joints in siding. May allow wind driven rain entry.





I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				





EVIDENCE OF WATER PENETRATION:

Possible from exterior penetrations / window / doors / trim boards / joints in siding not properly caulked/sealed.

THERMAL IMAGING:

No significant thermal anomalies observed at the time of inspection.



I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				

	This inspection consisted of using a FLIR or similar infrared camera and walking the interior of the property looking for anomalies that would warrant further investigation using a pin type moisture meter and areas of deficient insulation. Be advised that a thermal scan is not a substitute for indoor air quality testing (IAQ), testing for pollutants and other bio-hazards. If client is concerned about the quality of indoor air or presence of bio-hazards or pollutants, a qualified IAQ specialist should be consulted. Note: Any observed thermal anomalies are documented in appropriate categories of the report.
F.	Ceilings and Floors Comments: CEILINGS: No significant deficiencies or anomalies observed at the time of inspection. FLOORS: No significant deficiencies or anomalies observed at the time of inspection.
G.	Doors (Interior and Exterior) Comments: INTERIOR: No significant deficiencies or anomalies observed at the time of inspection.EXTERIOR: Auto/self-closing device on the door between the house and garage, as required by code, needs adjustment to operate properly,.

Door damaged; garage pedestrian.



I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

Weather-stripping torn/damaged and/or missing on one or more exterior door(s).



Observed sharp edges of weather stripping protruding out of door jamb; garage pedestrian door, recommend repair.



One or more exterior door threshold water channels need to be cleaned of debris to prevent water entry during driving rains; front door.



I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

Recommend caulking interior ends of the exterior door threshold water channel to prevent water entry during driving rains.



Note: Observed the 2nd floor attic access door to be cut short for jamb/ seal.



Prudent buyers replace/rekey exterior locks upon taking possession of property.

GARAGE:

Weather-stripping torn/damaged and/or missing on garage car door(s).

 $\overline{\mathbf{A}} \square \square \overline{\mathbf{A}}$

H. Windows Comments: WINDOWS:

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

Observed attic window not properly installed. Building wrap does not wrap through the opening at sides and/or rough sill not properly covered with poly or self-sealing flashing (aka Peel-N-Stick). There is potential for a water leak during wind-driven rains - similar details not observable in other windows.



One or more windows were difficult to open / close / operate.

SAFETY GLASS IN HAZARDOUS LOCATIONS: No significant deficiencies or anomalies observed at the time of inspection.


$\boxdot \Box \Box \Box$	I. Stairways (Interior and Exterior)
	Comments:
	INTERIOR:
	No significant deficiencies or anomalies observed at the time of inspection.

EXTERIOR: *Not present at the time of inspection.*

- □ ☑ ☑ □ J. Fireplaces and Chimneys Comments: Not present at the time of inspection.
- Image: Image: Decks and CarportsImage: Decks and CarportsComments:

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

Tripping hazard(s) - walks and/or driveways are uneven.



 $\Box \boxtimes \boxtimes \Box$

L. Other

Comments: Not checked/inspected.

II. ELECTRICAL SYSTEMS

A. Service Entrance and Panels

Comments:

Buyer's note: The inspector is not required to: (A) determine present or future sufficiency of service capacity amperage, voltage, or the capacity of the electrical system; (B) test arc-fault circuit interrupter devices when the property is occupied or damage to personal property may result, in the inspector's reasonable judgment; (C) conduct voltage drop calculations; (D) determine the accuracy of overcurrent device labeling; (E) remove covers where hazardous as judged by the inspector; (F) verify the effectiveness of overcurrent devices; or (G) operate overcurrent devices. 22 TAC §535.229 (a) Standards of Practice. Acceptance of these conditions rest solely with the buyer, if you have concerns or questions we recommend contacting a licensed electrical contractor for a professional analysis of the system, equipment and / or components.

125 AMP ELECTRICAL SERVICE PANEL LOCATED AT EAST EXTERIOR WALL No significant deficiencies or anomalies observed at the time of inspection.

Note: Inspector observed a temporary electrical meter and service panel in backyard. Recommend consulting with builder, possible work in progress.



I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient			
I NI NP D	ľ					
		vice wiring is undergro	und. erved at the time of inspection.			
	FEEDER WIRING: Observed type of feeder wiring is aluminum.					
	-	No significant deficiencies or anomalies observed at the time of inspection. Did not observe anti-oxidant compound (grease) on the exposed aluminum feeder wiring.				
		, oxuuni compound (gre	use) on the exposed diaminant jecuer with the			
	 B. Branch Circuits, Connected Devices, and Fixtures <i>Type of Wiring: Observed type of branch wiring is copper.</i> <i>Comments</i>: BRANCH WIRING: No significant deficiencies or anomalies observed at the time of inspection. 					
	FIXTURES: Light diffuser / glob	e cracked, damaged or n	nissing; above kitchen island.			
		0				

OUTLETS:

Did not observe GFCI protection of all outlets in required locations, including but not limited to the locations marked below. This condition is a recognized safety hazard and needs repair.

- \Box All bathrooms
- □ Kitchen island
- \blacksquare Not all exterior locations
- \Box Laundry sink
- \Box Other:

□ All kitchen countertop outlets


1 200

- \Box Wet bar locations
- □ In garage
- □ Pool area
- □ Spa / hot tub

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				



Did not observe proper dedicated 120-volt outlet for a gas dryer in the laundry room.



Garage and exterior outlets improperly tied together per 2014 NEC Code Change.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

Observed 4-prong outlet for electric dryer as required by the current code. Will not fit older electric dryer with a 3-prong electrical plug.

Outlets located in inaccessible areas (e.g., garage ceilings, exterior soffits, etc.) are not individually tested.

All exterior outlets whether in use or not are required to have in use weather proof cover per September 1st 2014 NEC Code Change.

GFCI reset locations; GFCI's for dishwaser, laundry room plugs, disposal are located in main breaker panel, 2- kitchen, 1- 2nd floor guest bath, 1- 1st floor guest bath, 2-garage, 1-attic.

SWITCHES:

No significant deficiencies or anomalies observed at the time of inspection. *Unknown control, mystery switch(s) found, probably / possibly for fan light kit.*

EQUIPMENT DISCONNECTS:

No significant deficiencies or anomalies observed at the time of inspection.

SMOKE DETECTORS AND ALARMS:

No significant deficiencies or anomalies observed at the time of inspection.

Smoke detectors are tested using the manufacturer supplied test button only. This inspection does not include testing units with actual smoke.

The installation of smoke alarm(s) is required inside of all bedrooms and in any rooms designated for the purpose of sleeping, and outside within the proximity of the doors to those rooms. Test all alarms and detectors weekly or monthly per manufacture instructions. The installation of carbon monoxide (CO) detector(s) is required in homes with fuel-fired appliances at every floor elevation and any areas where fuel-fired equipment is located. The installation of Type ABC fire extinguisher(s) at the kitchen, laundry, and garage, if applicable, is also advised. Test all of these devices monthly. Install new batteries semi-annually. Initiate and practice plans of escape and protection for all occupants in case any emergencies arise. Failure to repair defective or install absent alarms, detectors, and other safety equipment immediately can result in serious injury or death. For further information about fire safety and CO poisoning, consult your local fire department and your equipment manufacture(s), and read these links: www.cpsc.gov/CPSCPUB/PUBS/464.pdf, www.carbonmonoxidekills.com, www.nfpa.org/index.asp, and www.usfa.dhs.gov/downloads/pyff/inhome.html.

Per manufacturer's recommendations, smoke detection equipment should be replaced every 10 years.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

DOORBELL & CHIMES:

No significant deficiencies or anomalies observed at the time of inspection.

OTHER ELECTRICAL ITEMS:



Not checked/inspected.


III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS

✓ □ □ □ A. Heating Equipment

Type of System: Forced air Energy Source: Natural Gas *Comments:*

Buyer's Note; For heating, ventilation, and air conditioning systems inspected under TREC guidelines, the inspector is not required to perform the following actions: inspect duct fans, humidifiers, dehumidifiers, air purifiers, motorized dampers, electronic air filters, multi-stage controllers, sequencers, heat reclaimers, wood burning stoves, boilers, oil-fired units, supplemental heating appliances, de-icing provisions, or reversing valves; If buyer is concerned recommend consulting with a qualified HVAC specialist.

HEATING UNIT: (2021) GOODMAN



Report Identification:	220120CS-2819	Meandering	Elm Trail,	2819 Meandering	Elm Trail.	Houston,	ТΧ

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

No significant deficiencies or anomalies observed at the time of inspection.

Unit inspected visually only, not cycled / tested. No gas to property at time of inspection.

HOUSE HEATER EXHAUST VENT(S):

No significant deficiencies or anomalies observed at the time of inspection.

Unit inspected visually only, not cycled / tested. No gas to property at time of inspection.

BLOWER(S):

No significant deficiencies or anomalies observed at the time of inspection.

Unit inspected visually only, not cycled / tested. No gas to property at time of inspection.

THERMOSTAT(S):

No significant deficiencies or anomalies observed at the time of inspection.

Unit inspected visually only, not cycled / tested. No gas to property at time of inspection.

 $\boxdot \Box \Box \checkmark$

B. Cooling Equipment

Type of System: Central - Air Conditioner Comments:


Buyer's note: This inspector is not required to A) verify tonnage match of indoor coils and outside coils or condensing units B) determine the correct sizing, efficiency, or adequacy of the HVAC system. 535.230 Standards of Practice. Acceptance of these conditions rest solely with the buyer, if you have concerns or questions we recommend contacting a licensed HVAC technician for a professional analysis of the system.

CONDENSER UNIT: (2021) GOODMAN 3.5-TON/ 35 AMP

GOODMAN MAN	UFACTURING COMPAN	TON, TX 77056
5151 5411 -	SER	NAL NO 2109032400
MODEL <u>GSX140421K</u> A.C. VOLTS 208-230 VOLTAGE RANGE MAX. FUSE AMPS OF (TIME DELAY FUSE 0 (TIME DELAY FUSE 0	F PHASE 1 MIN. 197 MA MAX. CIRCUIT BREAKER MAXCR CIRCUIT BREAKER R	X. <u>253</u> 35 EQUIRED)
FAN MOTOR COMPRESSOR SHORT-CIRCUIT CUR SHORT-CIRCUIT CUR SHORT-CIRCUIT CUR SHORT-CIRCUIT SHORT-CIRCUIT SHORT FACTORY TEST PRES FACTORY TEST PRES	21.8 FLA 0.95 H RLA 18.7 H RENT: SKA RMS SYMMETRICAL ISURE PSIG 93 SURE PSIG 0 VARNING VARNING VARNING VARNING SURE PSIG ADVERTISSEEMENT ADVERTISSEEMENT	HIGH 450

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

Coil fins damaged/bent, need to be straightened to improve airflow/efficiency.



Unit inspected visually only, not cycled / tested.

Air conditioning units were not operated due to cold outside temperatures at the time of inspection. Running A/C unit when the outside ambient temperature is below 50 degrees can damage the compressor and will not give proper readings. Common industry practice is to have HVAC systems serviced annually, don't wait until it breaks.



EVAPORATOR COIL: (2021) ALUMACOIL 4-TON

No significant deficiencies or anomalies observed at the time of inspection.

Unit inspected visually only, not cycled / tested.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient				
I NI NP D							
	Air conditioning units were not operated due to cold outside temperatures at the time of inspection. Running A/C unit when the outside ambient temperature is below 50 degrees can damage the compressor and will not give proper readings. Common industry practice is to have HVAC systems serviced annually, don't wait until it breaks.						
	Temperature D Return Te		upply Temp: 0	Difference: 0.00			
	Temperature Differen	ntial not checked, uni	inspected visually on	ıly.			
		CONDENSATION DRAIN PAN/DRAIN LINES: No significant deficiencies or anomalies observed at the time of inspection.					
	Unit inspected visually only, not cycled / tested.						
	do not inspect for, an or other bio-hazards.	mpany does not insp d are not qualified to If this is a concern o	render opinions on, a r potential concern, F	HVAC Duct System. We any type of environment ox Inspection Group for further information /			
	Observed several/multiple areas in the attic where flex duct touch and are missing required 1" clearance from other ducts to prevent condensation between ducts that touch. Recommend general maintenance to flex ducts in the attic, Re-support where needed, seal/tape minor air leaks, repair torn/damaged vapor seal, etc.						



REI 7-5 (5/4/2015)

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

Some flex duct observed to be routed improperly, not to manufacturer's installation instructions. Recommend additional support and/or routing ducts to eliminate "snaking" drooping or crimping of flex duct more than 1" per foot which adds unnecessary additional resistance.



Some flex ducts observed to be improperly routed with sharp bends and/or excess material in bends. Improper routing increases frictional loss in the duct and reduces heating and cooling efficiency. Radius at the centerline of the bend should be no less than the diameter of the duct.



I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

Buyer's Note: Home is equipped with an electronic damper and/or fresh air system. This type of system is out of the scope of a normal TREC home inspection. If buyer has any concerns and or questions about this type of system, and HVAC specialist should be contacted for a separate inspection.



Not checked/inspected.

Media air filter(s) located in the attic that requires changing/cleaning every 6 months, recommend checking guide for proper maintenance information.



IV. PLUMBING SYSTEMS

 $\overline{\mathbf{A}} \square \square \overline{\mathbf{A}}$

A. Plumbing Supply, Distribution Systems and Fixtures

Location of water meter: Front of property Location of main water supply valve: west exterior wall of house Static water pressure reading: 55 psi Comments: WATER SUPPLY PLUMBING: Water supply piping observed to be predominantly PEX (cross-linked polyethylene) plastic.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

No significant deficiencies or anomalies observed at the time of inspection.

Water softener / treatment / filter equipment not checked / inspected.


COMMODES:

No significant deficiencies or anomalies observed at the time of inspection.

Note: Observed a missing toilet seat in 2nd floor guest bathroom.

SINKS:

Small leak below the sink; master bathroom right sink.



Small water leak from drain stopper lever fitting below sink; master bath right sink.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

FAUCETS:

Recommend caulking around all tub/shower faucets and spouts to prevent water entry behind the wall.




TUBS:

Note: Inspector does not test the bathtub overflow without access to the bath-trap due to the possibility of damage to the property. If this is a concern, recommend consulting with a qualified licensed plumber.

No significant deficiencies or anomalies observed at the time of inspection.

Note: Small scratches observed to master tub.



SHOWER(S): 24 hour shower pan test has been specifically excluded.

Shower head not secured in the wall; master shower.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				

One or more shower head(s) leak water; master shower.



LAUNDRY CONNECTIONS:

Recommend use of stainless steel braided "no burst" clothes washer water supply lines to reduce chance of water damage.

Hot & cold faucets of laundry room are not identified, color-coded (red-hot, blue-cold).



Note: Trim kit for laundry connections box missing.

EXTERIOR HOSE BIBS:

No significant deficiencies or anomalies observed at the time of inspection.

GAS SUPPLY SYSTEMS

Pressure test of gas lines has been specifically excluded. Gas meter located at the Not installed at time of inspection

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

Exposed exterior gas piping not protected from corrosion as required per IRC 2603.3



Unit inspected visually only, not cycled / tested. No gas to property at time of inspection.

OBSERVED BRANCH LINES: *Galvanized and/or black iron*

No significant deficiencies or anomalies observed at the time of inspection.

APPLIANCE CONNECTIONS:

Buyers note: Gas Appliance Connectors (GAC's) are not electrically bonded. Gas Appliance Connectors (GAC's) are the short run of yellow corrugated gas line similar in composition to Corrugated Stainless Steel Tubing (CSST) that connects gas appliances such as kitchen appliances, clothes dryers, water heaters, and house heaters to the natural gas piping in the home. Corrugated Stainless Steel Tubing(CSST) which is a similar material as Gas Appliance Connectors (GAC's), has been linked to fires caused from direct and indirect / close proximity lightning strikes. The lightning strikes have been linked to punctures / holes in the thin stainless steel tubing and igniting fires. CSST is now required to be properly bonded in an attempt to make it a safer product.

No significant deficiencies or anomalies observed at the time of inspection.

 \square \square \square \square B.

B. Drains, Wastes, and Vents

Comments: DRAIN, WASTE, VENT PLUMBING: *Type of drain waste vent material observed to be primarily plastic*

Hydrostatic pressure test of sewer lines was specifically excluded.

No significant deficiencies or anomalies observed at the time of inspection.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

Note: Observed laundry clean-out recessed in wall, recommend consulting with builder on proper access/ plate for clean-out.




There were no plumbing access / inspection panels behind one or more tub(s). Overflow gaskets and drains not checked. Recommend installation of bath plumbing access panels where possible.

$\boxdot \Box \Box \Box$

C. Water Heating Equipment

Energy Source: Natural Gas Capacity: unknown; unit(s) are tankless type of water heater(s) Comments:


WATER HEATING UNIT(S): (2021) RINNAI



Unit inspected visually only, not cycled / tested. No gas to property at time of inspection. Unit was observed to be unplugged at time of inspection.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	TEMPERATURE AN	ncies or anomalies obser	ved at the time of inspection. VALVE(S): ved at the time of inspection.
	D. Hydro-Massage Therapy <i>Comments:</i> <i>Not present at the time</i>	v Equipment	
	E. Other Comments: Not checked/inspected	ł.	
		V. APPLIANC	ES
	A. Dishwashers Comments: No significant deficien	ncies or anomalies obser	ved at the time of inspection.
$\Box \Box \Box \Box$	B. Food Waste Disposers Comments: Debris in the unit need	ds to be removed.	
	C. Range Hood and Exhaus Comments: No significant deficien		ved at the time of inspection.
		TOP: ncies or anomalies obser	ved at the time of inspection. d. No gas to property at time of inspection.

-	-		-	
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
	GAS OVEN:			
	Oven is not installed on	to recommended ant	i-tip bracket on the back side of the u	<u>nit.</u>
	Unit inspected visually Timer and cleaning cyc		ed. No gas to property at time of insp	ection.
	0		erved at the time of inspection. ed. No gas to property at time of insp	ection.
	E. Microwave Ovens Comments: No significant deficience	ies or anomalies obse	erved at the time of inspection.	
	F. Mechanical Exhaust Vents Comments: No significant deficienc		erved at the time of inspection.	
	Did not confirm/verify p	proper venting of all ı	inits to the exterior.	
	G. Garage Door Operators Comments:			
	0 1	-	perly located. Federal safety standard ttes "Locate control button: (a) within	



Electronic sensing eyes improperly installed, should be no more than 6" above the floor.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				



Locks should be made non-operational on garage doors equipped with openers.

Remote control hand held units were not checked/inspected.

H. Dryer Exhaust Systems

Comments:

No significant deficiencies or anomalies observed at the time of inspection.

Recommend periodic cleaning of the dryer vent ductwork to reduce the risk of fire.

Proper venting to the exterior was not verified.

I. Other

Comments: REFRIGERATOR: Not present at the time of inspection.

WASHER: *Not present at the time of inspection.*

DRYER: *Not present at the time of inspection.*

VI. OPTIONAL SYSTEMS

□ ☑ ☑ □ A. Landscape Irrigation (Sprinkler) Systems Comments: Not present at the time of inspection.

2022 FOX INSPECTION GROUP REAL ESTATE INSPECTION SERVICE AGREEMENT THIS IS INTENDED TO BE A LEGALLY BINDING CONTRACT BETWEEN YOU THE CLIENT AND FOX RESIDENTIAL SERVICES GROUP LLC, ITS SUBSIDIARIES, AND ALL SUBCONTRACTORS SCHEDULED OR ARRANGED THROUGH US PLEASE READ CAREFULLY

- SCOPE OF THE INSPECTION: The inspector will perform a general, non-Invasive limited visual ("eyeball") inspection 1. of the property structure at the address listed below to provide Client(s) with a written opinion as to the apparent general condition of the structure(s) components and systems at the time of the inspection. The inspection will be performed in a manner consistent with the "Standard of Practice" and "Code of Ethics" of "TREC" Texas Real Estate Commission and prepare a written report of the apparent condition of the readily accessible systems and components of the Property unless otherwise indicated existing at the time of the inspection. A copy of these Standards are readily available to the Client(s) at http://www.trec.state.tx.us/inspector/rules governing inspectors.asp Only systems and components that can be reached, entered, or viewed without difficulty, moving obstructions, or requiring any action which may result in damage to the property or personal injury to the Inspector will be inspected. Latent and concealed defects and deficiencies are excluded from the inspection, and Inspector is not liable for latent and concealed defects and deficiencies. Any area which is not exposed to view, concealed, is inaccessible because of soil, walls, floors, carpets, ceilings, furnishings or other things, or areas/items which have been excluded by "TREC" Texas Real Estate Commission standards and/or by the agreement of the parties is not included in this inspection. The inspection does not include any destructive testing or dismantling. In the event that the property is a part of a condominium unit, such inspection will not include any other connected or external portions of a multi unit building or any common areas covered by a joint use agreement or considered common areas.
- 2. STANDARDS OF PRACTICE: The parties agree that the Standards of Practice "TREC" Texas Real Estate Commission shall define the standard of duty and the conditions, limitations, scope, and exclusions of the inspection and are incorporated by reference herein.
- 3. CLIENT'S DUTY: Client agrees to read the entire report when it is received and promptly call the Inspector with any question or concern regarding the inspection or written report. The written report shall be the final exclusive findings of the Inspector. In the event client becomes aware of a reportable condition which was not reported by the Inspector, Client agrees to promptly notify Inspector and allow Inspector and/or Inspector's designated representative'(s) to inspect said condition'(s) before making any repair, alteration, or replacement.
- 4. FURTHER EVALUATION: Client acknowledges and agrees that the Inspector is a generalist and that further investigation of a reported condition by an appropriate certified licensed specialist may provide additional information that may affect a Client(s) decision to purchase the home. Client should seek further evaluation from licensed professionals regarding the deficiencies identified in the written report. Inspector is not liable for Client(s) failure to further investigate reported deficiencies.
- 5. CHANGE IN CONDITION(S): The parties agree and understand that conditions of systems and components may change between the inspection date and the time of closing. It is the Client's responsibility to further investigate before closing and the Inspector is not liable for any changes of conditions.
- 6. NOT A WARRANTY: The parties agree and understand the Inspector is not an insurer or guarantor against defects in the structure, items, components, or systems inspected. Client(s) understand that the inspection and inspection report does not constitute a guarantee or warranty of merchantability or fitness for a particular purpose, expressed or implied, or insurance policy, nor is it a substitute for real estate transfer disclosures which may be required by law. INSPECTOR MAKES NO WARRANTY, EXPRESS OR IMPLIED, AS TO THE PRESENT OR FUTURE FITNESS FOR USE, CONDITION, PERFORMANCE OR ADEQUACY OF ANY INSPECTED STRUCTURE, ITEM, COMPONENT, OR SYSTEM, THE PRESENCE OR ABSENCE OF LATENT OR HIDDEN DEFECTS THAT ARE NOT REASONABLY ASCERTAIN IN A COMPETENTLY PERFORMED HOME INSPECTION, OR THE REMAINING USEFUL LIFE OF ANY SYSTEM OR COMPONENT OF THE PROPERTY.

- 7. NOT AN APPRAISAL: The Inspection will not include an appraisal of the value or a survey of building and/or property lines. This inspection or the inspection report may not be construed as an appraisal or survey and may not be used as such for any purpose.
- 8. NOT A COMPLIANCE INSPECTION: This inspection or inspection report is NOT a code compliance inspection or certification for past or present governmental codes or regulations.
- 9. INSURABILITY: The inspection or inspection report does not determine whether the property is insurable.
- 10. THIRD PARTIES AND SUBROGATION: The inspection and written report are performed and prepared for the sole and exclusive use and possession of the Client. No other person or entity may rely on the report issued pursuant to this Agreement. In the event that any person, not a party to this Agreement, makes any claim against the Inspector, its employees or agents, arising out of the services performed by the Inspector under this Agreement, or claims alleging in whole or part any negligent act or omission of the Inspector, the Client agrees to indemnify, defend, and hold harmless Inspector from any and all damages, expenses, costs, and attorney fees, arising from such a claim.
- 11. LIMITATION OF LEGAL ACTION: The parties agree that any legal action must be brought within one (1) year from the date of the inspection(s), or will be deemed waived and forever banned.
- 12. LIABILITY: The parties agree that the Fox Inspection Group and its employees and its agents assume no liability or responsibility for cost of repairing or replacing any defects specified in the written report, as well as no liability for the costs of further evaluation or investigation of the defects specified in the written report. Further, the parties agree and understand that the Inspector and its employees and its agents assume no liability for the costs of repairing or replacing any of the unreported defects or deficiencies either current or arising in the future or any property damage, consequential damage or bodily injury of any nature. In the event of a claim by the Client that an installed system, or component of the premises which was inspected by the inspector was not in the condition reported by the Inspector, the Client agrees to notify the Inspector at least 72 hours prior to repairing or replacing such system or component. If repairs or replacement are done without giving the Inspector the required notice, the Inspector will have no liability to the client. Client agrees that prior to taking any action, legal or otherwise, Client shall: submit a written claim to Inspection Company within 10 days of the deficiency. Allow the Inspection Company, their agent or legal representative to perform a re-inspection of the deficiencies stated in the claim. Agree to not to disturb or repair the disputed item prior to a re-inspection except in cases where injury or subsequent property damage may occur.
- 13. DISPUTES AND ARBITRATION In the event a dispute arises regarding an inspection that has been performed under this service agreement, Client(s) agree to notify Fox Inspection Group within ten (10) days of the time of discovery to give Fox Inspection Group a reasonable opportunity to re-inspect the property and resolved the dispute amicably. Upon the request of either party, all unresolved disputes relating to this agreement shall be submitted for arbitration in accordance with (AAA) American Association of Arbitrators and pursuant to the Federal Arbitration Act then in effect with costs shared equally. This provision shall be specifically enforceable and damages for breach of this provision shall include but not limited to court costs and attorney's fees. Client agrees that Fox Inspection Group and it's agents liability, if any, shall be limited to the amount of the inspection fee paid for inspection. This limitation shall apply regardless of the cause of action or the legal theory pled or asserted specifically including, but not limited to, negligence.
- 14. SEVERABILITY: If any court of competent jurisdiction determines that any section, provision or part of this Agreement is void, unenforceable, or contrary to Texas law, the remaining sections of this Agreement shall remain in full force and effect.
- 15. DAMAGES: If the inspection company or any of its employees, agents, providers, officers, members, or shareholders, are found to be liable for any claim or damage due to the alleged negligence or willful misconduct of the Inspection company performing the home inspection or in the reporting on the condition of the property in the inspection report, THE MAXIMUM DAMAGE THAT THE CLIENT CAN RECOVER SHALL NOT EXCEED THE COST OF THE INSPECTION FEE PAID BY THE CLIENT. The Inspection Company shall not be liable to the Client for any loss of use of the property, repair or replacement cost, consequential or punitive damages or for attorneys' fees or court costs. The Inspection Company shall not be liable to the Client alters, tampers with or repairs or replaces the condition which is the subject matter of the Client's claim before the Inspection Company has had an opportunity to inspect the alleged defective condition.

- 16. CLIENT UNDERSTANDS: The integrity and moisture content of framing and sheathing behind finished wall coverings(exterior siding, stucco, cement stone coverings, fiber cement siding, drywall, interior bath and shower tile walls, etc) is not visible to inspect and beyond the scope of our services and is excluded within our services and is excluded within our inspection and inspection report. The lack of proper detailing and flashing may result in water penetration behind siding resulting in water penetration and structural damage which Fox Inspection Group makes no guarantee, warranty, or implied in the inspection or inspection report.
- 17. EXPERT TESTIMONY / LITIGATION FINANCIAL COMPENSATION CLAUSE: In the event our services are needed at any time in the future as expert testimony or in a litigation case, client agrees at this time / in advance to financially compensate this firm for it's time and services. Terms: Non-refundable retainer of \$2,500.00 upfront, Hourly rate of \$175.00 for any activities on our part for your case, including but not limited to; deposition, phone time, research, court time, travel time portal to portal, review of case prior to court appearance, etc. Balance due invoiced weekly, submitted Friday, payable the next Friday
- 18. RE-INSPECTIONS: Fox Inspection Group does not normally conduct re-inspection services. We are not in the business of certifying the workmanship and/or warranting another company's repair work. Receipts and/or warranty for work performed should be obtained from the company or companies who have provided repairs. In the event a re-inspection is performed it is agreed to in advance that Fox Inspection Group does not assume responsibility of any kind for another company's work.
- 19. LIMITATION AND EXCLUSION CLAUSE: The Client expressly acknowledges and agrees that the following are not included in the scope of the inspection and the inspection report and further acknowledges that the Inspector makes no representations or warranties as to them. THE FOLLOWING SYSTEMS, ITEMS, AND CONDITIONS WHICH ARE NOT WITHIN THE SCOPE OF THE BUILDING INSPECTION INCLUDE BUT ARE NOT LIMITED TO: recreational, leisure, playground or decorative equipment or appliances including but not limited to pools, hot tubs, saunas, steam baths, landscape lighting, fountains, shrubs, trees, and tennis courts. Cosmetic conditions wallpapering, painting, carpeting, scratches, scrapes, dents, cracks, stains, soiled or faded surfaces on the structure ,equipment or component, soiled, faded, torn, or dirty floor, wall or window coverings, etc. Noise pollution or air quality. Earthquake hazard, flood plain certification, liquefaction, soil, retaining walls, slide potential, wave action and hydrological stability, soil and earth measurements and stability, seismic safety, code and zoning, engineer level analysis, under ground utilities, sink hole potential, formaldehyde, lead paint, asbestos, toxic or flammable materials, molds, mildew, fungi, other environmental hazards, pest infestation, security systems, fire protection systems, sump pumps, household appliances, humidifiers, paint, other treatment windows, interior walls, ceilings and floors, water purification systems, (ozone generator/saltwater, etc), under ground storage tanks, energy efficiency measurements, motion or photo electric sensor lighting, concealed or private security systems, water wells, all over flow drains, heating system's accessories, solar heating systems, heat exchangers, wood burning stoves, sprinkler systems, water softener or purification systems, central vacuum systems, telephone intercom or cable TV systems, internet connections and cable connections, antennae, lightning arrestors, load controllers, governing codes, permits, ordinances, statues, and covenants, and manufacturer specifications, recalls, EIFS, Chinese drywall and tainted materials, plasterboard, sheet rock, gypsum board, latent and concealed defects, and manufactured stone veneer, culture stone siding, fiber cement siding, flues or chimneys, coal stoves, water leaks, water intrusion, design and architect problems, circuit breaker operation, fireplace drafting, boundaries egress and ingress, quality of materials, private sewage, wattage and wiring, electromagnetic field, non built in appliances, rodents, ants, birds, or other wood boring organisms, security locks and devices, thermostat and gauges. Client understands that these systems, items, and conditions, are excepted and excluded from this inspection and Inspection report. Any general comments about these systems, items, and conditions of the written report are informal only and DO NOT REPRESENT AN INSPECTION.
- 20. COMPENSATION BY OTHERS: Fox Inspection Group may accept a fee from various vendors in this real estate transaction to compensate for administrative / coordinating / scheduling their services. Fox Inspection Group is accepting a fee or other valuable consideration from HomeSwitch LLC., in this real estate transaction. Client(s) acknowledges that they have been informed of this arrangement between Fox Inspection Group and HomeSwitch LLC and authorizes HomeSwitch LLC to call Client at the phone number provided to discuss options regarding setting up TV, Internet, Home Phone, Electricity, Home Security, Pest Control even municipal utilities at their future home. If client(s) does not want to be contacted just let us know by phone (713-723-3330) or by email (Office@FoxInspectionGroup.com).

- 21. PERSONAL SAFETY: We are not responsible for another participant's personal safety during the inspection process. Client, their representative's, or others participation shall be at his/her own risk for falls, injuries, property damage, etc. We reserve the right to refuse service to anyone for any reason.
- 22. REGARDING PREVIOUSLY FLOODED HOMES: Client is hereby put on notice, Caveat emptor / buyer beware; this property inspection and report specifically excludes any representation that the structure has been properly renovated / repaired after being flooded. Ultimate responsibility for proper renovation and repair lies solely with the property owner / seller and their repair contractors (NOT others associated with the transaction such as Realtors, home inspectors, appraisers, surveyors, title companies, lenders, etc.) Client is strongly advised to obtain all mandatory seller disclosure and documentation, including but not limited to photos and video, regarding any past flooding of the structure, as well as repair methods and techniques used by others to restore the property to its pre-flood condition including their contact information for future reference.
- 23. This Agreement, including the terms and conditions on all pages, represents the entire agreement between the parties and there are no other agreements either written or oral between them. This Agreement shall be amended only by written agreement signed by both parties. ACKNOWLEDGMENT: the undersigned has reviewed this document, understands its content and agrees to the terms and conditions contained. The client further represents and warrants that he or she has full and complete authority to execute this contract on behalf of any spouse or significant other, and to fully bind any spouse or significant other to all terms, conditions, exclusions and limitations of this agreement. The report adheres to the "TREC" Texas Real Estate Commission Standards which is readily available) at

http://www.trec.state.tx.us/inspector/rules_governing_inspectors.asp.