

www.spacecityinspections.com 281-636-9419

ABOUT YOUR REPORT

This report was prepared at the request of Eric & Ashley Jenson and presents the results of inspecting the house at 506 Chip St., La Marque, TX 77568. The inspection was completed on 03/23/21 and was performed by Ed Fryday of Space City Inspections, LLC.

This report is intended only as a general guide to help make your own evaluation of the overall condition of the home and is not intended to reflect the value of the premises, nor to make any representation as to the advisability of purchase. Your report expresses the personal opinions of the inspector, based on his experience and visual impressions of the conditions that existed at the time of the inspection only. The inspection and report are not intended to be technically exhaustive, or that every possible defect was discovered. No disassembly of equipment, opening of walls, moving of furniture, appliances or stored items, or excavation was performed. All components and conditions which, by the nature of their location were concealed, camouflaged or impossible to inspect for other reasons are noted as not inspected and the reason given.

Photographs used in this report are representative only. This report will not contain a photo of every item mentioned in the report. There may be one or more photos of similar items used to clarify the report but there may be condition that occur in multiple locations where a photo of every location is not in the report.

Systems and conditions which are not within the scope of the inspection include, but are not limited to: formaldehyde, lead paint, asbestos, toxic or flammable materials, and other environmental hazards; pest infestation; playground equipment; efficiency measurement of insulation or heating and cooling equipment; internal or underground drainage or plumbing; any systems which are shut down or otherwise secured; water wells (water quality and quantity); zoning ordinances; intercoms; security systems; heat sensors; cosmetics or building code conformity. Any comments about these systems and conditions are informational only and do not represent an inspection.

This inspection report should not be construed as a compliance inspection of any governmental or non-governmental codes or regulations. The report is not intended to be a warranty or guarantee of the present or future adequacy or performance of the structure, its systems, or their component parts. This report does not constitute any express or implied warranty of merchantability or fitness for use regarding the condition of the property and it should not be relied upon as such.

We certify that our inspectors have no interest, present or contemplated, in this property or its improvement and no involvement with trades people or benefits derived from any sales or improvements. To the best of our knowledge and belief, all statements and information in this report are true and correct.

Any dispute arising from this report, except one for inspection fee payment, shall be resolved informally between the parties or by arbitration conducted in accordance with the rules of a recognized association. Except that the parties shall select an arbitrator who is familiar with the home inspection industry. In the event of a claim, the Client will allow Space City Inspections, LLC to inspect the claim prior to any repairs or waive the right to make the claim. Client agrees not to disturb or repair or have repaired anything, which may constitute evidence relating to the complaint, except in the case of an emergency.

Space City Inspections, LLC 301 Slossen St. Webster, TX 77598

Phone: (281)636-9419 Fax: (832)213-0388

Email:

edfryday@spacecityinspections.com

PROPERTY INSPECTION REPORT

Prepared For:	Eric & Ashley Jenson (Name of Client)		
Concerning:	506 Chip St., La Marque, TX 77568 (Address or Other Identification of Inspected Property)		
By:	Ed Fryday, Lic #6932 (Name and License Number of Inspector)	03/23/2021 (Date)	
	(Name, License Number of Sponsoring Inspector)		

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous

Promulgated by the Texas Real Estate Commission (TREC) P.O. Box 12188, Austin, TX 78711-2188 (512) 936-3000 (http://www.trec.texas.gov).

or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods. Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathroom, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as, smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms requires a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

D I.l.		1	Eric & Ashlev.	EUG CPIP Ct	1 ~ 1 / 1 ~ ~ ~	TV
Report Ide	ntitication:	IDNEON	FILL & ACUIEN	200 0.000 20	1 3 1/13/1/11/14	1 X

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

	ADDITI	ONAL INFORMATIO	N PROVIDED BY INSI	PECTOR
Present at Inspection:	☑ Buyer	☐ Listing Agent	☐ Buyer's Agent	☐ Occupant
Building Status:	☑ <u>Vacant</u>	☐ Owner Occupied	☐ Tenant Occupied	☐ Other
Weather Conditions:	☑ Fair	☐ Cloudy	☐ Rain Outside Te	emp Range: <u>66 to 75°F</u>
Utilities On:	✓ Yes	☐ No Water	☐ No Electricity	☐ No Gas
House Faces:	☐ North	☑ South	☐ East	☐ West
Special Notes:				
	1	INACCESSIDI E OD C	BSTRUCTED AREAS	
☑ Attic Space Limited			☐ Sub Flooring	9
✓ Plumbing Areas - O				ered or Freshly Painted
☑ Electrical Areas - Or	•	• .	_	iture and/or Stored Items
☐ Older Siding Covere	•	•		ed From Accessible Areas
J	,	ŭ	'	
				scope of this inspection at the ional investigation be obtained .
				CLIENT NAMED ABOVE.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	I.	STRUCTURA	L SYSTEMS
	A. Foundations Type of Foundation(s): Viewed From: Perimete Comments: Signs of Structural Mo Cracks in wall(s) and Cracks in brick, ston Doors and/or frames Framing, facia or frie	ovement or Settling or d/or ceiling e, or stucco s out of square - some of eze board separation	r other deficiencies ☐ Floors visibly not level ☐ Cracks in exposed concrete floors do not lock or latch properly ☐ One or more window pane cracks ☐ Excessive or improper shims
	differential movements	ns, leakage and other a are likely to occur. The structed areas of the st	adverse factors are able to effect structures, and e inspectors opinion is based on visual observations ructure at the time of the inspection. Future ed or warranted.
	☑ The foundation app	eared to be in servicea	ble condition.
	maintenance to all type Drainage must be direc cases, floor coverings a in all but the most seven survey nor was any spe visual inspection, as the structural movement is	s of foundations due to ted away from all sides and/or stored articles proper cases. It is important ecialized testing done of ese are specialized propers, and determine who ses, and determine who	E & CARE - Proper drainage and moisture the expansive nature of the area load bearing soils. of the foundation with grade slopes. In most event recognition of signs of settlement - cracking it to note, this was not a structural engineering of any sub-slab plumbing systems during this limited cesses requiring excavation. In the event that to consult with a Structural Engineer who can eat corrective steps, if any, should be considered to
	and drainage of the soil foundation and to avoid The ground adjacent to from the foundation wal other approved point of surface water away from minimum of 6-inches with Grade clearance - There and a minimum of 6-inched at flatwork such	adjacent to the founda water penetration prob the foundation should. Surface drainage should collection not to create the foundation walls. Ithin the first 10-feet. The should be at least a 4-thes where non mason as patios or porches	In flowing away from the foundation. Proper grading tion can be critical to the performance of the lems. be graded such that there is positive drainage away ould be diverted to a storm sewer conveyance or a hazard. Lots should be graded so as to drain. The grade away from foundation walls should fall a l-inch slab exposure where masonry veneer is used by siding is used. A grade clearance of at least 1" is
	Lot Grading and drain	age	
	☐ Improper grading/dra	ainage from foundation	

Report Identification: Jenson, Eric & Ashley, 506 Chip St., La Margue, TX I=Inspected NI=Not Inspected NP=Not Present D=Deficient NI NP D ☐ Gutters/downspouts draining too close to the structure ☐ Loose, missing and/or damaged gutters or downspouts ☐ Leaves/debris in the gutters and downspouts ☐ Trees/heavy foliage too close to the structure ☑ A/C primary condensation line terminates too close foundation ☐ Inadequate grading clearance to exterior wall surface ☐ Erosion or ponding next to foundation/driveway ☐ Plumbing leaks/Hose Bibs/Sprinkler System C. Roof Covering Materials Type(s) of Roof Covering: Composition shingles & Roll Roofing Viewed From: Ground & roof levels Comments: This roof is covered with 30 year composition shingles & 15 year roll roofing which appear to be about 12 or13 years old and in reasonable condition. ☐ Some worn, damaged and/or missing shingles ☐ Possible hail damage on some shingles ☐ Some shingles are "lifted" & subject to wind driven rain or wind uplift ☐ Brick chimney not properly flashed and counter-flashed ☐ Roof decking deflection and/or sagging ☐ Skylight covers not secured and/or flashed properly ☑ Satellite dish base bolted to roof through the roll roofing · Water ponding on the roll roofing ☐ Missing rain skirts on metal fireplace, water heater or furnace flues ☐ Roof penetration(s) not properly flashed/sealed ☐ Missing/damaged rain caps on furnace/water heater flues or chimney ☐ Apron flashing in need of repair ☐ Flashing over facia boards is missing or improperly installed ☐ Missing step flashing where a sloped roof intersects vertical sidewall(s) ☐ No kickout flashing where vertical sidewalls extend to or past the edge of the roof ☑ Tree branches are too close to the roof structure ☐ Roof ventilation system damaged and in need of repair ☐ Vent roof jacks missing or improper installation fasteners per shingle strip ☑ Roof covering fasteners could not be inspected because: ☑ The inspection could cause damage to the roof covering ☐ The roof was to steep, to high or otherwise not accessible ☐ The roof covering is in need of replacement or extensive repairs, a Certified Roofing Company should be consulted

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D



☑ □ □ ☑ D. Roof Structures and Attics

Viewed From: Entered Accessible & Decked Attic Area(s)

Roof Structure is wood framed and decked with:

☐ Plywood ☐ OSB ☑ Sawn Lumber

Radiant Barrier ☐ IS ☑ IS NOT present

Portions of the attic space(s) at this property were not safely accessible due to various factors such as (but not limited to) lack of attic floor decking, design and/or storage of personal property - limited inspection.

Approximate Average Depth of Insulation: 6"

Approximate Depth of Visible Vertical Insulation in Attic: N/A

Comments: Abandoned attic fan in attic not inspected

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D





Insulation:

New construction requirement for insulation in this area is R-38 on the attic floor and R-13 on vertical attic walls. (Inches of traditional insulation X 3 = Approximate R value, inches of open cell spray foam insulation X 3.7 = Approximate R value)

- ☐ Evidence of moisture penetration
- ☐ Damaged and/or missing vent screens
- ☐ Damaged and/or missing roof sheathing
- ☐ Inadequate roof support and/or failed members
- ☐ Attic ventilation fan(s) not working / not accessible limited inspection
- **☑** Some attic floor insulation is missing
- ☐ Some vertical insulation in the attic is missing or has fallen down
- ☐ Less than 30" of clear workspace in front of heater/A-C air handler
- ☐ Inadequate and/or unsafe access to air handler(s) or water heater(s)
- ☐ Attic access ladder improperly fastened in place/ not cut to proper length/ needs hinge repair



Report Identification: Jenson, Eric & Ashley, 506 Chip St., La Marque, TX					
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient		
I NI NP D					
	E. Walls (Interior and Exterior)	1			
	Type of framing: Wood Fra Comments: Interior Walls: Types(s): ☑ Gypsum ☑ \	aming			
	☐ Signs of Structural Settlin	ng ☐ Signs of Water Pene	etration ☑ <u>Freshly Painted</u>		
	• • • •	Cement Board ☑ Wood Aluminum ☐ Stucco	☐ Stone ☐ Asbestos		
	☐ Facia/trim boards are war ☐ Mortar is separated or mi ☐ Caulking/sealant is separ ☐ Some cracks at the brick, ☐ Wood siding is cracked, or ☐ Cement board siding is cracked. ☐ Some siding fasteners ar ☐ Weep holes not open and ☐ One or more areas were	ssing in some areas rated or missing in some are , stone, or stucco siding or water damaged in some a racked, damaged and/or loose backing out d/or improper spacing	as ireas se in some areas		
	F. Ceilings and Floors Type of floor structure: Vari Type of Ceiling Structure: ⊆ Comments: ☐ Ceiling cracks in some an ☐ Water stains on ceiling ☑ Freshly painted ceilings	reas ☐ Floor cracks ☐ Water stains ☐ Attic access	s in some areas s on floor s does not seal (energy loss)		
	Attic access ladder is nAttic ceiling not sealed		ched garage ceiling		

NI=Not Inspected

NP=Not Present

D=Deficient





A	G. Doors (Interior and Exterior)
	Comments:
	Interior Doors
	☐ Damaged doors at:
	☑ Door from hall to kitchen does not latch
	☑ Door from living room to hall drags & will not close
	☐ Doors rub, stick or hit frames at:
	☐ Closet doors slide poorly or are off of their rails at:
	☐ Doorknobs are in need of repair at:
	Eutorian Da ana
	Exterior Doors
	☐ Sliding glass door slides poorly or improperly installed at:
	☐ Sliding glass door does not latch/lock properly at:
	☐ Sliding screen door is missing/damaged at:
	☐ Deficiencies in operation of storm door or window or screen
	☐ Safety glass not present at:
	☐ Doors seal poorly at:
	☐ Doors do not latch properly at:
	☐ Doors rub, stick or hit frames at:
	☐ Door locks or doorknobs are in need of repair at:
	☐ Deadbolt locks do not extend to properly lock the doors at:
	☐ Deadbolt locks require keys to unlock from the inside (emergency egress hazard)
	☐ House door into garage not fire rated for use in attached garage
	= 110000 door line garage flot in o rated for doo in attached garage
	Garage Doors Type of Doors(s): ☑ Metal □ Wood □ Fiberglass
	☐ Some fastening hardware is loose
	☐ Door locking hardware is loose and/or missing
	☐ Doors and/or panels are water damaged
	☐ Tension springs are not safely secured

NI=Not Inspected

NP=Not Present

D=Deficient

- $\ oxdot$ No safety cables in the tension springs
- ☐ Garage door is "heavy" needs spring tension adjustment



	Н.	Windows
		Windows are: ✓ Single pane glass ☐ Storm windows ☐ Thermal pane glass
		☑ Single hung □ Double Hung □ Tilt out windows
		Comments: Den glass was damaged during the inspection while trying to operate the window lock
		☑ Glass panes were damaged in all bedrooms & the den
		 Window(s) would not stay open at middle BR, right side & laundry area Window would not stay open in front right of front BR
		☐ Some spiral rods, part of the lift balance system, were exposed & need repair
		 Many window lock were damaged & windows would lock on one side only Windows on east side of den would not lock
		☑ One or more missing or damaged screens. (The Texas Real Estate Commission's Standards of Practice for licensed Real Estate Inspectors requires that we report missing or damaged window screens as a deficiency.)
		Absence of safety glass at:
		☐ Windows in sleeping areas are of inadequate size for emergency egress at:
		Louvered shutters on front and middle bedrooms block emergency egress
		☐ Loose/cracked/damaged window glazing strips or glazing compound
		☐ Thermal pain window seals have failed and moisture has penetrated at:
		☐ Inspection of the windows was limited due to furniture, window covers and/or stored items


NI=Not Inspected

NP=Not Present


D=Deficient













NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D











☐ ☑ ☑ ☐ I. Stairways (Interior and Exterior)

Comments:






NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D









Sub Panel Location: In laundry area

ype of wire: ⊻	I <u>Copper</u> LI Aluminum
☑ Sub panel not labeled	☐ Sub panel(s) installed at improper location
☐ Sub panel cover(s) were loose	☐ Inadequate service space
☐ Double lugged breakers/fuses ir	n use
☐ Filler(s) needed in sub panel sa	fety cover
☐ Incorrect size of breakers/fuses	☐ Incorrect size wire on breaker/fuse
☐ Grounds and neutrals on same	bus bar (Not allowed in sub panels)
\square Some neutral wires are double I	ugged
\square No anti oxidant on aluminum wi	re connections
✓ Sub Panel is bonded to neutr	al or ground buss (only the main panel should be bond


NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D





Arc fault circuit interrupter (AFCI) safety protection

☐ AFCI breaker(s) failed to trip	or reset at position #
------------------	------------------	------------------------

- ☑ None installed ☐ Bedroom circuits only (per labeling)
- ☐ Bedroom & smoke alarm circuits only (per labeling)
- ☐ Per 2008 building standards or better (per labeling)
- ☐ Per current building standards or better

AFCI protection requirements first began in 1999 for bedroom <u>receptacles</u>. In 2002 the wording was changed to bedroom <u>outlets</u> which includes the lighting and smoke detectors. In 2008 the requirement changed to require AFCI's on most single pole 115 volt circuits in most residential rooms. The 2008 standard remained until the 2014 standards were adopted. Virtually all 115 volts circuits inside dwelling units to be AFCI protected per 2014 standards.

The above information is intended as general information only and is not intended to be code specific as all of the above also depends on when the codes were adopted by the local authorities.

Recommend further evaluation and or repair by a licensed master electrician

B. Branch Circuits, Connected Devices, and Fixtures
Type of Wiring: \square Copper \square Aluminum
Comments:
☐ One or more junction boxes do not have covers
☐ One or more wiring connections are not in junction boxes
☐ Wires lying on the ground under house
Outlet and Switches
☐ One or more loose outlets in some rooms
☑ Missing outlet covers in attic at heater & in laundry room
☐ Damp rated outlet covers at "wet" locations


NI NP D

NI=Not Inspected

NP=Not Present

D=Deficient

- ☐ Doorbell switch was loose and/or damaged ☐ Doorbell was inoperable ☐ No Doorbell ☐ Inspection of outlets, switches and accessory connections was limited due to concealment Most of the outlets are not grounded or are not the grounded type (typical of older homes with two wire systems) Many old 2 slot outlets have been upgraded to 3 slot outlets but not grounded ☐ Some outlets had no power at:
- ☑ Unidentified switches at front door and garage door
- **☑** Weather resistant outlets not installed at exterior location
- Front exterior lights on same circuit as a switch operated outlet in the living room
- 2 outlets had unusual reading with standard tester all three lights on improper
- No power to power strip on garage wall
- Exposed wire at power strip on garage wall









Ground Fault Circuit Interrupter (GFCI) Safety Protection

			• • •	•			
Kitchen count	ers:☑ <u>Ye</u> :	<u>s_</u> 🗌 No	□ N/A	Bathrooms:	✓ Yes	□ No	\square N/A
Exterior:	☐ Yes	☑ No	□ N/A	Garage:	☐ Yes	☑ No	□ N/A
Basement:	☐ Yes	□ No	☑ N/A	Wet Bar:	☐ Yes	□ No	☑ N/A
A/C Unit:	☐ Yes	□ No	☑ N/A	Pool/Spa lights	: □ Yes	□ No	☑ N/A
Hydro Massag	ge tub: 🗆	Yes □	No	Pool/spa moto	rs: 🗆 Yes	☐ No	☑ N/A
Dishwasher:	☐ Yes	☑ No	□ N/A	Hot Tub:	☐ Yes	□ No	☑ N/A

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	•	□ Yes □ No ☑ <u>N/A</u>	Laundry: ☐ Yes ☑ No ☐ N/A Outdoor 230/240 volt: ☐ Yes ☐ No ☑ <u>N/A</u> Kitchen 230/240 volt: ☐ Yes ☐ No ☑ <u>N/A</u>
		on at some outlets; ext gnized safety hazard an	erior. garage, laundry & dishwasher. <u>This is</u> d in need of repair
	feet of the water. In 19 include only those ext exterior outlets in 199 The requirement for spalong with boathouses outlets in crawlspaces 1996 the kitchen requithat serve kitchen islangarages were change motors of swimming pall utility room outlets and shower stalls requivith the 2020 updates.	erior outlets that were wing and hot tubs began in a summer of the summe	or swimming pools and exterior outlets within 15 overe included and that was amended in 1978 to thin 6' 6" of grade. It was changed back to ALL be added in 1975 and certain garage outlets in 1978 in 1981. Hydro-massage tubs were included in 1980 and outlets within 6' of the kitchen sink. In 1990 93 outlets within 6' of wet bar or utility sinks. In so include all counter top outlets and in 2003 outlets are included. As of 2005 GFCI requirements for cluding those in the ceiling. In 2008, pumps and ove GFCI protection. With the 2014 code changes d. Also new in 2014 outlets within 6' of bath tubs 2017 Dishwasher circuits & outlets were added. were included.
	Electrical Fixtures Some exterior & comissing Light fixture cover to Closet light fixture of Closet lights have to Closet lights have to Closet fights and/or	garage light fixtures and was missing at does not have proper cle	d/or bulbs did not function or bulbs were arance from closet shelf rate or torque
	☐ Alarm(s) are loose ☑ Hallway alarm did ☐ No alarms in hallway (Beginning with the alarms are required in performed if the home	I not function ays doption of the 2009 Inter new homes or in existin	☐ No alarms installed - Safety Hazard ☑ No alarms in the bedrooms ☑ No carbon monoxide alarm present national Residential Codes carbon monoxide g home where work requiring a building permit is s or an attached garage. The alarms are to be of the sleeping rooms)
	steel tubing & other ed	quipment such as gas sto	ter and gas pipes, including corrugated stainless oves & ovens, gas furnaces, gas fireplaces flues & cal cabinets, that may become electrically

energized, are required by National Standards, such as the National Electrical Code, to be electrically bonded together & to the electrical grounding system. Gas appliances with an electrical component such as a furnace blower or spark igniter (not a push button igniter) on a gas stove may be considered to be bonded because of their electrical ground connection.

Gas fueled appliances are typically connected to the gas distribution system with flexible gas appliance connectors (GACs) which are not required by code or manufacturer's instructions to be bonded but a fairly new product, corrugated stainless steel tubing (CSST), does require special bonding jumpers. Since the flex gas appliance connectors (GACs) are technically CSST, this inspector recommends bonding jumpers on all flex gas appliance connectors GACs) for additional safety.

Other metal components and systems that should also be bonded include metal fireplace/flue components, satellite dishes, telephone interfaces & TV cable systems.

- For More on this subject click here: http://goodsonengineering.com/wp-content/uploads/2011/08/ElectricallyInducedFuelGasFires_web.pdf
- Also see: http://subrogationrecoverylawblog.com/2011/04/18/flash-kaboom-water-heater-failures-involving-gacs/

If a visible bonding component has come loose or appears deficient it will be noted in this report. It is not possible to tell during this type of inspection if all bonding has been properly or effectively installed. The lack of bonding may allow metallic parts, in a home, to become electrically energized due to a number of electrical events not normal to an electrical system, such as a lightning event. A qualified master electrician should be consulted to verify all bonding has been installed in accordance with the current electrical code standard.

	A bond wire & clamp was visible on the Only one end of the bond wire was visible/identifiable. Further evaluation by a qualified master electrician is suggested to confirm proper & effective bonding.
	No bonding jumpers installed at the visible flex gas connectors to appliances or
	equipment
•	Bonding jumpers for use across flexible gas appliance connectors are readily available, Some
	even in kit form. Home Depot has such a kit. Please do not consider this as an endorsement
	of Home Depot - it is not. Click here to see a bonding jumper kit.
•	https://www.homedepot.com/p/Blackburn-Water-Heater-or-Meter-Bonding-Kit-WHMBONDKIT-
	B1-5/207070401?fbclid=lwAR3mLpiU606jMjUVIIh_RWCBVwI8Kq6ai419G3DoCH_bc_C9m-
	d0M0q_ktU_
	No bonding visible on the gas distribution system
	No bonding was visible on the metal water distribution system
	(Bonding is not needed on non-metal water distribution systems)
	No bonding was visible between metal hot & cold water lines
	No bonding was visible at fireplace/chimney or area was not accessible
	No bonding was visible other metal flues or vent pipes
V	No equinotential honding was visible

NI=Not Inspected

NP=Not Present

D=Deficient




- Other Electrical System Components:
 No electric receptacle outlet provided for washer or dryer
- A/C disconnect had no safety cover & 2 connections were double lugged









NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D



Recommend further evaluation and repair by a licensed master electrician

III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS

$ oldsymbol{I} $	A. Heating Equipment
	Type of System: Central
	Energy Source: Natural Gas
	Comments: The heating equipment was manufactured in 2011
	☐ Elucia logge or not properly connected to the unit
	☐ Flue is loose or not properly connected to the unit
	☐ Inadequate ventilation for combustible air
	☐ Flue is less than 1" from combustible materials
	☐ Flue not fully accessible - limited inspection
	☐ Rust at the burner and/or burner compartment
	☐ Improper clearance between door and closet mounted unit
	☐ Unit's blower fan and/or motor assembly vibrates
	☑ Flexible gas line enters into the furnace cabinet
	 For more info click here: https://www.youtube.com/watch?v=yfkMyKj1r9Q
	☐ No gas cutoff valve and/or improper gas valve
	☐ Gas is turned off and/or no pilot flame
	☑ No sediment trap in gas supply line to the heater
	 For more information on a sediment trap see:
	https://www.spacecityinspections.com/2013/07/Drip-Leg-VS-Sediment-Trap.html
	☐ Gas leaks detected at:
	☐ System(s) show signs of being dirty.
	☑ Recommend servicing and/or further evaluation by a licensed professional

NI=Not Inspected

NP=Not Present

D=Deficient



В.	Cooling Equipment Type of System: Central Energy Source Electric Comments: A/C condenser was made in 2009 & the evaporator in 1995. The system is charged with R-22 refrigerant which is no longer manufactured.
	Types of systems in use include ☑ 2 part Exterior condenser/Interior evaporator system(s) ☐ Package system ☐ Window unit(s) ☐ PTAC unit(S) Swamp Cooler(s)
	This home has <u>approximately 1361</u> Sq. Ft. and <u>approximately 3</u> tons of cooling
	As a general rule most homes in this area need about 1 ton of cooling for every 500 sq. ft. of air conditioned space. Some more energy efficient homes may not need as much. The proper sizing of this equipment should be done by a licensed HVAC company.
	 □ Freon lines not properly insulated at: □ Condenser(s) □ Air Handler(s) □ In Attic □ Condenser(s) coils dirty □ Condenser(s) not secured against high winds □ Condenser(s) are not level □ Condenser(s) coil fins are damaged
	☐ Condenser(s) contints are damaged ☐ Condenser(s) airflow is restricted by foliage ☐ Inadequate elevation of condenser pad above grade
	✓ Primary condensate drain terminates too close to the foundation✓ Primary condensate drain terminates into a sewer vent
	☐ Primary condensate drain termination was not visible
	 Rust in drain pan under the evaporator Secondary A/C drain not open from evaporator to pan
	□ No electrical cut-off within view of condenser unit
	No drain pan and/or drain line under the air handler
	Air handler plenum is not well sealed
	☑ Cooling system could not be operated or properly inspected because the external service switch was disabled
	☑ Refrigerant Schrader valves at the condenser(s) had no locking covers


NI=Not Inspected

NP=Not Present

D=Deficient

- Beginning with the adoption of the 2009 International Residential Code, refrigerant access ports located outside should have locking type or tamper resistant covers or should be otherwise secured to prevent unauthorized access. Condensers installed prior to 2009 should have them installed when serviced
- Recommend servicing and/or further evaluation by a licensed professional











Report Identification: Jenson, Eric & Ashley, 506 Chip St., La Marque, TX I=Inspected NI=Not Inspected NP=Not Present D=Deficient NI NP D \square \square \square C. Duct Systems, Chases, and Vents Comments: ☐ Duct Board Type of Ducting: ☑ Flex Ducting ☐ Metal Ducting ☐ Ducting is kinked or restricted in one or more places possibly affecting airflow ☑ Ducting moisture barrier is damaged or lose at one resister ☐ There is no central airflow to the room addition(s) and/or garage conversions ☐ Hi variance in temps between supply air temperatures in rooms ☐ Flexible air ducting is touching in some areas which may cause condensation ☐ Limited inspection due to restricted access attic space or visibility of ducts ☐ Return air filter(s) needs cleaning and/or replacement No return air filter - the evaporator fins may need cleaning ☐ Return air chase(s) not well sealed ☐ Return air filter grille(s) damaged ☐ One or more supply air registers loose or damaged ☑ Recommend servicing and/or further evaluation by a licensed professional Moisture barrier damage return air IV. **PLUMBING SYSTEMS** A. Plumbing Supply, Distribution Systems and Fixtures Location of water meter. Middle of back yard Location of main water supply valve: Exterior under the bathroom window Static water pressure reading: 50 lbs.psi (40 to 80 lbs psi is normal) Visible water piping is: ✓ PVC/CPVC ☐ PEX ☐ Copper ☐ Galvanized ☐ Polybutelene Comments: ☑ Public ☐ Private **Water Source:** Sewer Type: ☑ Public ☐ Private **Sinks** ☐ Leakage around faucet(s) ☐ Faucets have low water pressure ☐ Mechanical drain stop inoperable ☐ Hot and Cold water reversed ☐ Loose/damaged faucet handles ☐ Finish on sink is damaged

☐ Drains have no visible "P" trap

☐ Caulking or grout in need of repair

☐ No shut-off valves under sink

☐ Water hammering noted

Report Identification: Jenson, Eric & Ashley, 506 Chip St., La Margue, TX I=Inspected NI=Not Inspected NP=Not Present D=Deficient NI NP D ☐ Vegetable spray inoperable/leaking ☐ Sink(s) drain slow Hot water inoperable at kitchen sink because the valve is closed - wrong type of valve Could not open valve with no dishwasher hooked up This is for dishwasher/hot v **Bathtubs and Showers** ☐ Leakage around Faucet(s) ☐ Faucets have low water pressure ☐ Water hammering noted ☐ Leakage around shower(s) ☐ Absence of safety glass enclosure ☐ Shower head is leaking / improper spray pattern ☐ Hot and cold water reversed ☐ Loose/damaged faucet handles ☐ Tile loose and/or missing ☐ Improper slope of shower floor ☐ Shower diverter valve not operating ☐ Enclosure needs to be sealed ☐ Caulking or grout in need of repair ☐ Mechanical drain stop inoperable ☐ Soap dish missing ☐ Towel bar missing Water would not drain from the shower Recommend a plumber to do a drain camera inspection **Commodes** ☐ Leakage around commodes ☐ Seal leaking between tank & bowl ☐ Loose at floor mounting ☐ Bowl or tank is cracked/damaged ☐ Flush mechanism inoperable ☐ Tank water level is too high ☐ Tank lid broken or missing ☐ Bowl refill tube is missing ☐ Tank loose on bowl ☐ Flapper valves are faulty **Washing Machine Connections** ☐ Washing machine connected at this time - faucets, drains not tested for proper operation

☐ Leakage at plumbing connections


Washer connections not tested - drain was not open

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D



http://www.febcoonline.com/What_is_Backflow

☐ One or more faucet handles are loose, damaged or missing

Exterior Plumbing ☑ Exterior hose bibs do not have back-flow prevention

	☐ Leakage at:
В.	Drains, Wastes, and Vents Comments: Vent Piping is: □ PVC □ ABS ☑ Metal
	No main sewer clean out location was visible
	 □ Plumbing vent termination less than 6" above roof □ Plumbing vent within 12" of vertical surface □ Plumbing vent too close to building opening (min 10' Horiz., 4' below or 2 ft above) □ No Plumbing Vent Terminations above the Roof
C.	Water Heating Equipment Energy Source: Natural Gas Water Heater Type: Traditional Tank Type Comments: Water heater is located in the garage • Water heater was made in 2018 and has a 40 gallon capacity
	 ✓ Hot water temp. was approximately 130°F (Water temp. above 120°F is a safety hazard) ☐ Corrosion and/or signs of an intermittent leak at isolation valve and/or plumbing connections ☐ Unit is located in a garage or adjacent area and is not elevated so that its ignition source is 18" above the floor ☐ Unit was not in operation at the time of inspection. Hot water temperature was not checked, inspection limited

For more information concerning backflow preventers click this link:

I=Inspected NI=Not Inspected NP=Not Present D=Deficient NI NP D Unit has no drain pan and/or drain line installed under the unit (if a leak would cause damage) ☐ Pan drain line is not plumbed to the exterior ☐ Leakage around unit ☐ Leakage around connections ☐ Flue is loose, damaged or poorly connected ☐ Hot and Cold water lines reversed ☐ Unit is not properly vented for combustion air ☐ Cold water shut-off inoperable and/or missing ☐ Flue is less than 1" from combustible materials ☐ Flue not fully accessible - limited inspection ☐ Gas shut-off valve inoperable and/or wrong type ☐ Unit is not enclosed or protected from vehicular damage ☐ Gas leaks detected around unit ☑ No sediment trap in gas supply line to the water heater ☐ Mineral deposit noise can be heard in the unit Water Heater Temperature and Pressure Relief (T & PR) Valve ☐ T& PR valve has no drain line and/or wrong size ☑ T& PR drain line is not plumbed to exterior - valve not tested ☐ T& PR valve not installed at designated location ☐ T& PR drain line runs uphill at some point ☐ Corrosion and/or leakage at connections ☐ T& PR drain line is threaded at termination point ☐ T& PR valve failed to re-seat after the required manual test T & PR valves should be tested at least once a year. For more info click here: http://www.dummies.com/home-garden/plumbing/water-heaters/testing-your-water-heatertemperature-and-pressure-relief-valve/





D. Hydro-Massage Therapy Equipment Comments:

Report Identification: Jenson, Eric & Ashley, 506 Chip St., La Marque, TX										
I=Inspected NI=Not Inspected NP=Not Present D=Deficient										
I	NI	NP	D							
V				Е.	Other Comments:					
					Visible Gas System Information Type of fuel gas is use: ☑ Natural Gas ☐ LP Gas Location of Gas meter and Main Shut Off Valve: Middle of back yard Material Used for Visible Gas Distribution System ☐ Galvanized pipe Leaks were detected at: N/A					
						V. APPLIA	ANCES			
				A.	Dishwashers Comments:					
V				В.	Food Waste Disposers Comments: ☐ Unit leaking ☑ Electrical cord is not p ☐ Disposer case is corroc		☐ Splash guard damaged ☐ Unit drain below P-Trap			
					Electric cord no	ot secured				
				C.	Range Hood and Exhaust S Comments: ☐ Exterior vent cover dam ☐ Fan/Motor assembly vit ☐ Control knobs/switches ☐ Range hood vent pipe t ☑ Unit is recirculating type	naged orates and/or is nois defective or missing ermination not to ex	ng xterior			
V			$\overline{\mathbf{V}}$	D.	Ranges, Cooktops, and Ove Comments: Range Type: □ Electric					

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

☐ Control knobs are loose and/or missing
☐ Gas leaks were detected around unit
☐ Burners do not operate at high and low settings
☐ Gas shut off valve not readily accessible
☐ Improper materials used for gas connections
☑ No anti-tip device on stove
☐ Deficiencies in the operation of the gas flame
Combuctible material loce than 20" above burners



Oven Types:

☑ <u>Electric</u> ☐ Gas

Tested at 350°F, Variance noted: 10°F (max 25°F)

- ☐ Control knobs are loose and/or missing
- ☐ Gas leaks were detected around unit
- ☐ Oven convection fan was inoperable
- ☐ Broiler/heating element does not operate
- ☐ Deficiencies in door seal / tightness of closure
- ☐ Thermostat sensing element not properly supported
- ☐ Interior light did not function
- ☐ Inadequate clearance from combustibles
- ☐ Deficiencies in the operation of the gas flame

Report Identification: Jenson, Eric & Ashley, 506 Chip St., La Marque, TX NI=Not Inspected I=Inspected NP=Not Present **D=Deficient** NI NP D E. Microwave Ovens Comments: ☐ Deficiencies in door seal / tightness of closure ☐ Interior light does not function ☐ Does not heat a cup of water to 120° in one minute ☐ Timer does not function F. Mechanical Exhaust Vents and Bathroom Heaters Comments: Limited inspection of vent terminations due to inaccessibility Bathroom exhaust fan not required if bathroom has an openable window ☐ Exhaust fan was inoperable ☐ Heat lamp timer does not work ☐ Exhaust fan/motor was noisy in ☐ Missing cover on exhaust fan ☐ Exhaust fan not vented to exterior ☐ Exhaust fan loose/not secure in ☐ No exhaust fan or openable window in tub/shower area of master bath G. Garage Door Operators Comments: H. Dryer Exhaust Systems Comments: Dryer duct not fully visible or accessible - limited inspection ☐ Dryer vent cover is loose, damaged and/or missing ☐ Dryer vent is not vented to the exterior wall or roof ☐ No dryer vent exhaust system provided ☐ Dryer vent termination is screened or grated ☐ Dryer vent pipe is not smooth metal with smooth interior ☐ Dryer vent termination has no back draft damper ☐ Dryer vent terminates within 3' of an opening into the house

☐ Dryer venting into attic or under house

Summary of Inspection findings at 506 Chip St., 77568 on 03/23/21 (This is ONLY a summary. Read full report for complete information)

A. Structural Systems

- 1. A/C primary condensation line terminates too close foundation
- 2. Satellite dish base bolted to roof through the roll roofing, Water ponding on the roll roofing
- 3. Tree branches are too close to the roof structure
- 4. Some attic floor insulation is missing
- 5. Attic access ladder is not fire rated for use in attached garage ceiling, Attic ceiling not sealed at water heater flue
- 6. Door from hall to kitchen does not latch, Door from living room to hall drags & will not close
- 7. No safety cables in the overhead garage door tension springs
- 8. Glass panes were damaged in all bedrooms & the den
- 9. Window(s) would not stay open at middle BR, right side & laundry area
- 10. Window would not stay open in front right of front BR
- 11. Many window lock were damaged & windows would lock on one side only
- 12. Windows on east side of den would not lock, One or more missing or damaged screens
- 13. Louvered shutters on front and middle bedrooms block emergency egress

B. Electrical Systems

- 1. Main panel is not well labeled, Knockout(s) missing from panel, Ground rod not driven flush with earth
- 2. Nipple between meter box and breaker panel not bonded to neutral bar
- 3. A/C condensing unit specifies max amp breaker of 25 and a 30 amp breaker is in use
- 4. Sub panel not labeled, Sub Panel is bonded to neutral or ground buss (only the main panel should be bonded)
- 5. Missing outlet covers in attic at heater & in laundry room
- 6. Many old 2 slot outlets have been upgraded to 3 slot outlets but not grounded
- 7. Weather resistant outlets not installed at exterior location
- 8. Front exterior lights on same circuit as a switch operated outlet in the living room
- 9. 2 outlets had unusual reading with standard tester all three lights on improper wiring
- 10. No power to power strip on garage wall, Exposed wire at power strip on garage wall
- 11. No GFCI protection at some outlets; exterior, garage, laundry & dishwasher
- 12. Some exterior & garage light fixtures and/or bulbs did not function or bulbs were missing
- 13. Hallway smoke alarm did not function, no smoke alarms in the bedrooms, No carbon monoxide alarm present
- 14. No bonding jumpers installed at the visible flex gas connectors to appliances or equipment
- 15. No electric receptacle outlet provided for washer or dryer
- 16. A/C disconnect had no safety cover & 2 connections were double lugged

C. HVAC Systems

- 1. Flexible gas line enters into the furnace cabinet, No sediment trap in gas supply line to the heater
- 2. Primary condensate drain terminates too close to the foundation
- 3. Secondary A/C drain not open from evaporator to pan
- 4. Cooling system could not be operated or properly inspected because the external service switch was disabled
- 5. Refrigerant Schrader valves at the condenser(s) had no locking covers
- 6. Ducting moisture barrier is damaged or lose at one resister
- 7. No return air filter the evaporator fins may need cleaning

D .Plumbing Systems

- 1. Hot water inoperable at kitchen sink because the valve is closed wrong type of valve
- 2. Water would not drain from the shower, Exterior hose bibs do not have back-flow prevention
- 3. No sediment trap in gas supply line to the water heater
- 4. T& PR drain line from water heater is not plumbed to exterior valve not tested

E. Appliances

1. Electrical cord is not properly secured to the disposer, No anti-tip device on stove

Please remember to post a review!