

HEDDERMAN ENGINEERING, INC.

281-355-9911

office@heddermanengineering.com https://www.heddermanengineering.com



MECHANICAL INSPECTION

8924 Live Oak Grove Lane Houston Tx 77080

Richard Shackelford & Elizabeth Shackelford AUGUST 6, 2020



Inspector
Scott Gillis
TREC#22819
281-355-9911
office@heddermanengineering.com



PROPERTY INSPECTION REPORT

Prepared For: Richard Shackelford & Elizabeth Shackelford

(Name of Client)

Concerning: 8924 Live Oak Grove Lane, Houston Tx 77080

(Address or Other Identification of Inspected Property)

By: Scott Gillis - TREC#22819

08/06/2020 2:30 pm

(Name and License Number of Inspector)

(Date)

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. This inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. If is recommended that you obtain as much information as is available about this property, including seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for and by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods.

Promulgated by the Texas Real Estate Commission (TREC) P.O. Box 12188, Austin, TX 78711-2188 (http://www.trec.texas.gov)

(512) 936-3000

REI 7-5 (5/4/2015) 1 of 18

Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathrooms, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate license holders also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms require a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Hedderman Engineering Inc.:

>It is the purpose of this report to give our client my educated and experienced opinion of the condition and function of the stated property as visually inspected by Hedderman Engineering Inc. The inspection performed on this property is of a general nature and includes the following systems: electrical, mechanical, and plumbing. This does not include any specialized inspections and/or inspections of any hazardous materials (such as done in environmental inspections) or any of the following; structural systems, mold, audio/visual components, hazardous materials and gases, rated walls, led paint, destructive insects or pest, security items, water or air treatment systems, etc. This inspection is limited to those components which were visible and accessible at the time of the inspection. It is noted that this report contains the opinions of this inspector of the stated property as it appeared on the day of the inspection and is in no way a warranty of any component in the days and future following the inspection. All mechanical

REI 7-5 (5/4/2015) 2 of 18

components are judged on the basis of age, condition, and the function of those items as they appeared on the day of the inspection and are not guaranteed to continue functioning in that manner in the future. It is recommended that the our client purchase a home warranty policy to protect oneself from both unexpected and anticipated problems that may occur in the future.

>It is noted that Hedderman Engineering Inc. is not responsible for any problems found in the house during or after components are opened up, disassembled, uncovered, made visible, or made accessible by another entity after the inspection is completed.

>If a builder or service contractor examines an area of question and comes to the conclusion that there is no repair needed, have them present to you in writing that the item is in compliance with a prevailing code and is functioning properly, not in need of repair.

>It is the intent of this inspector to work in compliance with the Standards Of Practice For Real Estate Inspectors. It is not required of this company to exceed these standards. You may obtain a copy of the document referred to above by contacting the Texas Real Estate Commission. It is also noted that this inspection is not a "code inspection", but rather an inspection of the condition and function of the stated property.

>Although this report may include observations of some building code violations, total compliance with mechanical, plumbing, electrical codes, specifications, and/or legal requirements are specifically excluded. We do not perform "code" inspections, and since building codes change every few years, our inspections are not performed with the intention of bringing every item in the property into compliance with current code requirements. Rather, the standard of our inspections is a performance standard to determine if the items inspected are functioning at the time of the inspection, or are in need of repair. This is particularly applicable to Home Warranty policies, where the standards of the Home Warranty service company are often different than our stated performance standard for judging whether a piece of equipment is functional or in need of repair. If you intend to rely on a Home Warranty policy, then it is recommended that you contact the appropriate service companies for a more in-depth analysis of what may be required to meet their standards should a claim be made against the policy.

>If there are any questions or concerns please contact Hedderman Engineering, Inc. at 281-355-9911 or Office@HeddermanEngineering.com.

I. STRUCTURAL SYSTEMS

	A. Foundation Comments:
	B. Grading and Drainage Comments:
	C. Roof Covering Materials Comments:
	D. Roof Structures & Attics Comments:
	E. Walls (Interior and Exterior) Comments:
	F. Ceilings and Floors Comments:
	G. Doors (Interior and Exterior) Comments:
	H. Windows Comments:
	I. Stairways (Interior and Exterior) Comments:
	J. Fireplaces and Chimneys Comments:
	K. Porches, Balconies, Decks and Carports

The structural portions of this property were inspected by an engineer from Hedderman Engineering Inc. per the inspection agreement between this firm and our client. All comments regarding the structure and property grade are found in the structure report that is created and provided by the engineers at Hedderman Engineering Inc.

According to HAR, the house was built in 2017.

Comments:

Orientation - House Facing South:

For the purpose of the inspection, North is considered to be the rear of the house.

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

I NI NP D

II. ELECTRICAL SYSTEMS

☑ ☐ ☐ A. Service Entrance and Panels

Comments:

Electrical System Description:

The electrical service is provided by a 120/240 volt, single-phase, 125-ampere underground service to an electric meter located at the common at the East side of the complex.


Electrical Wiring Information

Service Wires	Branch Circuit Wires	Grounded or Ungrounded System
2/0 Aluminum	Copper	Grounded

Breaker Panel Information

Location	<u>Manufacturer</u>	Rating
1.East End	Square D	225-amperes
2.East Side House	Square D	225-amperes
3.Garage	Square D	225-amperes

Circuit Breaker Wiring Diagram









REI 7-5 (5/4/2015) 4 of 18

NI = Not Inspected

NP = Not Present

D = Deficient

NI NP D



Breaker Panel Equipment - Acceptable :

The interior of the breaker panel equipment was inspected and the breakers were all properly sized for the circuits they were protecting, the grounding and bonding were properly connected, no knockout clips were missing, and the wiring appeared to be in acceptable condition at the time of the inspection.

Breakers - Routine Check:

It is a general recommendation that all circuit breakers be tripped off and on at least once a year to ensure that they are still physically able to trip off. Occasionally, the points on a breaker will fuse to the main bus in the panel, preventing the breaker from tripping off, even if there is an overload on the circuit. If this condition occurs, it can be a fire hazard.

AFCI breakers- Not tripped off:

The Seventeen Arc Fault Circuit Interrupters in the panel were not operationally tested due to the house being occupied. Sudden loss of power can damage some electronic equipment, therefore, as a policy we do not trip off breakers inside an occupied house. If further investigation is desired, it is recommended that a service company be contacted when the house is not occupied or all of the electronics are unplugged.

Breaker panel legend:

The circuit breakers were labeled to identify the circuits they were protecting. We did not trip off every breaker and, therefore, could not verify the accuracy of the labeling. If further investigation is desired, it is recommended that an electrician be contacted.

☑ ☐ ☐ B. Branch Circuits, Connected Devices, and Fixtures

Comments:

Type of Wiring: Copper - Non-metallic sheathed

GFCIs - Functional:

Outlets that were protected by ground fault circuit interrupt (GFCI) devices were present and functioning properly at the time of the inspection. The GFCI devices were checked and the power to the outlets turned off when the test buttons were pressed. It is pointed out that GFCI devices can stop tripping/resetting properly at any point and should be tested periodically and replaced when necessary. Locations included: kitchen, bathrooms, exterior of the house, garage and utility room.

Ceiling Fans - Functional:

No items that were in need of repair were observed for the operation of the ceiling fan(s) at the time of the inspection.

Light Fixtures - Functional:

The light fixtures throughout the house were operated and were observed to be functional at the time of the inspection.

Outlets - Some inaccessible:

Some of the receptacle outlets in the home were inaccessible and could not be reached for inspection due to furniture, heavy storage items, personal effects, or conditions outside the control of the inspector.

Exterior Light Fixtures - Sensors/Timers:

Some of the exterior lights appeared to be on a daylight sensor or timer, and will not come on until it gets dark. Since it was not dark, the lights were not checked at the time of the inspection. Further

REI 7-5 (5/4/2015) 5 of 18

Report Identification: 8924 Live Oak Grove Lane, Houston Tx 77080

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

I NI NP D

investigation is recommended.



1: Smoke and Carbon Monoxide Detectors

We could not determine if the smoke and/or carbon monoxide detectors are connected to the security alarm system as is common practice, therefore, to avoid triggering the security alarm we did not operationally check each device. Further investigation is recommended with a service company who specializes in this field to determine if the devices are interconnected as currently required and functioning properly. For safety purposes, it is recommended that smoke detectors and carbon monoxide detectors be replaced every ten years. Further investigation is recommended.

2: Low Voltage Systems - Not inspected

It is pointed out that low voltage systems, low voltage wiring, and low voltage connections were not included in the scope of the inspection and were not checked, including: audio/visual systems, alarm systems, data lines, and phone lines. If further investigation is desired, it is recommended that a service company be contacted.

III. HEATING, VENTILATION & AIR CONDITIONING SYSTEMS

X]				A.	Heating	Equipme	ent
---	--	---	--	--	--	----	---------	---------	-----

Comments:

Type of System: Forced Air Energy Sources: Natural Gas

Gas Furnace Description:

The heating for the property was provided the following natural gas-fired equipment:

ZONE	BRAND	<u>BTU</u>	DATE	LOCATION
House	Lennox	88K	2017	Attic


REI 7-5 (5/4/2015) 6 of 18

NI = Not Inspected

NP = Not Present

D = Deficient

NI NP D





Heating Equipment - Functional:

The heating equipment was observed to be operating and functional at the time of the inspection. The heating equipment responded to the thermostat and the equipment appeared to be heating the air adequately.

Heat Exchanger - Information:

Gas furnaces are constructed in such a way that the units must be dismantled in order to view the entire heat exchanger inside. The equipment was not dismantled, and the heat exchanger was not able to be viewed for evidences of cracks. If further investigation is desired, it is recommended that a service company be contacted to dismantle the equipment. It is pointed out, for safety purposes, the heat exchanger should be inspected by an HVAC service company once a year.

Limited visual inspection:

It is pointed out that our inspection of the air conditioning and heating system(s) is a limited, visual inspection where we check the equipment as it has been installed to determine whether or not the system(s) is cooling and/or heating at the time of the inspection. Our inspection is necessarily a cursory inspection, as we do not determine the sizing, adequacy, or design of any component in the system, or the compatibility of the individual components, nor the installation of the system(s) to be in conformity to the latest building code requirements. If you desire an in-depth analysis of the HVAC system(s), then it is recommended that a service company be contacted to analyze the system(s). This is particularly important if the system(s) is an older system and has only a limited amount of remaining life due to its age and/or condition.

□ □ □ B. Cooling Equipment

Comments:

Type of System: Split system

A/C Equipment Description:

The type of air conditioning for the property is a forced air split system. The cooling equipment for the property was as follows:


e Brand	Size/Age Condenser	Size/Age Coil	Temp Drop	
---------	-----------------------	---------------	-----------	--

REI 7-5 (5/4/2015) 7 of 18

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

NI NP D

House Lennox 3.5-ton 2017 4-ton 2017 16 Degrees



Condensing Unit Equipment - Functional:

The condensing unit equipment was functional at the time of the inspection. The equipment responded to the corresponding thermostat, and the compressor components and fan motor components were operating.

Rear



Coil Equipment - Functional:

The coil equipment was operating and was providing a degree of cooling at the time of the inspection.

Overflow Pan - Water sensor present:

The overflow pan under the evaporator coil was equipped with a water sensor that is intended to shut off the air conditioning equipment if the pan fills with water.



Primary Drain - Terminated properly:

The primary condensate drain line was properly terminated into the P-trap under one a plumbing fixture at the interior of the property.

NI = Not Inspected

NP = Not Present

D = Deficient

NI NP D



Cooling Performance:

We measure the temperature drop (ΔT) across the indoor coil(s) at the time of the inspection and our observations have been recorded in this report. It is pointed out that our measurements of the cooling performance of the equipment is only at a "point in time", and cannot reflect whether the equipment has been recently serviced, or what the future performance of the equipment will be after the day of the inspection. Further investigation with the homeowner is recommended to determine when the equipment was last serviced.

☑ ☐ ☐ C. Duct System, Chases, and Vents

Comments: Type: Flex Duct

Duct Work - Acceptable:

The ductwork appeared to be in good condition at the time of the inspection and air was blowing out of each of the registers. The airflow may need to be adjusted in each room to meet your specific needs.







Return Air - Acceptable:

The return air system in the house had no visible items that were in need of repair and appeared to be performing as intended at the time of the inspection.

Thermostatically controlled damper system installed:

A thermostatically controlled damper system was installed in the duct work for the HVAC system creating two zones. The damper system was controlled by the thermostats located at the first floor and second floor. No items requiring repair were observed for the operation of the dampers or thermostats at the time of the inspection.



Heat, Energy, Humidity Control Ventilation Equipment:

Electronic ventilation control equipment was installed in the air duct system and is intended to supplement the HVAC systems performance to provide optimal performance and humidity control. It

9 of 18

NP = **Not Present** I = Inspected NI = Not Inspected

NI NP D

D = Deficient

is pointed out that the inspection of this equipment is beyond the scope of this inspection. If further information is desired regarding the equipment's performance, it is recommended that an HVAC service company be contacted.





IV. PLUMBING SYSTEMS

☑ ☐ ☐ A. Plumbing Supply, Distribution Systems, and Fixtures

Comments:

Location of water meter: The curb

Location of main water supply valve: Inside Garage

Static water pressure reading: 42 PSI

Water Supply Material: PEX

A plumbing system typically consists of three major components, including the potable water supply piping; the waste or drain piping; and the plumbing fixtures. The distribution piping brings the water from the public water main or a private well to the individual fixtures throughout the house. The water distribution system is under pressure, usually from 40 psi to 70 psi. The waste or drain piping carries the waste water and products underground to the sewer system or septic tank, and the waste piping is not under pressure, but operates by gravity flow. We typically run water down the drains from the sinks, tubs, showers, and toilets, but this cannot simulate the waste flow characteristics of full occupancy. There may be partial blockage of the underground waste lines from debris, broken pipes, or tree roots that cannot be detected by a visual inspection. If you desire a more in-depth inspection, it is recommended that you contact a qualified plumber.

Shut Off Valve - Interior location:

The shut-off valve for the main inlet water line was located at the interior of the garage.

Garage





Static Water Pressure:

The static water pressure to the house at the time of the inspection was measured with a pressure gauge at the hose bibb nearest the shut off valve, and the static pressure was observed to be 42 PSI.

10 of 18 REI 7-5 (5/4/2015)

NI = Not Inspected

NP = Not Present

D = Deficient

NI NP D



Sinks & Lavatories - Functional:

No items requiring repair were visible at the time of the inspection to the operation of the sinks and/or lavatories. The sinks were filled with water, and were observed to be draining properly, with no leaking piping or slow drains.

Toilets - Functional:


No items requiring repair were visible at the time of the inspection to the operation of the toilets. The toilets were flushing properly, with no leaks visible in the plumbing, the wax seal, or the internal valves.

Tub/Shower - Functional:

No items requiring repair were visible for the tub and/or shower at each bathroom. The tubs were partially filled with water and water was run in the showers, and they were observed to be operating adequately at the time of the inspection.

Shower - No evidence of shower pan leak:

No evidence of a current shower pan leak were visible at the time of the inspection for the shower(s). It is pointed out, our shower inspection is limited to a visual inspection and we did not perform a shower pan leak test. It is recommended that a plumber be contacted to perform a shower pan leak test to determine if any water is leaking past the shower pan.



Shower - Built-in Seat :

It has been our experience that plumbers do not always extend the shower pan material from the bottom of the shower, up over the shower seat area. This condition can allow water to migrate through the shower seat tiles into the wall cavity. It could not be determined if the shower seat(s) was properly wrapped with shower pan material at the time of the inspection. It is recommended that you keep the shower(s) well caulked and a sealer be applied to the seat to help prevent water penetration through the seat. If further investigation is desired, it is recommended that a service contractor be contacted.

Master Bath

Tub Trap - No access:

The piping at the trap area behind the tub was not visible for inspection due to a lack of access.

☑ ☐ ☐ B. Drains, Wastes, & Vents

Comments:

Sewer Piping Material: PVC

Sewer System - Functional:

No items requiring repair were visible for the operation of the drain system at the time of the

REI 7-5 (5/4/2015) 11 of 18


NI = Not Inspected

NP = **Not Present**

D = Deficient

NI NP D

inspection. No evidences of a system wide problem were observed when the system was operationally checked by running water through each of the plumbing fixtures during the duration of the inspection. It is noted that most of the drain waste system in the walls, under the floors, and in the ceilings is not visible. If further investigation is desired, it is recommended that a plumber be contacted to perform an in depth survey with a camera or hydrostatic test.



Sewer Clean Out - Present :

A sewer clean out was present. The clean out is needed in the event of a stoppage in the main sewer drain line, and the clean out is where a sewer snake would be utilized to remove a clog in the sewer line.

West Side



□ □ □ C. Water Heating Equipment

Comments:

Energy Source: Electric Capacity: 40 Gallons

Electric Water Heater Description:

The hot water for the property was provided by the following water heater(s):

Location	Brand	<u>Capacity</u>	Age	Energy Type
Garage	Rheem	40 Gal	2017	Electric

Garage


NI = Not Inspected

NP = Not Present

D = Deficient

NI NP D





Water Heater Equipment - Functional:

The water heater equipment was functional at the time of the inspection and providing hot water to the applicable plumbing fixtures.

Hot water - Temperature :

The generally recommended maximum temperature setting for a hot water heater, to prevent accidental scalding, is 120-125 degrees. It is recommended that the water heater thermostat be adjusted to and maintained in this temperature range.

The temperature of the hot water at the kitchen sink was measured to be 120 degrees.



	(skin thickness of 2.5 mm)	Children (skin thickness of .56 mm)	
WATER TEMPERATURE	Time required for a third-degree burn to occur		
155°F 68°C	1 second	0.5 second	
148°F 64°C	2 seconds	1 second	
140°F 60°C	5 seconds	1 second	
133°F 56°C	15 seconds	4 second	
127°F 52°C	1 minute	10 seconds	
124°F 51°C	3 minutes	1.5 minute	
120°F 48°C	5 minutes	2.5 minutes	
100°F 37°C	Safe temperature for bathing	Safe temperature for bathing	

Temp/Pressure Relief Valve - Information :

Temperature/pressure relief valves are not operationally checked by this firm during the inspection. Valves typically do not reseat properly when they are operated, which causes the valves to leak. It is best to replace the temperature/pressure relief valves for water heaters every 2-3 years to prevent them from getting clogged with mineral deposits.

🔲 🔲 🗵 🔲 D. Hydro-Massage Therapy Equip	\sqcup \sqcup \boxtimes	□ 🗵 □ D. Hvdro-Mass	sage Therapy Equip	oment
--	-------------------------------	---------------------	--------------------	-------

Comments:

Hydro - therapy equipment was not present at the time of the inspection. :


Comments:

Gas Meter Location:

The main gas shut off valve was located at the inlet side of the gas service meter.

East Side





NI = Not Inspected

NP = Not Present

D = Deficient

NI NP D

Gas System Inspection:

A cursory visual inspection was performed on the gas supply piping. The inspection was limited to the gas pipes that were visible and accessible at the time of the inspection. The use of specialized equipment to detect leaks is not included in the scope of this inspection, nor is determining the gas supply pressure or adequacy. If further investigation is desired, it is recommended that a plumber be contacted.

V. APPLIANCES

□ □ □ A. Dishwashers

Comments:


Functional:

The dishwasher was functioning and responded to the controls. The unit was run through a cycle at the time of the inspection and appeared to be operating properly.

Drain Line Loop Present:

The drain line under the sink was looped up so that the top of the loop was higher than the point where the drain line connected to the disposal. This will help to prevent garbage from running down the drain line into the dishwasher.





□ □ □ B. Food Waste Disposers

Comments:

Functional:

The disposal was operating and responded to the controls at the time of the inspection.

 $oxed{oxed}$ $oxed{oxed}$ C. Range Hood and Exhaust Systems

Comments:

Range Vent - Functional:

No items requiring repair were visible at the time of the inspection to the operation of the range vent. The vent fan was observed to be venting properly at the time of the inspection.



☑ ☐ ☐ D. Ranges, Cooktops, and Ovens

Comments:

Gas Cooktop - Functional:

14 of 18

NI = Not Inspected

NP = Not Present

D = Deficient

NI NP D

The gas cooktop was functioning and responded to the controls when they were operated. All of the burners and controls were operating properly at the time of the inspection.



Electric Oven - Functional:

The electric oven was oberved to be functioning and no items requiring repair were visible at the time of the inspection.

Oven - Calibrated properly:

No repair was needed to the calibration of the oven thermostat. The thermostat was set at 350 degrees, and the oven heated to within the allowable ± 25 degrees. The oven was checked with an oven thermometer and found to heat to 350 degrees.

				understand the standard of the
X				E. Microwave Ovens Comments: Functional:
				No items requiring repair were visible at the time of the inspection for the heating operation of the microwave. A cup of water was placed in the unit, and the microwave heated the water adequately. It is pointed out that the unit was not checked for microwave leakage.
\times				F. Mechanical Exhaust Vents and Bathroom Heaters
				Comments:
				Mechanical Vents - Functional:
				The mechanical vent fans were functional at the time of the inspection. The bath vent fans responded to the switches and were functional at all the bathrooms.
\boxtimes			X	G. Garage Door Operators Comments:
				1: Opener - did not auto-reverse
				The garage door opener did not stop the descent of the door when the door was subjected to a reasonable resisting pressure. This could cause possible personal injury or damage to house, and the opener is in need of adjustment. It is pointed out that the unit was equipped with the infra-red sensing safety device, and the device was operational at the time of the inspection. Obtain Cost Estimate
_	_	_	_	

Comments:

Dryer Vent:

The dryer vent appeared to be properly installed at the time of the inspection. It is pointed out that a portion of the dryer pipe was not visible where it entered the wall/ceiling. Also, dryer vents need to be cleaned periodically for safety reasons and to allow the dryer to operate properly.

Dryer vent - Dryer present:

The vent was connected to the dryer but was not tested. It is recommended that the vent be checked for

REI 7-5 (5/4/2015) 15 of 18

Report Identification: 8924 Live Oak Grove Lane, Houston Tx 77080

I = Inspected

NI = Not Inspected

NP = **Not Present**

D = Deficient

NI NP D

an excess of lint and that it be cleaned if necessary. (Information)

Vent - Check for lint:

It is recommended that the vent be checked periodically for an excess of lint and that it be cleaned if necessary. (Information)

 \boxtimes \square \square I. Other

Comments:

Non Built-in Equipment - Not inspected:

It is pointed out that non built-in refrigerators, wine coolers, small refrigerators, clothes washers, and clothes dryers are not included in the scope of this inspection and were not checked. If further investigation is desired, it is recommended that a service company be contacted.

Further investigation is recommended

Dryer Connection - No Gas - Electric 4 prong:

The 240-volt outlet for the electric dryer connections was observed to be the newer style 4-prong outlet rather than the older 3-prong outlet. You may want to check your clothes dryer to determine if you have the correct power cord for this outlet. A gas connection <u>was not</u> installed.

Refrigerator - Functional:

No items requiring repair were visible at the time of the inspection for the built-in refrigerator and freezer sections. The refrigerator and freezuer sections were observed to be cooling adequately at the time of the inspection. It is noted that the unit was not dismantled and the interior components were not checked.

Hot Water Dispenser - Functional:

No items requiring repair were visible at the time of the inspection for the operation of the hot water dispenser. The equipment was functional at the time of the inspection.

Kitchen





VI. OPTIONAL SYSTEMS

\times				A. Landscap	e Irrigation	(Sprinkler)	Systems
----------	--	--	--	-------------	--------------	-------------	---------

Comments:

Sprinkler System: Rainbird, Located inside garage, 2 zones -

An automatic sprinkler system was installed. The system included a control panel, one or more solenoid valves, underground water lines and with sprinkler heads.

Garage

REI 7-5 (5/4/2015) 16 of 18

NI = Not Inspected

NP = **Not Present**

D = Deficient

NI NP D



Backflow Prevention Device - present:

A backflow prevention device was present and was equipped with the two water shut off valves on the water supply line to the sprinkler system.

East Side



System - Operational:

No items requiring repair were visible at the time of the inspection in the operation of the individual zones. The control panel was functional, all zones were observed to be operating, and all the heads were observed to be spraying adequately.







Rain Sensor - Present -

It is currently required for automatic sprinkler systems to be equipped with a rain sensor device that will prevent the sprinkler system from operating during and shortly after a significant rain.



I = Inspected NI = Not Inspected NP = Not Present D = Deficient

I NI NP D

INFORMATION FROM HEDDERMAN ENGINEERING INC.

Closing Comments:

Opinions and comments stated in this report are based on the apparent performance of the items included within the scope of the inspection, at the time of the inspection. Performance standards are based on the knowledge gained through the experience and professional studies of the inspector. There is no warranty or guarantee, either expressed or implied, regarding the habitability, future performance, life, merchantability, and/or need for repair of any item inspected. It is recommended that a Home Warranty Policy be provided to protect the appliances and mechanical equipment against unforeseen breakdowns during the first year. Check with your agent for details.

Items identified in the report as Deficient and our Recommendations are provided in the above report. Many, but not all, recommendations are highlighted in bold red text. It is our intention, and your responsibility, that you follow up on these deficiencies and recommendations as part of your due diligence by contacting the appropriate service contractor for **Further Investigation**, **Obtain cost** estimate, and/or **Contact the builder**. It is pointed out that other related and/or underlying conditions may be present, and which may not be apparent without further investigation.

As an additional service, we strongly recommend using a new tool we have on our website that can quickly turn your inspection report into an easy-to-read estimate of repairs for a nominal fee. These pricing reports from a third party company called Repair Pricer not only make the inspection report easy to understand in terms of dollars and cents, but they are also useful negotiation tools. Just visit the page below on our website and upload your report into Repair Pricer. If you have any questions when you receive your report, you can contact them at info@repairpricer.com http://www.heddermanengineering.com/repair-cost-estimates