# **TEXAS PROFESSIONAL INSPECTIONS**

(979) 777-9401 admin@texasproinspections.com www.texasproinspections.com





# TPI HOME INSPECTION

6107 Briarstone Crest Dr Katy, TX 77493





# **PROPERTY INSPECTION REPORT FORM**

Nikki Gully Name of Client	08/08/2023 10:00 am Date of Inspection
6107 Briarstone Crest Dr, Katy, TX 77493	
Address of Inspected Property	
Travis Lyon	TREC #24778
Name of Inspector	TREC License #
Steve Jolly TREC #	7002
Name of Sponsor (if applicable)	TREC License #

#### PURPOSE OF INSPECTION

A real estate inspection is a visual survey of a structure and a basic performance evaluation of the systems and components of a building. It provides information regarding the general condition of a residence at the time the inspection was conducted. *It is important* that you carefully read ALL of this information. Ask the inspector to clarify any items or comments that are unclear.

#### **RESPONSIBILITY OF THE INSPECTOR**

This inspection is governed by the Texas Real Estate Commission (TREC) Standards of Practice (SOPs), which dictates the minimum requirements for a real estate inspection.

The inspector IS required to:

- use this Property Inspection Report form for the inspection;
- inspect only those components and conditions that are present, visible, and accessible at the time of the inspection;
- indicate whether each item was inspected, not inspected, or not present;
- indicate an item as Deficient (D) if a condition exists that adversely and materially affects the performance of a system or component **OR** constitutes a hazard to life, limb or property as specified by the SOPs; and
- explain the inspector's findings in the corresponding section in the body of the report form.

The inspector IS NOT required to:

- identify all potential hazards;
- turn on decommissioned equipment, systems, utilities, or apply an open flame or light a pilot to operate any appliance;
- climb over obstacles, move furnishings or stored items;
- prioritize or emphasize the importance of one deficiency over another;
- provide follow-up services to verify that proper repairs have been made; or
- inspect system or component listed under the optional section of the SOPs (22 TAC 535.233).

#### **RESPONSIBILTY OF THE CLIENT**

While items identified as Deficient (D) in an inspection report DO NOT obligate any party to make repairs or take other actions, in the event that any further evaluations are needed, it is the responsibility of the client to obtain further evaluations and/or cost estimates from qualified service professionals regarding any items reported as Deficient (D). It is recommended that any further evaluations and/or cost estimates take place prior to the expiration of any contractual time limitations, such as option periods.

**Please Note:** Evaluations performed by service professionals in response to items reported as Deficient (D) on the report may lead to the discovery of additional deficiencies that were not present, visible, or accessible at the time of the inspection. Any repairs made after the date of the inspection may render information contained in this report obsolete or invalid.

#### **REPORT LIMITATIONS**

This report is provided for the benefit of the named client and is based on observations made by the named inspector on the date the inspection was performed (indicated above).

ONLY those items specifically noted as being inspected on the report were inspected.

This inspection IS NOT:

- a technically exhaustive inspection of the structure, its systems, or its components and may not reveal all deficiencies;
- an inspection to verify compliance with any building codes;
- an inspection to verify compliance with manufacturer's installation instructions for any system or component and DOES NOT imply insurability or warrantability of the structure or its components.

#### NOTICE CONCERNING HAZARDOUS CONDITIONS, DEFICIENCIES, AND CONTRACTUAL AGREEMENTS

<u>Conditions may be present in your home that did not violate building codes or common practices in effect when the home</u> was constructed but are considered hazardous by today's standards. Such conditions that were part of the home prior to the adoption of any current codes prohibiting them may not be required to be updated to meet current code requirements. However, if it can be reasonably determined that they are present at the time of the inspection, the potential for injury or property loss from these conditions is significant enough to require inspectors to report them as Deficient (D). Examples of such hazardous conditions include:

- malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices and arc-fault (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

Please Note: items identified as Deficient (D) in an inspection report DO NOT obligate any party to make repairs or take other actions. The decision to correct a hazard or any deficiency identified in an inspection report is left up to the parties to the contract for the sale or purchase of the home.

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

#### ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Occupancy: Occupied Weather Conditions: Clear, Hot, Humid Inspection Information: NOTICE: This report is paid for by and prepared for the client named above and is not transferable.

Directional References Are Made From Facing Front Entry

**Pictures:** The digital pictures in this report are a sampling of the conditions or damages and should not be considered to show all of the conditions, damages, or deficiencies observed. The photographs included in this report are intended to illustrate some, but not all of the defects and to clarify the text information in the report.

The use of "special equipment" is at the discretion of the inspector in order to form opinions as he sees fit in certain instances.

Cosmetic and other defects related to age and use are not typically identified. Throughout the report the inspector may make recommendations as to possible repairs. These recommendations are not intended to be substitutes or construed to be more appropriate than the recommendations of the professionals actually making the repairs. Conflicts in recommendations should be resolved prior to repairs being made.

An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected.

Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. This inspection may not reveal all deficiencies. Some deficiencies can not be discovered by reasonable and customary observation or inspection. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy.

Page 2 of 19

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid.

## I. STRUCTURAL SYSTEMS

#### 🛛 🗆 🗆 🗆 A. Foundations

*Type of Foundation(s):* Slab on Grade

Comments:

**Inspection Notes** The structural function of a foundation is to support the structure while maintaining the surface levelness within permissible levelness tolerances, so that there is no significant structural damage to the house frame, doors, or windows. It is important to understand that foundations are not designed to eliminate the possibility of cosmetic damage or minor door problems.

#### Future performance of the structure cannot be predicted or warranted.

Foundation Opinion: Performing as intended

#### 🛛 🗆 🗆 🔹 B. Grading and Drainage


#### Comments:

**Maintenance** Keep debris from clogging drainage pathways. Keep foliage trimmed away from structures. Remove debris from any underground drainage inlets regularly.

**Inspection Notes** Soil and slope stability and hydrological conditions are not within the scope of this inspection. The functionality of underground drainage components cannot be determined during a typical inspection. In the absence of rain, consideration must be given to the possibility that drainage function cannot be adequately assessed; and, indications of past conditions or damage from moisture may not be evident.

*Observations:* Grading providing fair drainage of rain runoff *Maintain Underground Drainage:* 

The underground drainage system will need maintenance. Keep inlet basin covers clean.



Keep drainage inlets clear of debris





Keep drainage inlets clear of debris

Keep drainage inlets clear of debris

#### 🛛 🗆 🖾 C. Roof Covering Materials

*Types of Roof Covering:* Composition shingle *Viewed From:* Ladder

Comments:

The evaluation of a roof is primarily a visual assessment based on general roofing appearances. The life of a roof depends on local weather conditions, building and design, material quality, and adequate maintenance.

I=Inspected	NI=Not Inspected	NP=Not Present	<b>D=Deficient</b>



*Performance Opinion:* Good condition -Inspector Opinion of the roof condition is considered a professional courtesy to assist you in better understanding the condition

#### Evidence of past repairs noted: Sealant Applied

#### 1: Improper / temporary repair noted

Deficiency

Roof at patio addition

Excessive application of roofing cement is an improper repair method and should be considered temporary. Flashing, if properly installed, under shingles and siding should prevent water intrusion. Sealant between siding and shingles may trap or reroute water into the wall cavity.

Recommendation: Contact a qualified roofing professional.

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D



Joint between siding and shingles should not be sealed

Joint between siding and shingles should not be sealed

#### ☑ □ □ ☑ D. Roof Structure and Attic


Viewed From: Floored Attic Space

Approximate Average Depth of Insulation: 10-12

Comments:

**Notes** Framing techniques and codes change over time. The best indicator of framing performance is the current condition.

**Maintenance** Keep attic ventilation openings clean and covers secure. Accessible areas of attics are inspected. Power ventilation fans are not tested.



Observations: Floored storage area

Page 6 of 19

#### 1: Uneven attic insulation

Deficiency Left side attic

Attic insulation is inadequate in several areas. The insulation has been moved by foot traffic for repair / remodeling and was not redistributed evenly in some areas. Gaps in the insulation can cause condensation and heat loss. Replace insulation as necessary for adequate thermal protection. Current requirements are 12-14 inches of insulation.

Recommendation: Contact a qualified insulation contractor.



Left side of attic - insulation is uneven, compressed

$\mathbf{X}$				E. Walls (Interior and Exterior)
--------------	--	--	--	----------------------------------

Comments:

Walls are inspected for proper installation and deficiencies related to performance or water penetration.

X		<b>F. Ceilings and Floors</b> <i>Comments:</i> Cracks in tile or grout joints is common and may not be noted on this report. Cosmetic damage is not reported.
X		<ul> <li>G. Doors (Interior and Exterior) Comments:</li> <li>Doors should be readily openable from inside the dwelling without the use of a key or special knowledge or effort. Locks should engage easily.</li> <li>Change of Occupancy Client should consider replacing exterior door locks.</li> </ul>
X		<ul> <li>H. Windows <i>Comments:</i> Inspection Notes A representative number of accessible windows are tested. Window blinds and curtains are not inspected. Insulated Glass Conditions indicating a broken seal are not always visible or present and may not be apparent or visible at the time of inspection.</li></ul>
	X	I. Stairways (Interior and Exterior) Comments:

Report Identifi	cation: 6107 Briarstone Crest L	Dr, Katy, IX //493 - August	8, 2023	
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP	D			

Not present:

#### ☑ □ □ J. Fireplaces and Chimneys

*Comments: Electric fireplace :* 

The installed fireplace is an all electric model, which is essentially a built-in space heater. The unit appeared to be functioning as intended at the time of the inspection.



#### 🛛 🗆 🗆 🖾 K. Porches, Balconies, Decks, and Carports

#### Comments:

**Notes** Attached balconies, carports, and decks and porches that are used for ingress and egress are inspected. Other structures are optional and may not be inspected.

**Change of Occupancy** Accessory structures may have been installed for specific purposes and may need to be altered or removed.

**Maintenance** Wood structures in contact with the ground have a high occurrence of deterioration. Regular inspections are recommended.

Report Identification:	6107 Briarstone Crest Dr, Ka	aty, TX 77493 - August 8, 2	023
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient

## **II. ELECTRICAL SYSTEMS**

#### 🛛 🗆 🗆 🔲 A. Service Entrance and Panels

NI

NP

D

Comments:

**Notes** Main entry wiring, breaker panels, and grounding system comprise the service entrance. Loose or damaged electrical components should be considered safety hazards.

**Change of Occupancy** Don't rely on accuracy of breaker labels. Verify labels before starting any electrical repair. Electrical upgrades may require a permit from local municipality having jurisdiction. For optimum safety all electrical repairs should be made by licensed electricians.

**Inspection Notes** Inspector does not determine sufficiency of service capacity amperage, voltage, or the capacity of the electrical system. Breakers are not operated and accuracy of labeling is not verified.



Main disconnect breaker and electric meter located at right exterior wall



Main disconnect breaker and electric meter located at right exterior wall

Main Panel: 125 amp, Located on exterior Subpanels: Garage



Breaker panel in garage

Breaker panel in garage

### **B.** Branch Circuits, Connected Devices, and Fixtures

*Type of Wiring:* Copper *Comments:* **Notes** The majority of branch circuit wiring is inaccessible.

**Change of Occupancy** Wiring connections can loosen with time and use. Changes or additions to electrical circuits should be performed by a knowledgeable homeowner or licensed electrician. Electrical upgrades may require a permit.

**Inspection Notes** A representative number of electrical receptacles are tested. Security and alarm systems are not within the scope of this inspection. Evaluation of auxiliary, low voltage, electric or electronic equipment (e.g., TV, doorbell, cable, lightning protection, surge protection, low voltage lighting, intercoms, etc.,) is not performed as part of a standard home inspection.

X

Report Identification: 6107 Briarstone Crest Dr, Katy, TX 77493 - August 8, 2023

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				

#### 🛛 🗆 🗆 C. GFCI And AFCI Protection

Comments:

*GFCI protection:* GFCI protection is required for circuits in any areas with possible high moisture.

Code compliance is not required for existing homes, but highly recommended for safety items.

GFCIs (ground-fault circuit-interrupters) can greatly reduce the risk of shock by immediately shutting off an electrical circuit when that circuit represents a shock hazard. GFCIs can be installed as a circuit breaker in a panelboard or as a receptacle outlet.

#### AFCI protection:

Arc Fault Circuit Interrupters protect against fires caused by arcing faults. AFCI protection is provided by specialized circuit breakers or receptacles.

Arcing faults often occurring damaged or deteriorated wires and cords. Wires can be damaged by punctuation of wire insulation from picture hanging or cable staples, poorly installed outlets or switches, cords caught in doors or under furniture, furniture pushed against plugs in an outlet, natural aging, and cord exposure to heat vents and sunlight.

#### 🛛 🗆 🗆 D. Smoke and Carbon Monoxide Detectors

#### Comments:

Current code requires smoke alarms to be installed in each bedroom, each bedroom hallway, and on each floor of the residence.

Report Identificat	tion: 6107 Briarstone Crest D	r, Katy, TX 77493 - August	8, 2023	
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				


### **III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS**

#### X A. Heating Equipment

Type of Systems: Furnace Energy Sources: Natural Gas Comments:



Observations: Appears properly installed, Performing as intended




Heating temperature reading at supply Heating temperature reading at return

#### X **B.** Cooling Equipment

Type of Systems: Central Air Conditioner

Comments:

Observations: Performing as intended, Appears properly installed




X **B.** Cooling Equipment - Garage Type of Systems: Mini split Comments:

I=Inspected NI=Not Inspected NP=No	ot Present D=Deficient
------------------------------------	------------------------



Observations: Performing as intended, Appears properly installed



Cooling temperature reading at supply

temperature in garage

**C. Duct Systems, Chases, and Vents** *Comments:* 





Observations: Good Condition, Performing as intended, No visible damage

Report Identification	: 6107 Briarstone Crest Dr, Ka	aty, TX 77493 - August 8, 2	023
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient

### **IV. PLUMBING SYSTEMS**

#### 🛛 🗆 🗆 🗠 A. Plumbing Supply, Distribution Systems, and Fixtures

Location of Water Meter: Front Yard



Location of main water supply valve: Meter Static water pressure reading: 50-60 psi Type of Supply Piping Material: PEX, Copper -Note: Only visible supply plumbing can be verified at the time of inspection.

#### *Comments:*

I NI NP D

**Change of Occupancy** Changes in occupancy and vacancy may affect plumbing. Operation of seldom used water supply valves or fixtures may cause leaks. Client should closely monitor all plumbing after occupying a home. Mechanical devices can fail at any time, plumbing gaskets and seals may crack. Plumbing failures are more likely during changes or disruptions to water supply pressure, common during changes of ownership.

**Inspection Notes** Fixture shutoff valves to faucets and toilets are not tested. Due to their hidden nature, we do not review appliance water supply or drain connections, or hookups. A majority of supply and drain plumbing are not visible, especially at built in showers. While the inspector endeavors to verify current leaks at the time of inspection, sometimes leaks are incidental or due to specific uses not duplicated at the time of inspection.

#### 🛛 🗆 🗆 🖾 B. Drains, Wastes, and Vents

*Type of Drain Piping Material:* PVC - Note: Only areas of visible drain plumbing can be verified at the time of inspection.

Comments:

**Notes** Some drain pipe material will deteriorate and need replacement. Lifespans of some pipe material is affected by water quality.

**Change of Occupancy** Changes in occupancy and vacancy may affect plumbing. Operation of seldom used fixtures may cause leaks. Client should closely monitor all plumbing after occupying a home. Plumbing gaskets and seals will eventually fail. Drain pipe failures are more common with usage changes, especially at seldom used fixtures, common during changes of ownership.

**Maintenance** Monitoring of moisture conditions under sinks should be a normal part of routine home maintenance.

**Inspection Notes** Drainage and vent pipes are evaluated where visible and accessible only. We do not evaluate subterranean drainage systems. Tub and sink overflow drains are not tested. Due to their hidden nature, we do not review appliance drain connections. A majority of drain plumbing is not visible, especially at built in showers. While the inspector endeavors to verify current leaks at the time of inspection, sometimes leaks are incidental or due to specific uses not duplicated at the time of inspection.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				

#### 🛛 🗆 🗆 C. Water Heating Equipment

Energy Sources: Gas Capacity: 40gal Comments: Water heater lifespans largely depend on maintenance and water conditions in the area. Water heater manufactured April 2021


**Inspection Notes** Inspector does not test discharge piping or pan drain pipes; operate the temperature and pressure relief valve; or determine the efficiency or adequacy of the unit. Water heater outer covers can obscure deficiencies. Interior components and conditions are not visible.

**Change of Occupancy** Check thermostat set points. The temperature of domestic hot water should not be above approximately 120 F to help prevent scalding (child safety).

Water heater located in attic



Observations: 1-5 Years Old



Hot water temperature reading

 Image: Description of the second system
 D. Hydro-Massage Therapy Equipment

 Comments:
 Not present:

Image: Image shows a constraint of the system of the system and Gas AppliancesImage shows a constraint of the system of th

I=Inspected NI=Not Inspected	NP=Not Present	D=Deficient
------------------------------	----------------	-------------



Gas meter

*Type of gas distribution piping material:* Steel, Corrugated Stainless Steel Tubing (CSST) *Comments:* 

**Change of Occupancy** Changes in occupancy and vacancy may affect plumbing. Operation of seldom used gas supply valves or fixtures may cause leaks. Mechanical devices can fail at any time, plumbing gaskets and seals may crack. Plumbing failures are more likely during changes or disruptions to water supply pressure, common during changes of ownership.

**Inspection Notes** Fixture shutoff valves to appliances are not tested. A majority of gas supply plumbing is not visible. While the inspector endeavors to verify current leaks at the time of inspection, sometimes leaks are incidental or due to specific uses not duplicated at the time of inspection.

Report Identification: 6107 Briarstone Crest Dr, Katy, TX 77493 - August 8, 2023				
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				

# **V. APPLIANCES**

🛛 🗆 🗆 🖾 A. Dishwashers

Comments:



**B. Food Waste Disposers** *Comments:* 



**Comments:** 



**D.** Ranges, Cooktops, and Ovens *Comments:* 

I=Inspected NI=Not Inspected NP=Not Present D=De	eficient
--	----------



#### $\mathbf{X}$

X

E. Microwave Ovens Comments:



*Operational video:* Video shows tester that lights up with microwave energy.



#### □ □ □ F. Mechanical Exhaust Vents and Bathroom Heaters

Comments:

# Bathrooms with a tub or shower should have ventilation provided by an opening window or an exhaust fan vented to the building exterior. Ducts serving exhaust fans should terminate to well ventilated area.

- **G.** Garage Door Operators *Comments:*
- H. Dryer Exhaust Systems Comments:

Report Identification: 6107 Briarstone Crest Dr, Katy, TX 77493 - August 8, 2023


i inspecteu i i i i i i i i i i i i i i i i i i i	I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
---	-------------	------------------	----------------	-------------

# I NI NP D



Report Identification: 6107 Briarstone Crest Dr, Katy, TX 77493 - August 8, 2023				
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	

# VI. OPTIONAL SYSTEMS



Comments:

NI

I

NP

D











6