# **ALLSPEC** Property Inspection Report





2700 Fairway Dr , Orange, TX 77630 Inspection prepared for: Carey Demahy Real Estate Agent: Magen Wright - Remax Platinum

Date of Inspection: 10/7/2016 Time: 9:00 am Weather: Fair

Inspector: Tim Herrington License #9184 295 berkshire Ln., Beaumont, TX 77707 Phone: 409-767-6233 Email: timherrington41@yahoo.com www.beaumonthomeinspector.com

| A I | 1.5 | J |   | $\sim$   |
|-----|-----|---|---|----------|
| ΑL  | -LS | Р | Е | $ \cup $ |

|                            | PROPERTY INSPECTION REPOR                         | Т         |  |
|----------------------------|---|-----------|--|
| Prepared For: Carey Demahy |   |           |  |
|                            | (Name of Client)                                  |           |  |
| Concerning:                | 2700 Fairway Dr, Orange TX, 77630                 |           |  |
| -                          | (Address or Other Identification of Inspected Pro | perty)    |  |
| By:                        | Tim Herrington, License #9184                     | 10/7/2016 |  |
|                            | (Name and License Number of Inspector)            | (Date)    |  |
|                            |   |           |  |

#### PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods.

Promulgated by the Texas Real Estate Commission (TREC) P.O. Box 12188, Austin, TX 78711-2188 (512) 936-3000 (http://www.trec.texas.gov).

REI 7-5 (05/4/2015)

Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

#### TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices for electrical
- receptacles in garages, bathrooms, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- · lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms require a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

### ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

REI 7-5 (05/4/2015)

| I=Inspect |            |          | NI=Not Inspected  | NP=Not Present   | D=Deficient  |
|-----------|------------|----------|---|--|--|
| I NI      | <u>INP</u> | <u>U</u> |   |  |  |
|           |            |          | I. ST   | RUCTURAL SYSTEMS   |  |
|           |            |          | A. Foundations  |  |  |
|           |            |          | supporting the structu<br>foundation's future per<br>foundations do move a<br>the foundation as nee<br>changes can have an<br>scheduled foundation<br>home owner.<br>A.2. Slab-on-grade fou<br>residential. When sup<br>will frequently deflect of<br>brick veneer cracking<br>problems such as stic<br>grade foundation shou | Ill "appears" to be perform<br>re at time of inspection. In<br>formance. Due to the ex<br>and shift. It is important to<br>ded to insure proper perf<br>effect on foundation's fut<br>maintenance is strongly<br>undations are the most co<br>ported by active or expan-<br>enough to result in cosm-<br>and floor tile cracking) an<br>king doors. Any owner of | ming its intended function<br>No warranty is offered or implied for<br>cpansive nature of our soil,<br>hat the owner of property maintain<br>formance. Local soils and climatic<br>ture performance. Regularly<br>recommended to be performed by<br>common type of foundations for<br>nsive soils, this type of foundation<br>etic damage (usually sheetrock,<br>nd possibly some minor functional<br>f a building founded on a slab-on-<br>t a degree of cosmetic distress and<br>novement. |
| X         |            |          | B. Grading & Drainage   | )  |  |
|           |            |          |   | drain away from home.<br>hitoring drainage during h  | neavy rains.   |
| X         |            | Х        | C. Roof Covering Mate   | erials   |  |
|           |            |          | 25 - 30 years from dat<br>C.2. No other loose or<br>Roof "appears" to be i<br>C.3. This is not a "win<br>windstorm certification<br>C.4. Observed a rais<br>a professional roofe<br>C.5. Observed a cost<br>not a leak concern.<br>C.6. Observed pinch  | gles. Typical life expecta<br>e of installation per many<br>damaged shingles were<br>n satisfactory condition a<br>dstorm" inspection. Only<br>n<br>ed shingle on the front<br>r.  | e observed at time of inspection.<br>at time of inspection.<br>a structural engineer can issue a<br>slope, generally a simple fix by<br>e on the roof at front upper slope,<br>locations   |



provide added comfort.

# 2700 Fairway Dr , Orange, TX ALLSPEC NP=Not Present D=Deficient I=Inspected NI=Not Inspected NI NP D attic view E. Walls (Interior and Exterior) Х Wall Materials: Interior walls are sheetrock and wood panel.. Exterior walls are of brick and wood with stucco type finish at front gable area. Comments: E.1. Normal wear and tear to exterior walls and finishes. E.2. No significant interior or exterior cracks or stains were observed at time of inspection. E.3. As a note, typical wear / damage to the interior walls of garage. E.4. As a note, the inspector(s) cannot see through walls, floors or ceilings. E.5. Observed minor wood rot / weathering in several locations on the exterior of home. Observed minor wood rot / weathering in several locations on the exterior of home. F. Ceilings and Floors Х Ceiling & Floor Materials: Ceiling are sheetrock. Floors are wood laminate, carpet and tile. Comments: F.1. Floors are in satisfactory condition. F.2. Ceilings are in satisfactory condition. F.3. Normal wear for age. F.4. Observed loose tape seams at sheetrock in the garage, this is generally common due to the garage is not climate controlled.

| I=Inspected NI=Not Inspected NP=Not Present I  | D=Deficient   |
|--|---|
| I NI NP D  |   |
|  |   |
| Observed loose tape seams at sheetrock in the garage, this is gene<br>is not climate controlled.   | erally common due to the garage   |
| X G. Doors (Interior and Exterior)   |   |
| Comments:<br>G.1. All doors open and close normal at time of in<br>were tested. Normal wear and tear for age to doo<br>G.2. The door between an attached garage and a<br>wood door not less than 1-3/8 inches (35 mm) thi<br>steel door not less than 1-3/8 inches (35 mm) thi<br>door.<br>G.3. Door between garage and home is not a f<br>meet current industry standards.<br>G.4. There is no dead bolt lock at the front ent<br>meet "current" industry standards.<br>G.5. Several interior doors do not latch well, d<br>plate not carved out. | or surfaces.<br>a dwelling unit should be a solid<br>ick, a solid- or honeycomb-core<br>ck, or a 20-minute fire-rated<br>fire rated safety door. does not<br>trance door, this does not |
| ,  | ad bolt lock at the front entrance<br>es not meet "current" industry<br>standards.  |
| X H. Windows   | Standards.  |
| Window Types: Windows are single pane.<br>Comments:<br>H.1. Windows, tested (at random) open, closed a<br>H.2. No cracked panes were observed at time of<br>H.3. Normal wear and tear for age.   |   |
| REI 7-5 (05/4/2015)  | Page 6 of 20  |

| I=Inspected | NI=Not Inspected  | NP=Not Present  | D=Deficient  |
|-------------|---|---|--|
| I NI NP D   |   |   |  |
| x           | I. Stairways (Interior ar   | nd Exterior)  |  |
|             | I.2. Typical wear for ac<br>I.3. Pull down attic st   |   | / close at time of inspection,   |
|             |   |   |  |
|             | J. Fireplaces and Chim  | attic space.  | ion, leaking conditioned air into the  |
|             | Locations: Fireplace is<br>Types: Fireplace is ma<br>Comments:<br>J.1. Wood burning type<br>J.2. Damper opens / c<br>J.3. No fire was lit to d<br>J.4. Normal wear and<br>J.5. The interior of chir<br>inspection. You are ad<br>or other qualified perso<br>fireplace prior to using<br>J.6. Typical surface ru<br>J.7. Starter pipe is cap<br>J.8. Typical wear to int<br>J.9. Creosote build u<br>Recommend chimne<br>use.<br>J.10. Flue opening at<br>if available. | e located in the living roc<br>ason built<br>e.<br>loses at time of inspecti-<br>etermine draft.<br>tear for age.<br>mneys and their flue line<br>lvised to obtain the serv<br>onnel to perform a comp<br>the appliance.<br>st to upper damper com<br>ped off, due to no gas s<br>terior of firebox.<br><b>p observed to upper fi</b><br><b>y sweep check and cle</b> | on.<br>ers are not visible on our visual<br>ices of a qualified chimney sweepe<br>olete inspection and tune up of your<br>aponents in the firebox.<br>service to home.<br><b>Fire box and visible area of flue.</b><br><b>Fire box and visible area of flue.</b> |

# 2700 Fairway Dr , Orange, TX ALLSPEC NP=Not Present D=Deficient I=Inspected NI=Not Inspected NI NP D Flue opening at chimney is covered with bricks, see sellers disclosure if available. K. Porches, Balconies, Decks, and Carports Х Comments: K.1. Front and rear porch appear to be in satisfactory condition at time of inspection. K.2. Common settle cracks observed to garage floor. L. Other Х Materials: Home appears to have been vacant for period of time undisclosed time to inspector. All systems are turned on for the inspection. Buyer Should be advised upon first move in, latent defects may occur in plumbing, gas and electrical systems that may not have been evident at the time the inspection took place. Comments: L.1. As a note, this is not a mold inspection. A mold inspection is beyond the scope of inspection. If buyer has any concerns regarding mold, a environment hygienist is recommended. (Per TREC) home inspectors are not required to report on the presents or absence of mold or mildew.





While on the roof inspector observed evidence of excessive heat to plastic connection cover at one of the service entrance wires.

The interior cover (dead plate) in both exterior panels are missing, recommend installing for safety reasons.



View 2

| I=Inspected | NI=Not Inspected                          | NP=Not Present            | D=Deficient   |
|-------------|---|---------------------------|---|
| I NI NP D   |   |                           |   |
|             |   |                           |   |
|             | B. Branch Circuits, Co                    | nnected Devices, and F    | ixtures   |
|             | Type of Wiring: Coppe<br>Comments:        | er wiring, 100 Amp servi  | ce panel  |
|             |   | ircuits appear to be cop  | per. Receptacles throughout home  |
|             | B.2. Smoke detectors                      | n smoke alarms shall be   | e of occupancy to insure safety.<br>e installed in the following locations: |
|             |   |                           | he immediate vicinity of the  |
|             | 3. On each additional                     | end the addition of carbo | cluding inhabitable attics. I would<br>on monoxide detectors for safety     |
|             |   |                           | hroom did not trip when tested  |
|             | B.4. There are no GF meet "current" indus |                           | arage or outdoors, This does not  |
|             |   |                           | around the home in various  |
|             |   |                           | lets with open ground circuits in   |
|             | B.7. Possible worn r                      | heostat wall switch at t  | fan light in the living room.<br>rther evaluate / correct.                  |



Reverse polarity at receptacles in and around the home in various locations

The GFCI receptacle in the master bathroom did not trip when tested with external tester.



Possible worn rheostat wall switch at fan light in the living room.



REI 7-5 (05/4/2015)

| I=Inspected | NI=Not Inspected   | NP=Not Present   | D=Deficient   |
|-------------|--|--|---|
| I NI NP D   |  |  |   |
|             | C. Duct System, Chase  | es, and Vents  |   |
|             | time of inspection. All<br>properly. Interior walls<br>condition. Return filter<br>C.2. As a note inspect<br>comment will be made<br>can not see inside the<br>what can not be seen. | visible ductwork appear<br>in the return air space<br>was in place and in sat<br>or is not an indoor air q<br>regarding these and o<br>HVAC system and duc<br>Due to high levels of ir<br>view some areas of the | is of ducts only) were observed at<br>rs to be connected and functioning<br>appear to be in satisfactory<br>tisfactory condition.<br>Juality or mold inspector and no<br>ther related issues. The inspector<br>ets therfore comment is made on<br>insulation or limited attic access, the<br>e ducts, therefore, no comment can |

## 2700 Fairway Dr , Orange, TX

| I=Inspected     | NI=Not Inspected   | NP=Not Present  | D=Deficient  |
|-----------------|--|---|--|
|                 |  |   |  |
|                 | IV   | . PLUMBING SYSTEM   |  |
|                 | A. Plumbing Supply, D  | Distribution System and F   | Fixtures.  |
|                 | Comments:<br>A.1. Supply lines apport<br>fixtures or visible plun<br>during the inspection.<br>plumbing lines that an<br>A.2. Static Water Pres<br>the exterior wall of ho<br>A.3. Washing machine<br>of home and testing we<br>they were not opened<br>A.4. Typical wear to o | er Supply Valve: Meter<br>ear to be copper. No othen<br>bing at time of inspectio<br>As a note, the inspector<br>e buried in ground or in v<br>ssure: Reading was 52 lb<br>ome.<br>e plumbing connections a<br>vould result in water into | os tested at exterior hose bibb on<br>and drain are located in the interior<br>interior floor of home, therefore,<br>ne. |
|                 | A.6. Leak at the fill v<br>A.7. Damaged / miss<br>under the kitchen si   | alve in the toilet tank ir<br>sing supply handle at s   | n the master bathroom<br>hut off valve for the dishwasher  |
| Damaged / missi | ng supply handle at shu  | It off valve Leak at the fill   | Value in the toilet tank in the master   |
| for the dishw   | asher under the kitcher  | n sink.   | bathroom   |

### 2700 Fairway Dr , Orange, TX ALLSPEC NP=Not Present D=Deficient I=Inspected NI=Not Inspected NI NP D B. Drains, Wastes, and Vents Х Х Comments. B.1. Visible drain lines are PVC and cast iron. No other visible leaks at time of inspection. All visible drains flowed normal at time of inspection. B.2. As a note, in ground, in wall and under slab plumbing pipes can not be seen by the inspector and a pressure test on the drain lines is not part of the inspection. However, a pressure test at one of the exterior wall hose bibb was performed to determine supply pressure only, is not a pressure test for line leaks. B.3. Bath trap areas are not visible at time of inspection. B.4. Leak at drain line under the master bathroom sink. B.5. Pop up drain stopper in the master bathroom tub needs adjustments or replacement, does not hold water well. B.6. Recommend plumber to further evaluate / correct. Leak at drain line under the master bathroom sink. Pop up drain stopper in the master bathroom tub needs adjustments or replacement, does not hold water well. C. Water Heating Equipment Х Energy Source: Water heater is electric powered Capacity: Unit is 50 gallons Comments: C.1. 50 Gallon water heater located in the garage operated within industry standards. All visible areas of housing appear to be in satisfactory condition. No visible leaks. C.2. The functional test of the water heater is not a guarantee or warranty of future performance. Water heaters are prone to failure at any time. C.3. The Temperature and Pressure relief valve was not tested, valve may not reseat resulting in possible future leak at valve and possible future water leak.

| ALLSPEC     |                  |                | 2700 Fairway Dr , Ora | ange, TX |
|-------------|------------------|----------------|-----------------------|----------|
| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient           |          |
| I NI NP D   |                  | ipment         |                       |          |
|             |                  |                |                       |          |

### 2700 Fairway Dr , Orange, TX



| I=Inspected | NI=Not Inspected NP=Not Present D=Deficient   |
|-------------|---|
| I NI NP D   |   |
|             |   |
|             | E. Microwave Ovens  |
|             | Comments:<br>E.1. No microwave present  |
|             | F. Mechanical Exhaust Vents and Bathroom Heaters  |
|             | Comments:<br>F.1. The vent fan in the master bathroom operated correctly, there is no vent fan<br>in the hall bathroom however an operable window is present.<br>F.2. Electric wall heater in the hall bathroom correctly functioned. |
|             | G. Garage Door Operators  |
|             | Door Type: Overhead door<br>Comments:<br>G.1. Garage doors (2) open and close manually at time of inspection. Normal<br>wear and tear for age to door surfaces.<br>G.2. Several minor dents to right overhead door.                   |
|             | Several minor dents to right overhead door.   |
|             | H. Dryer Exhaust Systems  |
|             | Comments:<br>H.1. Dryer vents through wall to exterior of home.   |
|             | I. Other  |
|             | Observations:   |
|             |   |

| l=Inspe |       |   | NI=Not Inspected NP=Not Present D=Deficient                 |  |
|---------|-------|---|---|--|
| I NI    | NP    | D |   |  |
|         |       |   | VI. OPTIONAL SYSTEMS  |  |
|         |       |   | A Landagen a Invigation (Convigtion) Customer               |  |
|         |       |   | A. Landscape Irrigation (Sprinkler) Systems                 |  |
|         | . — . |   | Comments:   |  |
|         | X     |   | B. Swimming Pools, Spas, Hot Tubs, and Equipment            |  |
|         |       |   | Type of Construction:<br>Comments:                          |  |
|         | X     |   | C. Outbuildings   |  |
|         |       |   | Materials:<br>Comments:                                     |  |
|         | x     |   | D. Private Water Wells (A coliform analysis is recommended) |  |
|         |       |   | Type of Pump:<br>Type of Storage Equipment:<br>Comments:    |  |
|         | X     |   | E. Private Sewage Disposal (Septic) Systems                 |  |
|         |       |   | Type of System:<br>Location of Drain Field:<br>Comments:    |  |
|         | X     |   | F. Other  |  |
|         |       |   | Comments:   |  |
|         |       |   |   |  |
|         |       |   |   |  |
|         |       |   |   |  |
|         |       |   |   |  |
|         |       |   |   |  |
|         |       |   |   |  |
|         |       |   |   |  |
|         |       |   |   |  |
|         |       |   |   |  |

Report Summary

| STRUCTURAL SYSTEMS |                                   |  |  |
|--------------------|-----------------------------------|--|--|
| Page 3 Item: C     | Roof Covering<br>Materials        | <ul> <li>C.4. Observed a raised shingle on the front slope, generally a simple fix by a professional roofer.</li> <li>C.5. Observed a cosmetic damaged shingle on the roof at front upper slope, not a leak concern.</li> <li>C.6. Observed pinched drip edge tin in two locations</li> <li>C.7. Recommend professional roofer to further evaluate / correct.</li> </ul> |  |
| Page 4 Item: D     | Roof Structures<br>and Attics     | D.7. Missing insulation over formal dining room, recommend adding to reduce energy cost and provide added comfort.   |  |
| Page 5 Item: E     | Walls (Interior and<br>Exterior)  | E.5. Observed minor wood rot / weathering in several locations on the exterior of home.  |  |
| Page 5 Item: F     | Ceilings and Floors               | F.4. Observed loose tape seams at sheetrock in the garage, this is generally common due to the garage is not climate controlled.   |  |
| Page 6 Item: G     | Doors (Interior and<br>Exterior)  | G.3. Door between garage and home is not a fire rated<br>safety door. does not meet current industry standards.<br>G.4. There is no dead bolt lock at the front entrance door,<br>this does not meet "current" industry standards.<br>G.5. Several interior doors do not latch well, due to new<br>wood behind strike plate not carved out.                              |  |
| Page 7 Item: I     | Stairways (Interior and Exterior) | I.3. Pull down attic stairs do not completely close at time of inspection, leaking conditioned air into the attic space.   |  |
| Page 7 Item: J     | Fireplaces and<br>Chimneys        | J.9. Creosote build up observed to upper fire box and<br>visible area of flue. Recommend chimney sweep check<br>and clean chimney and box prior to use.<br>J.10. Flue opening at chimney is covered with bricks, see<br>sellers disclosure if available.<br>J.11. There is no spark arrestor present or visible.<br>J.12. Recommend fireplace professional to evaluate.  |  |
| ELECTRICAL SY      | STEMS                             |  |  |
| Page 9 Item: A     | Service Entrance<br>and Panels    | <ul> <li>A.3. The interior cover (dead plate) in both exterior panels are missing, recommend installing for safety reasons.</li> <li>A.4. While on the roof inspector observed evidence of excessive heat to plastic connection cover at one of the service entrance wires.</li> <li>A.5. Recommend electrician to evaluate / correct.</li> </ul>                        |  |

| Page 10 Item: B | Branch Circuits,<br>Connected<br>Devices, and<br>Fixtures | <ul> <li>B.3. The GFCI receptacle in the master bathroom did not trip when tested with external tester.</li> <li>B.4. There are no GFCI receptacles in the garage or outdoors, This does not meet "current" industry standards.</li> <li>B.5. Reverse polarity at receptacles in and around the home in various locations</li> <li>B.6. As a note, there are three pronged outlets with open ground circuits in the home in various locations.</li> <li>B.7. Possible worn rheostat wall switch at fan light in the living room.</li> <li>B.8. Recommend qualified electrician to further evaluate / correct.</li> </ul> |
|-----------------|---|--|
| PLUMBING SYSTEM |   |  |
| Page 13 Item: A | Plumbing Supply,<br>Distribution System<br>and Fixtures.  | <ul> <li>A.5. Toilet in the master bathroom is loose at floor mount</li> <li>A.6. Leak at the fill valve in the toilet tank in the master</li> <li>bathroom</li> <li>A.7. Damaged / missing supply handle at shut off valve</li> <li>for the dishwasher under the kitchen sink.</li> <li>A.8. Recommend plumber to evaluate / correct.</li> </ul>  |
| Page 14 Item: B | Drains, Wastes,<br>and Vents                              | B.4. Leak at drain line under the master bathroom sink.<br>B.5. Pop up drain stopper in the master bathroom tub<br>needs adjustments or replacement, does not hold water<br>well.<br>B.6. Recommend plumber to further evaluate / correct.   |
| APPLIANCES      |   |  |
| Page 16 Item: A | Dishwashers   | A.2. Unit is loose in the cabinet<br>A.3. Dishwasher drains into to plumbing drain line, it<br>should terminate into the disposal when one is avaliable.<br>A.4. Recommend a qualified appliance repair person<br>further evaluate.  |
| Page 16 Item: C | Range Hood and<br>Exhaust Systems                         | C.2. Unit makes irregular noise on start up  |
| Page 17 Item: G | Garage Door<br>Operators                                  | G.2. Several minor dents to right overhead door.   |