**Property Condition Report** 

Address:

Case Number: 512-251624 Contract Area: 2D

**Current Step:** 

1c-Ready to Show Condition

442 STEPHEN F AUSTI

Step Date: 12/23/2019 HOC:

Denver

| City, St Zip: | CONROE, 1X 7/302-0000 |
|---------------|-----------------------|
|               |                       |

|   |                       | Property Cor                                | ndition Repo | ort   |
|---|-----------------------|---|--------------|---|
| Item Description/Condition                              |                       | Item Functionality                          |              | Functionality/Test Notes  |
| Cooling/Air-ConditioneHeating/Furnace:HVAC System Duct: | r: OK<br>OK<br>OK     | HVAC tested and functional?:                | N/A          | Could not test due to damaged electrical system.                                |
| Electrical Wiring:Other:Other:                          | Damaged<br>N/A<br>N/A | Electric supply tested and functional?:     | No           | Electrical system is damaged. Property does not energize with generator bypass. |
| Stove/Range/Oven:Kitchen Cabinets:Other:                | OK<br>OK<br>N/A       | Built-in appliances tested and functional?: | Yes          | Refrigerator tested and functional with generator.                              |
| Plumbing:Sink:Other:                                    | OK<br>OK<br>N/A       | Water supply tested and functional?:        | Yes          | Plumbing holds pressure.  |
| Water Heater:   | ОК                    | Water heater functional?:                   | Yes          | Water heater is tankless, good condition.                                       |
| Sewer/Septic System:Toilet:Other:                       | OK<br>OK<br>N/A       | Sanitary & plumbing system functional?:     | Yes          | Toilets force flushed with no backup.<br>Antifreeze pour successful.            |
| Roof:<br>Other:   | OK<br>N/A             | Roofing in acceptable condition?:           | Yes          | Roof appears in good condition with no active leaks.                            |