

## CHICAGO TITLE

LLOLIND				
0 1/2"	ROD FOUND			
Ø 1/2"	ROD SET			
O 5/6"	ROD FOUND			
X" FOUND/SET				
A DAILIE	Con conven			

LEGEND

CONT FOR CORNER FENCE POST FOR CORNER

CONTROLLING MONUMENT

AIR CONDITIONER POOL EQUIPMENT

TRANSFORMER TE PAD

COLUMN

POWER POLE UNDERGROUND **ELECTRIC** 

OVERHEAD ELECTRIC

OVERHEAD ELECTRIC POWER

-OFS-OVERHEAD ELECTRIC SERVICE

> <del>--</del>O-CHAIN LINK пп

WOOD FENCE 0.5' WIDE TYPICAL

- III-IRON FENCE

BARBED WIRE

DOUBLE SIDED WOOD FENCE

EDGE OF ASPHALT EDGE OF GRAVEL


N. 500 CONCRETE

COVERED AREA

CURVE	ARC LENGTH	RADIUS
C1	53.00'	300.00

LINE	BEARING		DISTANCE
L1	S 78°00'28"	W	8.66'
L2	N 57°41'32"	W	25.99'





## **EXCEPTIONS:**

NOTE: PROPERTY SUBJECT TO TERMS,
CONDITIONS, AND EASEMENTS
CONTAINED IN INSTRUMENTS RECORDED IN
CAB. A, SHEET 84A; VOL. 795, PG. 504;
VOL. 866, PG. 134;
CCF# 8828176; 2000-010504; 2000-086359;
2004-123560; 2005-043792; 2005-140623;
2006-073735; 2006-100598; 2007-079939;
20110076094; 2010080411; 2011000758; 2011000759;
2011035432; 2011029242; 2011029243; 2011029244;
2011035432; 2011035433; 2011046587; 2011066772;

2011061645; 2011069961; 2011069962; 2011086772; 2011086773; 2011086774; 2011086775; 2011098198; 2011098199; 2011098200; 2011098202; 2011106506; 2012016444; 2012031540; 2012050540; 2012075546;

## NOTES:

NOTE: BEARINGS, EASEMENTS AND BUILDING LINES ARE BY RECORDED PLAT UNLESS OTHERWISE NOTED.

FLOOD NOTE: According to the F.I.R.M. No. 48339C0225G, this property does lie in Zone X and DOES NOT lie within the 100 year flood zone.

This survey is made in conjunction with the information provided by Chicago Title. Use of this survey by any other parties and/or for other purposes shall be at user's own risk and any loss resulting from other use shall not be the responsibility of the undersigned. This is to certify that I have on this date made a careful and accurate survey on the ground of the subject property. The plat hereon is a correct and accurate representation of the property lines and dimensions are as indicated; location and type of buildings are as shown; and EXCEPT AS SHOWN, there are no visible and apparent encroachments or protrusions on the ground.

MAIN