

## Ross repairs

Laurie Auzenne <lauries60@comcast.net>

Sun 6/7/2020 6:31 PM

To: Tracy Montgomery <tracy@tracysoldit.com>

We have corrected the following deficiencies found in the May 6 inspection of 17114 Ross Lake Ct

Part I section D - Sealed gap in front of house

section J - installed damper clamp

Part II Section B - tightened gang boxes

Part III Section C - raised ducts so they were no longer in contact with other ducts or refrigerant lines

Part IV Section A - properly installed master bathtub hot water faucet

Part V Section G - disabled manual door lock on small garage door

### Pool Report

1) Chiller - inspector did not open required valves for proper functioning. Chiller works as intended.

2) Cleaner - weights were removed from sweeper arm and water flow adjusted. Cleaner functions as intended.

3) Heater - cycled heater on and off successfully several times. Operated heater and raised the temperature of the spa by 3 degrees in 8 minutes. Heater working as intended.