	HOMEOWNER CHECKLIST			
	Property Address: 1 1007 Quet Dale Ct Houston 1 17093			
	What is the age of:			
	A/C: 3019 American Standard	Unit 2: NA		
	Heater/Furnace: 2066	Unit 2: NA		
	Water Heater: 2620	Dishwasher: 2008	and the state of t	
	Carpet: <u>2020</u>	Other flooring: 2026	(
	Interior Paint: 2008	Exterior Paint: 8 08	0	
	Stove: 2005	Oven: 1990		
	Roof: 2010	Fence: 2018 West side	HOA Replaced back	
	Pool: A/A	Spa/Hot Tub: NA		
	Hailian Committee	Double pane win	dows/high	
	Utility Suppliers:	21	3/2020	
	Gas Company: Conterpoint Sne	nay Phone: 2/3	3-659-2111	
	Electric Company: Releaset		3-488-3667	
	Telephone Company: \ Sinetel		meast	
	Water Company: Davis Co MUN		- 8161-6215	
	Trash Company: WCA		1- 368-8397	
	Average Mandala Dillian			
	Average Monthly Utilities:		. Ites now Window	
	Electricity: High \$ 212.0	0 Low \$ 75.00	after now Windows	
	Gas: High \$ 2	1000 Low\$ 5	1,00	
	Water: High \$	Low \$ 3	700	
	Tuesday All A	6.58 (3 montatels		
		arus Cumorosas p	Andrews of the second s	
	Please list any upgrades or remodeling you ha	ave done to the home and th	e dates:	
	2001 High Secrity Front Storm Door 2009 Grante Countertops Kitchen + Bath phis Backsplash 2016 New Portio + Sidewalk pressed concrete 2018 Replaced both Backdoors with doors that have blind in			
	2019 Remodeled Maint		res heads the glass	
		system for front	+ banky and	
	2020 > installed Guardea	in High Energy Hugh Effe	very doleble pane	
	2020 > sew carpet + e	entire Lovely High Effe regineral Heckory L	wood floors	
	Seller Andrew	Collow		
		Lingus	Janeson	
	Date: 07/29/2020	0	2 3	
	, ,			
	*	•		

From: Steve Wachel

Sent: Tuesday, June 30, 2020 6:45 PM

To: 2jamesonlg@gmail.com

Subject: 17007 Quiet Dale Ct. Foundation Inspection.

Mr. and Mrs. Jameson,

I enjoyed meeting both of you today. You have a beautiful home!

After inspection, I did not find any area of your foundation that needed attention. The readings were well within specifications. Outside inspection found a couple of corner spalls, but these are only cosmetic and are completely normal. After taking readings, .6 " was the largest variance from reference point to location. Well within foundation standards. Please feel free to call us anytime answer any questions that you may have.

Steve Wachel, CST
Certified Structural Technician
Certified Foundation Repair Specialist
Olshan Foundation Repair Co. of Houston LLC
281-541-4475 Cell