TEXAS OFFICIAL WO	Page 1 of 4		
69 N. Old Cedar Circle	The Woodlands	77382	
Inspected Address	City	Zip Code	

SCOPE OF INSPECTION

This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guest houses or any other structure
will not be included in this inspection report unless specifically noted in Section 5 of this report.

B. This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work.

Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other C. decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment, has rendered the pest(s) inactive.

D. If v	visible evidence of active or previous infestation	of listed wood destroying insects is reported, it sho	ould be assumed that some degree of damage is present.
---------	----------------------------------------------------	-------------------------------------------------------	--------------------------------------------------------

If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified expert. THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS. F

- F. G
- If termite treatment (including pesticides, baits or other methods) has been recommended, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticides to be used and complete details of warranty (if any). At a minimum, the warranty must specify which areas of the structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party.
- Н. There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and renewal options.
- There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is ١. visible evidence of an active infestation in or on the structure, (2) there is visible evidence of a previous infestation with no evidence of a prior treatment.
- If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The J. buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture.

1A. <u>Inspectors Service Group service@i</u> Name of Inspection Company	isgtx.com	1B. SPCS Business License	. <u>TPCL # '</u> Number	730859		
1C. <u>5100 Westheimer Rd.</u> #200 Address of Inspection Company	Houston, TX	<u> </u>		10) 274-0204 phone No.		
1D. <u>Chris Stull License# 725395 (936)</u> Name of Inspector (Please Print)	445-9986 1e	Certified Applicator		(check one)		
2. <u>NA</u> Case Number (VA/FHA/Other)	3. <u>4/3/201</u> Inspe	7 ction Date				
4A. <u>Stull Inspections for Erica Sprague (936) 355-0017</u> 						
4B. <u>Unknown</u> Owner/Seller						
4C. REPORT FORWARDED TO: Title Company or Mortgagee □ Purchaser of Service ☑ Seller □ Agent ☑ Buyer □ (Under the Structural Pest Control regulations only the purchaser of the service is required to receive a copy)						
The structure(s) listed below were inspected in accordance with the official insp to the conditions listed under the Scope of Inspection. A diagram must be attact 5. <u>Single Family Residence</u> List structure(s) inspected that may include residence, detached garages and o	ched including all structu	res inspected.		ce. This report is made subject		

A

(Rev. 09/01/07)


TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

6A. Were any areas of the (Refer to Part B & C, Scope				Yes 🗹	Ν	lo 🗆					
6B. The obstructed or inac Attic Deck Soil Grade Too High Other	ccessible areas	nclude but are not limited Insulated area of attic Sub Floors Heavy Foliage Specify:	マ	•		3	2	Planter box abutti Crawl Space Weepholes	ng structure		
7A. Conditions conducive to (Refer to Part J, Scope of I				Yes 🗹	1	No 🗆					
7B. Conducive Conditions i Debris under or around stru Planter box abutting structu Insufficient ventilation (T)	ucture (K)	not limited to: Wood to Ground (Footing too low of Wood Pile in Cont Other (C)	soil line too	o high (L) [ucture (Q) [Wood Wood		n place (I)	Heavy I	ve Moisture (J) Foliage (N)	
 Inspection Reveals Visib Subterranean Termites Drywood Termites Formosan Termites Formosan Termites Carpenter Ants Other Wood Destroying Specify:	g Insects previous treatm A of active or prev	ent (including pesticides, has bee ious infestation, it must b	n observed e noted. Th	in the followi	No 🗹 No 🗹 No 🗹 No 🗹 	or othe :: NA	Yes Yes Yes Yes Yes r methods) i		Previous T Yes Yes Yes Yes Yes dentified infes	No 🗹 No 🗹 No 🗹 No 🗹	 property
The conditions conducive t 9. Will be or has been mech If "Yes", specify corrections 9A. Corrective treatment re	hanically correc s: commended for	ted by inspecting compar	ence of prev	vious infestat	tion with	no prior	treatment	Yes 🗌 Yes 🔲			_
as identified in Section 8. (Refer to Part G, H and I, Scope of Inspection) Yes □ No 12 9B. A preventive treatment and/or correction of conducive conditions as identified in 7A & 7B is recommended as follows: Yes □ No 12 Specify reason: Refer to Scope of Inspection Part J											
10A. This company has tre If treating for subterranean If treating for drywood term 10B. NA	termites, the tre ites or related ir	atment was: isets, the treatment was: <u>N</u>	Partial Full	d destroying i	insects: <u> </u> Spot Limited		Ba NA		Other [_
Date of Treatment This company has a contra Yes	ict or warranty in No 🗌 🛛 L	ompany	Comm ollowing wo			:		Name of Pesticid	e, Bait or Oth	er Method	_

TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

Diagram of Structure(s) Inspected

The inspector must draw a diagram including approximate perimeter measurements and indicate active or previous infestation and type of insect by using the following codes: E-Evidence of infestation; A-Active; P-Previous; D-Drywood Termites; S-Subterranean Termites; F-Formosan Termites; C-Conducive Conditions; B-Wood Boring Beetles; H-Carpenter Ants; Other(s) - Specify



Additional Comments

Homes that receive no recommendation for treatment are eligible for a \$99.00 warranty that covers the cost of treatment should a hidden or new live infestation be discovered anywhere in the home within 1 year. This offer is only valid up to 60 days after your initial inspection report was issued.

Inspectors Service Group LLC (210) 481-9060 (210) 978-5220

TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

Page 4 of 4

Neither I nor the company for which I am acting have had, presently have, or contemplate having any interest in the property. I do further state that neither I nor the company which I am acting is associated in any way with any party to the transaction.

Signa	tures:	Notice	of Inspection Was Posted At or Near
11A.	Chris Stull License# 725395	12A.	Electric Breaker Box
	Inspector		Water Heater Closet
			Bath Trap Access
Appro	ved:		Beneath the Kitchen Sink
11B.	Trace Pharis CA# 561526PTL	12B.	Date Posted 4/3/2017
	Certified Applicator and Certified Applicator License Number		Date

Statement of Purchaser

I have received the original or a legible copy of this form. I have read and understand any recommendations made. I have also read and understand the "Scope of Inspection." I understand that my inspector may provide additional information as an addendum to this report. If additional information is attached, list number of pages:

Signature of Purchaser of Property or their Designee

Date