

Home Inspection - TREC



Inspection Date: 9/18/2020

Inspection Completed for: Graebel Companies - CO
(770) 325-4790
16346 Airport Circle
Aurora, CO 80011
APROA377362

Transferee / Property Information: Amanda Guza
106 Anchusa St
Lake Jackson, TX 77566

PROPERTY INSPECTION REPORT

Prepared For: Amanda Guza

(Name of Client)

Concerning: 106 Anchusa St Lake Jackson, TX 77566

(Address or Other Identification of Inspected Property)

By: Art Byrd - 1171

9/18/2020

(Name and License Number of Inspector)

(Date)

Art Byrd - 1171

(Name, License Number and Signature of Sponsoring Inspector, if required)

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods.

Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathrooms, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate license holders also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms require a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Date: 9/21/2020
Time: 10:21 AM
Weather: Fair
Temp: 88 ° F
Estimated Age of Dwelling: 6
Parties Present: Homeowner
Occupied: Yes
Type of Dwelling: Single Family
Approximate Square Footage: 2199

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

I. STRUCTURAL SYSTEMS

A. Foundations

Type of Foundation(s): concrete

Comments: See Summary Page

B. Grading and Drainage - Comments:

C. Roof Covering Materials

Type(s) of Roof Covering: Asphalt Shingles

Comments: See Summary Page.

Roof Approx Age: 6

Design Life: 20

D. Roof Structures and Attics

Viewed From: entered

Approximate Average Depth of Insulation: 12

Comments:

E. Walls (Interior and Exterior) - Comments:

F. Ceilings and Floors - Comments:

G. Doors (Interior and Exterior) - Comments: See Summary Page.

H. Windows - Comments:

I. Stairways (Interior and Exterior) - Comments:

J. Fireplaces and Chimneys - Comments:

K. Porches, Balconies, Decks, and Carports - Comments: See Summary Page.

L. Other - Comments:

II. ELECTRICAL SYSTEMS

A. Service Entrance and Panels - Comments:

B. Branch Circuits, Connected Devices, and Fixtures

Type of Wiring: copper

Comments:

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS

A. Heating Equipment

Type of Systems: Forced Air

Age: 6

Design Life: 20

Energy Sources: Natural Gas

Comments:

B. Cooling Equipment

Type of Systems: Central

Age: 6

Design Life: 15

Energy Sources: Electric

Comments: See Summary Page.

C. Duct Systems, Chases, and Vents - Comments:

IV. PLUMBING SYSTEM

A. Plumbing Supply, Distribution Systems and Fixtures

Location of water meter: street

Location of main water supply valve: right wall

Static water pressure reading: 60

Comments: See Summary Page.

B. Drains, Wastes, and Vents - Comments:

C. Water Heating Equipment

Energy Sources: Natural Gas

Age: 6

Design Life: 10

Capacity: 50 Gallons

Comments:

D. Hydro-Massage Therapy Equipment - Comments:

E. Other - Comments:

V. APPLIANCES

A. . Dishwashers - Comments:

B. . Food Waste Disposers - Comments:

C. . Range Hood and Exhaust Systems - Comments:

D. . Ranges, Cooktops, and Ovens - Comments:

E. . Microwave Ovens - Comments:

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

F. Mechanical Exhaust Vents and Bathroom Heaters - Comments:

G. Garage Door Operators - Comments:

H. Dryer Exhaust Systems - Comments:

I. Other - Comments:

VI. OPTIONAL SYSTEMS

A. Landscape Irrigation (Sprinkler) Systems - Comments:

B. Swimming Pools, Spas, Hot Tubs, and Equipment

Type of Construction:

Comments:

C. Outbuildings - Comments:

D. Private Water Wells (A coliform analysis is recommended.)

Type of Pump:

Type of Storage Equipment:

Comments:

E. Private Sewage Disposal (Septic) Systems

Type of System:

Location of Drain Field:

Comments:

F. Other - Comments:

PROPERTY INSPECTION REPORT SUMMARY

Record on this summary page, the corrective actions(s) required for all items determined to be defective, including the estimated costs of repairs, and explain any items reported as "Not Inspected." Note these are estimates only and are NOT bids, nor intended to be used as such.

Section	Remarks
Structural Systems	<p>Roof Covering Materials #1 Remarks: Limited assessment of the roof due to design.</p> <p>Doors (Interior and Exterior) Problem: The trim at the rear door is rotted. Corrective Action: Contractor to assess all trim around the home and repair / replace all affected trim. Obtain a cost estimate from a qualified and insured contractor.</p> <p>Porches, Balconies, Decks, and Carports Problem: A crack was observed in the rear patio. Corrective Action: Contractor to repair / seal the crack in the patio.</p>
Plumbing Systems	<p>Water Supply System and Fixtures Problem: Backflow prevention is missing at the rear faucet. Corrective Action: Plumber to install backflow prevention at all exterior faucets.</p>

Buyer's Initials: _____ / _____

Transferee(s): Amanda Guza
Transferee Property Address: 106 Anchusa St
City/State/Postal Code: Lake Jackson, TX 77566

**Estimated cost to correct items identified in this Property Inspection as defective and/or items that may require attention are NOT bids and do not give rise to performance obligations on the part of the ReloOlogy Inspection Management Services, LLC. Estimates are not provided in localities where prohibited.*

Client: Graebel Companies - CO

Client File #: APROA377362

THIS FORM IS USED IN CONJUNCTION WITH THE TREC PROPERTY INSPECTION REPORT
AND IS NOT INTENDED FOR USE NOR IS IT TO BE RELIED UPON BY ANY PARTY OTHER THAN THE CLIENT
© 2008, ReloOlogy Inspection Services, LLC

Buyer's Initials: _____ / _____

Customer: Graebel Companies - CO

Attn: Jill Nash

Date Inspected: 9/18/2020

Transferee:

Amanda Guza

106 Anchusa St

Lake Jackson, TX 77566

Inspection Type: Home Inspection - TREC

Customer File Number: APROA377362

ReloOlogy Number: 81252

*** Note: pictures with a RED border indicate a potential hazard, problem or defect ***



Front Elevation



Attic



Attic



Front Entry

Buyer's Initials: _____ / _____

Customer: Graebel Companies - CO

Attn: Jill Nash

Date Inspected: 9/18/2020

Transferee:

Amanda Guza

106 Anchusa St

Lake Jackson, TX 77566

Inspection Type: Home Inspection - TREC

Customer File Number: APROA377362

ReloOlogy Number: 81252

*** Note: pictures with a **RED** border indicate a potential hazard, problem or defect ***



Roof



Roof



Roof



Roof

Customer: Graebel Companies - CO

Attn: Jill Nash

Date Inspected: 9/18/2020

Transferee:

Amanda Guza

106 Anchusa St

Lake Jackson, TX 77566

Inspection Type: Home Inspection - TREC

Customer File Number: APROA377362

ReloOlogy Number: 81252

***** Note: pictures with a RED border indicate a potential hazard, problem or defect *****



Front Elevation



Roof



Roof



Roof

Buyer's Initials: _____ / _____

Customer: Graebel Companies - CO

Attn: Jill Nash

Date Inspected: 9/18/2020

Transferee:

Amanda Guza

106 Anchusa St

Lake Jackson, TX 77566

Inspection Type: Home Inspection - TREC

Customer File Number: APROA377362

ReloOlogy Number: 81252

***** Note: pictures with a RED border indicate a potential hazard, problem or defect *****



Roof



Left Elevation



Left Elevation



Right Elevation

Customer: Graebel Companies - CO

Attn: Jill Nash

Date Inspected: 9/18/2020

Transferee:

Amanda Guza

106 Anchusa St

Lake Jackson, TX 77566

Inspection Type: Home Inspection - TREC

Customer File Number: APROA377362

ReloOlogy Number: 81252

*** Note: pictures with a **RED** border indicate a potential hazard, problem or defect ***



Right Elevation



Storage Building



Rear Elevation



Roof

Buyer's Initials: _____ / _____

Customer: Graebel Companies - CO

Attn: Jill Nash

Date Inspected: 9/18/2020

Transferee:

Amanda Guza

106 Anchusa St

Lake Jackson, TX 77566

Inspection Type: Home Inspection - TREC

Customer File Number: APROA377362

ReloOlogy Number: 81252

*** Note: pictures with a RED border indicate a potential hazard, problem or defect ***



Roof



Rear Elevation



Rear Elevation



Missing Backflow Prevention at Hose Bib

Customer: Graebel Companies - CO

Attn: Jill Nash

Date Inspected: 9/18/2020

Transferee:

Amanda Guza

106 Anchusa St

Lake Jackson, TX 77566

Inspection Type: Home Inspection - TREC

Customer File Number: APROA377362

ReloOlogy Number: 81252

*** Note: pictures with a RED border indicate a potential hazard, problem or defect ***



Rotted Trim at Rear Door & Crack in Rear Patio



A/C Unit



Electric Panel



Electric Panel

Customer: Graebel Companies - CO

Attn: Jill Nash

Date Inspected: 9/18/2020

Transferee:

Amanda Guza

106 Anchusa St

Lake Jackson, TX 77566

Inspection Type: Home Inspection - TREC

Customer File Number: APROA377362

ReloOlogy Number: 81252

*** Note: pictures with a RED border indicate a potential hazard, problem or defect ***



Left Elevation



Attic



Water Heater



Water Heater