

McGown Professional Inspections 4615 North Freeway, Ste. #310 Houston, Texas 77022 (281) 701-5561 www.texasmpi.com

This Professional Inspection Report Has Been Prepared Exclusively For:

Anthony Gair 3914 Grapevine St. Houston TX 77045

Inspector: Steve McGown TREC#9859

McGown Professional Inspections 4615 North Freeway, Ste. #310 Houston, Texas 77022 (281) 701-5561

www.texasmpi.com swm_mpi@yahoo.com

PROPERTY INSPECTION REPORT

Prepared For: Anthony Gair

(Name of Client)

Concerning: 3914 Grapevine St., Houston, TX 77045

(Address or Other Identification of Inspected Property)

By: Steve McGown TREC#9859 Oct 07, 2020

(Name and License Number of Inspector (Date)

(Name, License Number and Signature of Sponsoring Inspector, if required)

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.state.tx.us.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is

Promulgated by the Texas Real Estate Commission (TREC) P.O. Box 12188, Austin, TX 78711-2188, (512) 936-3000 (http://www.trec.texas.gov)

not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods.

Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathrooms, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST) [or other metal gas tubing or piping where requires].

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Page 4 of 35

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms require a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS. CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Property inspected was: Vacant inspection: No other parties present during inspection.

Real Estate Office: Selling Agent:

Weather Condition at Time of Inspection

Weather Condition during inspection: Clear Outside temperature at Arrival: 84°

Outside temperature at Departure: 84°

Cost of inspection services: paid at:

Important Limitations and Disclaimers

This Property Inspection Report reports on only the items listed and only on the current condition of those items as of the date of inspection. This report reflects only if the items inspected are observed to be "operable" or "inoperable" at the time of inspection; that is whether such items are observed to serve the purpose for which they are ordinarily intended, at this time. This report reflects only those items that are reasonably observable at the time of inspection. NO RERPRESENTATION OR COMMENT is made concerning any latent defect or defects not reasonably observable at the time of the inspection or of items which require the removal of major or permanent coverings. For example, but without limitation, recent repairs, painting or covering may conceal prior or present leak damage which is not reasonably observable by the inspector and no representation or comment can be made. NO REPRESENTATION IS MADE CONCERNING ANY OTHER CONDITION OR THE FUTURE PERFORMANCE OF ANY ITEM. NO REPRESENTATION IS MADE AS TO ITEMS NOT SPECIFICALLY COMMENTED UPON. ALL WARRANTIES, EXPRESSED OR IMPLIED, NOT SPECIFICALLY STATED HEREIN ARE EXCLUDED AND DISCLAIMED. If a comment is made concerning the condition of any item, the Client is URGED to contact a qualified SPECIALIST to make further inspections or evaluations of that item. Client must notify McGown Professional Inspections in writing of any complaints within seven (7) days of the date of inspection and must thereafter allow prompt re-inspection of the item in question. Otherwise, all claims for damages arising out of such complaint are waived by Client. If Client institutes any legal action concerning this inspection, and fails to prevail on all causes of action alleged, Client shall be liable to McGown Professional Inspections for all of its attorney's fees incurred in such action. Actual damages for any breach of contract or warranty, negligence or otherwise are limited to the amount of the inspection fee paid. The Client, by accepting this Report or relying upon it in any way, expressly agrees to these Limitations and Disclaimers.

For more information concerning your rights, contact the Consumer Protection Division of the Attorney General's Office, your local District or County Attorney, or the attorney of your choice.

I FULLY and COMPLETELY understand that this inspection is not a warranty or guarantee. This inspection is essentially visual, it is not technically exhaustive, and it does not imply that every defect will be discovered. It is only a statement of opinion and/or condition as of and on this date[].

CLIENT SIGNATURE:	 DATE:

INSPECTED BY: _____ LICENSE #: ____

Page 5 of 35

Report Identification: 3914 Grapevine St. Houston TX 77045

Page 6 of 35

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

I. STRUCTURAL SYSTEMS

Type of Foundation(s): Concrete Slab

Comments:

(If all crawl space areas are not inspected, provide an explanation.)

Crawl Space inspected from:

Performance Opinion:

 \Box At this time, the foundation appears to be supporting the structure and immediate significant repair needs are not evident.

☑ Prior to closing, the foundation should be inspected by a qualified structural engineer, familiar with the soils and construction methods of the region, in order to determine if permanent repairs are required.

Additional Notes (An opinion on performance is mandatory):

Evidence found supports the opinion that the subject foundation has experienced excessive settlement of a differential nature. Evidence includes:

- 1. Exterior brick cracks.
- 2. Interior wall cracks.
- 3. Ceiling cracks.
- 4. Sloping floor.

Having a qualified foundation company further evaluate to determine if permanent repairs are required is recommended.

Note: evidence of previous foundation repairs. It is recommended to attain any records or documents from seller in regards to foundation repairs.



SUGGESTED FOUNDATION MAINTANENCE AND CARE- Proper drainage and moisture maintenance to all types of foundations due to the expansive nature of the area load bearing soils. Drainage must be directed to all sides of the foundation with grade slopes.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
	B. Grading and	Drainage		
	Comments:			
	□ No evidence	of water penetration obs	served at this time	
	□ Water spots	evident	ave been repaired	
	Drainage: Draina	ge DOES NOT appear to	be adequate	
	Additional Notes:			

Page 7 of 35

Report Identification: 3914 Grapevine St. Houston TX 77045

Soil is of reverse grade, creating vulnerability to the accumulation of standing water at the foundation wall, a condition known to be a factor in foundation failure. Re-grading is required.

NOTE: A regular watering plan should be imposed in order to keep the moisture level stable around the entire foundation. Also need to consider the gutter system must be clear of debris and attached properly to divert water from the foundation. Gutters and water diverting systems are a good way to keep water from ponding against the house and please consider that a 6 inch decline is required 10 feet away from the house to ensure that water will not pond against the house.

Report Identification: 3914 Grapevine St. Houston TX 77045 Page 8 of 35

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

	Type(s) of Roo Viewed From: \	Roof Covering Materials Type(s) of Roof Covering: Composition Roofing Material Viewed From: Walked some surfaces				
	Comments:					
	Condition: Ro	of should be evaluate	ed by certified roofing compa	any		
	□ Ridge shin	☐ Ridge shingles cracked / missing / loose				
	☑ Shingles c	racked / missing / loo	ose / damaged / worn / aged			
	☐ Valley in n	eed of repair	\square Starter strip missing / im	properly installed		
	□ Fasteners	improperly installed	\square Fasteners not viewed	☐ Nails or staples exposed		
	☐ Caulking n	eeded	☐ Small holes or openings			
	Gutters:	□ Bent Sections	☐ Debris			
	Downspouts:	☐ Missing	☐ Extension/splash block r	nissing		
	Note: This insp	ection does not warr	ant against future roof leaks	s.		
	Additional Note	s: (This inspector is	not a roofing expert. Client	should have a roofing company		

Roof/shingles appeared to be showing signs of age. Observed damaged/missing shingles.

inspect the roof for further evaluation if the Client so chooses)



Page 9 of 35

I=Inspected NI=Not Inspected NP=Not Present **D=Deficient** NI NP D D. Roof Structure and Attics Viewed From: From opening only Comments: Approximate Average Thickness of Insulation: 0" to 4" Attic Ventilation Type: Soffit vents; Ridge vents Attic Attic Insulation: Loose fill (aged) Roof Ventilation observed: Yes Condition: Ventilation adequate ☑ Ridge / Rafter sag noted ☐ Water leaks noted ☐ Previous repairs noted ☐ Vermin activity noted Additional Notes:

Note: some areas of the attic were not observed due to limited crawl space. Suggest installing attic ladder at the garage.

Evidence of roof sag at various locations. Cracked/damaged rafters were observed. Recommend further evaluation by a qualified contractor.







I NI NP D







Fascia trim panels appeared to be loose at several locations.





I NI NP D

Attic ladder was found damaged (unable to close).



I=Inspected NI=Not Inspected **NP=Not Present D=Deficient** NI NP D E. Walls (Interior and Exterior) Comments: Prevalent exterior siding: Brick Veneer Interior Wall: ☑ Water stains / damage ☑ Small drywall cracks ☐ Large drywall cracks ☐ Mildew ☑ Holes ☑ Previous repairs noted **Exterior Wall** ☐ Water stains / damage ☑ Small cracks ☐ Large cracks ☐ Weepholes missing / blocked ☐ Rotted / exposed wood ☑ Previous repairs noted ☐ Paint chipping ☑ Damage to trim, door, siding Additional Notes:

Evidence of damaged trim at the garage exterior door.



Separation was observed at the garage trim board & garage exterior door, a condition normally associated with foundation movement.





I NI NP D

Separation at window frame & exterior wall was found, a condition normally associated with foundation movement.



Stair step pattern of brick/mortar separation was found, a condition normally associated with foundation movement.



Large opening was found at the exterior wall (front corner).



I NI NP D

Evidence of damaged sheetrock at the bedroom & garage.





Interior wall cracks were observed at various locations. Also separation was observed where interior walls intersect. Settlement appears to be the cause.







☐ Rotting evident

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

High moisture content appears to be evident at both bathrooms (near toilet). Note: these areas were found to be small areas & there are no visual stains or discoloration; however, close monitoring is recommended.





Due to conditions found with the exterior & interior walls, having a qualified contractor further evaluate is recommended.

$\overline{\mathbf{Q}}$			$\overline{\mathbf{V}}$	F.	Ceilings	and	Floors
-------------------------	--	--	-------------------------	----	-----------------	-----	---------------

Comments:

☐ Water stains / damage ☐ Holes and openings

☑ Tiles – cracked / damaged / loose / missing

☐ Vinyl damage ☑ Slight sloping

Additional Notes:

Tile floors were found cracked throughout the house.



Page 16 of 35

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
	G. Doors (Interior Comments: Interior: ☑ Damage ☐ Holes and ☐ Rotting ev	openings	Location(s): [] [] []	
	☐ Not closing ☐ Hardware ☐ Gaskets Exterior:	g properly damage / inoperative	[] [] []	
	□ Damaged□ Hollow□ Holes and□ Rotting ev□ Not closing	ident g properly damage/inoperative	Location(s): []	
	Garage Door: ☐ Damaged Additional Notes:	☐ Bent panel	☐ Entry door damaged	

Interior doors throughout the house appeared to be missing (not lathing properly) or showing signs of deterioration.

Garage exterior door appeared to be showing signs of deterioration.



I NI NP D

Door knobs were found loose (back door).



Weather stripping is missing at the garage entry door & back door.





Door trims were found damaged.



I=Inspected NI=Not Inspected NP=Not Present **D=Deficient** NI NP D H. Windows Comments: ☑ Window inoperative ☑ Cracked window ☑ Broken window ☐ Moisture between panes ☐ Caulking/glazing needed ☐ Missing pane Locations: throughout Screens: ☐ Torn □ Bent ☐ Holes ☑ Missing Additional Notes:

Evidence of damaged/missing windows.









Page 19 of 35

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	I. Stairways (Inter Comments:	ior and Exterior)	
	J. Fireplace and C Comments: Type of fireplace Damper: Firebox:	Fuel So missing behind face brid ☐ Soot t ☐ Heal	
	K. Porches, Balco Comments: Rotting evident Trip Hazard Areas inaccessib Note: Structural load Additional Notes:	☐ Insect Damage ☐ Loose boards	☐ Wood/soil contact☐ Handrail/railing missing/damaged
	L. Other Comments:		

I NI NP D

II. ELECTRICAL SYSTEMS

 A. Service Entrance and Panels Comments: Main panel location: Exterior Wall □ Improper panel location						
Panel Condition: Damaged/rus			e panel labeling			
☐ Burned wires	□ Double-lug	•	☐ Defective breakers			
Type of wiring: Copper	J					
ARC Fault (Refer to OP-I form	1)					
ARC Outlet location(s):	´ []	☐ Missing	□ Not tripping			
` '	i i	☐ Missing	☐ Not tripping			
	ίi	☐ Missing	☐ Not tripping			
	ii	☐ Missing	☐ Not tripping			
Grounding Electrode present:		J	11 3			
Note: All systems in the house ☑ Due to defects observed, re						

☐ Due to aluminum wiring being found, recommend service and complete system check by licensed electrician

Additional Notes:


electrician


Overhead clearance at entrance cables is less than the required 10 feet minimum. Weather head needs to be raised.





Bridge mechanism for the 240-volt breaker is missing. Safety hazard.






Page 21 of 35

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

30-amp breaker was found installed on a 120-volt circuit. Typically 30-amp breakers are used for 240-volt circuits.



Page 22 of 35

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient		
I NI NP D					
		s, Connected Device	s, and Fixture	es	
	Type of Wiring: Cop	oper			
	Comments:				
	Receptacle Type:	□ 2 prong 3 prong	□ aluminum v	wiring observed	
	Ground Fault Circui	it Interrupter (GFCI) (Refei	to OP-I form)		
	GFCI Outlet location	n(s): Bathroom:	☑ Missing	□ Not tripping	
		Kitchen:	☑ Missing	□ Not tripping	
		Wet Bar:	☐ Missing	□ Not tripping	
		Garage:	☑ Missing	☐ Not tripping	
		Exterior:	☑ Missing	□ Not tripping	
	GFCI Reset Location	on(s): []	-		
	☐ Loose / broken /	inoperative outlet	☐ Loose / bro	oken / inoperative switch	
	☐ Loose / broken /	inoperative light			
	☐ Smoke detector i	inoperative	□ Ceiling fan	inoperative	
	☐ Improper wiring	. □ Exposed wir	e 🗆 Double-lug	iging	
	☐ Reverse Polarity	☑ Open ground	d		
	☐ Wire splices / op			op detected	
	Additional Notes:	•	ŭ	•	

Note: GFCI protection is absent at the kitchen, bathrooms, & exterior. Recommend upgrade.

Note: smoke alarms were absent at bedrooms. Recommend upgrade.

Open grounds or ungrounded outlets were observed throughout the house. Having a licensed electrician further evaluate this condition is recommended.





NI=Not Inspected

Page 23 of 35


D=Deficient

NP=Not Present

I NI NP D

I=Inspected

Light fixtures in the bedroom closets lack the required protective globes or covers.



Report Identification: 3914 Grapevine St. Houston TX 77045 Page 24 of 35

I=Inspected NI=Not Inspected **NP=Not Present D=Deficient** I NI NP D

III. HEATING, VENTING, AND AIR-CONDITIONING SYSTEMS A. Heating Equipment

Type of Systems: Forced Air System Energy Sources: Gas Comments: ☐ Heat pumps were not inspected since outside temperature is above 70°F ☑ Heating unit(s) were inspected but were not operated since the ambient temperature exceeds 70°F. Unit 1: Thermostat Location: Rear hallway □ Not level ☐ Not registering properly Condition: ☐ Loose Filter Type: replaceable Condition: Deficient ☐ Rust on burner ☐ Flame inconsistent ☐ Pilot not lit Gas: ☐ Improper venting ☐ Copper gas line ☐ No gas shut-off ☐ Gas leak ☐ Air blowing in burner chamber ☐ Gas line not supported Electric:

Not on □ Inoperable Blower: ☐ Fan loose ☐ Limit switch missing/inoperable ☐ Noisv ☐ Burned wires inside blower Additional Notes:

☐ Due to defects observed, recommend service by qualified H.V.A.C Service Company Note: Gas fired heat exchangers cannot be thoroughly inspected for deficiencies without disassembly. RECOMMEND MAINTENANCE AND SERVICE PRIOR TO USE.

Report Identification: 3914 Grapevine St. Houston TX 77045 Page 25 of 35

I=In	spec	tea		NI=	Not Insp	ected N	P=Not Present	D=Deficie	ent	
ı	NI	NP	D							
\square			V	B.	Type of Comme	Heat pumps a	ventional are operated in on ng unit(s) were ins low 60°F		not oper	rated since the ambient
				Return		Supply 70°	Δ Temperatur	e 8°		
					Unit 1:			ure differential sh	nould fall	between 15°F & 20°F for
						proper cooling Compressor: Impr Condenser: Condensate I	☐ Not on oper clearance ☐ Fan not on			☐ Not shutting off☐ Inoperative☐ Noisy
					A ddition	Primary: □ Tra Secondary:	☐ Clogged ay debris / standin ☐ Does not ex tion: side	ist □ Not :	☐ Tray readily vi	
					Auditioi	iai ivoles.				

Supply/return air temperature differential readings were found out of range. Readings are taken with a simple thermometer or infrared temperature-sensing gun at the appropriate return air plenum and supply registers. Differentials less than 15 degrees may simply indicate low refrigerant charge, if no other malfunction is present.

Insulation at the primary drain line (evaporator coil) was found damaged/missing. Should be properly insulated (first 12 feet) to prevent condensation/moisture penetration.



I NI NP D

A/C refrigerant line (low-pressure line insulation) was found exposed to the outdoor elements. Installing metal flashing along exterior wall may be desired to prevent the vulnerability of damage.



☑ Due to defects observed, recommend service by qualified H.V.A.C Service Company Note: RECOMMEND MAINTENANCE AND SERVICE PRIOR TO USE.

Page 27 of 35

D=Deficient

I=Inspected NI NP D

C. Duct Systems, Chases and Vents

Comments:

NI=Not Inspected

☐ Openings evident (return)

☐ Covering(s) torn / missing

Additional Notes:

Register vents were found dirty. Suggest having the ducts cleaned or serviced.

NP=Not Present





☐ Openings evident (supply)

Page 28 of 35

I=Inspected NI=Not Inspected NP=Not Present **D=Deficient**

I NI NP D

IV. PLUMBING SYSTEM

\square \square \square	A. Plumbing Supply,	Distribution S	ystems and Fixtures
-------------------------------	---------------------	----------------	---------------------

Location of water meter: by the street

Location of main water supply valve: Side yard

Static water pressure reading: [##]

Comments:

Note: Water pressure reported was a cursory test, the pressure can vary throughout the day.

Type of supply lines: Galvanized Iron

Anti Siphon / Back Flow / Air Gap(s): Not Present

Kitchen Sink: ☐ Faucet leak □ Drain leak ☐ Spray leak

> ☑ Drain clogged ☑ Sink leak ☐ Low / no

pressure

Additional Notes:

Leak was observed at the sink drain pipe connection. Recommend further evaluation by a qualified Plumber.



Report Identification: 3914 Grapevine St. Houston TX 77045 Page 29 of 35

•				9
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				

Hall:			
Bath Sinks:			
☑ Drain leak □ Slow drain	☐ Faucet leak	☐ Faucet/knob missing	
☐ Faucet/knob damaged	☐ Stopper missing/non-functioning		
Bathtubs:		_	
□ Drain leak □ Slow drain	☐ Faucet leak	☐ Faucet/knob missing	
☐ Faucet/knob damaged	☐ Stopper missing/	non-functioning	
☐ Diverter leak	☐ Diverter non-functioning		
☐ Grout/caulk missing	☐ Water damage		
Shower:	_		
□ Drain leak □ Slow drain	☐ Faucet leak	☐ Faucet/knob missing	
☐ Faucet/knob damaged	☐ Head leak	☐ Pan leak	
□ Door not closing properly	☐ Water damage	☐ Grout/caulk missing	
Commodes:	_	_	
☑ Loose on floor ☐ Fills slow	□ Not flushing prop	erly Leaking	
□ Not turning off			
Additional Notes:			

Leak was observed at the sink drain pipe connection. Recommend further evaluation by a qualified Plumber.




Report Identification: 3914 Grapevine St. Houston TX 77045 Page 30 of 35

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

<u>Master</u>			
Bath Sinks:			
☑ Drain leak ☐ Slow drain	☐ Faucet leak	☐ Faucet/knob missing	
☐ Faucet/knob damaged	☐ Stopper missing/non-functioning		
Bathtubs:		-	
□ Drain leak □ Slow drain	□ Faucet leak	☐ Faucet/knob missing	
☐ Faucet/knob damaged	□ Stopper missing	/non-functioning	
☐ Diverter leak	☐ Diverter non-functioning		
☐ Grout/caulk missing	☐ Water damage		
Shower:			
□ Drain leak □ Slow drain	☐ Faucet leak	☐ Faucet/knob missing	
☐ Faucet/knob damaged	☐ Head leak	□ Pan leak	
□ Door not closing properly	☐ Water damage	☐ Grout/caulk	
missing			
Commodes:			
☑ Loose on floor □ Fills slow	□ Not flushing properties	perly Leaking	
□ Not turning off			
Additional Notes:			

Leak was observed at the sink drain pipe connection. Recommend further evaluation by a qualified Plumber.



Report Identification: 3914 Grapevine St. Houston TX 77045 Page 31 of 35

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				

Outside Faucets:			
	🗆 🗖	□ D	□ 0:-I-
□ Leak Locatio	n: 🗆 Front	□ Rear	☐ Side
□ Inoperative	□ Front	□ Rear	☐ Side
☐ Missing/broken handle	□ Front	□ Rear	☐ Side
☑ Missing anti-siphon	□ Front	□ Rear	☐ Side
Additional Notes:			

Large amount of standing water was found near main water shut-off.
Underground leak appears to be evident. Recommend further evaluation by a qualified Plumber.



 $\ \square \ \square \ \square \ \square \ \square$ B. Drain, Wastes and Vents

Comments:
Additional Notes:

Cover is missing at the laundry drain pipe.



I NI NP D

☑ □ □ ☑ C. Water Heating Equipment

Energy Source: Gas Capacity: 40 Gallons

Comments:

(Refer to OP-I form)

Unit 1:

Location: Garage

Safety Pan and Drain Installed: No

Garage Unit(s): Physically Protected: Yes 18 inch Floor Clearance: No

Corrosion at supply connections: Yes

Gas Unit:

Gas Shut Off Valve: Present Improper venting: Yes

Additional Notes:

Evidence of excessive corrosion at supply connections.





Flue vent pipe was found damaged/detached at the attic space (Hazardous condition).



Due to these conditions found with the water heater, service by a qualified Plumber is recommended.

Report Identification: 3914 Grapevine St. Houston TX 77045 Page 33 of 35

D=Deficient I=Inspected NI=Not Inspected NP=Not Present I NI NP D D. Hydro-Massage Therapy Equipment Comments: GFCI condition: **GFCI** Reset Location: Underside of tub readily accessible: □ Leak ☐ Switches loose ☐ Unsafe location ☐ Debris in port openings Additional Notes: E. Other Comments:

Page 34 of 35

I=Inspected	NI=Not Inspected NP=Not Present D=Deficient
I NI NP D	V ADDITANOTO
	V. APPLIANCES
	A. Dishwashers Comments: Checked and tested @ [##]° Inoperative Leak High loop missing Noisy Soap tray defective Rust Rollers missing Trays damaged Loose in cabinet Door damage Additional Notes:
	B. Food Waste Disposers Comments: ☑ Inoperative □ Leak □ Stuck hammers □ Poorly secured □ Vibration □ Noisy □ Damaged splash guard Additional Notes:
	C. Range Hood and Exhaust Systems
	Comments: □ Filter Missing □ Vents into attic □ Inoperative □ Damaged switches □ No Light □ Noisy Additional Notes:
	D. Ranges, Cooktops, and Ovens
	Comments: Type of Range/ Cooktop: Type of Oven: Gas Shut Off Valve: Branch Line:
	☐ No gas shut-off in room ☐ Gas leak ☐ Anti-tip missing
	Cooktop: Not lighting off pilot
	E. Microwave Ovens Comments: □ Light inoperative □ Does not heat properly Additional Notes: □ Door seal damage □ Microwave inoperable □ Door handle missing/damaged

Report Identification: 3914 Grapevine St. Houston TX 77045 Page 35 of 35

I=Inspected	NI=Not Inspected NP=Not F	Present	D=Deficient
I NI NP D			
	F. Mechanical Exhaust Ve		
	 □ Exhaust fan inoperative □ Cover missing □ Heater inoperative Additional Notes: 	☐ Noisy☐ Damaged☐ Improper he	☐ Exhaust fan light inoperative ☐ Condensation / vent problems ater location
	G. Garage Door Operators Comments: Auto reverse block test acceptable: Electric eye reverse test acceptable: ☐ Improper sensor height (more than six inches above garage floor) ☐ Opener Inoperative ☐ Opener Damaged Additional Notes:		
	H. Dryer Exhaust Systems Comments:	S	

ADDITIONAL COMMENTS

Note: Galvanized pipes are usually found in older homes. Commonly, these pipes will rust from the inside out. The pipes can corrode at any time however this rust accumulates over decades. Suggest that a qualified Plumber service and or evaluate the entire system and repair as needed to ensure an efficient and safe system.