

LEGEND

- ◆ POWER POLE
- FL FLOW LINE
- BH BULKHEAD
- EW EDGE OF WATER
- R.O.W. RIGHT-OF-WAY
- I.R. IRON ROD
- R.C.P. REINFORCED CONCRETE PIPE
- CONC. CONCRETE

Notes:

- 1.) This property lies in Zone "VE", (BFE-15') and (BFE-18'), defined by FEMA as coastal flood zone with velocity hazard (wave action); base flood elevations determined, as scaled from Flood Insurance Rate Map Community-Panel Number 48201C1095 L, map revised June 18, 2007.
- 2.) This survey has been prepared without the benefit of a current title report or title commitment. This property may be subject to matters of record not reflected hereon which such a title report or title commitment may reveal.
- 3.) Elevations expressed hereon are based on TSARP RM 010010, Elev.=5.89', NAVD88 (2001 adjustment).

Survey Prepared for: Brint Construction

July 8, 2013

Survey of Lots One (1), Two (2), Three (3), Four (4) and Five (5), Block Eighty-One (81) of **TOWN OF SEABROOK**, a Subdivision in Harris County, Texas, according to the map or plat thereof recorded in Volume 1, Page 50, of the Map Records in the Office of the County Clerk of Harris County, Texas.

I hereby certify that on the above date, the herein described Lots, together with improvements located thereon, were surveyed on the ground and under my direction, and that this map, together with dimensions as shown hereon, accurately represents the facts as found on the ground this date.


Dale L. Hardy

GeoSury

Registered Professional
Land Surveyors

P.O. Box 246, League City, Texas 77574
281-554-7739 409-765-6030 Fax: 281-554-6928

GeoSury, LLC



Dale L. Hardy
Registered Professional
Land Surveyor 4847

