

LC Home Inspections, PLLC Property Inspection Report



Property Address 12407 Pepper Creek Lane Pearland, TX 77584

Inspection prepared for: Jenna L. Hazzard Date of Inspection: 01/11/2018

Age of Home: 1 year

Built: 2017

Size: 2,686 Sq. Ft

Inspector:Leonides Castillo License #: 21828 Phone: (281)734-4433 Email: castlelion143@outlook.com

PROPERTY INSPECTION REPORT

| Prepared For: | Jenna L. Hazzard | | | | |
|----------------------|------------------------------------------------------------------------------------------------------------------|----------------------|--|--|--|
| - | (Name of Client) | | | | |
| Concerning: | g: <u>12407 Pepper Creek Lane, Pearland, TX 77584</u> (Address or Other Identification of Inspected Property) | | | | |
| By: | Leonides Castillo, Lic #21828 (Name and License Number of Inspector) | 01/11/2018 (Date) | | | |

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREClicensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER

Promulgated by the Texas Real Estate Commission (TREC) P.O. Box 12188, Austin, TX 78711-2188 (512) 936-3000 (<u>http://www.trec.texas.gov</u>).

ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods. Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathroom, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as, smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms requires a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

| ADDITIONAL INFORMATION PROVIDED BY INSPECTOR | | | | | | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|--------------------------------------------------------|-------------------|------------------------------|--|--|
| Present at Inspection: | Buyer | Listing Agent | ☑ Buyer's Agent | Occupant | | |
| Building Status: | ✓ Vacant | Owner Occupied | ☐ Tenant Occupied | □ Other | | |
| Weather Conditions: | 🗆 Fair | Cloudy | Rain Outside Ter | np Range: <u>67°F - 70°F</u> | | |
| Utilities On: | 🗹 Yes | □ No Water | □ No Electricity | 🗆 No Gas | | |
| House Faces: | □ North | ☑ South | East | □ West | | |
| Special Notes: | | | | | | |
| | INAC | | UCTED AREAS | | | |
| □ Sub Flooring □ Sub Floors Covered □ Floors Covered or Freshly Painted □ Walls/Ceilings Covered or Freshly Painted □ Behind/Under Furniture and/or Stored Items Home staged for viewing □ Attic Space is Limited - Viewed from Accessible Areas □ Plumbing Areas - Only Visible Plumbing Inspected □ Siding Over Older Existing Siding □ Crawl Space is limited - Viewed From Accessible Areas | | | | | | |
| | • | included with this report; r intrusion is recommend | | • | | |

NOTICE: THIS REPORT IS PAID FOR BY AND PREPARED FOR THE CLIENT NAMED ABOVE. THIS REPORT IS NOT VALID WITHOUT THE SIGNED SERVICE AGREEMENT AND IS NOT TRANSFERABLE.

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient |
|-------------|----------------------------------------------------------------------------------|--------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| I NI NP D | | | |
| | I. | STRUCTURAL S | SYSTEMS |
| | A. Foundations <i>Type of Foundation(s)</i> : Pos <i>Comments</i> : | st Tension Slab on Grade | ç |
| | Performance Opinion: | (An opinion on performa | nce is mandatory) |
| | The foundation | appears to be perforr | ning the function intended |
| | structures, and differentian visual observations of ac | al movements are likely t ccessible and unobstructe | l other adverse factors are able to effect to occur. The inspectors opinion is based on ed areas of the structure at the time of the cannot be predicted or warranted. |
| | SUGGESTED FOUNDA | TION MAINTENANCE & | CARE - Proper drainage and moisture |

JGGES I ED FOUNDATION MAINTENANCE & CARE - Proper drainage and moisture maintenance to all types of foundations due to the expansive nature of the area load bearing soils. Drainage must be directed away from all sides of the foundation with grade slopes. In most cases, floor coverings and/or stored articles prevent recognition of signs of settlement cracking in all but the most severe cases. It is important to note, this was not a structural engineering survey nor was any specialized testing done of any sub-slab plumbing systems during this limited visual inspection, as these are specialized processes requiring excavation. In the event that structural movement is noted, client is advised to consult with a Structural Engineer who can isolate and identify causes, and determine what corrective steps, if any, should be considered to either correct and/or stop structural movement.

 $\boxdot \Box \Box \checkmark$

B. Grading and Drainage

Comments:

 \checkmark 1. Gutter splash block under gutter downspout not placed correctly- water should be allowed to flow freely away from the foundation. In current position, water will not run away from the house where it can pool and cause damaged to the foundation

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient | |
|-------------|------------------|----------------|-------------|--|
| I NI NP D | | | | |



 \blacksquare 2. Shrubs around foundation may cause future foundation problems.



 $\boxdot \Box \Box \blacksquare$

C. Roof Covering Materials

Type(s) of Roof Covering: Composition Asphalt Shingles *Slope:* 7:12 *Viewed From*: Roof Level *Comments*:

☑ 1. Torn, damaged, perforated or missing ridge cap shingles - shiingle should be repaired to prevent further damage and potential area for water intrusion.

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient |
|-------------|------------------|----------------|-------------|
| I NI NP D | | | |
| | | | |



 \square 2. Exposed or lifting nail heads - Nail heads should sealed. Unsealed head will rust and lead to possible moisture intrusion.



 \square 3. Paint peeling from roof flashing where roof meets exterior wall - painting of flashing any roof penetrations will prevent deterioration of flasing.



☑ 4. Missing step flashing where a roof intersects at exterior wall - Missing flashing will provide an opening for water intrusion and/or insect or rodent infestation

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient |
|-------------|------------------|----------------|-------------|
| I NI NP D | | | |



☑ 5. Lifting of roof shingle - potential area for water intrusion



<u>Minor repairs to the roofing are recommended</u>. Damaged roofing material should be repaired. All roof penetrations and flashing should be examined and sealed or painted as necessary

$\boxdot \Box \Box \blacksquare$

D. Roof Structures and Attics

Viewed From: Entered the Attic *Approximate Average Depth of Insulation*: Approximately 12 inches *Approximate Average Thickness of Vertical Insulation*: None found *Comments*:

 \square 1. The attic ladder was missing fasteners.- Attic ladder brackets are designed for specifict location of fasteners. Manufacturers typically require the use of 16d nails or 1/4" x 3" lag bolts be installed through the corner brackets for personal safety. This condition should be further evaluated and corrected as necessary

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient | |
|-------------|------------------|----------------|--------------------|--|
| I NI NP D | | | | |



$\boxdot \Box \Box \boxdot$

E. Walls (Interior and Exterior) Comments:

Interior Walls:

☑ 1. Minor cracks in wall joints or trim




| =Inspected | NI=Not Inspected | NP=Not Present | D=Deficient |
|------------|----------------------|--------------------------|-------------------------------------------------------------------|
| NI NP D | | | |
| | Floor/wall trim wall | in corner of living room | Hole in corner in storage area under stairs Master Bath Closet |
| | | | |

moulding above bathroom doorway to Master Bath

 \blacksquare 2. Incomplete seal to wall in garage

Separation of trim from ceiling

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient |
|-------------|------------------|----------------|-------------|
| I NI NP D | | | |
| | | | |



 \blacksquare 3. Mortar is separated or missing in some areas

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient | |
|-------------|------------------|----------------|-------------|--|
| I NI NP D | | | | |
| | | | | |





in mor

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient | |
|-------------|------------------|----------------|-------------|--|
| I NI NP D | | | | |







 \blacksquare 4. Caulking / sealant is separated or missing in some areas all expansion joints



| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient | |
|-------------|------------------|----------------|-------------|--|
| I NI NP D | | | | |



 \blacksquare 5. Possible water/insect penetration areas at exterior walls - all exterior wall penetrations should be sealed to prevent water or insect intrusion






| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient |
|-------------|------------------|------------------------------------|-------------|
| I NI NP D | | | |
| | | A CONTRACTOR OF THE ACCOUNT OF THE | |



| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient | |
|-------------|------------------|----------------|-------------|---|
| I NI NP D | | | | |
| | | | | 3 |



 \boxdot 6. Rust forming on steel lintles over doors and windows - The steel lintels should be treated and repainted to prevent further rusting. Over time, additional rusting lintels will expand and form cracks in the mortar.

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient | |
|-------------|------------------|----------------|--------------------|--|
| I NI NP D | | | | |
| | | | | |



The Interior and exterior walls are examined for signs and symptoms of adverse structural integrity and water penetration. Exterior walls are visually inspected for adverse performance issues, particularly at supporting members and common installation failures. Moisture intrusion is virtually impossible to detect if there are no active and visual signs. Therefore, your inspector will inspect for flashing deficiencies and common problem areas for signs of moisture damage. The interior is generally always obscured by wall coverings and paint. Insulation, plumbing, and electrical items behind these walls cannot be inspected. Your inspector will primarily focus on structural movement and installation deficiencies. Cosmetic items are not considered or annotated in the report unless they correlate to a more significant problem.

$\boxdot \Box \Box \Box$

F. Ceilings and Floors

Comments:

All components were found to be performing and in satisfactory condition on the day of the inspection.

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient | |
|---------------------------------------------|---------------------------|----------------|-------------|--|
| I NI NP D | | | | |
| $\blacksquare \square \square \blacksquare$ | G. Doors (Interior and Ex | terior) | | |

Comments:

Interior Doors

All components were found to be performing and in satisfactory condition on the day of the inspection.

Exterior Doors

✓ 1. Exterior door thresholds not sealed properly



 \square_2 . Self-closing hinges on the door that provides access to the home via the garage were not properly adjusted. Self-closing hinges serving the garage are intended to ensure garage door fire separation is intact in case of fire and provide a legitimate barrier to prevent Carbon Monoxide from entering into the home from the garage. Recommend adjusting to provide better performance of hinges.




Garage Doors

Type: Metal **Operation Type:**

U Wood ☐ Fiberglass ☐ Doors / panels are damaged □ Manual ☑ Electric Opener

 \blacksquare 3. Missing garage door hardware

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient |
|-------------|------------------|----------------|-------------|
| I NI NP D | | | |





Exterior doors should be installed to provide Weather tightness and reliable security. Weather tightness, locking mechanisms, glass panes, thresholds, and the overall condition of your doors are inspected. In addition, garage doors are inspected for fire safety compliance.

Interior doors provide privacy and noise reduction. They may also be an indicator of structural movement within the home. Interior doors should also allow for the adequate flow of conditioned air between passages. Interior doors are inspected for movement free of binding and proper latching. Mechanical hardware is also inspected.

H. Windows Comments:

All components were found to be performing and in satisfactory condition on the day of the inspection.

\square \square \square \square I.

I. Stairways (Interior and Exterior)

Comments:

All components were found to be performing and in satisfactory condition on the day of the inspection.

$\overline{\mathbf{A}} \Box \Box \overline{\mathbf{A}}$

J. Fireplaces and Chimneys Comments:

Type of Fireplace:

□ Masonry

Pre-Fabricated

Free Standing

□ Factory

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient | |
|-------------|------------------|----------------|-------------|--|
| I NI NP D | | | | |

- ☑ 1. No gas valve shut-off key available
- ☑ 2. Cardboard spacers found between fireplace stone veneer




$\boxdot \Box \Box \Box$

K. Porches, Balconies, Decks, and Carports *Comments*:

All components were found to be performing and in satisfactory condition on the day of the inspection.

Unknown objects embedded into patio floor - possible termite barrier. It appears home may have been treated for termites. recommend discussion with seller to determine reason and need for future potential maintenance.

| I NI NP D | I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient | |
|-----------|-------------|------------------|----------------|-------------|--|
| | I NI NP D | | | | |



II. ELECTRICAL SYSTEMS

 Image: Comments:

A. Service Entrance and Panels

Main Panel Location:CopperPanel Manufacturer:EatonElectrical System Phase:Consists of a single-phase, three-wire, 120/240 voltFeeder Conductors:CopperCapacity:150 AmpsGas Line Bonding Location:At gas line entering propertyService Type:Underground Service LateralOverhead Service

Main Disconnect Panel

☑ 1. Service lateral conduit not secured properly

| I=Inspected | NI=Not Inspected | NP=Not Present | D =Deficient | |
|-------------|------------------|----------------|---------------------|--|
| I NI NP D | | | | |



Sub Panels

Type of Wire: I Copper

All components were found to be performing and in satisfactory condition on the day of the inspection.

The electrical system has many components that must work in harmony in order to provide your home with electricity. The vast majority of residential homes are supplied with power via two 120 volt wires and one neutral wire, giving your modern home the much needed 240 volts necessary to power appliances like the stove, range, dryer, and HVAC system. Generally, homeowners are responsible for everything that happens after the attachment to the meter. The outlets, switches, fixtures, and grounding system also play a key role in your home's electrical system. Your inspector is limited by many factors on what can and cannot be properly inspected. However, safety of your home and family is of highest priority. We will report every defect that we can verify.

$\boxdot \Box \Box \Box$

B. Branch Circuits, Connected Devices, and Fixtures

Ground Fault Circuit Interrupters (GFCIs)


GFCIs are intended to protect persons from accidental electrocution in areas susceptible to moisture. Installations of these devices in the locations specified are recommended as safety upgrades. These locations include: *All kitchen countertop receptacles, and bathroom receptacles,*

| I=Inspected | NI=Not Inspecte | ed NP | =Not Present | D=Deficient | |
|-------------|-------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|----------------------|------------------------------------------------------------------------------------------------------------|--|
| I NI NP D | | | | | |
| | receptacles for | any overhead g | • | s and <i>all receptacles outlets, including ceiling</i> and the Missing GFCIs per today's standard is a | |
| | Ground Fault C | Gircuit Interrupt (| GFCI) Protection: | | |
| | Bathrooms: | 🗹 Yes 🗆 No | Reset located at: al | l at master bathroom | |
| | Garage: | 🗹 Yes 🗆 No | Reset located at: ga | arage | |
| | Outdoors: | 🗹 Yes 🗆 No | Reset located at: ea | ach outdoor outlet | |
| | Kitchen Island | 🗹 Yes 🗆 No | Reset located at: ki | tchen (2 circuits or devices) | |
| | Outlet and St | witches | | | |
| | All components were found to be performing and in satisfactory condition on th the inspection. ARC Fault Circuit Interrupt Safety Protection | | | | |

| Family Room: 🗹 Yes | □ No | □ Partial | Hallways: | ✓ Yes | 🗆 No | Partial |
|--------------------|------|-----------|-------------|-------|------|---------|
| Dining Room: 🗹 Yes | 🗆 No | Partial | Den/Office: | 🗹 Yes | 🗆 No | Partial |
| Living Room: 🗹 Yes | 🗆 No | Partial | | | | |
| Game Room: 🗹 Yes | 🗆 No | Partial | | | | |

All components were found to be performing and in satisfactory condition on the day of the inspection.

III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS



A. Heating Equipment

Type of System: Central and Zoned *Energy Source*: Gas *Location of Thermostat #1:Wall adjacent to stairs Location of Thermostat #2: Upstairs hall to bedrooms*

Comments:

This component appears to be performing adequately at the time of this inspection. It is achieving an operation, function, or configuration consistent with accepted industry practices.

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient | |
|-------------|------------------|----------------|--------------------|--|
| I NI NP D | | | | |



$\boxdot \Box \Box \blacksquare$

B. Cooling Equipment

Type of System: Central-Zoned Location of thermostat #1: Wall Adjacent to stairs Location of thermostat #2: Upstairs hall to bedrooms Seer/Tonnage Unit#1: 16 Seer, 4 Ton

Comments:

AC Condenser Unit : Supply Air Temp: <u>53</u>°F

Return Air Temp: 63°F

Temp. Differential: <u>10</u>°F

☑ 1. Condenser unit not level or 3" above grade

Refrigerant travels with the lubricating oil through an a/c system. When the condenser is out-of-level, the oil can separate and the compressor may operate without adequate lubrication. Most manufacturer installation manuals specify that the unit be mounted on a level surface. Additionally, refrigerant lines can be stressed

- ☑ 2. Condenser refrigerant and suction lines not capped
- ☑ 3. Recommend cleaning, servicing and / or further evaluation of condenser by a licensed professional

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient | |
|-------------|------------------|----------------|--------------------|--|
| I NI NP D | | | | |



 Image: C.
 Duct Systems, Chases, and Vents

 Comments:
 Comments:

 Type of Ducting:
 Image: Flex Ducting
 Duct Board
 Image: Metal

All components were found to be performing and in satisfactory condition on the day of the inspection.

IV. PLUMBING SYSTEMS

 $\overline{\mathbf{M}} \square \square \overline{\mathbf{M}}$

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient |
|-------------|------------------|----------------|-------------|
| I NI NP D | | | |



Comments:

Water Source: Development Private Sewer Type: Development Private

Sinks Comments:

All components were found to be performing and in satisfactory condition on the day of the inspection.

Bathtubs and Showers Comments:

☑ Lack of access to water supply connections

2015 International Residential Code P2704.1 Access to connections - General

"Slip joints shall be made with an *approved* elastomeric gasket and shall be installed only on the trap outlet, trap inlet and within the trap seal. Fixtures with concealed slipjoint connections shall be provided with an access panel or utility space at least 12 inches (305 mm) in its smallest dimension or other *approved* arrangement so as to provide access to the slip connections for inspection and repair. "

Commodes Comments:

All components were found to be performing and in satisfactory condition on the day of

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient |
|-------------|------------------|----------------|-------------|
| I NI NP D | | | |

the inspection.

Plumbing General Comments:

☑ 1. Rust on exterior gas line - excessive rust will eventually corrode line and lead to gas leak. Rust to the exterior gas line should be removed and painted to prevent further rusting



| $\boxdot \Box \Box \Box$ | B. | Drains, Wastes, and Vents |
|--------------------------|----|---------------------------|
| | | Comments. |

All components were found to be performing and in satisfactory condition on the day of the inspection.

 $\boxdot \Box \Box \Box$

C. Water Heating Equipment

Energy Source: Gas Location of main fuel supply valve: Adjacent to water heater Capacity: Unknown Comments:

This component appears to be performing adequately at the time of this inspection.

D. Hydro-Massage Therapy Equipment *Comments*:

V. APPLIANCES

 $\blacksquare \square \square \square$

A. Dishwashers Comments: This component appears to be performing adequately at the time of this inspection.

 $\boxdot \Box \Box \Box \Box$

B. Food Waste Disposers Comments:

This component appears to be performing adequately at the time of this inspection.

 $\boxdot \Box \Box \boxdot$

C. Range Hood and Exhaust Systems

Comments:

☑ 1. Fan / Motor assembly not secured properly



 $\overline{\mathbf{Q}} \square \square \overline{\mathbf{Q}}$

 D. Ranges, Cooktops, and Ovens Comments:
 Range Type: □ Electric ☑ Gas

Oven(s):

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient | |
|-------------|------------------|---------------------|--------------------|--|
| I NI NP D | | | | |
| | Tested at 350° | °F, Variance noted: | _°F (max 25°F) | |

☑ 1. Inoperative Oven





E. Microwave Ovens

Comments: One cup of water heated for one minute: approx. 170°F



This component appears to be performing adequately at the time of this inspection.

 $\boxdot \Box \Box \Box$

F. Mechanical Exhaust Vents and Bathroom Heaters Comments:

This component appears to be performing adequately at the time of this inspection.

☑ □ □ ☑ G. Garage Door Operators

Comments:

 \square Door locks have not been removed or disabled - failure to disable door lock can

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient | |
|-------------|------------------|----------------|--------------------|--|
| I NI NP D | | | | |

result in signifcant damage to the garage door if accidentally locked and automatic door opener activated.



\square \square \square \square H. Dryer Exhaust Systems

Comments:

Dryer exhaust duct has kink and too many turns for proper exhaust - Dryer will not exhaust properly and lint will accumulate within exhaust duct. This is a potential fire hazard





🗹 🗌 🖾 🗹 A. Landscape Irrigation (Sprinkler) Systems

Comments:

☑ 1. Unable to access zone control valves- access required to check for leaks or drip of control valve. However, rainy weather condition at day of inspection would have prevented accurate assessment

☑ 2. Pop-up sprayers not perpendicular (tilted) to grade and may require adjustment - improper spray head alignment may affect performance

| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient | |
|-------------|------------------|----------------|--------------------|--|
| I NI NP D | | | | |



| I=Inspected | NI=Not Inspected | NP=Not Present | D=Deficient | |
|-------------|------------------|----------------|--------------------|--|
| I NI NP D | | | | |



 \blacksquare 3. Non functioning or sunken pop-up sprayers



☑ 4. pop-up sprayers behind fence



Summary

All

GRADING AND DRAINAGE

- 1. Gutter splash block under gutter downspout not placed correctly
- 2. Shrubs around foundation may cause future foundation problems

ROOF COVERING MATERIALS

- 1. Torn, damaged, perforated or missing ridge cap shingles
- 2. Exposed or lifting nail heads
- 3. Paint peeling from roof flashing where roof meets exterior wall
- 4. Missing step flashing where a roof intersects at exterior wall
- 5. Lifting of roof shingle

ROOF STRUCTURES AND ATTICS

1. The attic ladder was missing fasteners.

WALLS (INTERIOR AND EXTERIOR)

- 1. Minor cracks in wall joints or trim
- 2. Incomplete seal to wall in garage
- 3. Mortar is separated or missing in some areas
- 4. Caulking / sealant is separated or missing in some areas all expansion joints
- 5. Possible water/insect penetration areas at exterior walls
- 6. Rust forming on steel lintles over doors and windows

DOORS (INTERIOR AND EXTERIOR)

Exterior Doors

- 1. Exterior door thresholds not sealed properly
- 2. Self-closing hinges on the door that provides access to the home via the garage were not properly adjusted.

- 3. Missing garage door hardware
- 4. Hole at bottom of metal garage door

FIREPLACES AND CHIMNEYS

- 1. No gas valve shut-off key available
- 2. Cardboard spacers found between fireplace stone veneer

SERVICE ENTRANCE AND PANELS

Main Disconnect Panel

1. Service lateral conduit not secured properly

COOLING EQUIPMENT

- 1. Condenser unit not level or 3" above grade
- 2. Condenser refrigerant and suction lines not capped
- 3. Recommend cleaning, servicing and / or further evaluation of condenser by a licensed professional

PLUMBING SUPPLY, DISTRIBUTION SYSTEMS AND FIXTURES

Plumbing General

1. Rust on exterior gas line

RANGE HOOD AND EXHAUST SYSTEMS

1. Fan / Motor assembly not secured properly

RANGES, COOKTOPS, AND OVENS

Oven(s):

1. Inoperative Oven

GARAGE DOOR OPERATORS

1. Door locks have not been removed or disabled

DRYER EXHAUST SYSTEMS

1. Dryer exhaust duct has kink and too many turns for proper exhaust

LANDSCAPE IRRIGATION (SPRINKLER) SYSTEMS

- 1. Unable to access zone control valves
- 2. Pop-up sprayers not perpendicular (tilted) to grade and may require adjustment
- 3. Non functioning or sunken pop-up sprayers
- 4. pop-up sprayers behind fence