ACCEPTANCE ADDENDUM

Addendum to Purchase Contract dated property located at <u>2410 Montana Blue Drive, Sprii</u> TX 77373-7870, between (Buyer) and NEI Global Relocati					
Company (Se	ller). This offer is hereby accepted subject to the fol	lowing:			
\boxtimes	Subject to the completion of the acquisition of the p and April Sylve.	roperty by NEI Global Relocation Company from Joseph			
\boxtimes	Subject to NEI Global Relocation Company's atta Purchase Contract and all attachments and addenda	ached Addenda which are the ruling documents of this thereto.			
\boxtimes	Subject to the terms of the attached, signed Inspection	on Addendum.			
\boxtimes	Subject to the terms of the attached, signed Inspection	on Disclosure Addendum.			
\boxtimes	Subject to the terms of the attached, signed Radon S	Service Agreement Addendum.			
	Subject to the terms of the attached, signed Lead-Ba	ased Paint Hazards Addendum.			
\boxtimes	Subject to the title commitment and the title policy l	being ordered from Stewart Title Company.			
\boxtimes	Subject to the closing being handled by Rebecca Wi	ipf/(281) 374-8700.			
\boxtimes	Subject to Seller conveying marketable title to the pr	roperty by limited/special warranty deed or its equivalent.			
	the event of a cash sale, Buyer to provide written available for closing) within five (5) calendar days	e letter of pre-qualification from the Buyer's lender (or, in evidence, acceptable to Seller, that all necessary cash is of the acceptance of the Purchase Contract. Examples of are the Buyer(s) name, property address, purchase price,			
\boxtimes	Buyer may not change financing terms or lender with	thout the written consent of Seller.			
	Subject to Arbitration/Mediation clauses being here state of California.	eby deleted from the Purchase Contract except for in the			
	(RESPA) by requiring that all monetary credits, c	ovisions of the Real Estate Settlement Procedures Act oncessions, and allowances be reflected on the Closing tary side agreements. No monetary credits, concessions osing.			
\boxtimes	Subject to no tax adjustments being made after closi	ing.			
	due to a delay by the Buyer or the Buyer's vendors	ate is extended beyond the Purchase Contract closing date (e.g., lender, underwriters, title company). The per diem $0.005 = $50/day$) for each day the closing is extended.			
	Possession by Buyer is subject to receipt by Seller/S funds.	eller's assigned closing representative of non-rescindable			
		nile or electronically via email shall be as legally binding nents, legal and otherwise, for the transfer of this property.			
therefore, Bu		apany and has never physically occupied the property; e condition of the property prior to closing. Seller makes condition of the property.			
IN NO EVEN	IT IS POSSESSION TO BE GIVEN PRIOR TO CL	OSING AND FUNDING.			
Buyer(s) Acc	eptance				
Buyer:		Date:			
Buyer:		Date:			
NEI Global R	elocation Company (Seller)				
By:		Date:			

INSPECTION ADDENDUM TO PURCHASE CONTRACT

The undersigned, parties to a Purchase Contract dated	on the property known as 2	410 Montana Blue
<u>Drive, Spring, TX 77373-7870</u> , hereby mutually agree to the following:		

The property being sold is not new, and Buyer hereby acknowledges that there has been no representation by the Seller or Seller's agent regarding the condition of the premises, or of any of the appliances that may be contained therein. Buyer is hereby informed that Seller is unaware of any latent defects in the property, or any component thereof, including but not limited to plumbing, heating, air conditioning and electrical systems, fixtures and appliances, roof, sewers, soil conditions, foundations, structural conditions and pool and related equipment, if applicable, unless otherwise mentioned in this contract or attached addendum. Buyer is also informed that Seller has no knowledge of the level of radon gas present in the Home, or of the presence of corrosive or defective drywall, unless otherwise mentioned in this contract or attached addendum.

Buyer is advised that the presence of certain kinds of mold (including "Toxic Mold"), fungi, mildew, and/or other organisms may adversely affect the property and the health of certain individuals. These conditions are often the result of moisture invasion or water leakage inside the Home. Buyer is advised to have the property inspected for the existence of such conditions or organisms, or the conditions that may lead to their formation, during the Buyer's physical inspection contingency period set forth herein. The closing of this sale shall constitute Buyer's acceptance of the condition of the Home, notwithstanding any past, present or future existence of mold in or around the Home, and agreement that Buyer has not, in any way, relied upon any representations of Seller. Buyer understands and agrees that Seller makes no guarantees or warranties, expressed or implied, regarding the past, present or future existence of mold in or around the Home, or regarding the effects of same. Buyer is advised to consult with appropriate experts regarding this topic if he/she/they have any questions or concerns.

Buyer is hereby granted the right to inspect the premises, or to obtain inspection reports of qualified experts at their own expense.

Should such reports reveal a level of radon gas exceeding the current recommended EPA standard or latent defects not discoverable by ordinary inspection, requested repairs, if any, must be submitted in writing to Seller's agent, not later than ten (10) calendar days after the offer is accepted. Seller shall review such requests and shall advise Buyer of the repairs, if any, that Seller agrees to make, or the costs, if any, to be credited Buyer at closing. If Seller permits Buyer to conduct invasive testing, the Buyer is required to return the property to its current condition.

In lieu of making such repairs, or partial repairs, Seller reserves the right to cancel this Purchase Contract, and upon return of the down payment, neither party shall have any further liability to the other.

If the Buyer has not made an examination of the property and submitted a report of any objections in writing to Seller's agent within ten (10) calendar days after offer is accepted, Buyer is deemed to have waived the right to so object, and is deemed to have accepted the condition of the property as satisfactory. Seller and Seller's agent are then relieved of all liability after closing.

Notwithstanding the foregoing, the closing of this sale shall constitute an acknowledgement by the Buyer that the premises and aforesaid systems were acceptable at the time the sale was closed, and Seller and Seller's agent are relieved of all liability after closing. Closing is to be considered the date all parties have signed the closing documents and the funds for disbursement to the Seller have been deposited with the Closing Agent.

Property will be dewinterized prior to closing and plumbing restored to working condition.

Buyer:	Date:
Buyer:	Date:
NEI Global Relocation Company (Seller)	
Ву:	Date:

INSPECTION DISCLOSURE ADDENDUM

We the undersigned, as of this acknowledge receipt of copie indicated invoices for work corepairs suggested in said insp 2410 Montana Blue Drive, Sp.	ompleted, wheetions, from	ich may reflect wo NEI Global Relo	ork completed for all or onl	y a portion of the
We understand that these reported Relocation Company harmless secure our own inspections and nature of any problems.	and waive a	ny recourse agains	st them for their content. W	e further agree to
Inspection Reports	Check if Included	Report Date	Work Invoice from (Included for Work Done, if any)	Work Invoice Date
ERC Relocation Property Assessment	X	06/01/2021		
Moisture Intrusion				
Mold Swab Clearance Test				
Mold Swab Sample				
Pest	X	06/01/2021		
Pool				
Private Sewage				
System/Septic				
Radon Test				
Roof				
Spa/Hot Tub				
Structural	**			
Stucco Identification				
Well				
Disclosures				
Homeowner's Property				
Questionnaire	X			
State Disclosures, if	X			
required	37			
Radon Service Agreement	X			
** Structural report to follow.				
Buyer:			Dated:	
Buyer:			Dated:	

Cover Page

160 West Carmel Drive,# 214
Carmel, IN 46032
317-867-7688
fax 317-867-9964

Inspection Services

Customer Information

Order#: 03839

Date 6/10/2021

File #: 277-12249

Location

Customer: NEI Global Relocation

Joseph & April Sylve 2410 Montana Blue Drive

Attention: Leah Tackitt

Spring TX 77373

Phone: 402-397-8486

Type of Service

Inspection Result Estimated Repair Cost pCi/L

Texas Real Estate Commission Home Inspection (TREC)

Service Summary

The Texas TREC report is not clear at the time of the inspection. The attached report indicates corrections and repairs are recommended. Read entire report for details and recommendations and call the listed reviewer with any questions.

This inspection and report adheres to the Texas Real Estate Commission (TREC) standards as required.

The price of repairs shown in the report is only a rough estimate. One or more qualified contractors should be contacted to provide a firm bid for any corrective action. The photos sent with this report may not reflect all defects and/or locations of needed repairs noted within the body or summary pages of the report. Please review the report in its entirety.

Thank you for your business.

Please contact the reviewer below with any questions on this report: Mark Tillett (317) 867-7688 Ext:363 matillett@ralis.com

ALWAYS Read Entire Report for Detailed Information

Initials _		/
------------	--	---



160 West Carmel Dr. Suite 214 Carmel, IN 46032 317-867-7688 Fax 317-867-9964

PROPERTY INSPECTION REPORT

Prepared For: NEI Global Relocation

(Name of Client)

Concerning: 2410 Montana Blue Drive Spring TX 77373 03839

(Address of Inspected Property) (City, State, Zip) (Invoice/Report Number)

By: Clayton Carter 24341 6/1/2021 (Name and License Number of Inspector) (Date)

Clayton Carter 24341

(Name, Signature and License Number of Sponsoring Inspector, if applicable)

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an items is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers.

You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods.

Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- •malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathrooms, kitchens, and exterior areas;
- •malfunctioning arc fault protection (AFCI) devices;
- •ordinary glass in locations where modern construction techniques call for safety glass;
- •malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- •malfunctioning carbon monoxide alarms;
- •excessive spacing between balusters on stairways and porches;
- •improperly installed appliances;
- •improperly installed or defective safety devices; and
- ·lack of electrical bonding and grounding; and
- •lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).



DocuSign Envelope ID: 54F1A27D-A395-4285-8207-8160B3CE67F1

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms requires a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

- Cosmetic Items are SPECIFICALLY EXCLUDED from this report.
- This report cannot and does not represent the operation or condition of any items after the date and time of this inspection.
- These items should not be considered a complete list of all defects with the house. This list is Limited to those items that are *Readily Accessible and the inspector(s) noted at the time of the inspection*.

Transferee Name: Jose	ph & April Sylve		Client File/Refero	ence Number: 277-12249	
Occupied: 🛛 Yes 🗆	No		Approximate Age of Home: 17 yrs.		
Time of Inspection: 10	Temp: 80 •	F	Weather: Overcast		
Dwelling Type:	☑ Detached Single	Family Town	nhouse 🔲 Condom	inium	
☐ Modular/Mobil		e 🔲 Othe	r		
People Present: Homeowner					



I =	i — inspected			I = Not Inspected	NP = Not Present	D = Deficient	
I	NI	NP	D				

			I. STRUCTURAL SYSTEMS
×		×	A. Foundations (An opinion on performance is mandatory)
			Type of Foundation: Slab
			Comments: See the note(s) under the Structural section of the Summary page(s).
			Visible evidence of ongoing water penetration? ☐ Yes ☒ No
			Vantage point used to inspect the crawlspace:
			☐ Entered ☐ Viewed from opening ☐ No Access ☒ Not Applicable
×		×	B. Grading and Drainage
			Comments: ⊠See the note(s) under the Structural section of the Summary page(s).
			Does sump pump appear to be functioning properly? ☐ Yes ☐ No ☒ Not Present
			Visible evidence of negative grade towards foundation of home? ☐ Yes ☒ No
			Do gutters/downspouts effectively direct water away from foundation? ☐ Not Present
			NOTES: PROPER DRAINAGE AND SOIL MOISTURE CONTENTS SHOULD BE MAINTAINED AROUND THE FOUNDATION TO HELP MINIMIZE FUTURE FOUNDATION PROBLEMS. WE MAKE NO STATEMENT CONCERNING SITE STABILITY.
×		×	C. Roof Covering Materials
			Type of Roof Covering (1): Asphalt/Fiberglass Shingle
			Viewed From: ⋈ Walked ☐ From eaves ☐ From ground with binoculars
			Type of Roof Covering (2):
			Viewed From: ☐ Walked ☐ From eaves ☐ From ground with binoculars
			Type of Roof Covering (3):
			Viewed From: ☐ Walked ☐ From eaves ☐ From ground with binoculars
			Describe and explain any levels of roof not accessed: N/A
			Evidence of previous repairs to roofing material? Yes No
			Evidence of water penetration? \(\subseteq \text{Yes} \) No
			Comments: \(\sumset See the note(s) under the Structural section of the Summary page(s).
			Approximate age of roof (1): 17 yrs. Location (1): Entire structure
			Design Life (1): 15-20 yrs.
			Approximate age of roof (2): yrs. Location (2):
			Design Life (2): yrs.
			Approximate age of roof (3): yrs. Location (3):
			Design Life (3): yrs.



1 =	Inspecte	u	11/1	1 = Not Inspected NP = Not Present D = Deficien	iii
I	NI	NP	D		
×			×	D. Roof Structures and Attics	
				Viewed From: ■ Entered □ Viewed from opening □ No Access	
				Approximate Average Depth of Insulation: 8 inches Unknown	☐ Not Present
				Evidence of water penetration? \(\subseteq \text{Yes} \sumseteq \text{No} \)	
				Comments: See the note(s) under the Structural section of the Summe	ary page(s).
×			×	E. Walls (Interior and Exterior)	
				Evidence of water penetration?	
				Comments: See the note(s) under the Structural section of the Summe	ary page(s).
				Exterior Surface Types and Locations:	
				Surface 1 Type: Cementitious Composite Location: Front an	d rear
				Surface 2 Type: Brick Location: Front an	d sides
				Surface 3 Type: Location:	
×			×	F. Ceilings and Floors	
				Evidence of water penetration? ☐ Yes ☒ No	
				Comments: See the note(s) under the Structural section of the Summe	ary page(s).
×			×	G. Doors (Interior and Exterior)	
				Evidence of water penetration?	
				Comments: ⊠ See the note(s) under the Structural section of the Summe	ary page(s).
X				H. Windows	
				Evidence of water penetration?	
				Comments: See the note(s) under the Structural section of the Summe	ary page(s).
				NOTES: SIGNS OF FAILED SEALS IN THE THERMAL PANE WINDO AND DISAPPEAR AS TEMPERATURE AND HUMIDITY CHANGES. SO WITH FAILED SEALS MAY NOT HAVE BEEN EVIDENT AT THE TIM INSPECTION. WINDOWS ONLY CHECKED FOR OBVIOUS FOGGING	OME WINDOWS E OF THE
				STORM WINDOWS ONLY CHECKED FOR DAMAGED OR MISSING O	GLASS.
		×		I. Stairways (Interior and Exterior)	
				Comments: See the note(s) under the Structural section of the Summe	ary page(s).
×			×	J. Fireplaces and Chimneys	
				Comments: ☑ See the note(s) under the Structural section of the Summe	ry page(s).
				Number of Fireplaces: 1 Fuel: ⊠ Gas ☐ Wood	
				Type: ☐ Metal Box & Flue(s) ■ Masonry/Brick ☐ Wood Stove ☐ Oth	ier
				NOTE: INSPECTION OF FLUE LINERS IS LIMITED.	
					Initial Here Initial Here

I =	Inspect	ed	N	II = Not Inspected NP = Not Present	D = Deficient
I	NI	NP	D		
×			×	K. Porches, Balconies, Decks, and Carports	
				Comments: ⊠ See the note(s) under the Structural sect	tion of the Summary page(s).
X				L. Other	
		1	1	Comments: See the note(s) under the Structural sect	ion of the Summary page(s).
				Walks: Visible trip hazards or defects noted?	☐ Yes No ☐ Not Present
				Driveway: Visible trip hazards or defects noted?	☐ Yes No ☐ Not Present
				Retaining Walls: Visible defects noted?	☐ Yes ☐ No ☒ Not Present
				II. ELECTRICAL SYS	STEMS
X				A. Service Entrance and Panels	
				Comments: See the note(s) under the Electrical section	on of the Summary page(s).
				Amps: 125 Volts: 110/220	
				Is incoming electrical service adequate to meet the ne dwelling? ☐ Yes ☐ No	eds of the
×			×	B. Branch Circuits, Connected Devices, and Fix	tures
				Type of wiring: Copper	
				Comments: See the note(s) under the Electrical section	on of the Summary page(s).
				III. HEATING, VENTILATION AND AIR	CONDITIONING SYSTEMS
×				A. Heating Equipment	
				Type of System (Unit 1): Forced Air	
				Energy Source (Unit 1):	Other
				Type of System (Unit 2):	
				Energy Source (Unit 2):	
				Comments: See the note(s) under the Heating / AC so	ection of the Summary page(s).
				Number of heating units present: 1	
				Approximate Age (Unit 1): 17 yrs Design Life Location (Unit 1): Attic	e (Unit 1): 15-20 yrs
				Approximate Age (Unit 2): yrs Design Life Location (Unit 2):	e (Unit 2): yrs
				Evidence of fuel storage tank? ☐ Yes ☒ No	In use? ☐ Yes ☐ No
					Location:
				NOTES: FULL EVALUATION OF THE INTEGRITY OF DISMANTLING OF THE FURNACE AND IS BEYOND T	
					-Initial-Here
					-initial-Here - mitist Here

I =	Inspect	ed	N	II = Not Inspected NP = Not Present D = Deficient
I	NI	NP	D	
			×	B. Cooling Equipment
	"			Type of System (Unit 1): Central
				Type of System (Unit 2): Comments: \(\nabla\) See the note(s) under the Heating \(\lambda\) C section of the Summary page(s)
				Comments: See the note(s) under the Heating / AC section of the Summary page(s).
				Number of cooling units present: 1
				Approximate Age (Unit 1): 17 yrs Design Life (Unit 1): 10-15 yrs Location (Unit 1): Exterior
				Location (Clift 1): Exterior
				Approximate Age (Unit 2): yrs Design Life (Unit 2): yrs
				Location (Unit 2):
				NOTES: UNITS ARE NOT INSPECTED FOR PROPER SIZE OR EFFICIENCY. UNITS ARE NOT OPENED FOR INSPECTION. WINDOW A/C UNITS ARE NOT INSPECTED.
×				C. Duct System, Chases, and Vents
				Comments: ☑ See the note(s) under the Heating AC section of the Summary page(s).
				NOTE: INSPECTION OF FLUES IS LIMITED.
				IV. PLUMBING SYSTEMS
×				A. Plumbing Supply, Distribution Systems and Fixtures
				Location of water meter: Front
				Location of main water supply valve: Garage
				Static water pressure reading: 60 psi
				Comments: ∑See the note(s) under the Plumbing section of the Summary page(s).
				Water Source: ☑ Public ☐ Private (See Optional Systems)
	1			How verified: Known area
×				B. Drains, Wastes, and Vents
				Comments: ∑See the note(s) under the Plumbing section of the Summary page(s).
				Sewage Service: ☑ Public ☐ Private (See Optional Systems)
				How verified: Known Area
×				C. Water Heating Equipment
				Comments: See the note(s) under the Plumbing section of the Summary page(s).
				Energy Source (Unit 1): Gas Capacity (Unit 1): 50 gal
				Energy Source (Unit 2): Capacity (Unit 2): gal
				Approximate Age (Unit 1): 1 yrs Design Life (Unit 1): 10-15 yrs
				Location (Unit 1): Garage
				Approximate Age (Unit 2): yrs Design Life (Unit 2): yrs Location (Unit 2):
				Initial Here Initial Here Initial Here

I =	Inspected N		N	II = Not Inspected NP = Not Present D = Deficiency
Ι	NI	NP	D	
×	П			D. Hydro-Massage Therapy Equipment
		ш	Ш	
				Comments: See the note(s) under the Plumbing section of the Summary page(s).
				V. APPLIANCES
×			×	A. Dishwashers
				Comments: See the note(s) under the Appliances section of the Summary page(s). NOTE: LOWER PANEL NOT REMOVED FOR INSPECTION.
×				B. Food Waste Disposers
				Comments: ☑ See the note(s) under the Appliances section of the Summary page(s).
×			×	C. Range Hood and Exhaust Systems
				Comments: See the note(s) under the Appliances section of the Summary page(s). NOTE: RANGE VENT NOT CHECKED FOR CLEANLINESS.
×				D. Ranges, Cooktops, and Ovens
				Comments: See the note(s) under the Appliances section of the Summary page(s). Range: Oven: Cooktop: □ Electric □ Gas □ Electric ☒ Gas □ Electric ☒ Gas NOTES: IF PRESENT, DELAY TIMER AND SELF-CLEAN MODE ARE NOT TESTED.
×				E. Microwave Ovens
		1		Comments: See the note(s) under the Appliances section of the Summary page(s). NOTE: MICROWAVE OVEN NOT INSPECTED FOR RADIATION LEAKS.
×				F. Mechanical Exhaust Vents and Bathroom Heaters
				Comments: ∑See the note(s) under the Appliances section of the Summary page(s).
×				G. Garage Door Operators
				Comments: ⊠ See the note(s) under the Appliances section of the Summary page(s).
×			×	H. Dryer Exhaust Systems
				Comments: See the note(s) under the Appliances section of the Summary page(s). NOTE: DRYER VENT NOT CHECKED FOR CLEANLINESS.

Address of Inspected Property: 2707 North 118th Street

I = In	spected	NI = N	lot Inspe	cted NP = Not Present D = Deficiency
I	NI	NP	D	
				VI. OPTIONAL SYSTEMS
		×		A. Landscape Irrigation (Sprinkler) Systems
				Comments: ☑ See the note(s) under the Optional Systems section of the Summary page(s).
				Control Panel Location: Number of Zones used:
				Valve Box Location:
				Coverage: ☐ Front Yard ☐ Back Yard ☐ Side Yard(s) ☐ Other
				NOTE: SPRINKLER CONTROLS ARE OPERATED IN MANUAL MODE ONLY.
		×		B. Swimming Pools, Spas, Hot Tubs, and Equipment
				Comments: ⊠ See the note(s) under the Optional Systems section of the Summary page(s).
				Type of Construction (pool):
				Type of Construction (hot tub/spa):
				Is pool winterized? ☐ Yes ☐ No
				Type of pool: ☐ In ground ☐ Above ground ☐ Other
				Type of pool filter: ☐ Sand ☐ Cartridge ☐ D.E. ☐ Other
				Is hot tub/spa winterized? ☐ Yes ☐ No
				Type of hot tub/spa: ☐ In ground ☐ Above ground ☐ Other
				Type of hot tub/spa filter: ☐ Sand ☐ Cartridge ☐ D.E. ☐ Other
				NOTE: NOT CHECKED FOR POOL SHELL LEAKAGE OR IN BACKWASH MODE. THE POOL COATING IS CONSIDERED COSMETIC AND NOT PART OF THIS INSPECTION. ALL CONTROLS ARE OPERATED IN THE MANUAL MODE ONLY. ANCILLARY EQUIPMENT SUCH AS COMPUTER CONTROLS, CHLORINATORS OR OTHER CHEMICAL DISPENSERS, WATER IONIZATION DEVICES OR CONDITIONERS ARE NOT INSPECTED.
		×		C. Outbuildings
				Comments: ☑ See the note(s) under the Optional Systems section of the Summary page(s).



I = In	Inspected NI = Not Inspec			cted NP = Not Present D = Deficiency
I	NI	NP	D	
	1			
				D. Private Water Wells (A coliform analysis is recommended)
				Type of pump:
				Type of storage equipment:
				Comments: ⊠ See the note(s) under the Optional Systems section of the Summary page(s).
				Location of well in
				relationship to the home? North South East West Unknown
				Approximate distance between well and septic system? ft
				Is distance acceptable to current standards? ☐ Yes ☐ No ☐ N/A ☐ City Water
				Does well have a visible riser? ☐ Yes ☐ No
				Location of pressure tank? Garage Utility Room Basement/Crawl Other
				Estimated pressure? psi Estimated flow after 30 minutes? gpm
				Date water sample sent to local lab:
				Lab name: Lab phone:
		Г		•
		×		E. Private Sewage Disposal (Septic) Systems
				Type of System: Private Aerobic Other
				Location of drainfield: North South East West Unknown
				Comments: ⊠ See the note(s) under the Optional Systems section of the Summary page(s).
				Is property occupied at time of inspection? ☐ Yes ☐ No
				NOTE: If No, report is qualified as the system was not under regular use at the time of the inspection.
				Does tank have a visible riser? ☐ Yes ☐ No
				Approximate distance between septic system and well?
				Is distance acceptable to current standards? ☐ Yes ☐ No ☐ N/A ☐ City Water
				Method of evaluation: ☐ Dye & Visual ☐ Visual only
				Was water ran for a minimum of 30 minutes? ☐ Yes ☐ No
				Was any effluent and/or dye visible on ground? ☐ Yes ☐ No
				Functional drainage? ☐ Yes ☐ No



Record on this page the corrective action required for all items determined to be defective including the estimated cost of repairs and explain any items that were reported as "Not Inspected." These estimates are not bids, nor are they intended to be used as such. Other information may also be listed on this page as "NOTES" or "FYI".

A home inspector with only a general knowledge of potential costs provided the estimated costs of repair shown below. RAL recommends that at least one qualified repair contractor provide a more accurate and detailed bid for these repairs prior to closing.

This inspection report was solely intended for use by RAL's specific relocation client who may decide to provide to other interested parties for disclosure purposes only. The information contained within this report is NOT intended to be used or relied upon by any other interested party. All interested parties should obtain their own independent inspections.

I. STRUCTURAL SYSTEMS

I.A. FOUNDATIONS

1. Qualified contractor to correct as determined necessary the corner spall at front right corner, exposed post tension cables at various areas, and exposed framing on left side slab.

I.B. GRADING & DRAINAGE

- 1. Qualified contractor to correct as determined necessary the following conditions:
- a) Erosion at both sides of house.
- b) Downspouts terminate too close to foundation.

I.C. ROOF COVERING MATERIALS #1

1. Qualified roofing contractor to correct as determined necessary the exposed fasteners at ridge caps.

I.D. ROOF STRUCTURES & ATTICS

1. Qualified insulation contractor to correct as determined necessary the low areas of insulation at front and rear attic.

NOTE: Assessment of attic was limited to approximately 75% that was visible due to design, insulation, and ventilation ducts. (FYI)

I.E. WALLS (INTERIOR & EXTERIOR)

- 1. Qualified contractor to correct as determined necessary the following conditions:
- a) Missing drywall at garage wall.
- b) Damaged siding/trim at chimney chase.

I.F. CEILINGS & FLOORS

1. Qualified contractor to correct as determined necessary the fastener pops and tape fracture at front room and master bathroom.

I.G. DOORS (INTERIOR AND EXTERIOR)

1. Qualified contractor to correct as determined necessary the cracked trim at rear door.

I.H. WINDOWS

1. No visible defects noted at the time of the inspection.



I.I. STAIRWAYS (INTERIOR AND EXTERIOR)

1. Not present.

I.J. FIREPLACES AND CHIMNEYS

1. Qualified contractor to correct as determined necessary the deteriorated sealant at chimney rain cap.

NOTE: The inspection of exterior chimney components and interior components of fireplaces, chimneys and flues can be limited by design or accessibility with areas that are beyond the scope of this visual inspection. (FYI)

I.K. PORCHES, BALCONIES, DECKS AND CARPORTS

1. Qualified contractor to correct as determined necessary the cracks at rear patio.

I.L. OTHER

1. No visible defects noted at the time of the inspection.

II. ELECTRICAL SYSTEMS

II.A. SERVICE ENTRANCE AND PANELS

1. Qualified electrical contractor to correct as determined necessary the open, unprotected breaker slot at panel front. (Safety)

II.B. BRANCH CIRCUITS, CONNECTED DEVICES, AND FIXTURES

1. Qualified electrical contractor to correct as determined necessary the loose receptacle on kitchen island, missing cover plate at attic outlet, improper use of an extension cord as permanent wiring, missing safety cage at attic light fixture, exposed wiring at garage, missing cover plate at garage outlet, and unsealed exterior outlet cover. (All Safety)

III. HEATING, VENTILATION, AND AIR CONDITIONING SYSTEMS

III.A. HEATING EQUIPMENT (UNIT #1)

1. No visible defects noted at the time of the inspection.

III.B. COOLING EQUIPMENT (UNIT #1)

1. Qualified electrical contractor to correct as determined necessary the white wires at AC disconnect are used as "hot" legs and lack proper labeling/color coding. (Safety)

III.C. DUCT SYSTEMS, CHASES, AND VENTS

1. No visible defects noted at the time of the inspection.

IV. PLUMBING SYSTEM

IV.A. PLUMBING SUPPLY, DISTRIBUTION SYSTEMS AND FIXTURES

1. No visible defects noted at the time of the inspection.

NOTE: Plumbing supply lines are PVC. (FYI)

IV.B. DRAINS, WASTES, AND VENTS

1. No visible defects noted at the time of the inspection.



NOTE: Plumbing drain lines are PVC. (FYI)

IV.C. WATER HEATING EQUIPMENT (UNIT #1)

1. No visible defects noted at the time of the inspection.

IV.D. HYDRO-MASSAGE THERAPY EQUIPMENT

1. No visible defects noted at the time of the inspection.

V. APPLIANCES

V.A. DISHWASHERS

1. Qualified contractor to correct as determined necessary the missing air gap/high loop at dishwasher drain line.

V.B. FOOD WASTE DISPOSERS

1. No visible defects noted at the time of the inspection.

V.C. RANGE HOOD AND EXHAUST SYSTEMS

1. Qualified contractor to correct as determined necessary the light does not function at vent hood.

V.D. RANGES, COOKTOPS, AND OVENS

1. No visible defects noted at the time of the inspection.

V.E. MICROWAVE OVENS

1. No visible defects noted at the time of the inspection.

V.F. MECHANICAL EXHAUST VENTS AND BATHROOM HEATERS

1. No visible defects noted at the time of the inspection.

V.G. GARAGE DOOR OPERATORS

1. Qualified contractor to correct as determined necessary the locks at the overhead garage door are not properly disabled. (Safety)

V.H. DRYER EXHAUST SYSTEMS

1. Qualified contractor to correct as determined necessary the improper vent type used at dryer exhaust. (Safety)

VI. OPTIONAL SYSTEMS

VI.A. LANDSCAPE IRRIGATION (SPRINKLER) SYSTEMS

1. Not present.

VI.B. SWIMMING POOLS, SPAS, HOT TUBS, AND EQUIPMENT

1. Not present.

VI.C. OUTBUILDINGS

1. Not present.



VI.D. PRIVATE WATER WELLS

1. Not present.

VI.E. PRIVATE SEWAGE DISPOSAL (SEPTIC) SYSTEMS

1. Not present.





Inspection Location: Joseph & April Sylve 2410 Montana Blue Drive Spring, TX 77373

Page: 1

File #: 03839



Line Item #: I

Description: Front of home.



Line Item #: I

Description: Front of home.



Line Item #: I

Description: Right side of home.

Line Item #: I

Description:

Rear view of home.



Initials _____/



Inspection Location: Joseph & April Sylve 2410 Montana Blue Drive Spring, TX 77373

Page: 2

File #: 03839



Line Item #: I

Description:

Rear view of home.



Line Item #: I

Description:

Left side of home.



Line Item #: I

Description:

Left side of home.



Line Item #: I.A

Description:

Corner spall at front right corner.


Initials ____/_



Inspection Location: Joseph & April Sylve 2410 Montana Blue Drive Spring, TX 77373

Page: 3

File #: 03839



Description:

Exposed post tension cables at various

areas.



Line Item #: I.A

Description:

Exposed post tension cables at various

areas.



Line Item #: I.A

Description:

Exposed framing on left side slab.



Line Item #: I.B.

Description:

Erosion on left side of home.



Initials _____/___



Inspection Location: Joseph & April Sylve 2410 Montana Blue Drive Spring, TX 77373

File #: 03839

Page: 4



Line Item #: I.B.

Description:

Erosion on right side of home.



Line Item #: I.B.

Description:

Downspouts terminate too close to foundation.



Line Item #: I.C.

Description:

View of roof - front.



Line Item #: I.C.

Description:

View of roof - rear.

Initials ____/_



Inspection Location: Joseph & April Sylve 2410 Montana Blue Drive Spring, TX 77373

Line Item #: I.C.

Description:

View of roof - right side.

Page: 5

File #: 03839



Line Item #: I.C.

Description:

View of roof - left side.



Line Item #: I.C.

Description:

Exposed fasteners at ridge caps.



Line Item #: I.D.

Description:

Low area of insulation at front attic.

Initials ____/_



Inspection Location: Joseph & April Sylve 2410 Montana Blue Drive Spring, TX 77373

File #: 03839

Page: 6



Line Item #: I.D.

Description:

Low area of insulation at rear attic.



Line Item #: I.D.

Description:

NOTE: Assessment of attic was limited to approximately 75% that was visible due to design, insulation, and ventilation

ducts. (FYI)



Line Item #: I.E.

Description:

Missing drywall at garage wall.



Line Item #: I.E.

Description:

Damaged siding/trim at chimney chase.


Initials ____/



Inspection Location: Joseph & April Sylve 2410 Montana Blue Drive Spring, TX 77373

Page: 7

File #: 03839





Example of fastener pops and tape fracture at front room.



Line Item #: I.F.

Description:

Example of fastener pops and tape fracture at master bath.



Line Item #: I.G.

Description:

Cracked trim at rear door.



Line Item #: I.J.

Description:

Deteriorated sealant at chimney rain cap.



Initials _____/



Inspection Location: Joseph & April Sylve 2410 Montana Blue Drive Spring, TX 77373

Page: 8

File #: 03839

Line Item #: I.K.

Description:

Cracks at rear patio.



Line Item #: II.A.

Description:

View of main electric panel at garage.



Line Item #: II.A.

Description:

View of main electric panel with cover



Line Item #: II.A.

Description:

Open, unprotected breaker slot at panel front.



Inspection Location: Joseph & April Sylve 2410 Montana Blue Drive Spring, TX 77373

Page: 9

File #: 03839



Line Item #: II.B.

Description:

Loose receptacle on kitchen island.



Line Item #: II.B.

Description:

Missing cover plate at attic outlet, and improper use of an extension cord as permanent wiring.



Line Item #: II.B.

Description:

Missing safety cage at attic light fixture.



Line Item #: II.B.

Description:

Exposed wiring at garage.

Initials ____/



Inspection Location: Joseph & April Sylve 2410 Montana Blue Drive Spring, TX 77373

Page: 10

File #: 03839



Line Item #: II.B.

Description:

Missing cover plate at garage outlet.



Line Item #: II.B.

Description:

Unsealed exterior outlet cover.



Line Item #: III.A

Description:

View of HVAC at attic.



Line Item #: III.A

Description:

View of HVAC with cover off.

Initials _____/



Inspection Location: Joseph & April Sylve 2410 Montana Blue Drive Spring, TX 77373

Page: 11

File #: 03839



Line Item #: III.B.

Description:

White wires at AC disconnect are used as "hot" legs and lack proper labeling/color coding.



Line Item #: IV.C.

Description:

View of water heater at garage.



Line Item #: V.A.

Description:

Missing air gap/high loop at dishwasher drain line.



Line Item #: V.C.

Description:

Light does not function at vent hood.

Initials _____/



Inspection Location: Joseph & April Sylve 2410 Montana Blue Drive Spring, TX 77373

Page: 12

File #: 03839



Line Item #: V.G.

Description:

Locks at the overhead garage door are not properly disabled.



Line Item #: V.H.

Description:

Improper vent type used at dryer

exhaust.