# American Dream Home Inspections, LLC

9307 Reston Grove Ln, Houston, TX

I=Inspected NI=Not Inspected NP=Not Present

D=Deficient

I NI NP D



Second-floor bedroom left side noted at time of inspection. Observational an informational purposes only



Guest bedroom noted top right side observational informational purposes only.



Second-floor guest bathroom Noted at time of inspection. Observational an informational purposes only.



All metal lentils above garage and windows should be sanded cauliked sealed and painted properly. Conducive to moisture intrusion, damage and potential WDO. Recommend having a professional inspect and correct

# Jul-25 (Seller Comment)

• Repairs completed on metal lentils above garage and doors



REI 7-5 (05/4/2015) Page 18 of 77



Jul-25 (Seller Comment)

• Repairs completed on gas meter penetration



Galvanized plumbing at gas meter penetration into wall systems should be sealed properly. Conducive to moisture intrusion, damage and potential WDO. Observational an informational purpose only.

F. Ceilings and Floors

- Ceiling and Floor Materials:
  Ceiling is drywall with smooth finish
  Cathedral ceiling
  Floors had carpet covering in various locations
  Floors had laminate and/or engineered wood flooring in one or more locations
  Floors had tile and/or stone covering in one or more areas
- Comments:
- All components were found to be performing and in satisfactory condition at the time of the inspection
- Slab not visible due to floor coverings

REI 7-5 (05/4/2015)

Page 19 of 77

American Dream Home Inspections, LLC 9307 Reston Grove Ln, Houston, TX I=Inspected NI=Not Inspected NP=Not Present D=Deficient I NI NP D

**B.** Cooling Equipment

- Type of Systems:
   Gas fired forced hot air
- The home has a gravity style octopus system.
- The home has a split system.

### Comments:

- Basic components of a standard residential HVAC cooling system. Observational and informational purposes only.
- Diagram of basic residential cooling system and its components. Composite pad is important to keep unit above grade level which is conducive to moisture intrusion, damage, corrosion to unit. Have HVAC unit min. 3 inches above grade
- This unit appears to be functioning as intended at the time of inspection and consistent with accepted industry standards
   The main condensation drain is located in Guest bathroom under sink.
- The cooling system differential was in normal range 0f 14-22 degrees.
- The cooling system appears to have reached its serviceable life expectance
- The secondary condensate drain was discharging water to the exterior indicating a possible problem with the primary drain
- Temperature Differential was 10 Degrees and not in normal range. Recommend having a professional inspect for optimum efficiency.



Secondary drain noted on right side of house underneath soffit he's draining at time of inspection. Conducive to main drain needing to be cleaned out. Recommend having a professional inspect incorrect problem



Main condensation drain noted under sink and guest bathroom at time of inspection. Observational an informational

REI 7-5 (05/4/2015) Page 37 of 77

# Jul-25 (Seller Comment)

- A/C serviced see below receipt
- Primary A/C drain cleaned by AC tech
- Temperature differential (16 degrees)

✓ SAME DAY SERVICE ✓ ALL WORK GUARAN ✓ ALL MAJOR CREDIT ✓ FINANCING AVAILA	CARDS ACCEPTED	1	SE SE	UDGET HOME RVICES	PLUMBI		85263  G & HEATING
8811 FAIRBANKS - N.	HOUSTON RD., HOL	JSTON, TX 7	7064	713-686	-7000   1	fax 713-68	36-4729
CUSTOMER	NAME	CUS	TOMER	ADDRESS		PHONE NUM	BER
Cousson	,	9307	P	- GROVE	337-6	01-669	,
COLLECTION		COLLECTIO	N ADDR	ESS (If Different)	201-3	EMAIL ADDR	ESS
				77095			
STATE OF THE PERSON NAMED IN		DIA	GNOSIS	/SOLUTION	NEW A	NO DE LA COLUMN	10   2001
DATE 7/9/21	KEY	408	4				
Hung So	HERMOS TH	or Su	Pur	AND/OR COMM	ARES A	Aug in Serin crockes	RR.
WORK AUTHORIZATION AUTHORIZATION PROCEED WITH ARE Let underlighted, agree to hald Bill he made or mode related have at claims at and askenshedges are to see claims at and askenshedges are to see claims at the appropriate of the see claims at the appropriate of the appropriate of the appropriate this agreement before commoning the type operation of the proceeding of the type operation of the appropriate TREMIT TO:	omities and exempt from liability for to person, dismages to properly sing from audifor related to work party would not commence work by the sums and conditions just for work. Customer warrants and not work. Customer and all occupants of oney of the content and ADICULATION THE DESCRIBED WORK AT A	and/or death in any in any way. Custome without the custome orth on the face and presents that custom the premises in which TO OWNER ON THE	demands, loss- way related to or understands r executing this reverse side of er has authori- the work is to REVERSE SIDE.	ACCEPTANCE OF WORK PERM connection with the above we agree that the amount set for the total and complete flat rat costs in the event of legal accinevalingly that there read to Owner on the reverse side. Sam and Spm.  Authorized Signature  OUSTON RD.	ork mentioned, to it on this contract i e minimum charge, I ion. A monthly servi and received a legible All warranty work wi	have been completed in the amount labeled "lagree to pay reasonable ice charge of 1.5% will it e copy of this contract, a lill be performed Monday	a satisfactory manner. I BNOICE ANDUNT* to be attorney's fees and court be added after 30 days. I and I have read the Notice by through Friday between
INVOICE AMOUNT	UNIT NUMBER	CASH	CHECK	Silving was	CREDIT	CARD #	War in the later of
\$ 6250	130/KIRK	-2		Exp. Date	Code	Approval #@	91431
AC REPAIR	"WE CON	ME OUT	FOR ERATED B	BING & A FREE AND F BY NATIVE HOUST	FIX FOR	LESS" (CE 1992	INANCING VAILABLE

PRESS HARD - USE BALL POINT PEN - YOU ARE MAKING TWO COPIES

# American Dream Home Inspections, LLC

9307 Reston Grove Ln, Houston, TX

NI=Not Inspected I=Inspected

NP=Not Present

D=Deficient

NI NP D



Observational an informational purpose only.



Lennox Unit # 2 HVAC exterior condensor, 4 Ton, R22 Freon, 2001 MFD, 45 AMP 12 SEER. Unit was working but appears to be at the end of its life expectancy.



Missing float switch noted. Recommend having one added for proactive protection in case drain pan gets full of water "Float Switch" Will shut off system for protection from moisture damage and intrusion from drain pan potentially overflowing.



Interior view of drain pan noted. Observational an informational purpose only.

Page 42 of 77



REI 7-5 (05/4/2015)

# C. Duct Systems, Chases, and Vents

- Filter is located in the hall area wall
- Filter Size 20x30x1
- Ductwork in attic space was observed to be sagging and/or kinked and is not supported at {4'} spacing as recommended

American Dream Home Inspections, LLC

9307 Reston Grove Ln, Houston, TX

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



20x30x1 filter size noted. Observational an informational purpose only.



View of HVAC ducts noted in attic area at time of inspection noted. Observational an informational purpose only.



All HVAC ducts should not touch one another and be properly hung. Conducive to moisture intrusion, damage and potential WDO

### IV. PLUMBING SYSTEM

REI 7-5 (05/4/2015)

Page 43 of 77

# Jul-25 (Seller Comment)

- Floating switch added to drain pan and
- **HVAC ducts** adjusted see receipt on previous page

# I=Inspected NI=Not Inspected NP=Not Present D=Deficient I NI NP D Badger food disposal noted at time of inspection. Observational an informational purposes only Badger food disposal manufacturers label noted at time of inspection. Observational an informational purposes only

Video

American Dream Home Inspections, LLC

Food disposal working properly at time of inspection. I was relational in informational purposes only.

9307 Reston Grove Ln, Houston, TX

Observational an informational purpose only.



# C. Range Hood and Exhaust Systems

- The range hood was operating properly at time of inspection
  The range hood was functional at the time of the inspection.
  The range hood was noticed as a self filtering unit with fan.
  Self filtering with carbon type filters.


- The unit appeared noisy and/or vibrating

REI 7-5 (05/4/2015) Page 55 of 77

# Jul-25 (Seller Comment)

• Range hood filter – replaced – range hood fan is no longer noisy and/or vibrates

# American Dream Home Inspections, LLC 9307 Reston Grove Ln, Houston, TX I=Inspected NI=Not Inspected NP=Not Present D=Deficient I NI NP D



Observational an informational purpose only.

✓ I. Other

### Observations:

• If you're reading this report but did not hire me, Paradigm Inspections, Llc. to perform the original inspection, please note that it is likely that conditions related to the home have probably changed, even if the report is fairly recent. Just as you cannot rely on an outdated weather report, you should not rely on an outdated inspection report. Minor problems noted may have become worse, recent events may have created new issues, and items may even have been corrected and improved. Don't rely on old information about one of the biggest purchases you'll ever make. Remember that the cost of a home inspection is insignificant compared to the value of the home. Protect your family and your investment, and please call me directly at 713-826-1083 to discuss the report you're reading for this properly so that we can arrange a re-inspection.

## VI. OPTIONAL SYSTEMS

✓ A. Landscape Irrigation (Sprinkler) Systems

### Comments

- The sprinkler system was not functional at the time of the inspection
- One or more of the zones did not respond under manual testing

REI 7-5 (05/4/2015) Page 62 of 77

# Jul-25 (Seller Comment)

- All sprinkler zones (1 to 8) response under manual testing
- The sprinkler system shows a 9<sup>th</sup> zone that isn't connected

American Dream I	Home Inspections, LLC		9307 Reston Grove Ln, Hous		
l=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient		
I NI NP D					
	B. Swimming Poo	ls, Spas, Hot Tubs,	and Equipment		

Type of Construction:

• In-Ground

• Gunite

Comments:

- The pool and/or spa components appeared to be functioning as intended at the time of the inspection
- NOTE: This segment of the Inspection Report is based upon the current conditions of the pool and/or tub spa components at the time of the inspection. This inspection reflects deficiencies in the condition of the above ground controls and/or devices, visible pool surfaces noting cracks in the tile, coping and deck surface and all standard compliance issues for pool barriers. The pool lighting, steps, slides, diving boards are reviewed as well as drains, skimmers and valves. As per TREC guidelines; the Inspector is not required to dismantle or operate valves, determine the presence of subsurface leaks, add water into the pool and/or spa, inspect any winterized components or chlorinators and chemical dispensers aside from visual leakage and/or deterioration. It is recommended that a qualified pool service technician be consulted for a complete review of the entire system
- The pool sweeper appeared to be functioning as intended at the time of the inspection
- A (GFCI) receptacle is required to be installed (10' 20') from the pool.
   Recommend having a professional inspect and correct if needed.
- Current standards require all doors that allow access to the pool area be equipped with an audible alarm heard throughout the house and sound for {30} seconds continuously. The alarm device should be mounted at a height of not less than {54"} above the door threshold. A self-closing and self-latching door device may be another acceptable safety practice
- Further information can be obtained from {cpsc.gov} regarding the safety regulations
- There was no pool heater in place at the time of the inspection
- A cartridge type filter was noted at the pool equipment.
- The pump was unusally noisy when operating and this may indicate failure and should be further evaluated
- One or more areas noted grout deterioration and should be repaired
- One or more areas noted missing sealant between the deck surface and the coping

REI 7-5 (05/4/2015) Page 64 of 77

# Jul-25 (Seller Comment)

- Pool pump installed Sep-2019
- Pool pump sounds the same as the day it was installed



a neighborly company

Mr Electric of Northwest Houston 13329 Veterans Memorial Dr. Suite Q Houston, TX 77014 Phone (281) 919-2130

License # 28038

Estimate 61378595 Job 61378066 Estimate Date 9/16/2019 Technician Chris Monclova

Job Address Heather Cousson 9307 Reston Grove Lane Houston, TX 77095 USA

Billing Address Heather Cousson 9307 Reston Grove Lane Houston, TX 77095 USA

### **Estimate Details**

Pool Equipment: Mr. Electric offers an alternative payment option and that is our 18 month no interest payment plan

Task #	Description	Quantity	<b>Your Price</b>	Your Total
<b>FEEDISPATCH</b>		0.00	\$45.00	\$0.00
Z1501	BASIC CIRCUIT RESTORATION INCLUDES ONE DEVICE REPLACEMENT (SWITCH, BREAKER OR OUTLET) *NO WIRE INCLUDED	1.00	\$229.50	\$229.50
\$3950	REPLACE 1-1/2 HP POOL PUMP MOTOR	1.00	\$655.50	\$655.50
Z10000	1 YEAR PLAN - with 15% Savings Our Mr. Electric Advantage Plan Includes the following:  - Priority Scheduling  - Preferential Pricing  - Periodic Specials  - Personalized Records  - Transferable Agreement  - Multiple Site Coverage  - Extended Labor Warranty  - Ka an Advantage Plan customer you receive preferred customer status and special discounts at participating locations of our sister companies: AireServ, Mr. Appliance, Glass Doctor, and Mr. Rooter	1.00	\$65.00	\$65.00

IMPORTANT NOTICE: You and your contractor are responsible for meeting the Terms and Conditions of this contract. If you sign this contract and you fail to meet the terms and conditions of this contract, you may lose legal ownership rights to your home. KNOW YOUR RIGHTS AND DUTIES UNDER THE LAW, YOU, THE BUYER, MAY CANCEL THIS TRANSACTION AT ANY TIME PRIOR TO MIDNIGHT OF THE 3RD BUSINESS DAY AFTER THE DATE OF THIS TRANSACTION. SEE THE ATTACHED NOTICE OF CANCELLATION FORM FOR AN EXPLANATION OF THIS RIGHT. algore that initial price quoted prior to the start of work does not include a you'ditional or unforeseen tasks. Nor materials which may be found to be necessary to complete repairs or replacements. I also agree to hold Mr. Electric® or its assigns harmless for parts deemed corroded, unusable or unreliable for completion of stated work to be done hereby authorize Mr. Electric to perform proposed work and agree to all agreement conditions as displayed and further acknowledge that this invoice is due upon receipt. A monthly service charge, at maximum allowed by law, will be added after 10 days. Independently owned and operated franchise. Amount to Authorize: \$950.00



9/16/2019