TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

Rule §7.176 Requires this department prescribed form to be used for real estate transactions in Texas regarding the visible presence or absence of wood destroying insects and conditions conducive to infestations of wood destroying insects.

9230 Fm 1371	Chappell Hill	77426
Inspected Address	City	Zip Code

SCOPE OF INSPECTION

- A. This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guest houses or any other structure will not be included in this inspection report unless specifically noted in Section 5 of this report.
- B. This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work.
- C. Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment; has rendered the pest(s) inactive.
- D. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is present.
- E. If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified expert.

F. THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS.

- G. If termite treatment (including pesticides, baits or other methods) has been recommended, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticides to be used and complete details of warranty (if any). The warranty should specify which areas of the structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party.
- H. There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and renewal options.
- There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure,
 (2) there is visible evidence of a previous infestation with no evidence of a prior treatment.
- J. If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture.

9230 Fm 1371	Ch	appell Hill		77426
Inspected Address	City			Zip Code
1AWDIsolutions	1B		TPCL # 730859	
Name of Inspection Company		SPCS Business	License Number	
1C. 5100 Westheimer Rd. #200	Houston	ТХ	77056	832-292-3094
Address of Inspection Company	City	State	Zip	Telephone No.
1D. Roy Brashier # 713-545-5652 roy@brashierh Name of Inspector (Please Print)	omeinspection.com	_1.E Certified Applica Technician	tor	(check one)
0000026815	1F.		02/10/2021	
	Inspection			
2. Cassy Mayes Name of Person Purchasing Inspection		_Seller 🗌 Agent 🗌 Buyer	X Management Co	. Other
3. N/A				
Owner/Seller 4.REPORT FORWARDED TO: Title Company or Mortgagee (Under the Structural Pest Control regulations only the structural Pest Control regulations on the structural			Agent 🔀	Buyer 🔀
The structure(s) listed below were inspected in accordance with This report is made subject to the conditions listed under the Sco				
5AList structure(s) inspected that may include residence, detached	Single Family F	Residence		
List structure(s) inspected that may include residence, detached	garages and other structur	res on the property. (Refer to I	Part A, Scope of Inspe	ection)
5B. Type of Construction: Foundation: Slab ☑ Pier & Beam ☑ Pier Type: Pier & Siding: Wood ☐ Fiber Cement Board ☐ Brick ☐ Stone ☐ Roof: Composition ☑ Wood Shingle ☐ Metal ☐ Tile ☐		Other: <u>N/A</u> Vinyl siding		
6A.This company has treated or is treating the structure for the f			— N/A	
If treating for subterranean termites, the treatment was: If treating for drywood termites or related insects, the treatment v	Partial	Spot Bait Limited	D Oth	ner 🗌
6BN/A		N/A		N/A
Date of Treatment by Inspecting Company	Comm	non Name of Insect	Name of Pes	sticide, Bait or Other Method
This company has a contract or warranty in effect for control of t	ne following wood destroyir	-		
Yes INO IN List In If "Yes", copy(ies) of warranty and treatment diag	sects:	I	N/A	
Neither I nor the company for which I am acting have had, prese I nor the company for which I am acting is associated in any way Signatures:	ntly have, or contemplate h		hase or sale of this pro	operty. I do further state that neither
Inspector (Technician or Certified Applicator Name and Licens	se Number)			
Others Present: 7B		.		
Apprentices, Technicians, or Certified Applicators Name(s) and	d Registration/License Num	nber(s)		
Notice of Inspection Was Posted At or Near: 8A. Electric Breaker Box 8B. Water Heater Closet 1	Date Posted:	02/10/2021		
Beneath the Kitchen Sink 9A.Were any areas of the property obstructed or inaccessible?	Yes	X No	Г	
(Refer to Part B & C, Scope of Inspection) If "Yes" specify in 9B 9B.The obstructed or inaccessible areas include but are not limit	ed to the following:	Areas Dian	tor boy obuitting atrust	
Attic Insulated area of Deck Sub Floors Soil Grade Too High Heavy Foliage	attic X Plumbing X Slab Join Eaves	ts ☐ Craw X Wee	ter box abutting struct /I Space pholes	ure
Other Specify: 10A.Conditions conducive to wood destroying insect infestation: (Refer to Part J, Scope of Inspection) If "Yes" specify in 10B.	Yes	N/A □ No		
10B.Conducive Conditions include but are not limited to:		— — — — — — — — — —	··· -	
Planter box abutting structure (O) Wood Pile in C	vor soil line too high (L) ontact with Structure (Q)	 Formboards left in place Wood Rot (M) Wooden Fence in Con 	Heavy Heavy	ive Moisture (J) □ Foliage (N) □ e (R) □
Insufficient ventilation (T) Other (C)	Specify:		N/A	
		exas Department of Agriculto Phone 866-918-4481, Fax 88		
SPCS/T-5 (Rev. 9/1/2020)				Page 2 of 4
				1 ugo 2 01 4

2000 5 1071				77.000
9230 Fm 1371		Chappell Hill		77426
Inspected Address		ity		Code
 Inspection Reveals Visible Evidence Subterranean Termites 	e in or on the structure:	Active Infestation Yes 🔲 No 🔀	Previous Infestation Yes 🔲 No 🔀	Previous Treatment Yes 🔲 No 🔀
11B.Drywood Termites		Yes D No 🛛	Yes 🔲 No 🔀	Yes 🔲 No 🔀
11C Formosan Termites		Yes 🔲 No 🔀	Yes 🔲 No 🔀	Yes 🗌 No 🔀
11D.Carpenter Ants 11E .Other Wood Destroying Insects		Yes □ No 🛛 Yes □ No 🖾	Yes □ No 🛛 Yes □ No 🖾	Yes □ No 🛛 Yes □ No 🖾
, .	//A			
opeony.		s, existing treatment stickers or other met	oods) identified: N/A	
	autient (including pesticides, bait			
	N/A	has been observed in the followir	N/A	
11G.Visible evidence of:				
		ed. The type of insect(s) must be listed in	the first blank and all identified infe	sted areas of the property
inspected must be noted in the second b		cope of Inspection) ice of previous infestation with no prior tre	atmost as identified in Section 11	(Pofor to Part C H and I
Scope of Inspection)		s \square No \square		
	ection of conducive conditions as	identified in 10A & 10B is recommended	as follows: Yes 🔲 No 🛛	
Specify reason: N/A				
Refer to Scope of Inspection Part J				
	Diag	ram of Structure(s) Inspected		
	uding approximate perimeter mea	asurements and indicate active or previous		
	vious; D-Drywood Termites; S-So	ubterranean Termites; F-Formosan Termit	es; C-Conducive Conditions; B-Woo	od Boring Beetles; H-
Carpenter Ants; Other(s) – Specify		<u>N/A</u>		
		31		
		Garage		
	Driveway	21	-21	
		Slab		
		19		
			25	
		Pier & Beam	³⁵ Ac	
	16	Fiel & Dealli		
		Approx 223 Ln Ft		
	16			
	40	40		
	16	16		
		8 8 Pati	0	
Additional Commente Vour home is a	ligible for a 12 month warran	ty. Your Increation requite do not pr	vide for a tractment recommen	dation at this time
Additional Comments Your home is eligible for a 12 month warranty. Your Inspection results do not provide for a treatment recommendation at this time. However this does NOT mean that this home does not have a hidden or inaccessible infestation or could be attacked at any time by a new infestation.				
Please see the attached addendum for important information.				

SPCS/T-5 (Rev. 9/1/2020)

Page 3 of 4

9230 Fm 1371		Chappell Hill	77426
Inspected Address	City		Zip Code
		atement of Purchaser	
I have received the original or a legible copy of this form I understand that my inspector may provide additional ir			I have also read and understand the "Scope of Inspection."
If additional information is attached, list number of page	s:	1	_
Signature of Purchaser of Property or their Designee		Date	
Customer or Designee Not Present	Buyer's Initials		







Thank you for your purchase of a WDI report (Termite inspection). Your report shows no signs of <u>visually accessible</u> insect activity at this time. However...

This does NOT mean it is free of a visually hidden, obstructed or inaccessible infestation. It could have an infestation right now that is impossible to determine by a visual inspection alone.



Now you can protect your new home with a choice of Termite protection plans.

Our Silver Warranty Program is only \$149.00 a year.

This comes with a one year warranty that covers the cost of termite treatment should an infestation be discovered or a new one occurs.

This warranty is renewable at \$99 and includes an annual inspection with a booster treatment.

Our Gold Warranty Program is only \$249.00 a year.

This includes a one year renewable warranty for subterranean termites and carpenter ants. It includes a suppression treatment of your homes perimeter as well as an annual inspection with a booster treatment.

This gold warranty program is renewable at \$199 and includes an annual inspection with a booster treatment



Call Ron Plogman Sales & Scheduling 210-668-3936 ron@bugstop.co



