UPDATES – 1314 MABRY MILL

ITEM – YEAR	DETAILS
AC-Furnace (2021)	New AC (Oxbox/Trane)-inside & outside unit. Furnace replaced as well.
	Replaced AC ducts, grill boxes, & plenums (2010)
	First floor inlet plenum box (designed to accommodate extra thick filter).
	New thermostat wiring with backup wire installed to AC control.
Primary Bath	New frameless glass shower and shower floor installed with new Moen fixtures.
Remodel	New American Standard jetted tub with Moen fixtures and timer wall control.
(2021)	New quartz countertop with matching quartz surrounding tub and window.
	New double sinks with Moen faucets.
	Shaker-style custom made vanity (drawers built with full extension-soft close slides and new pulls (knobs).
	and new pulls/knobs).
	New tile installed through shower and tub areas. New floor tile.
	New LED lighting.
	Custom lighting accents added to both closets.
	Premium Braun Ceiling Fan.
	New toilet.
Kitchen Remodel-	Cabinetry refinished; new hardware; full extension drawer slides, and soft close
Upgrade	cabinet door hinges.
(2021)	New ceiling LED lighting installed.
, ,	Sink faucet, soap dispenser, and disposal actuation knobs replaced.
	Fresh paint – ceiling, walls, trim.
Secondary Upstairs	New Jacuzzi fiberglass tub new Moen fixtures.
Bath Remodel	New quartz countertop with new double sinks and new Moen faucets.
(2021)	Renovated vanity with Shaker-style cabinet doors and drawers with new full extension of taless drawers slides.
	extension-soft close drawer slides. • New floor tile with reinforced flooring.
	LED dimmable lighting.
	New Simonton double-pane window.
	New toilet.
New Flooring	New tile in hallway, bathrooms, and fireplace.
(2021)	New vinyl flooring and baseboard molding throughout downstairs living areas.
	 New carpet in primary bedroom, stairs, game room, and secondary bedrooms.
Half Bathroom &	New light with coordinating mirror and fixtures.
Laundry Room	New pedestal sink with wall chair rail accent.
Remodel	New toilet.
(2021)	Premium Braun ceiling fan.
Fireplace-Flue-Base	Superior brand Fireplace with replaced footing, framing, and insulation (2019).
(2019 & 2021)	New direct venting and stainless-steel chimney cap installed. New direct venting and stainless-steel chimney cap installed.
	Wall lighting and fire on/off switch added. Custom stoneywork floor tile, and months (2024).
	Custom stonework, floor tile, and mantle (2021) HDMLand electrical power utilities run thrus well to allow a least and the control of the control o
	 HDMI and electrical power utilities run thru wall to allow above-mantel TV installation. Chimney exterior surfaces sealed with Chimney Saver repellant.
Hi Efficiency, Double	Simonton double pane – vacuum filled windows in upper bedrooms and bath.
Pane Windows	Custom window moldings installed.
(2007)	Hardiplank trim installed around window with rubber sealing tape behind trim.
All Exterior Doors	Front door replaced with Mahogany Finish slab and Central Glass Oval. High quality
(2010)	Schlage lockset installed with custom door frame/decorative exterior moldings.
(/	Rear door to patio replaced. Custom pressure treated frame cut and installed along
	with rubber storm guard.
	Side garage door replaced with Feathercraft fiberglass unit & Schlage lockset.
Roof Replaced	New roof installed with GAF Timberline shingles (M&M Roofing).
(2009)	Roof ridge vents, extra soffit vents and roof vents added for increased ventilation.
	Rubber Storm Guard installed in all valleys and vulnerable areas.

0:11	
Siding, Trim, Soffits	Hardiplank siding and trim installed on sides and rear of home.
Plywood Sheathing	Plywood sheathing installed under new siding adding structural integrity to home.
(2007)	All facia and majority of soffit replaced.
, ,	New custom vents, trim, and soffits installed on both front peaks.
	Exterior trim and siding painted.
Skylight	Velux skylight installed with hurricane proof attachment hardware.
(2009)	Weather guard shielding and Velux flashing skirt installed.
	Custom molding and interior window frame box installed.
Driveway – 4 Panels	4 front driveway panels replaced.
(2005)	• 1/2" Rebar on 12 inch centers installed. 4-6 inch cement thickness poured.
Rear Patio – 4 Panels	4 rear patio panels replaced.
(2019)	6-8 inch crushed Granite base used under concrete.
(2010)	• 1/4" Rebar on 8 inch centers installed. 4-6 inch cement thickness poured.
Front Stone Walk	Replaced walkway with flagstone.
(2005)	Topidoca walkway with hagotone.
Interior General –	All walls re-plastered with smooth texture; replaced corner bead.
Molding, Lighting	Fresh paint on entire interior of home.
(2021)	Electrical switches replaced throughout.
(2021)	Custom installed chair rail moldings in game room and half bath.
	New light fixtures
	New Hunter ceiling fans – living room, primary bathroom, and game room.
1	Custom window moldings – valance, frame, sill (bedrooms)
	New doorknobs and locksets throughout.
	5 interior doors replaced with new units.
Bedrooms	New ceiling fan (primary only).
(2021)	New light fixtures (secondary bedrooms).
(2021)	New carpet and padding.
	Custom window valance.
	• Fresh paint.
Outdoors	Side fencing repaired and/or replaced (2021).
Cutadors	Back fencing replaced (withstood all hurricanes/storms since built in 2007).
	Custom front top peak vent made with treated wood.
	Front Oak and Pine trees pruned by professional tree service.
	Custom made swing (encased 30+ inches in concrete)
	Picnic table (made with knot-free pressure treated pine)
	Sandbox (custom made with hinged top cover)
	- Carrador (castern made that imiges top serie.)