

## 357 Mallard Point Replacements and Improvements

- Renovation 2007-2008
  - Master Bath downstairs
  - Master Bath upstairs
  - Added concrete slab under single car garage
  - Installed coated black cyclone fencing (3/2008)
  - Removed old insulation and re-insulated attic (2/2008)
- Heat Pump-Upstairs attic unit (2011)
- Remodeled back entrance (mud room) (10/2013)
  - Added windows
  - Cement board siding
- Small House by lake (10/2013)
  - Added windows
  - Clearcoat on the woodwork
- Goodman AC unit downstairs (4/2015)
- Replaced breaker box (4/2016)
- Replaced lake sprinkler pump with cast iron pump (7/2016)
- Pergo Pet Resistant flooring (4/2017)
- Replaced roof with 30 year GAF Shingles (10/2017)
- Installed Insinkerator garbage disposal (9/2019)
- Renovated upstairs landing area (3/2019)