
# **Cover Page**

160 West Carmel Drive,# 214
Carmel, IN 46032
317-867-7688
fax 317-867-9964
Inspection Services

Initials \_\_\_\_\_

Customer Information		Order#: 06937	Date 1/21/2022
File #: EE220018		Location	
Customer: WHR Group, Inc		Robert Childress	
Attention: Lauren Sherwood		27110 Cardiff Rocks Drive Katy TX 77494	
		Raly 17 11494	
<b>Phone</b> : 2625237511			
Type of Service			
			Estimated Repair
Inspection		Result	Cost pCi/L
Texas Real Estate Commission Home	e Inspection (TREC)	Clear 📝 Not Clear	
	<u> </u>		
Service Summary			
The Texas TREC report is not cleorrections and repairs are recordecommendations.	ear at the time of in ommended. Please	nspection. The attached report read the entire report for detai	indicates ils and
This inspection and report adhe required.	ere to the Texas Re	al Estate Commission (TREC)	standards as
The photos sent with this report within the body or summary page			
Thank you for your business.			
ayearer year ademees			
	Report Ro	eviewed by:	
Ва	rb Obert (317) 867-776	8 Ext:273 bobert@ralis.com	
AI WAYS F	Read Entire Re	port for Detailed Informa	ation



# PROPERTY INSPECTION REPORT

Prepared For: WHR Group, Inc

(Name of Client)

**Concerning:** 27110 Cardiff Rocks Drive Katy TX 77494

(Address of Inspected Property) (City, State, Zip) (Invoice/Report Number)

By: **Marc Gessner** 6033 1/20/2022 (Date)

(Name and License Number of Inspector)

6033

(Name, Signature and License Number of Sponsoring Inspector, if applicable)

### PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an items is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers.

You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods.

Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

# TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- •malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathrooms, kitchens, and exterior areas;
- •malfunctioning arc fault protection (AFCI) devices;
- •ordinary glass in locations where modern construction techniques call for safety glass;
- •malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- •malfunctioning carbon monoxide alarms;
- •excessive spacing between balusters on stairways and porches;
- •improperly installed appliances;
- •improperly installed or defective safety devices; and
- ·lack of electrical bonding and grounding; and
- •lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms requires a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

### ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

- Cosmetic Items are SPECIFICALLY EXCLUDED from this report.
- This report cannot and does not represent the operation or condition of any items after the date and time of this inspection.
- These items should not be considered a complete list of all defects with the house. This list is Limited to those items that are *Readily Accessible and the inspector(s) noted at the time of the inspection*.

Transferee Name: Rob	ert Childress		Client File/Refere	ence Number: EE22	20018		
Occupied: 🛛 Yes 🗆	] No		Approximate Age	e of Home: 8	yrs.		
Time of Inspection: 10	0:00 AM	<b>Temp:</b> 41 •	F	Weather: Clear			
<b>Dwelling Type:</b>	<b>☑</b> Detached Single	Family   Tow	nhouse 🔲 Condom	inium			
	☐ Modular/Mobile	e 🔲 Othe	r				
People Present: Homeowner							

I = Inspected		NI = Not Inspected		NP = Not Present	D = Deficient		
I	NI	NP	D				

		_	I. STRUCTURAL SYSTEMS			
×		×	A. Foundations (An opinion on performance is mandatory)			
			Type of Foundation: Slab			
			Comments: See the note(s) under the Structural section of the Summary page(s).			
			Visible evidence of ongoing water penetration? ☐ Yes ☒ No			
			Vantage point used to inspect the crawlspace:			
			☐ Entered ☐ Viewed from opening ☐ No Access ☒ Not Applicable			
×		×	B. Grading and Drainage			
			Comments: \( \sumset See the note(s) under the Structural section of the Summary page(s).			
			Does sump pump appear to be functioning properly? ☐ Yes ☐ No ☒ Not Present			
			Visible evidence of negative grade towards foundation of home?   ✓ Yes □ No			
			Do gutters/downspouts effectively direct water away			
			NOTES: PROPER DRAINAGE AND SOIL MOISTURE CONTENTS SHOULD BE MAINTAINED AROUND THE FOUNDATION TO HELP MINIMIZE FUTURE FOUNDATION PROBLEMS. WE MAKE NO STATEMENT CONCERNING SITE STABILITY.			
×		×	C. Roof Covering Materials			
			Type of Roof Covering (1): Asphalt/Fiberglass Shingle			
			Viewed From: ⋈ Walked ☐ From eaves ☐ From ground with binoculars			
			Type of Roof Covering (2): Not Present			
			Viewed From: ☐ Walked ☐ From eaves ☐ From ground with binoculars			
			Type of Roof Covering (3): Not Present			
			Viewed From: ☐ Walked ☐ From eaves ☐ From ground with binoculars			
			Describe and explain any levels of roof not accessed: Upper not walked due to height.			
			Evidence of previous repairs to roofing material?   Yes No			
			Evidence of water penetration?   Yes No			
			Comments: \( \sumset See the note(s) under the Structural section of the Summary page(s).			
			Approximate age of roof (1): 8 yrs. Location (1): Whole house			
			Design Life (1): 15-20 yrs.			
			Approximate age of roof (2): yrs. Location (2):			
			Design Life (2): yrs.			
			Approximate age of roof (3): yrs. Location (3):			
			Design Life (3): yrs.			

I = ]	Inspect	ed	N	I = Not Inspected NP = Not Present D = Deficient
I	NI	NP	D	
×	×			D. Roof Structures and Attics
				Viewed From: ■ Entered □ Viewed from opening □ No Access
				Approximate Average Depth of Insulation: 5-6 inches ☐ Unknown ☐ Not Present
				Evidence of water penetration?   Yes  No
				Comments: ⊠ See the note(s) under the Structural section of the Summary page(s).
×			×	E. Walls (Interior and Exterior)
				Evidence of water penetration?
				Comments: See the note(s) under the Structural section of the Summary page(s).
				<b>Exterior Surface Types and Locations:</b>
				Surface 1 Type: Brick Location: All Sides
				Surface 2 Type: Cementitious Composite Location: Sides/Rear
				Surface 3 Type: Location:
×			×	F. Ceilings and Floors
				Evidence of water penetration?
				Comments: See the note(s) under the Structural section of the Summary page(s).
×			×	G. Doors (Interior and Exterior)
		•	•	Evidence of water penetration?
				Comments: \( \sumset See the note(s) under the Structural section of the Summary page(s).
×				H. Windows
				Evidence of water penetration?
				Comments: \( \sumset See the note(s) under the Structural section of the Summary page(s).
				NOTES: SIGNS OF FAILED SEALS IN THE THERMAL PANE WINDOWS MAY APPEAR AND DISAPPEAR AS TEMPERATURE AND HUMIDITY CHANGES. SOME WINDOWS WITH FAILED SEALS MAY NOT HAVE BEEN EVIDENT AT THE TIME OF THE INSPECTION. WINDOWS ONLY CHECKED FOR OBVIOUS FOGGING.
				STORM WINDOWS ONLY CHECKED FOR DAMAGED OR MISSING GLASS.
×				I. Stairways (Interior and Exterior)
				Comments: ∑See the note(s) under the Structural section of the Summary page(s).
×				J. Fireplaces and Chimneys
				Comments: ⊠See the note(s) under the Structural section of the Summary page(s).
				Number of Fireplaces: 1 Fuel: ☑ Gas ☐ Wood
				Type: ☐ Metal Box & Flue ☐ Masonry/Brick ☒ Insert ☐ Wood Stove ☐ Other
				NOTE: INSPECTION OF FLUE LINERS IS LIMITED.

I =	Inspect	ed	N	II = Not Inspected NP = Not Present	D = Deficient			
I	NI	NP	D					
×				K. Porches, Balconies, Decks, and Carports				
				Comments: See the note(s) under the Structural sect	tion of the Summary page(s).			
×				L. Other				
	l		1	Comments: See the note(s) under the Structural sect	ion of the Summary page(s).			
				Walks: Visible trip hazards or defects noted?	☐ Yes ☒ No ☐ Not Present			
				Driveway: Visible trip hazards or defects noted?	☐ Yes   No ☐ Not Present			
				Retaining Walls: Visible defects noted?	☐ Yes ☐ No ☒ Not Present			
				II. ELECTRICAL SY	STEMS			
×				A. Service Entrance and Panels				
			1—	Comments: See the note(s) under the Electrical secti	on of the Summary page(s)			
				Amps: 200 Volts: 120/240	on of the Summary page(s).			
				Is incoming electrical service adequate to meet the ne	eeds of the			
				dwelling? ✓ Yes □ No				
X			×	B. Branch Circuits, Connected Devices, and Fix	tures			
	•	•	•	Type of wiring: Copper				
				Comments: See the note(s) under the Electrical secti	on of the Summary page(s).			
				III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS				
X				A. Heating Equipment				
				Type of System (Unit 1): Heat Pump				
				Energy Source (Unit 1):  Electric  Gas  Oil	] Other			
				Type of System (Unit 2): Heat Pump	_			
				Energy Source (Unit 2): $\square$ Electric $\square$ Gas $\square$ Oil $\square$ Other Comments: $\square$ See the note(s) under the Heating / AC section of the Summary page(s).				
					ection of the Summary page(s).			
				Number of heating units present: 2				
					e (Unit 1): 10-15 yrs			
				Location (Unit 1): Attic				
				Approximate Age (Unit 2): 8 yrs Design Life Location (Unit 2): Attic	e (Unit 2): 10-15 yrs			
				Evidence of fuel storage tank? ☐ Yes ☒ No	In use? ☐ Yes ☐ No			
					Location:			
				NOTES: FULL EVALUATION OF THE INTEGRITY OF	A HEAT EXCHANGER REQUIRES			
				DISMANTLING OF THE FURNACE AND IS BEYOND T				

I =	I = Inspected N		N	I = Not Inspected NP = Not Present D = Deficient
I	NI	NP	D	
×			×	B. Cooling Equipment
				Type of System (Unit 1): Central
				Type of System (Unit 2): Central
				Comments: See the note(s) under the Heating / AC section of the Summary page(s).
				Number of cooling units present: 2
				Approximate Age (Unit 1): 8 yrs Design Life (Unit 1): 10-15 yrs Location (Unit 1): Right
				Approximate Age (Unit 2): 8 yrs Design Life (Unit 2): 10-15 yrs Location (Unit 2): Right
				NOTES: UNITS ARE NOT INSPECTED FOR PROPER SIZE OR EFFICIENCY. UNITS ARE NOT OPENED FOR INSPECTION. WINDOW A/C UNITS ARE NOT INSPECTED.
×				C. Duct System, Chases, and Vents
				Comments: See the note(s) under the Heating AC section of the Summary page(s).  NOTE: INSPECTION OF FLUES IS LIMITED.
				IV. PLUMBING SYSTEMS
×			×	A. Plumbing Supply, Distribution Systems and Fixtures
	ı	1	I	Location of water meter: Front
				Location of main water supply valve: Garage
				Static water pressure reading: 60 psi
				Comments: ∑See the note(s) under the Plumbing section of the Summary page(s).
				Water Source: ☑ Public ☐ Private (See Optional Systems)
			1	How verified: Visual
×				B. Drains, Wastes, and Vents
				Comments:   See the note(s) under the Plumbing section of the Summary page(s).  Sewage Service:   Private (See Optional Systems)
	1			How verified: Visual
X				C. Water Heating Equipment
				Comments: ⊠ See the note(s) under the Plumbing section of the Summary page(s).
				Energy Source (Unit 1): Electric Capacity (Unit 1): 40 gal
				Energy Source (Unit 2): Electric Capacity (Unit 2): 40 gal
				Approximate Age (Unit 1): 8 yrs Design Life (Unit 1): 10-15 yrs
				Location (Unit 1): Garage
				Approximate Age (Unit 2): 8 yrs Design Life (Unit 2): 10-15 yrs Location (Unit 2): Garage

I =	I = Inspected N		N	I = Not Inspected NP = Not Present D = Deficiency
I	NI	NP	D	
			T	
×			×	D. Hydro-Massage Therapy Equipment
				Comments: See the note(s) under the Plumbing section of the Summary page(s).
				V. APPLIANCES
	×			A. Dishwashers
				Comments: See the note(s) under the Appliances section of the Summary page(s).  NOTE: LOWER PANEL NOT REMOVED FOR INSPECTION.
	×			B. Food Waste Disposers
	•			Comments: See the note(s) under the Appliances section of the Summary page(s).
	×			C. Range Hood and Exhaust Systems
				Comments: See the note(s) under the Appliances section of the Summary page(s).  NOTE: RANGE VENT NOT CHECKED FOR CLEANLINESS.
	×			D. Ranges, Cooktops, and Ovens
				Comments: See the note(s) under the Appliances section of the Summary page(s).  Range: Oven: Cooktop:  □ Electric □ Gas □ Electric □ Gas  NOTES: IF PRESENT, DELAY TIMER AND SELF-CLEAN MODE ARE NOT TESTED.
	×			E. Microwave Ovens
				Comments: See the note(s) under the Appliances section of the Summary page(s).  NOTE: MICROWAVE OVEN NOT INSPECTED FOR RADIATION LEAKS.
X				F. Mechanical Exhaust Vents and Bathroom Heaters
	1	ı	ı	Comments: ∑See the note(s) under the Appliances section of the Summary page(s).
×				G. Garage Door Operators
				Comments: ⊠ See the note(s) under the Appliances section of the Summary page(s).
	×			H. Dryer Exhaust Systems
				Comments: See the note(s) under the Appliances section of the Summary page(s).  NOTE: DRYER VENT NOT CHECKED FOR CLEANLINESS.

Address of Inspected Property: N27 W23681 Paul Road

I = Inspected NI = Not Inspe			ot Inspe	cted NP = Not Present D = Deficiency
I	NI	NP	D	
				VI. OPTIONAL SYSTEMS
	×			A. Landscape Irrigation (Sprinkler) Systems
				Comments: ⊠ See the note(s) under the Optional Systems section of the Summary page(s).
				Control Panel Location: Number of Zones used:
				Valve Box Location:
				Coverage: ☐ Front Yard ☐ Back Yard ☐ Side Yard(s) ☐ Other
				NOTE: SPRINKLER CONTROLS ARE OPERATED IN MANUAL MODE ONLY.
		×		B. Swimming Pools, Spas, Hot Tubs, and Equipment
				Comments: ⊠ See the note(s) under the Optional Systems section of the Summary page(s).
				Type of Construction (pool):
				Type of Construction (hot tub/spa):
				Is pool winterized? ☐ Yes ☐ No
				Type of pool: ☐ In ground ☐ Above ground ☐ Other
				Type of pool filter: ☐ Sand ☐ Cartridge ☐ D.E. ☐ Other
				Is hot tub/spa winterized? ☐ Yes ☐ No
				Type of hot tub/spa: ☐ In ground ☐ Above ground ☐ Other
				Type of hot tub/spa filter: ☐ Sand ☐ Cartridge ☐ D.E. ☐ Other
				NOTE: NOT CHECKED FOR POOL SHELL LEAKAGE OR IN BACKWASH MODE. THE POOL COATING IS CONSIDERED COSMETIC AND NOT PART OF THIS INSPECTION. ALL CONTROLS ARE OPERATED IN THE MANUAL MODE ONLY. ANCILLARY EQUIPMENT SUCH AS COMPUTER CONTROLS, CHLORINATORS OR OTHER CHEMICAL DISPENSERS, WATER IONIZATION DEVICES OR CONDITIONERS ARE NOT INSPECTED.
		×		C. Outbuildings
				Comments:   See the note(s) under the Optional Systems section of the Summary page(s).

I = In	spected	NI = N	ot Inspe	ted NP = Not Present D = Deficiency		
I	NI	NP	D			
		×		D. Private Water Wells (A coliform analysis is recommended)		
				Type of pump:		
				Type of storage equipment:		
				Comments: See the note(s) under the Optional Systems section of the Summary page(s).		
				Location of well in relationship to the home?  North South East West Unknown		
				Approximate distance between well and septic system? ft		
				Is distance acceptable to current standards? ☐ Yes ☐ No ☐ N/A ☐ City Water		
				Does well have a visible riser? ☐ Yes ☐ No		
				Location of pressure tank?   Garage Utility Room Basement/Crawl Other		
				Estimated pressure? psi Estimated flow after 30 minutes? gpm		
				Date water sample sent to local lab:		
				Lab name: Lab phone:		
		×		E. Private Sewage Disposal (Septic) Systems		
				Type of System:    Private    Aerobic    Other		
				Location of drainfield: North South East West Unknown		
				Comments: ⊠ See the note(s) under the Optional Systems section of the Summary page(s).		
				Is property occupied at time of inspection? ☐ Yes ☐ No		
				NOTE: If No, report is qualified as the system was not under regular use at the time		
				of the inspection.		
				Does tank have a visible riser? ☐ Yes ☐ No		
				Approximate distance between septic system and well?		
				Is distance acceptable to current standards? ☐ Yes ☐ No ☐ N/A ☐ City Water		
				Method of evaluation: ☐ Dye & Visual ☐ Visual only		
				Was water ran for a minimum of 30 minutes? ☐ Yes ☐ No		
				Was any effluent and/or dye visible on ground? ☐ Yes ☐ No		
				Functional drainage? ☐ Yes ☐ No		

Record on this page the corrective action required for all items determined to be defective including the estimated cost of repairs and explain any items that were reported as "Not Inspected." These estimates are not bids, nor are they intended to be used as such. Other information may also be listed on this page as "NOTES" or "FYI".

RAL recommends that at least one qualified repair contractor provide a detailed bid for these repairs prior to closing.

This inspection report was solely intended for use by RAL's specific relocation client who may decide to provide to other interested parties for disclosure purposes only. The information contained within this report is NOT intended to be used or relied upon by any other interested party. All interested parties should obtain their own independent inspections.

#### I. STRUCTURAL SYSTEMS

#### I.A. FOUNDATIONS

1. Qualified contractor to correct as determined necessary the exposed post tension cable end at the left rear corner of the home.

#### I.B. GRADING & DRAINAGE

1. Qualified contractor to correct as determined necessary the negative grading and high soil line at the front.

#### I.C. ROOF COVERING MATERIALS #1

1. Qualified roofing contractor to correct as determined necessary the loose flashing at the lower front center.

#### I.D. ROOF STRUCTURES & ATTICS

1. No visible defects noted at time of the inspection.

NOTE: Attic framing was not inspected due to insulation.

FYI

NOTE: Inspection of attic was limited due to design, ductwork, and insulation.

FYI

#### I.E. WALLS (INTERIOR & EXTERIOR)

- 1. Qualified siding contractor to correct as determined necessary the deficiencies listed below:
- a. Siding seams need sealing at the left and right sides of the home.
- b. Cracked sealant around the window frames and garage door trim.
- 2. Qualified contractor to correct as determined necessary the crack at the wall in the second floor utility room

### I.F. CEILINGS & FLOORS

1. Qualified contractor to correct as determined necessary the crack at the family room ceiling.

#### I.G. DOORS (INTERIOR AND EXTERIOR)

1. Qualified contractor to correct as determined necessary the doors to study that have been moved to exterior of the door frame and do not lock properly.

#### I.H. WINDOWS

1. No visible defects noted at time of the inspection.

# I.I. STAIRWAYS (INTERIOR AND EXTERIOR)

1. No visible defects noted at time of the inspection.

#### I.J. FIREPLACES AND CHIMNEYS

1. No visible defects noted at time of the inspection.

NOTE: The inspection of exterior chimney components and/or interior components of fireplaces, chimneys and flues can be limited by design or accessibility with areas that are beyond the scope of this visual inspection.

FYI

#### I.K. PORCHES, BALCONIES, DECKS AND CARPORTS

1. No visible defects noted at time of the inspection.

#### I.L. OTHER

1. No visible defects noted at time of the inspection.

#### **II. ELECTRICAL SYSTEMS**

#### **II.A. SERVICE ENTRANCE AND PANELS**

1. No visible defects noted at time of the inspection.

### II.B. BRANCH CIRCUITS, CONNECTED DEVICES, AND FIXTURES

1. Qualified electrical contractor to correct as determined necessary the missing GFCI protection at the outlets in the upper and lower utility rooms.

#### III. HEATING, VENTILATION, AND AIR CONDITIONING SYSTEMS

#### III.A. HEATING EQUIPMENT (UNIT #1)

1. No visible defects noted at time of the inspection.

### III.B. COOLING EQUIPMENT (UNIT #1)

1. Qualified HVAC contractor to correct as determined necessary the rust in both of the emergency drain pans.

#### III.C. DUCT SYSTEMS, CHASES, AND VENTS

1. No visible defects noted at time of the inspection.

#### IV. PLUMBING SYSTEM

#### IV.A. PLUMBING SUPPLY, DISTRIBUTION SYSTEMS AND FIXTURES

- 1. Qualified plumbing contractor to correct as determined necessary the deficiencies listed below:
- a. No positive stop on the hall bathtub faucet.
- b. Missing anti-siphon devices at the exterior hose bibs.

NOTE: Nibco PEX piping with plastic fittings.

FYI

NOTE: Water softener was not inspected as part of this home inspection.

FYI

# IV.B. DRAINS, WASTES, AND VENTS

1. No visible defects noted at time of the inspection.

### IV.C. WATER HEATING EQUIPMENT (UNIT #1)

1. No visible defects noted at time of the inspection.

#### IV.D. HYDRO-MASSAGE THERAPY EQUIPMENT

1. Qualified contractor to correct as determined necessary the missing access to the hydro-therapy tub motor.

# V. APPLIANCES

## **V.A. DISHWASHERS**

1. Not Inspected.

### **V.B. FOOD WASTE DISPOSERS**

1. Not Inspected.

#### V.C. RANGE HOOD AND EXHAUST SYSTEMS

1. Not Inspected.

# V.D. RANGES, COOKTOPS, AND OVENS

1. Not Inspected.

#### **V.E. MICROWAVE OVENS**

1. Not Inspected.

#### V.F. MECHANICAL EXHAUST VENTS AND BATHROOM HEATERS

1. No visible defects noted at time of the inspection.

#### **V.G. GARAGE DOOR OPERATORS**

1. No visible defects noted at time of the inspection.

# V.H. DRYER EXHAUST SYSTEMS

1. Not Inspected.

## **VI. OPTIONAL SYSTEMS**

### VI.A. LANDSCAPE IRRIGATION (SPRINKLER) SYSTEMS

1. Not Inspected. Not requested at time of inspection.

#### VI.B. SWIMMING POOLS, SPAS, HOT TUBS, AND EQUIPMENT

1. Not Present.

#### **VI.C. OUTBUILDINGS**

1. Not Present.

VI	D	PRI	<b>VATE</b>	WA-	TFR	WFI	I S
VI.	. <b>.</b>	FNI	VAIL	VV A	ıLn		டப

1. Not Present.

# VI.E. PRIVATE SEWAGE DISPOSAL (SEPTIC) SYSTEMS

1. Not Present.

PLEASE SEE NEXT PAGE FOR PROGRAM REQUIRED REPAIRS.

#### HOME INSPECTION- PROGRAM REQUIRED REPAIRS- ROBERT CHILDRESS

### 27110 Cardiff Rocks Dr., Katy, TX 77494

### 1. Foundation

Qualified licensed structural engineer to further evaluate the post tension cable ends at the left rear corner of the home. Qualified structural engineer to further evaluate, make any necessary repairs and verify in writing no further action needed. WHR Group to obtain bid.

### 2. Roof

Qualified licensed roofing contractor to further evaluate and correct as determined necessary the loose flashing at the lower front center of the roof. Qualified roofing contractor to make any necessary repairs and verify in writing no further action needed. WHR Group to obtain bid.

***	Buver	Initials	/	***



Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: 1

File #: 06937



Line Item #: I

Description: Front of home.



Line Item #: I

Description: Front of home.



Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: 2

File #: 06937

Line Item #: I

Description: Right side of home.



Line Item #: I

Description: Right side of home.





Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: 3

File #: 06937



Line Item #: I

Description: Rear view of home.

Line Item #: I

Description: Rear view of home.





Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: 4

File #: 06937



Line Item #: I

Description:

Left side of home.



Line Item #: I

Description: Left side of home.



Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: 5

File #: 06937

Line Item #: I.A

Description:

Exposed post tension cable end at the left rear corner of the home.



Line Item #: I.B.

Description:

Negative grading and high soil line at the front.



Initials \_\_\_\_\_/



Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: 6

File #: 06937

Line Item #: I.C.

Description: **Roof view** 



Line Item #: I.C.

Description: **Roof view** 





Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: 7

File #: 06937

Line Item #: I.C.

Description: **Roof view** 



Line Item #: I.C.

Description: **Roof view** 





Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: 8

File #: 06937

Line Item #: I.C.

Description: **Roof view** 



Line Item #: I.C.

Description: **Roof view** 





Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: 9

File #: 06937

Line Item #: I.C.

Description:

Loose flashing at the lower front center.



Line Item #: I.D.

Description: NOTE: Attic framing was not inspected due to insulation.





Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: 10

File #: 06937



Line Item #: I.D.

### Description:

NOTE: Inspection of attic was limited due to design, ductwork, and insulation.



Line Item #: I.E.

# Description:

Example of siding seams need sealing at the left and right sides of the home.

Initials \_\_\_\_\_/



Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: 11

File #: 06937



Line Item #: I.E.

### Description:

Example of siding seams need sealing at the left and right sides of the home.



Line Item #: I.E.

# Description:

Example of siding seams need sealing at the left and right sides of the home.

Initials \_\_\_\_\_/\_\_\_



Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: 12

File #: 06937



Line Item #: I.E.

### Description:

Example of siding seams need sealing at the left and right sides of the home.



Line Item #: I.E.

# Description:

Example of cracked sealant around the window frames.


Initials \_\_\_\_\_/\_\_



Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: **13** 

File #: 06937



Line Item #: I.E.

Description:

Example of cracked sealant around the window frames.



Line Item #: I.E.

Description: **Example of cracked sealant around the window frames.** 

Initials \_\_\_\_/\_\_



Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: **14** 

File #: 06937



Line Item #: I.E.

Description:

Example of cracked sealant around the window frames.



Line Item #: I.E.

Description: **Example of cracked sealant around the window frames.** 

Initials \_\_\_\_\_/\_\_



Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: **15** 

File #: 06937



Line Item #: I.E.

Description:

Example of cracked sealant around the window frames.



Line Item #: I.E.

Description: **Example of cracked sealant around the window frames.** 

Initials \_\_\_\_/\_\_\_



Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: **16** 


File #: 06937



Line Item #: I.E.

Description:

Example of cracked sealant around the window frames.



Line Item #: I.E.

Description:

Example of cracked sealant around the garage door trim.


Initials \_\_\_\_/\_\_



Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: **17** 

File #: 06937





Example of cracked sealant around the garage door trim.



Line Item #: I.E.

Description:

Crack at the wall in the second floor utility room.





Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: 18

File #: 06937

Line Item #: I.F.

Description:

Crack at the family room ceiling.



Line Item #: I.G.

Description:
Doors to study have been moved to exterior of the door frame and do not lock properly.



Initials \_\_\_\_/\_\_\_



Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: 19

File #: 06937




Line Item #: I.G.

Description:

Doors to study have been moved to exterior of the door frame and do not

lock properly.



Line Item #: II.A.

Description:

Main Electrical Panel.

Initials \_\_\_\_/\_\_



Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494


Page: 20

File #: 06937

Line Item #: II.A.

Description:

Main electrical panel with cover off.



Line Item #: II.B.

Description:
Missing GFCI protection at the outlets in the upper and lower utility rooms.





Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: **21** 

File #: 06937

Line Item #: II.B.

Description:

Missing GFCI protection at the outlets in the upper and lower utility rooms.



Line Item #: III.A

Description:

Air Handler Unit #1.





Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494


Page: **22** 

File #: 06937



Line Item #: III.A

Description: Air Handler Unit #1 data plate



Line Item #:

Description: Air Handler Unit #2.


Initials \_\_\_\_\_/\_\_



Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: **23** 

File #: 06937



Line Item #:

Description:

Air Handler Unit #2 data plate



Line Item #: III.B.

Description: **A/C unit #1.** 

Initials \_\_\_\_/\_\_



Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: **24** 

File #: 06937

Line Item #: III.B.

Description: **A/C unit #2.** 



Line Item #: III.B.

Description: Rust in the emergency drain pan.






Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: **25** 

File #: 06937





Rust in the emergency drain pan.



Line Item #: IV.A.

Description: No positive stop on the hall bathtub faucet.



Initials \_\_\_\_\_/\_\_



Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: **26** 

File #: 06937



Line Item #: IV.A.

Description:
Missing anti-siphon devices at the exterior hose bibs.



Line Item #: IV.A.

Description: Nibco PEX piping with plastic fittings.

Initials \_\_\_\_\_/\_\_\_



Inspection Location: Robert Childress 27110 Cardiff Rocks Drive Katy, TX 77494

Page: **27** 

File #: 06937

Line Item #: IV.C.

Description: Water Heater Unit #1.



Line Item #: IV.C.

Description: Water Heater Unit #2.

