HouseCheck Property Inspection Report



33 Violet Sunset Ln, Tomball, TX 77375 Inspection prepared for: Rich Newhart Real Estate Agent: Jane Hardcastle - Jane Hardcastle Realty

> Date of Inspection: 10/28/2019 Time: 9:00 AM Age of Home: 2019 Size: 4000 Weather: 70F Clear Order ID: 1407

Inspector: Russell Redfield TREC # 21614 403 Pin Oak Ln, Magnolia, TX Phone: 713-502-5221 Email: Russell.Redfield@housecheck.com

HOUSE CHECK Inspections. Done Right.

Н	οu	se	Cł	he	ck
					<u> </u>

PROPERTY INSPECTION REPORT					
Prepared For: Rich Newhart					
(Name of Client)					
Concerning: <u>33 Violet Sunset Ln, Tomball TX, 77375</u>					
(Address or Other Identification of Inspected Property)					
Russell Redfield, TREC # 21614	10/28/2019				
(Name and License Number of Inspector)	(Date)				
	Rich Newhart (Name of Client) 33 Violet Sunset Ln, Tomball TX, 7 (Address or Other Identification of Inspected Prop Russell Redfield, TREC # 21614				

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods.

Promulgated by the Texas Real Estate Commission (TREC) P.O. Box 12188, Austin, TX 78711-2188 (512) 936-3000 (http://www.trec.texas.gov).

REI 7-5 (05/4/2015)

Page 1 of 40

Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices for electrical
- receptacles in garages, bathrooms, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms require a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.


ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

REI 7-5 (05/4/2015)

HouseCheck			33 Violet Sunset Ln, Tomball, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	I. ST	RUCTURAL SYSTEMS	5
	A. Foundations		
	Type of Foundation(s) • Slab on grade founda Comments: • About Foundations:		
	Foundations are desig components of a dwel ground. Foundation m systems of the house. soil and, during the life that do not operate pro	ned to provide a base f ling as well as transfer t ovement can have a ne Slab-on-grade foundati the foundation, you ca operly, as well as cracks	e slab or pier and beam. For the framing and structural the weight of the dwelling to the egative impact on the structural ions are designed to move with the in expect to find doors and windows is to interior/exterior walls. These are dation failure or adverse
	Inspectors' opinions and components. Imperfect coverings, behind wall engineering measurer condition of any found professional for further • Note: No signs of set time of the inspection. • Foundation elevation Point zero was set at to the residence. Variance	re limited to the visible i stions can be obstructed s, landscaping and othe nents or perform any te ation. We recommend f r evaluation and diagno ttlement were observed as were measured throu the center of the home a ces detected in a slab ca these readings, the four	on are not visually accessible. nterior and exterior structural d or hidden behind wall and floor er items. Inspectors do not take sts that would indicate the exact further evaluation by a qualified sis if there are concerns. to the foundation structure at the ughout the home using a Zip Level. and measured through each side of an indicate possible signs of ndation appears to be performing as

HouseCheck


I=Inspected NI=Not Inspected NP=Not Present D=Deficient NI NP D 1 Slab on grade foundation Zip level front center



Zip level front left

Page 4 of 40

Zip level front right



HouseCheck			33 Violet Sunset Ln, Tomball, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	of the foundation. Wa encourage growth of should slope 6" within should be at least 4" f materials. Grading an research, soil and top inspection. Any deficit condition and should concerns. • The grade of the growthe the flow of water away the residence. This case as the installation of a	Drainage: rainage away from the structure possible organic materials in the first 10' away from the for brick, stone, or fiber ce and drainage is inspected vi pographical studies are no be evaluated by a qualifie bund around the residence y from the property in the an be achieved by the ado	ucture is vital to the performance ood rot, attract insects and s. As a general rule, the ground he house. Clearance to wall siding ement and 6" for any other siding isually around the site. Flood plain t performed as a part of the indication of a more serious ad professional if there are e should be improved to promote following locations: back side of dition or removal of top soil as well ound should slope away from the he first 10 feet.




Type(s) of Roof Covering:

- Composition shingle
- Viewed From:
- Ground with binoculars
- Comments:
- About Roof Coverings:

The roof consists of different materials and layers that come together to keep water from penetrating the structure. These systems include the outer roof covering materials, underlayment, metal flashings, sheathing, and roof decking. The roof is inspected visually and is limited to what can be seen at all accessible locations of the roof. Many elements of the roof are hidden and there is no guarantee that all damage, installation defects, and leaks can be detected. We always recommend consultation with a qualified roofing professional if there are any concerns or a need to determine insurability, life expectancy, or the potential for future problems which may arise. Any deficiencies found could be an indication of a more serious condition.

• The roof covering was inspected and no deficiencies were observed at the time of the inspection.






Left side roof slope

Rear roof slope




Rear roof slope


HouseCheck			33 Violet Sunset Ln, Tomball, T>
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D)		
	_		
	D. Roof Structure and	Attics	
	Viewed From: • Attic Approximate Average • Radiant Barrier Prese • Insulation depth is be Comments: • About the Roof Struc	ent etween 10 and 12 inche	s
	the attic is an essentia in the attic must be of should also be sufficie home. The overall attic	I element to creating an sufficient depth to achie nt air flow and/or humid c venting ratio should be	al reasons. In warm, moist climates a energy-efficient dwelling. Insulation eve proper energy efficiency. There lity control in all confined areas of a e at least 1/150th of the total are taken as a part of the
	can only visibly inspect considered safe to acc remain hidden or inacc defects and leaks can Any deficiencies found	t these components in a cess by the inspector. M cessible. There is no gu be detected. Inspection I could be an indication aluation by a qualified p	de decking of the roof. Inspectors areas that are accessible and lany elements of the roof and attic arantee that all damage, installation as are limited to accessible areas. of a more serious condition. We professional for further evaluation
			r view all areas of the attic due to a
			nt in the attic space per today's
	installed to allow home	eowners or service pers erior wall in lower attic h	Il screws.Doors should have hinges onnel to access attic without tools. has been damaged. This should be



I=Inspected NI=Not Inspected NP=Not Present D=Deficient	
I=Inspected NI=Not Inspected NP=Not Present D=Deficient	
I NI NP D	
I NEWP D If NEWPP D If NEWPPP D If NEWPPPP D If NEWPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPP	



HouseCheck			33 Violet Sunset Ln, Tomball, T
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
x	F. Ceilings and Floors		
	Ceiling and Floor Mate • Floor covering materi • Floor covering materi Comments: • About Ceilings and F	ial is carpet ial is tile	
	structural performance that do not indicate a n Any area that is enclos deficiencies noted can	Condition of surface find nore serious problem and sed, inaccessible, or not be an indication of a manual aluation by a qualified p	noisture penetration and general inishes and cosmetic imperfections re not noted in the inspection report. t visible cannot be inspected. Any fore serious condition. We professional for further evaluation
	 All ceilings and floors of the inspection. 	were inspected and no	o deficiencies were noted at the time
	Floor covering		Floor covering




HouseCheck			33 Violet Sunset Ln, Tomball,⊺
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
x	H. Windows		
	Window Types: Comments: • About Windows:		
	examined for broken s all proper locations. A	seals/glazing strips and to ny deficiencies found car nend further evaluation b	functionality. Windows are he presence of tempered glass in n be an indication of a more serious y a qualified window repair
		Output	
\mathbf{x}	I. Stairways (Interior a	•	
	Comments: • About Stairways:		
	practices. Safety conc of the inspection report	erns of risers, steps and t. Any deficiencies noted	ompliance with common building rails are noted within this section d could indicate a more serious ed professional if there are
	 The stairway(s) were inspection. 	e inspected. No deficienc	ies were noted at the time of the

Х

HouseCheck			33 Violet Sunset Ln, Tomball, T
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
	J. Fireplaces and Chimn	,	
	time of the inspection. À inspection report. Inspec flue, lintel, fuel source, a can only be determined Exterior chimney compo- chimney cap and crown tested. We always recor necessary) by a qualifier or any of its accessories condition and should be concerns. • The fireplace was insp inspection.	Fireplaces: Fireplaces: Any defects observed and ction fireplace compone and hearth extension. Pr if the attic penetration is prents include the chimr Drafting capability of the nmend a complete exard and licensed chimney Any deficiencies noted evaluated by a qualified ected and no deficiencies ected. The gas service	ney extension, spark arrestor, ne chimney is not measured or mination and cleaning (if sweep prior to using the fireplace d could indicate a more serious d chimney professional if there are es were noted at the time of the was verified at the supply line. No

X




HouseCheck			33 Violet Su	unset Ln, Tomball, T>
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
		Rear patio		
	L. Other	·		
	Materials: Comments:			
	II. E	LECTRICAL SYSTEMS	5	
REI 7-5 (05/4/20)15)			Page 19 of 40

HouseCheck				33 Violet Sunset Ln, Tomball, T⊁
l=Inspecte	d	NI=Not Inspected	NP=Not Present	D=Deficient
ININ	IP D			
	X	A. Service Entrance and	d Panels	
		Panel Locations: • Electrical panel is loca Materials and Amp Rat • Copper wiring presen • 150 amp service Comments: • About Electric Panels	ing: t	the building
		inspection. The electric	al service system inclu ter and service panel. I	al service system are included in the ides components such as the inspectors will attempt to remove to do so.
		walls or other obstruction visible inspection, there conditions that are hidd effectiveness or perform has any concerns with encouraged to consult	ons. Though some con e may be some underly den from view. The insp mance of any over-curr the electrical system of with a licensed electric serious condition and	t accessible as it is hidden behind ditions can be discovered by a ring hazardous or damaging bector does not verify the rent devices/breakers. If the client r its insurability, they are ian. Any deficiencies found could be further evaluation/diagnosis by a
		carrying a live load.	it panel enclosure prop	arked to identify if the conductor is erly. This appears to be due to
150	0 Amp	Square D service panel	I Service	e panel with dead front removed

X

HouseCheck			33 Violet Sunset Ln, Tomball, T
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
	arked white conductors		Image: Note of the sector of
	B. Branch Circuits, Co		
	 Type of Wiring: Copper wiring prese Comments: About Branch Circuit 		s and Fixtures:
	fixtures. Much of the e walls or other obstruct visible inspection, ther conditions that are hid inspected and reporte sources for smoke ala suitability for the heari	electrical system in notions. Though some care may be some under den from view. GFC d by the inspector. The rms are noted, their e ng impaired are not v	such as wiring, switches, outlets and t accessible as it is hidden behind onditions can be discovered by a rlying hazardous or damaging and AFCI protection devices are ough general locations and power effectiveness, interconnectivity or erified. Low voltage systems and not included in the inspection.
	 Exterior GFCI outlet(Bathroom GFCI outlet Laundry room GFCI Kitchen GFCI outlets Garage GFCI outlet(et(s) reset in the front outlet(s) reset in the k reset is located in the	downstairs bathroom ‹itchen e kitchen
	III. HEATING, VENTILA	TION AND AIR CONI	DITIONING SYSTEMS


HouseCheck			33 Violet Sunset Ln, Tomball, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
x	A. Heating Equipment		
	Type of Systems: • Gas fired forced hot a • The home has two sp • Brand: Lennox // Mar • Brand: Lennox // Mar Energy Sources: • Both furnaces are ga Comments: • About Heating Equip	blit systems nufactured in:2019 nufactured in:2019 s powered.	
	units often work in con operates the heating e	junction with central co	late the inside air. Central heating oling systems. The inspector safe to do so. Inspectors visually and safety issues.
	part of the home inspe accuracy of the thermo uniformity of the air su heating/cooling system deficiencies can be an	ction. Inspectors do not ostat, integrity of the hea pply. In order to maximi n, it is advisable to have indication of a more se	heating or cooling components as a t verify compatibility of components, at exchanger, sizing/tonnage, or ize the efficiency of a them serviced annually. Any prious condition, and further dvised if there are concerns.
	Temperature measure Adequate warm air wa Temperature measure • Flue pipe for upstairs	d at the supply registers s noted throughout the d at the supply registers	second story of the home. s:119 electrical circuit. Flue pipe is
Le	ennox gas furnace		Eennox gas furnace



HouseCheck			33 Violet Sunset Ln, Tomball, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	B. Cooling Equipment		
	Type of Systems: • Brand:Lennox • Brand: Lennox • Year(s) Manufactured • Refrigerant: R-410A • The home has two sp Comments: • About Cooling Equipr	lit systems	
	conditioning units ofter inspector operates the degrees and deemed s	work in conjunction wit	d circulate the inside air. Central air th central heating systems. The e outside temperature is above 60 s visually inspect the cooling sues.
	part of the home inspe- accuracy of the thermo order to maximize the have them serviced an	ction. Inspectors do not stat, sizing/tonnage, or efficiency of a heating/c nually. Any deficiencies	heating or cooling components as a verify compatibility of components, uniformity of the air supply. In ooling system, it is advisable to can be an indication of a more icensed HVAC specialist is advised
	 14 - 22 degrees for the Second floor air differe is 14 - 22 degrees for t Secondary drain lines 	cooling equipment.) ntial tested: Register = he cooling equipment.)	2// Return = 73. (Standard range is 55// Return = 73. (Standard range location. Drain lines are required to interior.
	ht # 1: Downstairs el Lennox 4 ton condens	er	



Thermal image of return air grille



=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
	•		
x	X C. Duct Systems, Cha	uses, and Vents	
	throughout the reside system, chases or ver very important for the	nce. Any deficiencies w nts will be reported. Ven overall performance of	s verified at very accessible registe hich can be identified in the duct itilation in the residence and attic is the structure. Proper ventilation car armful combustion gases.
	 Limitation of Scope: A home inspection is not a mold or air quality assessmer Texas law does not allow a home inspector to positively identify or report the presence of mold. Environmental and mold investigations should be only be conducted by a trained and state licensed professional. Any issues noted coul indicate a more serious condition and should be evaluated further by a license HVAC professional if there are concerns. All deficiencies noted should be evaluated and repaired by a licensed HVAC professional. The air filter(s) are located in the following locations: in attic at/near air handl Duct system is compressed against framing, equipment and ducts are compressed together in several locations. This can cause air flow restrictions are result in water condensing on outer jacket of ducts 		
Media fi	ter located at base of furn	ace Media	filter located at base of furnace

HouseCheck 33 Violet Sunset Ln, Tomball, TX I=Inspected NI=Not Inspected NP=Not Present D=Deficient I NI NP D



Ductwork compressed

Ductwork compressed



Ductwork compressed

IV. PLUMBING SYSTEMS

HouseCheck			33 Violet Sunset Ln, Tomball, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	A. Plumbing Supply, D	istribution System and F	Fixtures
	Location of Water Meter • Front yard Location of Main Wate • Left front bedroom clo Comments: • About Plumbing Supp	er Supply Valve: oset	
	plumbing drains, plum not accessible as it is l conditions can be disc	bing vents, and fixtures. hidden behind walls or c overed by a visible insp	shutoff valve, water supply lines, Much of the plumbing system is other obstructions. Though some ection, there may be some that are hidden from view.
	required to inspect (be as pool pumps, under backflow devices. Pota home inspection. Wate there are concerns. Ar	eyond a visual inspection ground irrigation lines, fi ability and/or water qual er testing should only be ny deficiencies noted co	berate any shutoff valves and is not n) other mechanical systems such lter systems, fire sprinklers or ity is not assessed as part of a e done by qualified professionals if uld be an indication of a more vised if there are concerns.
	 Static Water Pressur Plumbing Supply Material 	e Reading: 55 PSI terial(s): PEX	
Mair	water supply valve		<image/>
war	i walei suppiy vaive		water pressure

HouseCheck 33 Violet Sunset Ln, Tomball, TX I=Inspected NI=Not Inspected NP=Not Present D=Deficient NI NP D B. Drains, Wastes, and Vents Х Comments: About Drains and Waste Vents: The inspection of the plumbing drainage system includes basins which hold water, drain stops, overflow drains, visual drain pipes, and clean-outs spaced throughout the residence. Limitation of scope: Much of the plumbing drain line system is not accessible and is hidden behind walls, attic spaces, or other obstructions. Functionality of floor drains can only be assessed by running plumbing supplies within the corresponding wet areas. All bathtubs filled and drained


Waste plumbing cleanout located in front flowerbed


HouseCheck			33 Violet Sunset Ln, Tomball, T
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP [)		
	C. Water Heating Equip	pment	
	Energy Source: • Water heaters are ga • Water heaters are loc Capacity: • Both unit capacities a Comments: • About Water Heaters	cated in the attic are 40 gallons	
	throughout the home. water heating unit (if a are assessed by the in schedule the manufact heaters. If the client is maintenance, consulta deficiencies noted cou	This report includes the vailable or listed). Gene spector. Annual mainte turer advises) should be not comfortable perforn tion with a qualified pro Id be an indication of a	bughout designated fixture supplies e energy source and capacity of the eral installation and safety issues enance (or whatever maintenance e performed to residential water ming general water heater ofessional is advised. Any more serious condition, and further mmended if there are concerns.
	pressure relief valve th pressure or temperature tested as a part of the	nat is designed to relieve re exceeds the unit's ca	equipped with a temperature and e back pressure in the unit if the apacity. This component is not ter heating unit, as any failure may operty.
	 Brand: Rheem // Yea Brand:Rheem // Year Hot water was verifie temperature measured 	⁻ Manufactured:2019 d at all interior fixtures a	and showers. Hot water
		MINIMUM CLEARANDER FOR	AUS-38N RH62 Cap. U.S. Gals. 40 TYPE GAS - NATURAL C Manifold - 4.0 Max. Inlet - 10.5 Min. Inlet - 5.0 CSA 4.1-2017 CATEGORY I NATURAL DRAFT OM COMBUSTIBLE OR NONCOMBUSTIBLE IT rear in a closel - 0"Sides and rear in an In closel door We or closel and on MAX WORKING PRESSURE 150 PSI

Rheem natural gas water heaters


Data plate

Х









HouseCheck			33 Violet Sunset Ln, Tomball, T
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
		Dent in door of oven	Kitche
	E. Microwave Ovens		
	report.	using an LED microway	e indicator. No deficiencies to
	Comments: • All exhaust fans and were noted.	/or bathroom heaters w	ere operated and no deficiencies
REI 7-5 (05/4/2	015)		Page 36 of 40

Х

HouseCheck			33 Violet Sunset Ln, Tomball, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
	G. Garage Door Ope Door Type: • One 16' steel secti Comments: • Note: No overhead inspection. Garage		re present at the time of the
	H. Dryer Exhaust Sy Comments: • Dryer vent access	ystems obstructed by shelf. The state of the	

HouseCheck			33 Violet Sunset Ln, Tomball, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D	-		D-Dencient
	I. Other		
	Observations:		
	VI.	OPTIONAL SYSTEMS	
	A. Landscape Irrigation	n (Sprinkler) Systems	
	Comments: • Irrigation system not Water supply lines ope	tested. System was not en at left side of lot.	fully installed at time of inspection.
	B. Swimming Pools, S	pas, Hot Tubs, and Equip	pment
	Type of Construction: Comments:		
	C. Outbuildings		
	Materials: Comments:		
	D. Private Water Wells	s (A coliform analysis is re	ecommended)
	Type of Pump: Type of Storage Equip Comments:	oment:	
	E. Private Sewage Dis	posal (Septic) Systems	
	Type of System: Location of Drain Field Comments:	j:	
	F. Other		
	Comments:		

Glossary

Term	Definition
AFCI	Arc-fault circuit interrupter: A device intended to provide protection from the effects of arc faults by recognizing characteristics unique to arcing and by functioning to de-energize the circuit when an arc fault is detected.
GFCI	A special device that is intended for the protection of personnel by de-energizing a circuit, capable of opening the circuit when even a small amount of current is flowing through the grounding system.

Report Summary

STRUCTURAL SYSTEMS				
Page 6 Item: B	Grading and Drainage	• The grade of the ground around the residence should be improved to promote the flow of water away from the property in the following locations: back side of the residence. This can be achieved by the addition or removal of top soil as well as the installation of a drainage system. The ground should slope away from the home at a rate of no less than 6 inches within the first 10 feet.		
Page 10 Item: D	Roof Structure and Attics	 Attic access doors require removal of drywall screws.Doors should have hinges installed to allow homeowners or service personnel to access attic without tools. Sheathing begins interior wall in lower attic has been damaged. This should be repaired to insure proper R value of wall. 		
Page 12 Item: E	Walls (Interior and Exterior)	 All exterior trim materials should be properly sealed around the perimeter of the home. Missing z-flashings were noted above the exposed windows and doors throughout the home. 		
Page 15 Item: G	Doors (Interior and Exterior)	 Door latch to study not operable. Latch painted in open position. 		
ELECTRICAL SY	ELECTRICAL SYSTEMS			
Page 20 Item: A	Service Entrance and Panels	 White conductors in service panel are not marked to identify if the conductor is carrying a live load. Dead front does not fit panel enclosure properly. This appears to be due to routing of service entrance conductor. 		
HEATING, VENT	LATION AND AIR C	ONDITIONING SYSTEMS		
Page 22 Item: A	Heating Equipment	• Flue pipe for upstairs furnace in contact with electrical circuit. Flue pipe is required to have 1" of clearance from combustibles.		
Page 24 Item: B	Cooling Equipment	• Secondary drain lines terminate at improper location. Drain lines are required to terminate above window as to be visible from interior.		
Page 27 Item: C	Duct Systems, Chases, and Vents	• Duct system is compressed against framing, equipment and ducts are compressed together in several locations. This can cause air flow restrictions and result in water condensing on outer jacket of ducts		
APPLIANCES				
Page 34 Item: D	Ranges, Cooktops, and Ovens	• Oven door has large dent in door.		
Page 37 Item: H	Dryer Exhaust Systems	Dryer vent access obstructed by shelf.		