Dukes Home Inspections Property Inspection Report



70 Warbonnet Dr, Conroe, TX 77304 Inspection prepared for: Angela Leims Real Estate Agent: Sherry Fulton - Coldwell Banker United, Willis

Date of Inspection: 3/22/2022 Time: 2:00 PM Size: 1863 Weather: Clear and 66 degrees Home faces south Home occupied Owner & agent Sherry Fulton present.

> Inspector: Randall Heath Wilson TREC #25217 Phone: 832-458-9377 Email: randallhwilson@outlook.com



PROPERTY INSPECTION REPORT FORM

Angela Leims	3/22/2022
Name of Client	Date of Inspection
70 Warbonnet Dr, Conroe, TX 77304 Address of Inspected Property	
Randall Heath Wilson	TREC #25217
Name of Inspector	TREC License #
Name of Sponsor (if applicable)	TREC License #

PURPOSE OF INSPECTION

A real estate inspection is a visual survey of a structure and a basic performance evaluation of the systems and components of a building. It provides information regarding the general condition of a residence at the time the inspection was conducted. It is important that you carefully read ALL of this information. Ask the inspector to clarify any items or comments that are unclear.

RESPONSIBILTY OF THE INSPECTOR

This inspection is governed by the Texas Real Estate Commission (TREC) Standards of Practice (SOPs), which dictates the minimum requirements for a real estate inspection.

The inspector IS required to:

- use this Property Inspection Report form for the inspection;
- inspect only those components and conditions that are present, visible, and accessible at the time of the inspection;
- indicate whether each item was inspected, not inspected, or not present;
- indicate an item as Deficient (D) if a condition exists that adversely and materially affects the performance of a system or component **OR** constitutes a hazard to life, limb or property as specified by the SOPs; and
- explain the inspector's findings in the corresponding section in the body of the report form.

The inspector IS NOT required to:

- identify all potential hazards;
- turn on decommissioned equipment, systems, utilities, or apply an open flame or light a pilot to operate any appliance;
- climb over obstacles, move furnishings or stored items;
- prioritize or emphasize the importance of one deficiency over another;
- provide follow-up services to verify that proper repairs have been made; or
- inspect system or component listed under the optional section of the SOPs (22 TAC 535.233).

RESPONSIBILTY OF THE CLIENT

While items identified as Deficient (D) in an inspection report DO NOT obligate any party to make repairs or take other actions, in the event that any further evaluations are needed, it is the responsibility of the client to obtain further evaluations and/or cost estimates from qualified service professionals regarding any items reported as Deficient (D). It is recommended that any further evaluations and/or cost estimates take place prior to the expiration of any contractual time limitations, such as option periods.

Please Note: Evaluations performed by service professionals in response to items reported as Deficient (D) on the report may lead to the discovery of additional deficiencies that were not present, visible, or accessible at the time of the inspection. Any repairs made after the date of the inspection may render information contained in this report obsolete or invalid.

REPORT LIMITATIONS

This report is provided for the benefit of the named client and is based on observations made by the named inspector on the date the inspection was performed (indicated above).

ONLY those items specifically noted as being inspected on the report were inspected.

This inspection IS NOT:

- a technically exhaustive inspection of the structure, its systems, or its components and may not reveal all deficiencies;
- an inspection to verify compliance with any building codes;
- an inspection to verify compliance with manufacturer's installation instructions for any system or component and DOES NOT imply insurability or warrantability of the structure or its components.

NOTICE CONCERNING HAZARDOUS CONDITIONS, DEFICIENCIES, AND CONTRACTUAL AGREEMENTS

Conditions may be present in your home that did not violate building codes or common practices in effect when the home was constructed but are considered hazardous by today's standards. Such conditions that were part of the home prior to the adoption of any current codes prohibiting them may not be required to be updated to meet current code requirements. However, if it can be reasonably determined that they are present at the time of the inspection, the potential for injury or property loss from these conditions is significant enough to require inspectors to report them as Deficient (D). Examples of such hazardous conditions include:

- malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices and arc-fault (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

Please Note: items identified as Deficient (D) in an inspection report DO NOT obligate any party to make repairs or take other actions. The decision to correct a hazard or any deficiency identified in an inspection report is left up to the parties to the contract for the sale or purchase of the home.

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

•Improperly installed or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathrooms, kitchens, and exterior areas;

•Improperly installed or missing arc fault protection (AFCI) devices for electrical receptacles in family rooms, dining rooms, living rooms, parlors, libraries, dens, bedrooms, sunrooms, recreation rooms, closets, hallways, or similar rooms or areas;

•Ordinary glass in locations where modern construction techniques call for safety glass; •The lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;

- •Excessive spacing between balusters on stairways and porches;
- Improperly installed appliances;
- Improperly installed or defective safety devices; and


•Lack of electrical bonding and grounding.


To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.


Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms requires a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

Table Of Contents





- Nails missing from flashing.
- Cricket flashing needed.



Dukes Home Inspec	ctions		70 Warbon	net Dr, Conroe, T
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D)			



North side.




Nails exposed and Should be caulked. This is common maintenance.

Cricket flashing needed.



Debris should be removed from the roof covering and/or gutter system.



• One or more of the attic ladder components were observed to be damaged and should be corrected for safety reasons.

I=Inspected NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D Т



Attic ladder is not insulated or weather stripped at this time. This is an "As Built" condition that does not meet current energy standards. It is recommended to insulate the hatch door after taking ownership of the property.





Roof structure.



Roof structure.

```
I=Inspected
```

```
NI=Not Inspected
```

NP=Not Present

D=Deficient

I NI NP D



Insulation is low in one or more spots. Should be replaced.

E. Walls (Interior and Exterior)

- Exterior brick veneer and/or structural walls noted.
- Exterior wood or wood like lap siding noted.
- Comments:

• The areas between the exterior cladding / veneer and ALL wall penetrations need to be properly sealed such as utility connections, downspouts, hose bibs, lighting fixtures, receptacles, window frames etc with an exterior grade elastomeric sealant. This is regular maintenance.


• The foliage growing on, over or around the exterior walls of the structure should be trimmed back at least {12"}. The plant material may limit the Inspectors visual observation of the existing surfaces.(Regular home Maintenance).

• Earth to siding contact was observed on the exterior siding and should be a minimum of {4"} clearance from the ground for brick/stone {6"} for wood and {8"} for stucco. Common in older homes.

• Caulking needed at one or more places around the home/building. This is common maintenance.

• There were no weepholes observed in the lower course of the masonry veneer in one or more areas of the structure. Under current building standards; there should be open weepholes not less than $\{3/16^{"}\}$ in diameter on the lower course of the masonry wall and spaced no more than $\{33^{"}\}$ apart to drain excess water from the interior of the wall voids.

- Irregular workmanship.
- Mortar thin in multiple areas around home.



I=Inspected NI=Not Inspected NP=Not Present D=Deficient NI NP D Т Primary bedroom. Closet. 0



Irregular workmanship.

Primary closet.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



Living room.



Dinning room.



Sunroom.

Garage.

Dukes Home Inspect	ions		70 Warboni	net Dr, Conroe, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				




West side.

South side.



East side.

North side.





Earth to siding contact was observed on the exterior siding and should be a minimum of {4"} clearance from the ground for brick/stone {6"} for wood and {8"} for stucco. Common in older homes.




- Ceiling is made of drywall with popcorn and/or texture finish.
- Floors had carpet covering in various locations.
- Floor cover is tiled in areas.
- Floor cover is vinyl in areas.
- Comments:
- Satisfactory at time of inspection.
- Floors were found to be in good shape at time of inspection.

REI 7-6 (8/9/21) Promulgated by the Texas Real Estate Commission • (512) 936-3000 • www.trec.texas.gov Page 15 of 41



There were no weepholes observed in the lower course of the masonry veneer in one or more areas of the structure. Under current building standards; there should be open weepholes not less than {3/16"} in diameter on the lower course of the masonry

wall and spaced no more than {33"} apart to drain excess water from the interior of the wall voids.



- Garage walk door should be self closing.
- Some doors were observed to be sticking, not closing properly, out-of-level, frame damage or missing and/or non-functional hardware. Not uncommon in older homes.
- One or more doors were closing on there on.May need adjusting.Common in older homes.



One or more doors were closing on there on. May need adjusting. Common in older homes.



Doors between the garage and the residence should be equipped with a solid wood door not less than $\{1 \ 3/8''\}$ in thickness, solid or honeycomb core steel door not less than $\{1 \ 3/8''\}$ thick or $\{20\}$ minute fire rated doors equipped with a self closing device.



• Windows are made of aluminum.

Comments:


- Window screens were observed to be damaged or missing in one or more locations.
- Window(s) would not open in one or more locations.

• One or more of the bedroom windows are inoperable. At least one window in each bedroom should fully open with free access to the outside for safety concerns.


Some doors were observed to be sticking, not closing properly, out-of-level, frame damage or missing and/or non-functional hardware. Not uncommon in older homes.




Garage walk door should be self closing.



• Creosote build up. Creoste build up can cause chimmney fires. Recommend a professional chimney sweep.





I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



Double tap on breaker(S) were observed in the service panel. One wire under each screw is recommended.



Dead front cover off.



Missing screw to secure dead front cover.

Dukes Home Inspect	ions		70 Warbonnet Dr, Conroe, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
v	B. Branch Circuits, (Connected Devices,	and Fixtures
	 kitchens, bathrooms, gara whirlpool tubs. GFCI rect bathroom within {3'} of t monoxide detectors in ho appliances should have ca Damaged and/or missin creates a Safety Hazard a Outlet(s) cover missing Open ground(s) noticed 	ages, laundry rooms, ext eptacles are required in he sink edge. Also reco ome after closing. Home arbon monoxide detecto g outlet and/or switch c nd should be corrected or damaged. at one or more location were observed and sho ctors and is considered n one or more locations	overs were observed. This situation as around the home. build be installed with a covered junction a Safety Hazard. s.
Light cover(s)	missing in one or more location	ns. (Outlet(s) cover missing or damaged.

Dukes Home Insp	pections		70 Warbonnet Dr, Conroe, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP	D		
Open ground(s)) noticed at one or more locations arc home.	ound the Damaged an observed. This	nd/or missing outlet and/or switch covers were s situation creates a Safety Hazard and should be corrected



Spliced and taped wires were observed and should be installed with a covered junction box with approved connectors and is considered a Safety Hazard.

Electrical wire not properly secure in one or more locations.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D





Sediment trap.



Heater supply temp 103.3 degrees.



B. Cooling Equipment

- Central forced air.
- Comments:
- Supply temp 58.6 degrees.
- Return temp 71.6 degrees.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



Return temp 71.6 degrees.



Supply temp 58.6 degrees.



Outside unit.



Comments:

- Ductwork should not be touching.
- Ductwork is leaking at connections.

<page-header><table-container><table-container> 1 N N D


Range vent.




Comments:

Dukes Home Inspec	ctions		70 Warbonnet Dr, Conroe, TX
Lippopoted	NIL Not Increated	NP=Not Present	D. Deficient
I=Inspected	NI=Not Inspected	NF=NOL FIESEIIL	D=Deficient
<u>I NI NP D</u>)		
	IV.	PLUMBING SYSTEMS	
	• A. Plumbing Supply	y, Distribution System	and Fixtures
	• Location of water meter	er: Rear of structure.	
	• Location of main water Comments:	supply valve: North side.	
	Type of Supply Piping	Material: PEX & Galvani	
	• Water ran for several drain lines. We simply lo	minutes at each fixture. W	'e do not preform water leak tests on is quite limited by our short time at the
	property.		
	operating range. Pressure	e exceeding these limits or	lly at {40-80 psi} in the normal higher than {80 psi} is likely to put
	excessive pressure on the plumber and/or the city	e household water system. water department further e	It is recommended that a licensed valuate in the event a pressure reducing
	valve is required for safe	ety concerns.	
	 Water pressure was 58 Shower or tub area neg 		
	Image: Additional and the second se		Guest shower.
	Guesi bulli bom.		Guest shower.


I=Inspected NI=Not Inspected NP=Not Present D=Deficient NI NP D Т Guest bath tub. Primary bathroom. Primary bath tub. Primary shower.






No sediment trap on gas line.

Water heater was not equipped with a corrosion resistant drain pan .







Dukes Home Inspections

70 Warbonnet Dr, Conroe, TX

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



Cooktop.



Top oven.





Bottom oven.



Comments:

• Counter top type and was not tested.





Dukes Home Inspect	ions		70 Warbonnet Dr, Conroe, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
	VI.	OPTIONAL SYSTEMS	
	A. Landscape Irriga	tion (Sprinkler) Syste	ms
	Comments: B. Swimming Pools ,	Spas, Hot Tubs, and I	Equipment
	Comments:		
	C. Outbuildings		
	• Tool Shed noted. Comments:		
		Outbuilding noted.	
	D. Private Water W	ells (A coliform analys	sis is recommended)
	Comments: E. Private Sewage D	isposal Systems	
	Comments:		

Dukes Home Inspec	tions		70 Warbonnet Dr, Conroe, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	F. Outdoor kitchens		
	Comments:		

Report Summary

STRUCTURAL	STRUCTURAL SYSTEMS			
Page 5 Item: A	Foundations	• Unable to see all of the slab due to high soil,decks,porches etc. There should be 4 inches of clearance for brick and stone.6 inches for wood and 8 inches for stucco.		
Page 5 Item: C	Roof Covering Materials	 Nails exposed and Should be caulked. This is common maintenance. Debris should be removed from the roof covering and/or gutter system. Nails missing from flashing. Cricket flashing needed. 		
Page 8 Item: D	Roof Structure and Attics	 Insulation is low in one or more spots.Should be replaced. Attic ladder is not insulated or weather stripped at this time. This is an "As Built" condition that does not meet current energy standards. It is recommended to insulate the hatch door after taking ownership of the property. One or more of the attic ladder components were observed to be damaged and should be corrected for safety reasons. 		
Page 10 Item: E	Walls (Interior and Exterior)	 Earth to siding contact was observed on the exterior siding and should be a minimum of {4"} clearance from the ground for brick/stone {6"} for wood and {8"} for stucco. Common in older homes. Caulking needed at one or more places around the home/building. This is common maintenance. There were no weepholes observed in the lower course of the masonry veneer in one or more areas of the structure. Under current building standards; there should be open weepholes not less than {3/16"} in diameter on the lower course of the masonry wall and spaced no more than {33"} apart to drain excess water from the interior of the wall voids. Irregular workmanship. Mortar thin in multiple areas around home. 		
Page 16 Item: G	Doors (Interior and Exterior)	 Doors between the garage and the residence should be equipped with a solid wood door not less than {1 3/8"} in thickness, solid or honeycomb core steel door not less than {1 3/8"} thick or {20} minute fire rated doors equipped with a self closing device. Garage walk door should be self closing. Some doors were observed to be sticking, not closing properly, out-of-level, frame damage or missing and/or non-functional hardware. Not uncommon in older homes. One or more doors were closing on there on.May need adjusting.Common in older homes. 		
Page 17 Item: H	Windows	 Window screens were observed to be damaged or missing in one or more locations. Window(s) would not open in one or more locations. One or more of the bedroom windows are inoperable. At least one window in each bedroom should fully open with free access to the outside for safety concerns. 		

REI 7-6 (8/9/21) Promulgated by the Texas Real Estate Commission • (512) 936-3000 • www.trec.texas.gov Page 40 of 41

	L	
Page 18 Item: J	Fireplaces and	• Chimney cap and or rain cap is rusty.
	Chimneys	• Mortar cracked.
		• Creosote build up. Creoste build up can cause chimmney fires. Recommend a professional chimney sweep.
	OVOTEMO	Recommend a professional eminicy sweep.
ELECTRICAL		
Page 20 Item: A	Service Entrance and Panels	• Panel should be labeled.
		• Double tap on breaker(S) were observed in the service panel. One wire under each screw is recommended.
		• Blanks are missing on dead front cover and should be replaced so no sharp objects or insects can enter the breaker area.
		Missing screw to secure dead front cover.
Page 22 Item: B	Branch Circuits, Connected Devices, and Fixtures	• Recommend GFCI protection(If not present) on 15A/20A circuits providing power to kitchens, bathrooms, garages, laundry rooms, exterior receptacles, pools, spas and whirlpool tubs. GFCI receptacles are required in the kitchen within {2'} of the sink and bathroom within {3'} of the sink edge. Also recommended to upgrade smoke and carbon monoxide detectors in home after closing. Homes with attached garages and gas appliances should have carbon monoxide detectors.
		• Damaged and/or missing outlet and/or switch covers were observed. This situation creates a Safety Hazard and should be corrected
		• Outlet(s) cover missing or damaged.
		 Open ground(s) noticed at one or more locations around the home. Spliced and taped wires were observed and should be installed with a covered junction box with approved connectors and is considered a Safety Hazard.
		considered a Safety Hazard.Light cover(s) missing in one or more locations.
		 Electrical wire not properly secure in one or more locations.
	NTIL ATION AND	
		O AIR CONDITIONING SYSTEMS
Page 26 Item: C	Duct Systems,	• Ductwork should not be touching.
		• Ductwork is leaking at connections.
PLUMBING SY	YSTEMS	
Page 28 Item: A	Plumbing Supply, Distribution System and Fixtures	• Shower or tub area needs caulking.
Page 30 Item: B	Drains, Wastes, and Vents	• Drain pipes should be painted. They are not UV resistant.
Page 31 Item: C	Water Heating Equipment	 Water heater was not equipped with a corrosion resistant drain pan . No sediment trap on gas line.
APPLIANCES	1	
	Carago Door	The compact door company should be installed within (CD) = 0.4
Page 36 Item: G	Garage Door Operators	• The garage door sensors should be installed within {6"} of the finished floor.