Jay Hicks Inspection Service

COVER PAGE

"STRUCTURAL & MECHANICAL INSPECTION REPORT"

(832) 867-6253 Jay Hicks

Texas Real Estate Commission Professional License # 5332

☑ Prop □ Vaca □ Othe	-	□ O\	ent Present wner Present Jent Present		☑ Slab on ☐ Pier and ☐ Raised			House ng Property rical Home
Client:	Crawford and	Deborah V	Veir					
Property Address:	25334 Intrepid	I						
City:	Galveston			State To	exas	Zip	77554	
Pin #	202021J							
Inspection Type:	□ Stru	uctural		Mechanical	V	Structu	ıral/Mechanical	
House is a	4 story dwel	lling.	Supra Key I	Equipped:□	Yes	✓ No		
Date of Inspection:	July 20, 2020	Time	9:30	☑ AM □ PM				☐ Term
Weather Conditions:	☐ Sunny	☑ Cloudy	☐ Windy	☑ Raining	☐ Thun	der/Lightening		
Reference:								

terence:

Agent: Angela Sanders



Returned Checks \$50 plus all bank charges

Repair reinspection 1/2 inspection fee or \$100 minimum

THIS REPORT IS TO BE USED SOLELY FOR THE BENEFIT OF THE PROSPECTIVE CLIENT (ONLY)
LISTED IN THIS REPORT. THIS REPORT IS NOT TRANSFERABLE TO ANY OTHER FUTURE
CLIENTS OR INDIVIDUALS WITHOUT WRITTEN PERMISSION FROM JAY HICKS INSPECTION SERVICES.

This report is not a warrantee or guarantee of any kind. Consult your agent about warrantee companies.

PROPERTY INSPECTION REPORT

Jay Hicks Inspection Services

Prepared For: Crawford and Deborah Weir

Concerning: 25334 Intrepid 202021J Texas 77554

By: Jay Hicks

TREC Licensed # 5332

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL the information. This report may not be complete without the attachments.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov

The TREC Standards of Practice (Sections535.227 - 535.233 of the rules) are the minimum standards for inspections by TREC licensed inspectors. An inspection addresses only those components and conditions which are present, visible, and accessible at the time of the inspection. While there may be other parts, components, or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or or stored items. The inspection report may address issues that are code based or may refer to a particular code; however, this is NOT a code complaiance inspection and does NOT verify compliance with a manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or it's components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection and the inspector is NOT required to identify all potential hazzards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported as Deficient may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods. Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repair have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathrooms, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
 - · malfunctioning carbon monoxide alarms;
 - excessive spacing between balusters on stairways and porches;
 - · improperly installed appliances;
- · improperly installed or defective safety devices; and
- · lack of electrical bonding and grounding.

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms require a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENTWITH THE STANDARD FORM, IS NOTN REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTURAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTURAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTURAL TERM CONTAINED IN THIS SECTION, OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

See the attached agreement page.

All directions are front street facing the house (front door).

Future performance can not be determined on any item(s).

If you have any concerns, you, the client named on this report, should contact technical personell to evaluate any and all comments.

It is understood that my opinion and testing methods may differ from the opinions of other inspectors, contractors, or licensed technicians.

ATTENTION CLIENTS

Detailed limitations regarding the scope of this report are outlined in the attached

Inspection and Liability Limitation Agreement

located attached to this report

and on the Foundation Information section located on page 4 of 16 of this report.

THE REPORT IS INCOMPLETE IF THESE ITEMS ARE NOT ENCLOSED IN THIS REPORT.

Report Identification: 25334 Intrepid Page 4 of 16

Report Number: 202021J Date: July 20, 2020

Jay Hicks T.R.E.C. # 5332

I = Inspected NI = Not Inspected NP = Not Present D = Deficiency

NI NP D INSF	PECTED ITEM
--------------	-------------

I. STRUCTURAL SYSTEMS
A. Foundations

П

4

Comments:

Type: □ pier and beam □ block and beam

 $\ensuremath{\square}$ Foundation is performing as intended - Can not determine future performance

"Normal Settlement Indicated"



- $\hfill\square$ Recommend professional foundation repair company inspect and repair as needed
- \square Previous foundation repairs indicated see warranty for details:

Important Notice >>> The condition of the foundations is reported on the day of inspection.

This report is of the general condition (Not an engineers report), Future performance can not be determined after that day. If you have any concerns. You should contact a structural engineer.

It is always recommended to get a second opinion on the foundation performance

FOUNDATION INFORMATION:

The following evidence and consequences are generally associated with foundation differential movement: the structure and loss and gain of moisture content of framing lumber. It is not uncommon for foundations to reveal some systems of differential movement. At the time of inspection, this inspector may have observed evidences and consequences of differential movement. Unless noted otherwise, these evidences and consequences may not be excessive and do not indicate the immediate presence of significantly deflected foundation or foundation failure. Therefore, if indicated, any discrepancy should be evaluated by a Structural Engineer or foundation repair company. Expansive soils that are common in the "Gulf Coast" area can dramatically adversely affect the performance of a foundation. Variations in moisture content produces swelling and shrinkage of the soil which can result in differential heaving and settlement of a foundation. The opinion rendered in this report does not apply to future changing conditions and structural consequences affected by thermal/climatic conditions, moisture or any other conditions that affect foundation movement. Differential movement in the foundation can occur rapidly under certain conditions and the future performance or stability of the foundation cannot be predicted. If in-depth information is desired on the foundation, soil stability or any part thereof, a Structural Engineer should be consulted.

Foundation movement may not necessarily be the cause of cracks in the home gypsum board (sheetrock) and brick veneer. Expansion and contraction of the home's framing may cause the following: 1) Horizontal cracking of sheetrock at the inside corners of windows is due to thermal expansion/contraction of the window framing. 2) Cracks in corners of raised ceilings are most commonly the result of thermal expansion/contraction in attic framing. 3) Minor separations in brick/sheetrock connections are commonly due to different expansion/contraction rates of different materials. 4) Cracks in top "soldier brick" rows are commonly caused by framing movement. 5) Foundation corners that chip off are caused from improper removal of foundation wooden form boards or by frictional forces from the movement between the brick veneer and concrete foundation. 6) Minor cracks may appear in brick veneer due to normal structural movement of walls installed without brick expansion joints or at the weak areas of brick walls under windows.

Report Identification: 25334 Intrepid Page 5 of 16
Report Number: 202021J Date: July 20, 2020

Jay Hicks T.R.E.C. # 5332

				= Inspected		P = Not Present	D = Deficiency	
Τ	NI	NP	D		INS	SPECTED ITE	M	
>				Com ☐ High ☐ Mile ☐ Da ☐ Lor There shou	ding and Drainage ments the soil level: all around ssing downspout splash blocks maged or missing gutters or downsp w area next to slab: ald be approximately 4 " of sla and the ground. This allows the	ab exposed betwee		
v	П		V	C. Roo	f Covering Materials			
		12 4-		THE RESERVE	☑ Field Gl	asses Walked or	n roof	
1			Lin	□ Me	etal	☐ Wood sha	ke □Til	e
		-	1	1	f slopes are not determined			
			E .		nments: damaged flashing	across the exteri	or of the master	dock
				☑ Pre	ing (NOTED) evious repairs top floor roo ose shingles: move Debris: orofessional roofer should inspect the		opropriate recommend	ations.
		7		D. Roo	f Structure and Attic			
				Acce		☐ Very Lim		lot Accessible
					lation Type: ☐ Blanket	□ Loos		
				Con Ra Wa Min	roximate Depth:inches nments: diant barrier in use: ater damaged roof decking: ssing section(s) of attic insulation: maged/deficient attic access ladder: fters pulling away from ridge board professional roofer should inspect the			dations.

This inspection is neither intended nor implied to certify that the roof assembly is free of active leaks.

Important Notice Roofs are inspected only from the ground/ we do not walk on the roof(s). The condition of the roof is reported on the day of the inspection. The report is a general condition of the roof material. Future performance can NOT be determined after today. If you have ANY concerns, you should contact a roofing company for an evaluation. This company does not issue WPI-8 certificates. It is always recommended to get a second opinion on the roofs performance.

Report identification: 25334 Intrepid Page 6 of 16
Report Number: 202021J Page 5 of 16
Date: July 20, 2020

Jay Hicks T.R.E.C. # 5332 NI = Not Inspected NP = Not Present I = Inspected D = Deficient NP D INSPECTED ITEM NI Walls (Interior and Exterior) NOTE: Items marked " not inspected" may not be installed yet. NOTE: Bed rooms are numbered front to back and from left to right (front street facing). Interior Walls: Comments: Type: ☑Sheetrock □Paneling □Wallpaper □Other □Fresh paint: behind the master bedroom door ☑Repirs/patching □Holes \square Discolorations \square Nails pushing through sheetrock: **Exterior Walls:** \square Brick ☑Hardy Plank \square Wood □T-111 □Vinyl □Cinder Block □Masonite □Aluminum Siding □Cracks in Mortar/Bricks arch on the kitchen porch ☑Siding deteriorating ☑Facia boards/trim deteriorating around the main floor right side rear window **Ceilings and Floors** Ceilings: Comments: □Fresh paint: □Cracks: □Holes: $\square {\sf Discolorations:}$ ☑Repairs: master bath, living room over the main floor stairs ☐Water penetration: □Nails pushing through sheetrock: Floors: □Ceramic Tile: □Vinyl ☑Carpet: □Wood: ☑Wood laminate: ☑Carpet is damaged/stained: master bedroom \square Wood floor is warped/discolored/damaged:

We do Not do invasive moisture penetration tests. The inspection is visual only. Some cracks and separations are caused by structural or foundation movement.

Report Identification: 25334 Intrepid Page 7 of 16
Report Number: 202021J Date: July 20, 2020

Jay Hicks T.R.E.C. # 5332

I = Inspected NI = Not Inspected NP = Not Present D = Deficient NI **INSPECTED ITEM** G. Doors (Interior and Exterior) V Comments: ☑ Damaged and / or missing door stops: ☑ Door sticks in frame: master bedroom 2nd floor front bedroom small closet door, A/C closet door ☑ Door hinge damaged or loose: □ Need 20 minute fire rated door between the house and the garage: ☐ Adjust door striker plate **Garage Doors** □ Not Present ✓ Present Door Type: \square Wood ☐ Other ☑ Metal \square Door is bent or damaged: \square Glass is broken or damaged: Windows J All sleeping rooms MUST be equipped with emergency escape and rescue openings. Recommend removal of all bars on windows and doors. \square Low-e double pane aluminum windows ☐ Single pane wood windows $\ensuremath{\,\,\overline{\,}}$ Low-e double pane vinyl tilt out windows ☐ Single pane aluminum windows ☑ Double windows ☐ Low-e double pane vinyl windows Comments: window sills are discolored in the Iving room ☑ Missing and / or damaged screens: \square Cracked and/or missing glass: ☐ Damaged window glazing/weather stripping: middle floor front bedroom ☐ Safety glass is required (if window covering(s) not present) Stairways: Interior and Exterior I. **V** ☑ Baluster/spindle spacing: Should have a maximum opening of 4" (TREC Guidelines) \square Stairway: Missing hand railing if over 4 steps / Improper: ☐ Stairway handrail is loose ☐ Missing stair stringer (step supports): **√** □ J Fireplaces and Chimneys Not all areas of the flue liners are accessible for inspection. П П Chimneys should be cleaned annually. Crown / Cap is not accessible for inspection. ☐ Wood burning ☐ Gas Only ☐ Combination gas and wood: Comments: $\hfill\square$ Build up indicated in flue liners / should be cleaned: ☐ Damper does not operate properly: \square Loose firebricks and or cracks indicated in firebox: Porches, Balconies, Decks, and Carports Comments: ☐ Baluster/spindle spacing: Should have a maximum opening of 4" (TREC Guidelines) \square Not Secured and / or wobbles: ☑ Wood rot and / or water damaged indicated: arch on kitchen porch

Report Identification: 25334 Intrepid Page 8 of 16

Report Number: 202021J Date: July 20, 2020

Jay Hicks T.R.E.C. #5332

			I = Inspected	NI = Not Ins	•		lot Present	D = Defic	ient	
<u> </u>	NI	NP	D			NSPE	CTED ITEM	<u>/I</u>		
			II. ELEC	TRICAL SY	STEMS					
7			A. Serv	ice Entrance	and Panels	;			200	AMPS
			Wiring	Type: ☑	Copper		Aluminum		opper/Alumi	num mixed
			Locatio	_	Front [□ Back	☐ Right Side		eft Side	☑ Patio
			Comme							
			= 1	nstalled in hazard			_			
			_	olor: White wires	used as power v	wires (No	ted):			
			_	s not labeled						
				breaker knockou						
				l Pacific Electric (f g/deficient ARC fa						
				e wires to breaker	•	W CONSUL	iction only)			
				r size improper::		reaker	in use on A/C	Shoul	d be	AMP breake
				r size improper::			in use on A/C			AMP breake
							ir entire electrical			
										ning their state
								-		all needed rep
							_			_
			1	Note: Only ite	ms visually	access	ible at the tim	e of inspe	ection are	commented o
			Note: This insp	ection does	NOT addres:	s electi	rical design, c	apacity, v	viring / br	eaker adequac
✓							s and Fixtures			
						maste	r bath shower,	, 2nd floo	r front be	droom closet,
				nstairs close	ts					
			Plugs:				Switches:			
			□Damag				☐ Damaged:			
			□Inopera				☐ Inoperable:	r(c):		
			☐ Missing				☐ Missing Cove ☐ Not securley			
				curley mounted:			☐ Displays evid		na or evcessi	VA
				s evidence of arci	ng or excessive	heat:	□ Displays evid	ence or arch	ig or excessi	ve
			☐ Incorre	ct polarity						
			☐ Missing	/deficient conduit	:					
			☐ Missing	emergency shut	off switch on A/	/C and he	ating unit(s)			
			-	junction box(s):			Exterior wiring no			
				junction box cov			Improper wiring	•	,	
			_	vire connected to		_	Lack of equipmer		. ,	
				d /uncapped wirir	_		Appliances/metal	pipes not bo	onded or gro	unded:
				lowing recept			•	~ -	76	
				n plugs on the plug to le] Master Bath Roor □ Hall Bath		□Garage □Crawl Spac	
				right of the fri		-	⊒ Hall Bath			e pool/Spa light
				r plug on left	•				⊒ Laundry/ut	
				Alarm(s)					-	
				re NOT present in		☑ Presen	t □Unit(s) are not p		ot Present	ne dwelling
				are not present in			☐ Damaged/deficie		an acony on th	ic aweiling
			٠,	ell(s) and Chi		vays i ☑ Presen	<i>J</i> ,		ot Present	
			☑ Operab	` '					oc i rescrit	
			·	Cover(s):						
					electrician inspec	ct and re	pair the entire elec	trical system	as needed	
								3,213		

 $\begin{tabular}{ll} \textbf{Note:} Only \ \underline{accessible} \ branch \ circuits, connected \ devices \ and \ fixtures \ are \ commented \ on. \end{tabular}$

Texas Real Estate Commission Standards of Practice requires the following:

" The inspector shall report as deficient the absence of, improper installation or improper operation of Ground Fault Circuit "GFCI" devices in all bathrooms, all exterior, garages, kitchens (within 6 ft. of outsied edge of sink), crawl spaces, unfinished basements". (TREC inspectors can not grandfather GFCl's)

Report Identification: 25334 Intrepid Page 9 of 16

Report Number: 202021J Date: July 20, 2020

Jay Hicks T.R.E.C. # 5332

I = Inspected NI = Not Inspected NP = Not Present D = Deficient NI NP **INSPECTED ITEM** D III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS **V ✓** ☐ See Cooling Equipment Α. **Heating Equipment** ☐ Space Heater Unit Type: ☑ Central Air ☐ Window Unit ☐ Heat Pump Comments: □ N/A main floor middle floor ☐ Unit is heating as intended: ☑ Unit is heating as intended: \square Gas ☐Gas \square Unit is NOT heating as intended: ☑ Unit is NOT heating as intended: ☑ Electric ☑ Electric Supply Air: Supply Air: Return Air: Return Air: Differential: Differential: Proper operating differential temperature is between 30 and 40 degrees Fahrenheit ☐ Flexible gas line can not terminate into pilot apparatus. \square Improper gas line in use. (MUST be yellow flex) \square Missing flexible gas line ☐ Missing drip leg (gas trap):. \square Recommend removal of space heater from wall ☐ Deficient thermostat:

Recommend a licensed A/C Heat technician inspect and issue a report containing their state license number and contact information detailing their findings and all needed repairs.

The following applicaplicable components of the heating system are commented on: Unit performance, thermostat controls/limit controls, burner assembley/compartment, condition of flame, vent pipe clearence and routing, combustion/draft air, and gas supply lines and shut off valves. Heat exchangers are NOT disassembled to inspect internal parts. Testing for carbon monoxideis performed but a definitive condition of the heat exchangercan not be determined without disassembley of the unit by a licensed HVAC company. Electrical heat strips are no accessible to evaluate. If an in depth evaluation of the heating system is desired, consult a licensed HVAC company.

See section C (page 10) for information on furnace vent(s)

Report Identification: 25334 Intrepid Page 10 of 16
Report Number: 202021J Date: July 20, 2020

Jay Hicks T.R.E.C. # 5332

			I =	: Inspected	NI = Not Inspected	NP = Not Pi	resent D	= Deficient		
П	NI	NP	D			INSPECTE				
<u>-</u> ✓			✓	B. Coo	ling Equipment	☐ See Heating B				
_	_			Unit Ty		☑ Mini Split	:	☐ Heat Pump	☐ Space Heater	
				Approx	imate ambient temp	perature: 83	_		•	
	-			☐ Outside	ambient temperature is t	too cold - did not test	differentials			
					nts: mini split syst					
					erating differential r	ange is betweer			enheit	
				4	n floor cooling as intended:	☑ N/		niddle floor nit is cooling as inter	- d - d.	
					NOT cooling as intended:	™ 14/		nit is NOT cooling as		
				Return Air	=		Return	_	, interrucar	
	1			Supply Air	63		Supply	Air: 59		
	i i	4		Differential			Differer			
									_	
			Un		N/A					
					cooling as intended:	L	76			
					NOT cooling as intended:					
				Return Air Supply Air				and the same		
				Differential						
				Differential	. •		10 18	Acres	and the same of th	
				☐ Missing	drain pan drain line:					
				☐ Reinsul	ate refrigerant pipe::					
				☐ Rust in	Auxiliary drain pan:					
					ary drain line is capped: 〈			,		
									report containing th	
				state	e license number ar	nd contact inforr	mation deta	ailing their find	<mark>ings and all needed</mark>	repairs.
				If the fil	ter is missing, the e	avanorator shou	ld he clean	ed Air conditi	oning eveteme	
					tested if the ambier					
					ator casings, plenu	=		_		
				_	d. Inacessible com				Model Number: 41XASS3SA19N9CA Rated Voltage 206/230V/1	
							-		Rated Frequency 60 Hz Cooling Capacity 33600(7406-36000)@su/h	
									Heating Capacity 34800(15000-36000)Bhulb Compressor RLA 17.56A	
									Compressor LRA Outdoor Fan Motor Amp. 8.73A	
									Design Press High 550 PSIG	
									Max Chi Srk Size AtA Win Circuit Ampacity 24A	
									Refrigerant R418A Factory Refrigerant Charge 91,71 OZ	
									MARKING RISK OF ELECTRIC SMOCK MAY CAUSE WILVEY OR DEATH DISCONNECT ALL ELECTRIC POWER SUPPLY SEFORE SERVICING	
V				C. Duct	Systems, Chases,	and Vents			AVERTISSEMENT RISQUE OF CHOCS ELECTRIQUES. FEUT CAUSED DES BLEGSURES ET MÉME ENTRAÎNER LAMOST.	
				Comme	•			-	COUPER LES SOURCES D'ALIMENTATION À DISTANCE AVANT LE DÉPANAGE	
				Ducts:				-	AMERICAN CONFORMS FO	
				☐ Damag	ed A/C ducts or insulation		□ A/0	C duct is not secure	d to the plenum	
				☐ Improp	er or inadequate clearenc	es of ducts and/or ple	enums 🗆 A/0	C ducting is not susp	pended in attic	
				Chases		dan barra	and to 1	T		
					es, electrical wiring, junct	ion boxes, or sewer v	vents in chase	- ımproper		
				Vents:			□ D - C '			
					around all vents at roof le er vent pipe on gas water		_	ound dryer vent pipe		
					er vent pipe on gas furna			und kitchen vent pij	ent pipe at roof level oe at roof level	
					er vent cap on gas water				: pipe(s) at roof level	
					er vent cap on gas furnac			ound furnace vent p		
					-			- 1	•	

Report Identification: 25334 Intrepid Page 11 of 16
Report Number: 202021J Date: July 20, 2020

Jay Hicks T.R.E.C. # 5332

I = Inspected NI = Not Inspected NP = Not Present D = Deficient NP **INSPECTED ITEM** NI ח Water wells and Septic Systems are **NOT** inspected. IV. PLUMBING SYSTEM Plumbing Supply, Distribution, and Fixtures \checkmark Static water pressure reading: 66 psi. Must be between 40-80 psi. Water meter location: ☐ Front ☑ Left side \square Right side Back □Back ☑ Left side ☐ Right side Main shut off location: ☐Front ☐ Garage ☑ PVC ☐ PEX Hoses ☐ Galvanized Water pipe material: ☐ Copper ☐ Recommend licensed plumber inspect and repair entire plumbing system as needed. Kitchen Sink, Wet Bar, Utility Sink, and Laundry Sink: a. П V Comments: faucet: ☐ Stem packing leaks: supply pipes/valves: \square Missing/leaking shut off valve(s) under sink(s) spray attachments: \square Does not operate properly: ☐ Recommend licensed plumber inspect and repair entire plumbing system as needed. b. Laundry Connections / Sink(s): Drain lines are not physically tested П ✓ Comments: not accessible \square Hot/cold faucets are not marked **Master Bath** \Box П Comments: Lavatory(s): $\hfill\square$ Missing waste stop: ☐ Broken waste stop: Tub/Shower: \square Open joints indicated / re-caulk or re-grout: \square Shower diverter is not operating properly ☐ Tank is loose from Commode Base: \square Commode Base is not secured to floor: Commode(s): ☐ Recommend licensed plumber inspect and repair entire plumbing system as needed. □ d. Main Floor Hall Bath V П Comments: ☐ Missing waste stop: ☐ Broken waste stop: Lavatory(s): Tub/Shower: ☐ Open joints indicated / re-caulk or re-grout: ☐ Shower diverter is not operating properly Commode(s) ☐ Tank is loose from Commode Base: ☐ Commode Base is not secured to floor: ☐ Recommend licensed plumber inspect and repair entire plumbing system as needed. e. Top Floor Hall Bath \checkmark Comments: Lavatory(s): \square Missing waste stop: ☐ Broken waste stop: Tub/Shower(s): ☐ Open joints indicated / re-caulk or re-grout: \square Shower diverter is not operating properly Commodes: \square Tank is loose from Commode Base: ☐ Commode Base is not secured to floor: \square Recommend licensed plumber inspect and repair entire plumbing system as needed. Half Bath **✓** П □ g. Comments: Lavatory(s): ☐ Missing waste stop: ☐ Broken waste stop: Commodes: \square Tank is loose from Commode Base: \square Commode Base is not secured to floor: \square Recommend licensed plumber inspect and repair entire plumbing system as needed. ☑ h. Other $\overline{\mathbf{A}}$ Comments: Water supply line (s): ☑ Water leaks indicated: faucet is leaking Outside faucet (s): ☑ Missing handles: in back $\ensuremath{\square}$ Recommend licensed plumber inspect and repair entire plumbing system as needed.

Report Identification: 25334 Intrepid Page 12of 16
Report Number: 202021J Date: July 20, 2020

Jay Hicks T.R.E.C. # 5332 I = Inspected NI = Not Inspected D = Deficient NP = Not Present NI NP D **INSPECTED ITEM** IV. PLUMBING SYSTEM (Cont'd) Drains, Wastes, and Vents V Comments: Kitchen: Laundry Room: Laundry room drain lines are not physically tested (visual inspection only) Master Bath: Hall Bath: Half Bath: \square Deficient installation/termination of plumbing vent system ☐ Recommend licensed plumber inspect and repair entire plumbing system as needed. Water Heating Equipment ☑ C. ~ Energy Source: Number of units □Gas ☑ Electric ☐ Attic ☐ Garage \square Laundry room Location: ☑ Middle floor closet □ Tankless ☑ Standard 50 Gallon Tank Type: Comments: \square Lack of protection from physical damage to unit located in a garage: $\hfill\square$ Power wire- Romex type wiring should be in conduit ☐ Electric or Gas Water heater should be raised 18" off of garage floor ☐ Corrosion noted on pipe connections; $\hfill\square$ Temperature & Pressure valve does not turn - inoperable: ☐ Damaged drain pan ☐ Temperature & Pressure valve drain lines runs uphill: ☐ Missing drain pan ☐ Temperature & Pressure valve drain line is missing - Improper: \square Missing gas shut off valve: ☐ Temperature & Pressure valve drain line should terminate to outside: ☐ Drain pan drain line is missing ☐ Obstructed T&P valve ☐ Rusted tank case Missing drain pan drain line ☐ Cold water supply valve handle is broken ☐ Gas line is missing drip leg (to catch moisture & sediment) \square Recommend licensed plumber inspect and repair entire water heating system as needed: Recommend a licensed plumber inspect and issue a report containing their state license number and contact information detailing their findings and all needed repairs. See section C (page 10) for information on water heater vent system Water temperature should be max. temperature of 130 degrees Temperature and Pressure relief (T&P) valves may or may NOT be tested due to the possibility the the valve may not re-seat (causing a water leak). The valve should be tested by the home owner annually. D. **Hydro - Massage Therapy Equipment** П П $\overline{}$ Comments: $\hfill\square$ Unit is inoperable $\hfill\square$ Recaulk or regrout around unit ☐ Vacuum switch does not operate ☐ Unit is leaking ☐ Ports and /or valves do not work properly ☐ Faucet Drips: ☐ Warning: THIS UNIT IS NOT GFCI ☐ Inaccessible pump/motor \square Recommend licensed plumber inspect and repair entire plumbing system as needed. E. Other/Gas Distribution Systems $\overline{\mathbf{v}}$ П Comments: ☐ Front □ Back ☐ Left side ☑ Right side Gas meter location: ☐ Improper gas line ☐ Gas line is not supported \square Deficient installation/termination of plumbing vent system

☐ System is not grounded

☐ Recommend licensed plumber inspect and repair entire plumbing system as needed.

Report Identification: 25334 Intrepid Page 13 of 16
Report Number: 202021J Date: July 20, 2020

Jay Hicks T.R.E.C. # 5332

I = Inspected NI = Not Inspected NP = Not Present D = Deficient NI NP **INSPECTED ITEM** V. APPLIANCES A. Dishwasher 4 **4** Comments: unit is improperly installed ☐ Unit is inoperable: ☑ Soap dish lid is damaged stays open ☐ Rusted dish racks: ☑ Drain line should loop to the highest point of the sink then down to drain line: **Food Waste Disposers** Comments: ☐ Unusual vibrations or noises: ☐ Unit is inoperable: \square Romex wiring should be in conduit: ☐ Visible leaks indicated: \square Damaged rubber splash guard: \square Unit is not properly secured: Range Hood and Exhaust Systems ☑ Recirculating vent ✓ ☐ Terminates outside Comments: ☐ Unit is inoperable: \square Vent pipe does not terminate outside: ☐ Unusual sounds or vibrations: \square Missing/damaged filter: ☑ Light is out: See section C (page 10) Ducts, Chases, and Vents for more vent information Ranges, Cooktops, and Ovens 7 Comments: Range Type: ☑ Electric □Gas \Box There should be a working vent system when a gas range is in use. ☐ Improper flexible gas line in use (should be yellow flex) ☐ Element on range does not operate properly: ☑ Missing Anti-Tip Device Ovens Oven type: ☑ Electric □Gas ☐ Convection \square Oven light is out or is not covered: \square Improper flexible gas line in use (should be yellow flex) **Oven Temperature** All units are tested on bake setting at 350 degrees. Single unit 353 degrees Broiler O.K. ☑ Yes □No □Yes □No **Upper Unit** degrees Broiler O.K. Lower Unit degrees Broiler O.K. □Yes □No If temperature variance is not within 25 degrees, calibration is recommended. □ **E**. **Microwave Ovens** V (Built -in only. Counter top units are NOT tested.) Comments: ☐ Unit is inoperable: ☐ Turn table does not turn: ☐ Handle is broken: \square Unit is not properly secured:

Report Identification: 25334 Intrepid Page 14 of 16 Report Number: 202021J Date: July 20, 2020

Jay Hicks T.R.E.C. # 5332

I = Inspected NI = Not Inspected NP = Not Present D = Deficient NI NP **INSPECTED ITEM** V. APPLIANCES (cont'd) **Mechanical Exhaust Vents and Bathroom Heaters** П g. Comments: ☐ Unit is inoperable ☐ Exhaust fan vent should terminate to atmosphere (Not Attic Area): ☐ Unit is noisy: **Garage Door Operators** \checkmark Comments: ☑ Unit does Not reverse - Recommend Adjustments: ☐ Not Tested ☐ Unit is inoperable: **Dryer Vent** □ j. \checkmark П Comments: ☐ Damaged louver cover: ☐ Missing louver cover: ☐ Dryer exhaust line should terminate to atmosphere: VI. OPTIONAL SYSTEMS An additional fee is charged for the inspection of the following systems. Landscape Irrigation (Sprinkler) Systems Number of Stations: Comments: \square Stations do not operate properly stations 3 and 4 В Swimming Pools, Spas, Hot Tubs, and Equipment and Equipment ✓ П ☐ If checked - Refer to separate POOL REPORT (attached): C. **Outbuildings** П **√** Comments: ☐ Roof leaks: ☐ Plugs are not GFCI protected: \square Compromised structure: ☐ Heat /cool does not work (if applicable) Comments: Private Water Wells (A coliform analysis is recommended) ✓ Pump type: ☐ Above ground: ☐ Submersible ☐ Other: Estimated proximity to septic system: Ft. Comments: $\hfill\square$ Unit is inoperable: ☐ Damaged controls: ☐ Damaged pressure switch \square Damaged/inoperable gauge □ D. Private Sewage Disposal (Septic) Systems П ✓ System type: ☐ Gravity fed □ Aerobic ☐ Other: Estimated proximity to water well: Location of field bed: ☐ Front ☐ Left side ☐ Right side □ Back □Unknown Comments: ☐ Odor present ☐ Damaged controls ☐ Inoperative aerator or dosing pump ☐ Seepage detected **Additional Comments** damaged hot water handle on outside shower

Attached is a "Liability Limitation Agreement". Please read carefully. Acceptance and reliance upon this inspection report is contingent upon acceptance and understanding of this liability agreement.

832-867-6253 / 409-316-2044

Important Inspection and Liability Limitation Agreement

We are a general real estate inspection company. We are licensed and regulated by the Texas Real Estate Commission. Our inspection and inspection forms are designed to adhere to guidelines in the 'Rules of the Texas Real Estate Commission' for home inspectors effective January 1,2014 and all subsequent amendments. {This Report complies with the January 1, 2009 requirements from the T.R.E.C.}

We perform a visual inspection of accessible areas and items and report to you the general conditions of inspected areas and/or items. Our inspection is limited to items specifically listed in this report only. We inspect and report to you if an item is performing the function for which it was designed or is deficient. We will explain our report to you or your designated agent. We perform our inspection in a professional and workmanlike manner. Our report of the inspection and its contents are based solely on the condition and appearance existing at the time of inspection. We do not address or comment on the condition or functional abilities of any item past the date and time of inspection. If we report that an item is not functioning or is deficient and is in need of replacement, we urge you to have the item examined by a specialist prior to making the final purchase of the property. We also advise you to re-check the functional ability of systems to insure no defects have occurred after the date of our inspection and prior to closing. If a structure has been unoccupied for an extended period of time, it is not uncommon for defects

We are not liable for damage or defects which may have been cosmetically masked or altered or are not completely visual and apparent under normal conditions. Weather conditions may affect the Inspector's ability to detect defects. Example: Minor areas of moisture penetration may not be visible at different times of the day or with low levels of humidity.

The information contained in this report is the sole possession of the buyer.

(2) What We Do Not Do:

We do not offer guarantees, warranties or insure the future performance or condition of any item, whether inspected or not. If you desire a guarantee, warranty, insurance policy or certification you must obtain such products and information from a company in that business endeavor. We do not inspect any item we cannot see in a normal manner of inspection.

We do not move furniture, rugs, carpet, paintings or any other furnishings or stored items in the course of our inspection.

We do not enter areas with less than proper clearance space needed, or areas, which in the opinion of the Inspector, is unsafe

We do not walk on wood shake, wood shingle, tile or any roof areas we may damage or any roof area which the Inspector considers unsafe to walk. These areas will be viewed either from the attic or ground or both, whichever is applicable.

We do not dismantle any item or system to check component parts, including gas fired heat exchangers.

We do not inspect for building codes, soil analysis, design adequacy, capacity, efficiency, sizing, value, flood plain location, pollution, environmental hazards or habitability.

We do not inspect for termites or any other insect infestation. We do not inspect security systems.

We do not inspect for, nor comment on, cosmetic damage.

to occur, particularly in plumbing joints or HVAC systems.

We do not operate equipment or systems outside the parameters of manufacturers recommendations.

We do not re-inspect repair work (all repairs are to be done by licensed professional repair tradesman)

(3) What You Do:

You agree not to allow <u>anv</u> third party not associated with the negotiations and consummation of the sale of the inspected property to have access to or rely on information contained in this report. You agree to notify the Inspector within 30 (thirty) days from the date of this inspection of any items disputed in this report and to allow a re-inspection of the disputed item **prior** to any repairs. You agree to limit any liabilities incurred by us and/or our associates which pertain to this inspection to the amount of the fee paid for this inspection and release our company and its associates from any further liability. You are to put into writing to our company any disputes. Communications must be consistent in that the party originally accompanying the inspector will be the party resolving the problem. You agree you will not post any information on any social media which may be derogatory or inflamatory towards Jay Hicks, Jay Hicks Inspection Services, their associates, or employees.

DISPUTE RESOLUTION: In the event of a dispute between the parties relating to this agreement, the parties or their representatives will meet promptly in an effort to resolve the dispute amicably. Upon the request of any party to this agreement, all unresolved disputes (not limited to breech of contract action), shall be submitted for binding arbitration in accordance with the Better Business Bureau Rules of Arbitration then in effect, and then neither party shall have a right to bring a suit in court. You agree to pay any and all fees incurred by all parties concerned. Any and all litigation, arbitration, or third party dispute resolution of any kind must take place in Galveston county, Texas.

You agree any payment made for inspection services that are subsequently dishonored will result in an additional \$100.00 fee. RE-INSPECTION FEE \$100.00. (To come back and finish job / due to utilities not on or outside temperature too low for A/C.) You attest that the inspector performing this inspection has made no oral representation that differ from the contents of this agreement.

You agree to the provisions and limitations of this contract and report by your reliance upon it whether you sign it or not.

You agree to pay a \$75.00 (seventy five dollars) billing fee for inspections not paid for at the time/day of inspection.

These inspections are visual only and structure and equipment is determined operable (unless otherwise indicated) at the time of inspection only.

Any use or this report constitutes acceptance or the above listed terms and conditions.

No warrantees or guarantees are offered for inspected components.

I HAVE READ THIS AGREEMENT AND I UNDERSTAND AND ACCEPT THESE CONDITIONS:

Address:	Address: 25334 Intrepid Report # 0		0	Date: July 20, 20		
					//	
Client's Signa	ture			Real Estate Inspector	//	Professional Inspector