

DESCRIPTION AND ESTIMATE of the Present Cash Value

Of the 1-2 story Wood shingles, Asbestos & ^{COMP.} roofed Frame building
 Situated on Lot No. 9 in Block No. SE 13 No. 3108 N Street
 in the City of Galveston, owned by Mrs. Fred Oehlert

Occupancy: {
 Basement 1' BP for _____
 First Floor by owner for Dwlg
 Second Floor by " for "
 Third Floor by _____ for _____

DESCRIPTION

When built? About 1901 Last repaired or painted? Insulation siding not aff 1960
 Is it on leased grounds? no When does lease expire? _____

What is used for lighting? Elect Is gasoline used? _____

Size of building? See Dia 24x24, 20x24 5/2 x 12 Porch 10x28

Plastered _____

Number of rooms Rough celled and papered 6 Halls 2 Bath room 1
 Celled and painted 1

Number closets? _____ Porches? 1 Mantels and grates? no

Number of flues and construction thereof? 2 bk 1 to gnd & 1 to 2 1/2' bkt (incased with wood to fl)

Is Fred B. Oehlert, individually, etc., to 00 feet? Yes Within 1000 feet? _____
Rosalie Oehlert, widow, lot 9 in the southeast block of outlet 13 and improvements, \$10. (No rev. stamp). 10/20/57

The above described building would cost, at present value of materials and labor \$ 8111

Genoice Waker and wife to Violet Moore Aaron and Mary Lee Moore, lot 9 in southeast block of out 13 in Galveston and improvements, \$10. (No rev. stamps). 8/29/66
 Deduct for depreciation from age, use or location 48 per cent 45

Making the present Cash Valuation _____ \$ _____

OTHER IMPROVEMENTS

Deduct for depreciation from age, use or location _____ per cent \$ _____

Making the present Cash Value _____ \$ _____

REMARKS: Poor Tax Bill on case of Pt - Tax Paper of Damaged last storm 13
advised RD 5-17-48

INSPECTOR