Tri-City Exterminating Company 3304 Spurlock Road Nederland, TX 77627 (409) 724-2843

INVOICE



Jonathan Layton 4449 Sherylwood Drive Port Arthur, TX 77642 Service Address

Jonathan Layton 4449 Sherylwood Drive

Port Arthur, TX 77642

Jonathan Layton 832-248-7088 Mobile

Account #
Invoice #

2109 4581

Invoice Date

03/28/23

Invoice Total

\$199.99

ITEM	DESCRIPTION	COST	QTY	PRICE	
WDI Rep WDI REI Wood		\$184.75	1	\$184.75	
Terms		Subtotal		\$184.75	
Payment i	s due on receipt	Jefferson Cty		\$12.47	
We accept Cash, Check & Credit Cards		Port Arthur		\$2.77	
we doocp	t dadii, diladik a dibak dahad	Total		\$199.99	
You may u	use our "online payment" option when receiving invoices via email	Amount Paid		\$0.00	
We appreciate your business!		Amount Due		\$199.99	
		Past Balance		\$0.00	
Notes Thank you	u for your business.	Balance Due		\$199.99	

We checked in at 2:27pm and checked out at 3:58pm.

Licensed and regulated by the Texas Department of Agriculture P.O. Box 12847, Austin, Texas 78711-2847 Phone (866) 918-4481 Fax (888) 232-2567

Jason Allbritton 46217

PAYMENT STUB

Tri-City Exterminating Company 3304 Spurlock Road Nederland, TX 77627

Customer	Jonathan Layton
Account #	2109
Invoice #	4581
Invoice Date	03/28/23
Balance Due	\$199.99
Amount Enclosed	

TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

Rule §7.176 Requires this department prescribed form to be used for real estate transactions in Texas regarding the visible presence or absence of wood destroying insects and conditions conducive to infestations of wood destroying insects.

4449 Sherylwood Drive	Port Arthur	77642	
Inspected Address	City	Zip Code	

SCOPE OF INSPECTION

- A. This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guest houses or any other structure will not be included in this inspection report unless specifically noted in Section 5 of this report.
- B. This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work.
- C. Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment; has rendered the pest(s) inactive.
- D. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is present.
- E. If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified expert.
- F. THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS.
- G. If termite treatment (including pesticides, baits or other methods) has been recommended, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticides to be used and complete details of warranty (if any). The warranty should specify which areas of the structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party.
- H. There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and renewal options.
- I. There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure, (2) there is visible evidence of a previous infestation with no evidence of a prior treatment.
- J. If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture.

4449 Sherylwood Drive	Port Arthu	ur	77642	
Inspected Address	City		Zip Code	
1A Tri-City Exterminating Company	1B	TPC	L 5063	
Name of Inspection Company		SPCS Business	s License Number	
1C 3304 Spurlock Road	Nederland		627 (409) 724-2843	
Address of Inspection Company	City	State Zip	- Parameter - Para	>
1D. Jason Allbritton Name of Inspector (Please Print)	1	 Certified Applicator Technician 	check o	ne)
	1F. 03/28/23			
		Inspection Date		
Jonathan Layton Name of Person Purchasing Inspection	Seller Agent	☑ Buyer ☐ Manage	ement Co. Other	
3. NA				
Owner/Seller				- 1
 REPORT FORWARDED TO: Title Company or Mortgagee (Under the Structural Pest Control regulations only the purchaser of the Company of the Company or Mortgagee) 	Purchaser of Sen ne service is required to		☐ Agent ☑ Buyer ☐	
The structure(s) listed below were inspected in accordance with the official is Control Service. This report is made subject to the conditions listed under the	inspection procedures e Scope of Inspection.	adopted by the Texas D A diagram must be attac	repartment of Agriculture Structur ched including all structures inspe	al Pest ected.
5A. HOUSE / DETACHED POOL BATHROOM List structure(s) inspected that may include residence, detached garages and	d other structures on th	e property. (Refer to Pa	art A. Scope of Inspection)	
		,,, ,. ,, ,	, , , , , , , , , , , , , , , , , , , ,	
5B. Type of Construction: Foundation: Slab ☑ Pier & Beam ☐ Pier Type:	Basement	Other:		
Siding: Wood Fiber Cement Board Brick Stone	Stucco Other: V	NYL		
Roof: Composition W Wood Shingle Metal M Tile			_	
6A. This company has treated or is treating the structure for the following wo	ood destroying insects:	NA		
If treating for subterranean termites, the treatment was:	Partial	☐ Spot ☐	Bait Other	
If treating for drywood termites or related insects, the treatment was:	Full	Limited		
6B. <u>NA</u>		NA		
Date of freathers by moperating company	on Name of Insect		e of Pesticide, Bait or Other Meth	od
This company has a contract or warranty in effect for control of the following	wood destroying insec	ts:		
Yes ☐ No ✓ List Insects: NA If "Yes", copy(ies) of warranty and treatment diagram must be a	attached.			
Neither I nor the company for which I am acting have had, presently have, o	r contemplate having a	ny interest in the purcha	ase or sale of this property. I do fu	urther
state that neither I nor the company for which I am acting is associated in an	ny way with any party to	this real estate transac	ction.	
Jose Cellita				
Signatures:				
7A. Jason Allbritton / 46217 Inspector (Technician or Certified Applicator Name and License Number	<u>r)</u>			
127	•			
Others Present: 7B. NONE				
Apprentices, Technicians, or Certified Applicators Name(s) and Registrat	tion/License Number(s)			
Notice of Inspection Was Posted At or Near:				
AND SOURCE AND A PROCESS OF A SOURCE AND A S	ate Posted: 03/28/23			
Water Heater Closet				
Beneath the Kitchen Sink			N- M	
9A. Were any areas of the property obstructed or inaccessible? (Refer to Part B & C, Scope of Inspection) If "Yes" specify in 9B.	Yes	Ø	No LJ	
9B. The obstructed or inaccessible areas include but are not limited to the fo			Planter box abutting structure	
Attic Insulated area of attic Deck Sub Floors Heavy Foliage	Plumbing Areas Slab Joints		Crawl Space	
Soil Grade Too High Heavy Foliage	Eaves	***************************************	Weepholes	1
Other Specify: SEE SCOPE OF INSPEC	TION AND ADDENDU	M A		
10A. Conditions conducive to wood destroying insect infestation: (Refer to Part J, Scope of Inspection) If "Yes" specify in 10B.	Yes		No 🗆	
10B. Conducive Conditions include but are not limited to:			Excessive Moistur	re / I\ m
Debris under or around structure (K) Wood to Ground Contact (G Planter box abutting structure (O) Footing too low or soil line to	oo high (L)	Formboards left in place Wood Rot (M)	Heavy Foliage (N)	
Insufficient ventilation (T) Wood Pile in Contact with S	tructure (Q)		act with the Structure (R)) [
Other (C) 🗹 Spe	ecify: SEE SCOPE OF	INSPECTION AND ADD	DENDUM A	
	. the Towns Demoster	nt of Agricultura		
Licensed and Regulated by PO Box 12847, Austin, Texas 7871			67	
Service State (Section 2011) Section 2011 Control of the Control o				ge 2 of 4
SPCS/T-5 (Rev. 9/1/2020)			. 48	

4449 Sherylwood Drive Inspected Address	Port Arthur City	77642 Zip Code
11. Inspection Reveals Visible Evidence in or on the structur 11A. Subterranean Termites 11B. Drywood Termites 11C. Formosan Termites 11D. Carpenter Ants 11E. Other Wood Destroying Insects Specify:	Yes □ No ☑ Ye	Previous Infestation Previous Treatment S No M Yes No M
11F. Explanation of signs of previous treatment (including p	esticides, baits, existing treatment stickers or other r	nethods) identified:
NONE NOTED, NO SIGNS AND/OR TREATMENT TAGS,	SHOULD CONTACT OWNER ON HISTORY	
11G. Visible evidence of: SEE 11F	Nhas been observed in the following areas:	ONE VISIBLE AT TIME OF IMSPECTION (SEE COPE
OF INSPECTION)		
If there is visible evidence of active or previous infestation, the property inspected must be noted in the second blank.	Refer to Part D, E & F, Scope of Inspection)	
o, ii, and i, ocope or inspection,	L No L	
12B. A preventive treatment and/or correction of conducive Specify reason: IF A WARRANTY IS NEEDED	conditions as identified in 10A & 10B is recommend	ed as follows: Yes 🗹 No 🗌
Refer to Scope of Inspection Part J		
	Diagram of Structure(s) Inspected	
The inspector must draw a diagram including approximate following codes: E-Evidence of Infestation, A-Active; P-Pre B-Wood Boring Beetles; HCarpenter Ants; Other(s) – Spec	rious; D-Drywood Termites; S-Subterranean Termite	ious infestation and type of insect by using the s; F-Formosan Termites; C-Conducive Conditions;
		ere greene greene ge
and the second s	and an ann an	CANADANANA CANADANANA DA
the entry of the second	and the second and th	reconstruction of the second s
	energeneral arresponsaciones al secondarios and accompanies and processing constructions and the secondarios and the secondari	ever verenieven vereni
SEE	ATTACHED DIAGRAM	
Additional Comments Recommend treating slab lines, co	ld joints and all downstairs Plumbing penetrations for	or termites for \$ 1,082.50 with a 10 year
transferable warranty for \$250+tax a year.		
SPCS/T-5 (Rev. 9/1/2020)		Page 3 of 4

4449 Sherylwood Drive	Port Arthur City	77642 Zip Code
Inspected Address		Zip Code
	Statement of Purchaser	
I have received the original or a legible copy of this form. I have Inspection." I understand that my inspector may provide additional additional information is attached, list number of pages: 2	read and understand any recommendations made. I have all information as an addendum to this report.	e also read and understand the "Scope of
Signature of Purchaser of Property or their Designee	Date	
☑ Customer or Designee Not Present Buyer's Initials	·	
		V ₂
	9	
	4	
56	8	
	I. I	
	A TTA CH	
		,
	X	

SPCS/T-5 (Rev. 9/1/2020)


Page 4 of 4

DIAGRAM OF STRUCTURE(S) INSPECTED

The inspector must draw a diagram including approximate perimeter measurements and indicate active or previous infestation and type of insect by using the following codes:

E - Evidence of infestation; A - Active; P - Previous; D - Drywood Termites; S - Subterranean Termites; F - Formosan Termites;

C - Conducive Conditions; B - Wood Boring Beetles; H - Carpenter Ants; Other(s)



Additional Comments: IF A WARRANTY IS NEEDED, A TREATMENT RECOMMENDED.(SEE SCOPE OF INSPECTION SECTION A THRU J)

CONTINUATION OF SECTIONS 6B, 7B, 8G: DIAGRAM CODES AND ADDITIONAL COMMENTS

6B: ODSTRUCTIONS OR INACCESSIBLE AREAS FROM BOX 6B, PAGE 2 OF 5 include but are not limmited to the following:

built-ins and cabinets, door trim and thresholds, window trim and sills, curtains and blinds, wall and flooring coverings, hardwood flooring and carpeting, ceramic wall and floor tiles, paneling and modeling, finished walls and ceilings, stored items, appliances and furniture, plumbing penetrations in slab, plumbing in wall voids, outside faucets, bathtraps and shower base, a/c ducts and lines, electrical conduits and outlets, exhaust vents, utility lines, soil over slab, landscaping materials, cold joints, crack in slab and mortar patches, crack corners, attic spaces, insulation materials, roofing and decking, eaves and flashing, rain gutters and down spouts, exterior siding and trim, slab grade against and over siding, fireplace base and stack, footing too low or soil garde too high, bark mulch and heacy foliage, columns bases

7B: CONDUCIVE CONDITIONS TO WOOD DESTROYING INSECTS FROM PAGE 2 OF 5 include but are not limited to: (SEE DIAGRAM PAGE 4 OF 5)

(C16) foliage against exterior siding (C18) wood deay on columns (C19) attach wooden fencing (C20) bark mulch against slab

ADDITIONAL COMMENTS: CONTINUED

SEE PAGE ONE SCOPE OF INSPECTION (SECTION J) AND RECOMMEND MONITORING ALL CONDUCIVE CONDITIONS IN THE FUTURE, IF A WARRANTY IS NEEDED IN ANY OF THOSE AREAS, A TREATMENT IS RECOMMENDED.







(C16)(C20) A.jpg



(C16)(C20) B.jpg



(C18) A.jpg



(C18) B.jpg



(C19) A.jpg