


HEDDERMAN PEST CONTROL

281 - 355 - 9980 HPC@Hedderman.com TPCL License Number #0816143

Wood Destroying Insect Report

Inspection Performed by Juan Mireles TPCL #838092 4/11/2022



1119 Walden Hill Ct.

1119 Walden Hill Ct.	Houston	77077
Inspected Address	City	Zip Code

TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

Rule §7.176 Requires this department prescribed form to be used for real estate transactions in Texas regarding the visible presence or absence of wood destroying insects and conditions conducive to infestations of wood destroying insects.

SCOPE OF INSPECTION

- A. This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guest houses or any other structure will not be included in this inspection report unless specifically noted in Section 5 of this report.
- B. This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work.
- C. Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment; has rendered the pest(s) inactive.
- D. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is present.
- E. If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified expert.
- F. THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS.
- G. If termite treatment (including pesticides, baits or other methods) has been recommended, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticides to be used and complete details of warranty (if any). The warranty should specify which areas of the structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party.
- H. There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and renewal options.
- I. There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure, (2) there is visible evidence of a previous infestation with no evidence of a prior treatment.
- J. If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture

	1119 Walden Hill Ct.	Houston		_	77077			
_	Inspected Address		City			Zip	Code	
1B	HEDDERMAN PEST CONTROL	1A.		081614				
	Name of Inspection Company			SPCS Business Li	cense Number			
1C	10678 Ehlers Rd. Address of Inspection Company	Conroe	Texas State	77302 Zip		281 - 355 Telephone N		
		J.,		—·r				
	Juan Mireles TPCL #838092 6					ed Applicator		(check one)
	Name of Inspector (Please Print)	Inspection	n Date April 1	1, 2022	Tech	nician	\boxtimes	
2	Marley Vansanten	☐ Seller ☐ Agent ☒ Bu	yer	ent Co. DOther:			_	
N	ame of Person Purchasing Inspection							
3	Unknown							
	Owner/Seller ORT FORWARDED TO: Title Company or Mortgage ler the Structural Pest Control regulations only the purch	•			ent 🗆	Buyer \square		
,	ructure(s) listed below were inspected in accordance wi	·		• /	ment of Agricul	ture Structural Pa	et Control	Sanvica This
	is made subject to the conditions listed under the Scope					ture Structural 1 t	est Control	Service. Triis
5A	House and Garage List structure(s) inspected that may include res	sidence, detached geregee on	d other atrustures	on the property	(Poter to Part A	Coope of Inapa	ation)	
5D T	`, ,	sidence, detached garages an	d other structures	s on the property.	Refer to Part A	, Scope of Insper	ction)	
	/pe of Construction: Foundation: ⊠ Slab □ Pier & Beam Pier Type:			Basement [Other: N/A	\		
Qi.	ding: ☐ Wood ☐ Hardie Plank ☒ Brick ☐ Stone	Stucco Other						
	pof: ☐ Composition ☐ Wood Shingle ☐ Metal ☐							
	•		NI/A					
	nis company has treated or is treating the structure for thing for subterranean termites, the treatment was:	Partial	Spot	Bait 🗆	Other			
	ing for drywood termites or related insects, the treatmen		Limited					
6B.	N/A	N/A			N/A			
_	Date of Treatment by Inspecting Company	Common Nam	e of Insect	_	Name of Pe	sticide, Bait or Ot	her Metho	 d
This co	ompany has a contract or warranty in effect for control o	f the following wood destroyir	ng insects:					
	Yes □ No ⊠ List Inser	cts: N/A						
	If "Yes", copy(ies) of warranty and treatmen	nt diagram must be attached	l.					
	r I nor the company for which I am acting have had, pre			t in the purchase o	r sale of this pr	operty. I do furth	er state th	at neither I nor th
Signat	ures:	ing party to this real estate tra	risaction.					
7A	Juan Mireles TPCL #838092 Inspector (Technician or Certified Applicator Name	e and License Number)						
Others 7B.	s Present: N/A							
Apprer	ntices, Technicians, or Certified Applicators Name(s) an	d Registration/License Numb	er(s)					
Notice	of Inspection Was Posted At or Near:							
8A.	Electric Breaker Box BB.	Date Posted: 4/11/202	2		_			
	Water Heater Closet							
	ere any areas of the property obstructed or inaccessible to Part B & C, Scope of Inspection) If "Yes" specify in S		No					
9B. Th	e obstructed or inaccessible areas include but are not li	mited to the following:						
Attic	☐ Insulated area of attic ⊠	Plumbing Areas		Planter box abut	ting structure			
Deck	Sub Floors	Slab Joints		Crawl Space				
Soil Gi	rade Too High $\hfill \Box$ Heavy Foliage $\hfill eta$	Eaves		Weepholes				
	Other U Specify:							
	conditions conducive to wood destroying insect infestation to Part J, Scope of Inspection) If "Yes" specify in 10B.	on: Yes 🗵	No) [
10B.C	onducive Conditions include but are not limited to:	ound Contact (C)	□ :	ando loft in al	□ -	analys Mari	,, _	
Debris		ound Contact (G) low or soil line too high (L)	☐ Formboa ☐ Wood R	ot (M)	_	essive Moisture (avy Foliage (N)	(J) 🖂	
	_	Contact with Structure (Q)		Fence in Contact v		, , ,		
	cient ventilation (T)	Specify:						

Licensed and Regulated by the Texas Department of Agriculture PO Box 12847, Austin, Texas 78711-2847 Phone 866-918-4481, Fax 888-232-2567

1119 Walden Hill Ct.	Houston		77077		
Inspected Address	City		Zip Code		
11. Inspection Reveals Visible Evidence in or on to 11A. Subterranean Termites 11B. Drywood Termites 11C. Formosan Termites 11D. Carpenter Ants 11E. Other Wood Destroying Insects Specify: 11F.Explanation of signs of previous treatment (in	he structure: Active Infestation Yes No Yes	Previous Infestation Yes No Yes	Yes □ No ☒ Yes □ No ☒		
11G.Visible evidence of:	has been observed in the following areas:				
If there is visible evidence of active or previous infestation, it must be noted. The type of insect(s) must be listed in the first blank and all identified infested areas of the property inspected must be noted in the second blank. (Refer to Part D, E & F, Scope of Inspection) 12A. Corrective treatment recommended for active infestation or evidence of previous infestation with no prior treatment as identified in Section 11. (Refer to Part G, H, and I, Scope of Inspection) 12B. A preventive treatment and/or correction of conducive conditions as identified in 10A & 10B is recommended as follows: Yes No Specify reason: The conducive conditions listed in sections "10A" and in "Additional Comments" should be corrected to deter insect activity.					
of Infestation, A-Active; P-Previous; D-Drywood T	Diagram of Structure(s) Inspecter roximate perimeter measurements and indicate active or previermites; S-Subterranean Termites; F-Formosan Termites; C-C	ous infestation and type of insec			
Conducive Conditions G - Wood to ground contact I - Formboards left in place J - Excessive moisture K - Debris under / around structure L - Footing low / Soil too high M - Wood rot N - Heavy foliage O - Planter box abutting structure Q - Wood pile contact structure R - Wooden fence contact structure T - Insufficient ventilation C - Other Types of Insects E - Evidence of infestation A - Active P - Previous D - Drywood S - Subterranean Termites F - Formosan Termites C - Conducive conditions B - Wood boring beetles H - Carpenter ants E - Other(s)		9' 6' 12' 9' 21' 18' 36' 12' 9' 21' N GARAGE 24'N	R		
	age should be cut back to provide at least 3 inches		ture.		

Conducive conditions obstruct visibility and limit the inspection for wood destroying insects. It is recommended that all conducive conditions be corrected and the obstructed areas be reinspected once the work is complete.

1119 Walden Hill Ct.	Houston	77077		
Inspected Address	City	Zip Code		
Statement of Purchaser				
I have received the original or a legible copy of this form. I have read and understand any recommendations made. I have also read and understand the "Scope of Inspection." I understand that my inspector may provide additional information as an addendum to this report.				
If additional information is attached, list number of pages: 1 Cover Page, 1 Receipt Page, and/or One or More Photo Pages				
Signature of Purchaser of Property or their Designee	Date			
☐ Customer or Designee Not Present	Buyer's Initials			

1119 Walden Hill Ct.	Houston	77077	
Inspected Address	City	Zin Code	

Addendum to Report

Obstructed/Limited Visibility

The inspection of certain areas was limited due to obstructed visibility and/or a lack of adequate access. The inspection for wood destroying insects was significantly limited and could not be thoroughly checked at some areas due to the following conditions:

Stored items in closets	☐ Stored items in attic	
		△ Stored items in garag

- ☐ Vehicle(s) in garage
- □ Furniture throughout the house ☐ Behind locked door ☐ Crawlspace not accessible ☐ Portions of crawlspace not accessible
- ☐ Zero property line ☐ Common walls between properties ☐ Vines covering wall(s)
- ☐ Insulated sub floors at crawlspace ☐ Foam insulation coating roof framing
- ☐ Materials behind vinyl siding ☐ Porch/Deck covers foundations

Obstructed View

Items stored in garage obstructing view





Tile/Pavers obstructing view of the foundation





Inspected Address

City

Zip Code

Conducive Conditions

Heavy Foliage





Wood fence in contact with the ground and structure





Other Conditions

Pics of the attic





Inspected Address City Zip Code



HEDDERMAN PEST CONTROL

281 - 355 - 9980 HPC@Hedderman.com TPCL License Number #0816143

RECEIPT

DATE: 4/11/2022

TO: Marley Vansanten

REF: WDI inspection for the house located at 1119 Walden Hill Ct.

Total cost of inspection: \$140.00

Total Paid: \$140.00

Total Due: - 0 -