Jay Hicks Inspection Service

COVER PAGE

☐ New Construct

"STRUCTURAL & MECHANICAL INSPECTION REPORT"

(832) 867-6253

☐ Client Present

Alan Harper

☑ Slab on Grade

Texas Real Estate Commission Professional License # 21133

☐ Other ☐ Agent Present ☐ Raised Foundation ☐ H	Historical Home
Client: Chris James Property Address: 2750 Holly Hall # 1006	
City: Houston State Texas Zip 77054 Pin # 203235A	
Inspection Type: Structural Mechanical Structural/Mechan	ical
inopositori Typo.	icai
Trouble to a 1 story awailing. Supra No. 2 quipped.— 100 No.	□ Term
Date of Inspection: November 18, 2020 Time 9:30 ☑ AM ☐ PM	L Telli
Weather Conditions: $\ \ \square$ Sunny $\ \ \square$ Cloudy $\ \ \square$ Windy $\ \ \square$ Raining $\ \ \square$ Thunder/Lightening	
Reference: Agent: Kathryn Peters 713-598-0547	



Returned Checks \$50 plus all bank charges

☐ Property Occupied

Repair reinspection 1/2 inspection fee or \$100 minimum

THIS REPORT IS TO BE USED SOLELY FOR THE BENEFIT OF THE PROSPECTIVE CLIENT (ONLY)
LISTED IN THIS REPORT. THIS REPORT IS NOT TRANSFERABLE TO ANY OTHER FUTURE
CLIENTS OR INDIVIDUALS WITHOUT WRITTEN PERMISSION FROM JAY HICKS INSPECTION SERVICES.

This report is not a warrantee or guarantee of any kind. Consult your agent about warrantee companies.

Important Notice:

All directions are front the street facing the house (Front door)

Future performance can <u>not</u> be determine on <u>any</u> item.

"if any concerns - You "<u>the buyer</u>" should contact technical personnel to evaluate any and all items or comments."

It is understood that my opinion and testing methods may differ from the opinion of other inspectors or licensed technicians.

ATTENTION CLIENTS:

Detailed limitations regarding scope of this report are outlined in the following (attached):
INSPECTION AND LIABILITY LIMITATION AGREEMENT, and "FOUNDATION
INFORMATION" sheet. Please call our office if any of these items are not enclosed with this report.

We shall forward you copies immediately.

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

PROPERTY INSPECTION REPORT

Jay Hicks Inspection Services

Prepared For: Chris James

Concerning: 2750 Holly Hall # 1006 203235A Texas 77054

By: Alan Harper

TREC Licensed # 21133

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL the information. This report may not be complete without the attachments.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov

The TREC Standards of Practice (Sections535.227 - 535.233 of the rules) are the minimum standards for inspections by TREC licensed inspectors. An inspection addresses only those components and conditions which are present, visible, and accessible at the time of the inspection. While there may be other parts, components, or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or or stored items. The inspection report may address issues that are code based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with a manufacturer's installation instructions. The inspection does NOT imply insurability or warrant ability of the structure or it's components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported as Deficient may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods. Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repair have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathrooms, kitchens, and exterior areas;
 - · malfunctioning arc fault protection (AFCI) devices;
 - ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
 - · malfunctioning carbon monoxide alarms:
 - excessive spacing between balusters on stairways and porches;
 - · improperly installed appliances;
- · improperly installed or defective safety devices; and
- · lack of electrical bonding and grounding.

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms require a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Report Identification: 2750 Holly Hall # 1006 Page 4 of 16

Report Number: 203235A Date: November 18, 2020

Alan Harper T.R.E.C. # 21133

I = Inspected NI = Not Inspected NP = Not Present D = Deficiency

I	NI	NP D	INSPECTED ITEM
7			I. STRUCTURAL SYSTEMS A. Foundations Comments: Home Owner Association's- responsibility
			Type:
			☐ Previous foundation repairs indicated - see warranty for details:
			☐ Binding, out of square, non-latching twisted doors or
			☐ Wall, floor , or ceiling cracks:
			☐ Separation of walls from ceilings or floors:
			$\ \square$ Differential movement of walkways, driveways, and patios:
			☐ Inadequately ventilated crawl space: ☐ Deteriorated materials:
			☐ Damaged blocking:
			☐ Non-supporting piers/posts:

Important Notice >>> The condition of the foundations is reported on the day of inspection.

This report is of the general condition (Not an engineers report), Future performance can not be determined after that day. If you have any concerns. You should contact a structural engineer.

It is always recommended to get a second opinion on the foundation performance

FOUNDATION INFORMATION:

The following evidence and consequences are generally associated with foundation differential movement: the structure and loss and gain of moisture content of framing lumber. It is not uncommon for foundations to reveal some systems of differential movement. At the time of inspection, this inspector may have observed evidences and consequences of differential movement. Unless noted otherwise, these evidences and consequences may not be excessive and do not indicate the immediate presence of significantly deflected foundation or foundation failure. Therefore, if indicated, any discrepancy should be evaluated by a Structural Engineer or foundation repair company. Expansive soils that are common in the "Gulf Coast" area can dramatically adversely affect the performance of a foundation. Variations in moisture content produces swelling and shrinkage of the soil which can result in differential heaving and settlement of a foundation. The opinion rendered in this report does not apply to future changing conditions and structural consequences affected by thermal/climatic conditions, moisture or any other conditions that affect foundation movement. Differential movement in the foundation can occur rapidly under certain conditions and the future performance or stability of the foundation cannot be predicted. If in-depth information is desired on the foundation, soil stability or any part thereof, a Structural Engineer should be consulted.

Foundation movement may not necessarily be the cause of cracks in the home gypsum board (sheetrock) and brick veneer. Expansion and contraction of the home's framing may cause the following: 1) Horizontal cracking of sheetrock at the inside corners of windows is due to thermal expansion/contraction of the window framing. 2) Cracks in corners of raised ceilings are most commonly the result of thermal expansion/contraction in attic framing. 3) Minor separations in brick/sheetrock connections are commonly due to different expansion/contraction rates of different materials. 4) Cracks in top "soldier brick" rows are commonly caused by framing movement. 5) Foundation corners that chip off are caused from improper removal of foundation wooden form boards or by frictional forces from the movement between the brick veneer and concrete foundation. 6) Minor cracks may appear in brick veneer due to normal structural movement of walls installed without brick expansion joints or at the weak areas of brick walls under windows.

Report Identification: 2750 Holly Hall # 1006 Page 5 of 16

Report Number: 203235A Date: November 18, 2020

Alan Harper T.R.E.C. # 21133

I = Inspected NI = Not Inspected NP = Not Present D = Deficiency

ī		NI	NP		- ilispe		INC		TED ITEM	- Deliciei	<u>,</u>
ı			INP			0		אבו	, IED IIEM		
V					В.	Grading and D Comments Ho ☐ High soil level:	rainage ome Owner Assoc	ciatio	n's- responsibi	ility	
						☐ Erosion:					
						☐ Missing downspo	out splash blocks				
						☐ Low area next to	o slab:				
					There	should be appro	oximately 4 " of sla	b exp	osed between tl	he botton	n of the brick
					or sid	ling and the grou	nd. This allows the	early	detection of an	ts, termit	es, and etc
V					C.	Roof Covering	l				
								asses	☐ Walked on roo	of	
						☐ Metal	Asphalt shingles		☐ Wood shake		☐ Tile
						Levels or surface	ces not accessed:				
						Comments: He	ome Owner Assoc	ciatio	n's- responsibi	ility	
						✓ Aging (NOTED) ☐ Curling:			☐ Defic	cient fasteni	ing of roof covering material:
						□ carmig.			□ Dam	aged skylig	hte
						☐ Remove Debris:			□ Daiii	lagea skylig	no.
							ot appropriate for slope		□Rem	ove Debris:	
						in Roof covering the	or appropriate for slope			e shingles:	
						☐ Nails pushing up	shinales.		□ L003	e silligles.	
						a pasg up	g		☐ Prev	ious repairs	
						□ ∆ professional re	oofer should inspect the	roof a		•	
**	This	insı	oecti	on is n	either		plied to certify th				
		_			D.	Roof Structure	-			,	
	✓			√		Access:	□ Good		☐ Very Limited		☑ Not Accessible
						Insulation Type	· □ Blanket		□ Loose Fi	II	
						Approximate De			Thickness:		
						Comments:				-	
						☐ Water damaged	roof decking:				
						☐ Attic structure b	pracing not properly atta	ached:			
						☐ Missing section(s	s) of attic insulation:				
						☐ Improper/Deficie	ent attic ventilator/venti	lation:			
is re	eport	ed o	n the		the ins	s are inspected of spection. The rep	ort is a general cor	d/ we nditior	do not walk on a of the roof material of the roof m	the roof(s terial. Fut	nmendations. s). The condition of the roof ure performance can y for an evaluation. This

company does not issue WPI-8 certificates. It is always recommended to get a second opinion on the roofs performance.

Report identification: 2750 Holly Hall # 1006 Report Number: 203235A Page 6 of 16

Date: November 18, 2020

Alan Harper T.R.E.C. # 21133

					l = In	spected	NI = Not In	spected	NP = Not Pi		ficient	
I	1	NI .	NP	D					INSPECTE	ED ITEM		
V			U	l			rior and Ext					
					N N	OTE: Item	is marked "	not inspec	ted" may not	be installed ye and from left to	t. . riaht/fron	t street facing)
						terior Wa		numbereu	TOTAL TO BACK	and from left to	rigiit(iioii	t street lacing).
						omments:						
					T	уре:	☑Sheetro	ock				
					ПЕ	resh paint:						
						reon painer		N.				
					□F	Repairs/patch	ing			-		
						-,,	3					
						Cracks			4			
					ПН	loles						A I I
						.0.05						
						Discolorations	;					
					□v	Vater penetra	ation:					
												THE RESERVE TO THE RE
							through sheetr		ociation's- re	sponsibility		
						☑Brick		☐ Hardy Pla		□Wood	i	□T-111
					_	☑Vinyl		□Aluminum	Siding	□Cinde		□Masonite
						omments: Cracks in Mor		inyl near f	ront door, left	t side of front po	orch - abov	re photo
						JI dCKS III MUI	tal/ DITCKS					
					□F	ascia boards,	/trim					
_	_		_		F. C	oilinge an	d Floors					
✓						eilings an eilings:	iu rioois					
						omments:						
						Fresh paint:						
					П	Cracks:						
						Holes:						
						Discoloration	15:					
						Repairs:						
						Water penet	ration:					
						Naile puchin	a through chee	trock:				
						ivalis pusiliii	g through shee	uock.				
						Floors:	□ Ceram	ic Tile:	□Vinyl	□Carpet:	⊒W	ood laminate:
						Floor is unev	/en					
						Floor is not	level					
						Vinyl flooring	g is ripped/torn	:				
					_	Tile is missi-	og:					
						Tile is missir	ıy.					
						Ceramic tile	is cracked:					
						Carpet is da	maged/stained	:				
					П	Wood floor is	s warped/disco	lored/damage	d:			
								cu, uarriage				

We do Not do invasive moisture penetration tests. The inspection is visual only. Some cracks and separations are caused by structural or foundation movement. Report Identification: 2750 Holly Hall # 1006 Page 7 of 16

Report Number: 203235A Date: November 18, 2020

Alan Harper T.R.E.C. # 21133

I = Inspected NI = Not Inspected NP = Not Present D = Deficient NP **INSPECTED ITEM** NI G. Doors (Interior and Exterior) ~ Comments: ☑ Damaged and / or missing door stops: hallway closet, hall bath, master closet - photo ☐ Missing Doors: laundry room ☐ Door knobs damaged/missing \square Door not square in frame: ☐ Warped Door: \square Door hinge damaged or loose: ☑ Adjust door striker plate laundry room ☐ Wood rot indicated to exterior doors: $\hfill\square$ Missing and /or damaged door screens: ☐ Present ☑ Not Present **Garage Doors** □ Metal ☐ Wood □ Other Door Type: \square Door is bent or damaged: $\hfill\Box$ Glass is broken or damaged: H. Windows All sleeping rooms MUST be equipped with emergency escape and rescue openings. Recommend removal of all bars on windows and doors. Comments: re caulk around interior of all windows-right photo ☑ Single pane aluminum windows Missing and / or damaged screens: ☐ Damaged window springs: \square Insulated windows are fogged $\hfill\square$ Damaged or missing locks: ☑ Damaged window glazing/weather stripping: master bedroom - left photo Stairways: Interior and Exterior V ☐ Baluster/spindle spacing: Should have a maximum opening of 4" (TREC Guidelines) $\hfill\square$ Stairway: Missing hand railing if over 4 steps / Improper: ☐ Missing stair stringer (step supports): Fireplace / Chimney Not all areas of the flue liners are accessible for inspection. Chimneys should be cleaned annually. Crown / Cap is not accessible for inspection. □ Wood burning ☐ Gas Only \square Combination gas and wood: Comments: ☐ Build up indicated in flue liners / should be cleaned: ☐ Improper lintel and hearth extension: ☐ Remove combustible material near firebox: ☐ Improper location for gas log lighter valve: ☐ Missing fire blocking at attic level: ☐ Improper/missing combustion air vents: \square Loose firebricks and or cracks indicated in firebox: ☐ Improper chimney structure: ☐ Damper does not operate properly: ☐ Improper chimney termination: \square Improper coping, crown cap, spark arrestor: \square Inoperative circulating fan: Κ Porches, Decks and Carports (Attached) Comments: ☐ Baluster/spindle spacing: Should have a maximum opening of 4" (TREC Guidelines) ☐ Not Secured and / or wobbles: $\hfill\square$ Wood rot and / or water damaged indicated:

Report Identification: 2750 Holly Hall # 1006 Page 8 of 16

Report Number: 203235A Date: November 18, 2020

Alan Harper T.R.E.C. #21133

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

Ī	1	NI	NP	D			INSPEC [®]	TED ITEM		
					II. ELECTRICAL	SYSTEMS				
V]	A. Service Entra	nce Panel				
					Wiring Type:	☑ Copper		luminum		luminum mixed
	_				Location:	☐ Front	☐ Back	☐ Right Side	☑ Guest Bedroo	m
		4			THE STATE OF THE S		- 1		AR	3
					Altra print					
				- 1-2	The state of the s			A KAT JA		
									oven	1
					B 1-4 B 100 B 10 B					
							1			1
					THE RE			V/3		
					HIS SILVE			30		
					In This is			8	6	
					luc chill		3	10000	1	A STATE OF THE PARTY OF
						THE REAL PROPERTY.	111		E11 214 - 1111	
									SRIGHING I	
									S VERT VERT	
					772 Jan 1 1 1 1 2 7		2111			
		_			☑ Panel is not fully la					
					☑ Recommend licens					
										are commented on
		_			e: This inspection do					breaker adequacy
√			J			its - Connecti	on Devices	and Fixtures		
					Comments: ligh			THE STATE OF THE S		
					low and loose fr Plugs:	om cening		7		
					□ Damaged:				C George I Stall	
					☐ Inoperable:		3. 4		MB102H	美美 雪松
					☐ Open ground:			-1	OPEN SECURE O G G OPEN NOT O G HITTERO, REVENUE O G	
					☑ Incorrect polarity:			E.	CORRECT 0 0 0	
					hall bath - photo)				
										The state of the state of
					☑ Painted over plugs all	- improper:				
					an				1	
					☐ Missing junction bo	x covers			Name of Street	
					3,					10. 2 2
					☐ Exposed /uncapped	d wiring:				
					The following re	ceptacles are	NOT GFCI	protected		
					☑ Kitchen 2 front	plugs		ster Bath Room	☐ Half Ba	ath
					☐ Wet Bar		□ Jac		☐ Crawl :	•
					☐ Garage		□ Hal			ning pool/Spa light
					☐ Exterior			l Bath faulty	☐ Laundı	ry/utility
					☑ Recommend a licer		pect and repair	the entire electric	cal system as	
					Smoke Alarm(s)	□ F	Present		☑ Not present	
					☐ Hard wired system		□ Ir	ndividually installe	d	
					☑ Missing smoke alar					
					☐ Improperly located					
			NI.	ote: 1	☐ Damaged/deficient		otod dovice	e and fiveures	aro commented	on

Note: Only <u>accessible</u> branch circuits, connected devices and fixtures are commented on.

Texas Real Estate Commission memorandum effective January 1, 2009 requires the following: "The

inspector shall report as deficient the absence of, improper installation or improper operation of

Ground Fault Circuit "GFCI" devices in all bathrooms, all exterior, garages, kitchens (all kitchen counter areas) crawl spaces, unfinished basements, or in laundry, utility and wet bar areas. (TREC inspectors can not grandfather GFCI's)

Report Identification: 2750 Holly Hall # 1006

Page 9 of 16 Report Number: 203235A Date: November 18, 2020

Alan Harper T.R.E.C. # 21133

I = Inspected NI = Not Inspected NP = Not Present D = Deficient NI NP D **INSPECTED ITEM** III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS ☐ See Cooling Equipment $\overline{\mathbf{v}}$ **Heating Equipment** Comments: Unit# Unit# ☑ Unit is heating as intended: ☐ Unit is heating as intended: ☐ Gas ☐ Gas ☐ Unit is NOT heating as intended: ☐ Unit is NOT heating as intended: ☑ Electric ☐ Electric Supply Air: 113 Supply Air: Return Air: Return Air: Differential: Differential: Unit# Unit# ☑ N/A ☐ Unit is heating as intended: ☐ Unit is heating as intended: □ Gas ☐ Gas \square Unit is NOT heating as intended: \square Unit is NOT heating as intended: ☐ Electric □ Electric Supply Air: Supply Air: Return Air: Return Air: Differential: Differential: Proper operating differential temperature is between 30 and 40 degrees Fahrenheit Gas Systems: \square Improper gas line in use. (MUST be yellow flex) ☐ Missing drip leg (gas trap):. \square Lack of protection from physical damage: \square Recommend removal of space heater from wall ☐ Recommend a licensed HVAC technician inspect and repair the entire HVAC system as needed. **Electric Systems:** ☐ Deficient operation of heating element: \square Missing emergency shut off switch : ☐ Recommend licensed A/C Heat technician inspect and repair entire A/C heat system as needed

The following applicable components of the heating system are commented on:

Unit performance, thermostat controls/limit controls, burner assembly/compartment, condition of flame, vent pipe clearance and routing, combustion/draft air, and gas supply lines and shut off valves. Heat exchangers are NOT disassembled to inspect internal parts. Testing for carbon monoxides performed but a definitive condition of the heat exchanger can not be determined without disassembly of the unit by a licensed HVAC company. Electrical heat strips are no accessible to evaluate. If an in depth evaluation of the heating system is desired, consult a licensed HVAC company.

See section C (page 10) for information on furnace vent(s)

Report Identification: 2750 Holly Hall # 1006 Page 10 of 16

Report Number: 203235A Date: November 18, 2020

Alan Harper T.R.E.C. # 21133

I = Inspected NI = Not Inspected NP = Not Present D = Deficient NP **INSPECTED ITEM** В. **Cooling Equipment** ☐ See Heating Equipment **V** Central Air Conditioning Unit(s): Approximate ambient temperature: Comments: Unit # AMPS 30 Unit # **AMPS** ☑ Unit is cooling as intended: ☑ N/A ☐ Unit is cooling as intended: ☐ Unit is NOT cooling as intended: ☐ Unit is NOT cooling as intended: Return Air: Return Air: 71 **Supply Air: Supply Air:** Differential: Differential: Proper operating differential range is between 15 and 20 degrees Fahrenheit ☑ Dirty condensing coils: photo ☑ Recommend licensed A/C Heat technician inspect and repair entire A/C heat system as needed If the filter is missing, the evaporator should be cleaned. Air conditioning systems are not tested if the ambient temperature is less than 60 degrees Fahrenheit. Evaporator casings, plenums, and transitions are not disassembled and tape is not removed. Inaccessible components are not inspected. \Box 1 C. **Ducts, Chases, and Vents** Comments: not accessible **Ducts:** ☐ Damaged A/C ducts or insulation ☐ A/C duct is not secured to the plenum ☐ Improper routing of ducts ☐ Improper duct material in use ☐ Improper or inadequate clearance from the ground ☐ A/C ducting is not suspended in attic Chases: ☐ Gas pipes, electrical wiring, junction boxes, or sewer vents in chase - Improper Vents: ☐ Reseal around all vents at roof level ☐ Re-Seal around dryer vent pipe at roof level ☐ Improper vent pipe on gas water heater: ☐ Re-seal around water heater vent pipe at roof level ☐ Improper vent pipe on gas furnace: ☐ Reseal around kitchen vent pipe at roof level ☐ Improper vent cap on gas water heater: ☐ Reseal around bath room vent pipe(s) at roof level ☐ Improper vent cap on gas furnace ☐ Re-seal around furnace vent pipe at roof level ☐ Missing filters: ☐ Improper return air location: ☐ Deficient air register ☐ Inadequate air flow at supply register(s) ☐ Missing/damaged grills: ☑ Recommend licensed A/C Heat technician inspect and repair entire A/C heat system as needed

Report Identification: 2750 Holly Hall # 1006 Page 11 of 16

Report Number: 203235A Date: November 18, 2020

Alan Harper T.R.E.C. # 21133

I = Inspected NI = Not Inspected NP = Not Present D = Deficient NI NP **INSPECTED ITEM** IV. PLUMBING SYSTEM $\overline{}$ Water Supply System And Fixtures Static water pressure reading: 58 psi. Must be between 40-80 psi. Water meter location: ☐ Front □ Back ☐ Left side ☐ Right side ☑ N/A Main shut off location: ☐ Front ☐ Back ☐ Left side ☐ Right side ☑ N/A ☐ PVC ☐ Galvanized ☐ PEX Hoses Water pipe material: ☐ Copper ☐ Front □ Back ☐ Left side ☐ Right side ☑ N/A Gas meter location: \square Water pressure is low when more than 1 faucet is in use at a a time. ☐ Recommend licensed plumber inspect and repair entire plumbing system as needed. Kitchen: a. 1 Comments: faucet: ☐ Stem packing leaks: supply pipes/valves: ☐ Missing/leaking shut off valve(s): spray attachments: \square Does not operate properly: ☐ Recommend licensed plumber inspect and repair entire plumbing system as needed. П 7 b. Wet Bar: Comments: faucet: ☐ Stem packing leaks: Laundry Connections / Sink(s): Drain lines are not physically tested C. П Comments: ☐ Hot/cold faucets are not marked d. **Master Bath** П ✓ Comments: Lavatory(s): faucet: ☐ Stem packing leaks: ☐ Hot/cold faucets are not marked supply pipes/valves: \square Missing waste stop: ☐ Broken waste stop: sink(s): \Box Damaged/cracked sink: ☐ Unit is loose from wall - improperly Tub/Shower(s): faucet: ☐ Stem packing leaks ☐ Hot/cold faucets are not marked supply pipes/valves: ☐ Missing tub drain plug: ☐ Broken tub drain plug enclosure(s): ☐ Open joints indicated / re-caulk or re-grout: □ Damaged tub ☐ Shower diverter does not work properly Commodes: supply pipes/valves: \square Shut off valve leaks: bowl / tank: ☐ Tank is loose from Commode Base: anchorage: \Box Commode Base is not secured to floor: ☐ Toilet runs ☐ Recommend licensed plumber inspect and repair entire plumbing system as needed. Hall Bath Comments: shower faucet handle is extermly loose Lavatory(s): faucet: ☐ Stem packing leaks: ☐ Hot/cold faucets are not marked supply pipes/valves: $\hfill\square$ Missing waste stop: ☐ Broken waste stop: sink(s): □ Damaged/cracked sink: ☐ Unit is loose from wall - improperly Tub/Shower(s): faucet: ☐ Stem packing leaks ☐ Hot/cold faucets are not marked supply pipes/valves: ☐ Missing tub drain plug: ☐ Broken tub drain plug enclosure(s): ☐ Open joints indicated / re-caulk or re-grout: □ Damaged tub Shower diverter does not work properly Commodes: supply pipes/valves: \square Shut off valve leaks: bowl / tank: <a>Image: Tank is loose from Commode Base: anchorage: ☐ Commode Base is not secured to floor: Other: ☐ Toilet runs Recommend licensed plumber inspect and repair entire plumbing system as needed.

Report Identification: 2750 Holly Hall # 1006 Page 12 of 16

Report Number: 203235A Date: November 18, 2020

Alan Harper T.R.E.C. # 21133

I = Inspected NI = Not Inspected NP = Not Present D = Deficient
I NI NP D INSPECTED ITEM

	 	 	IV. PLUMBING	SYSTEM (Cont'd)	
				ly System And Fixtures	(Cont'd)
	✓		e. Hall Bath	., .,	(00000)
			Comments:		
			Lavatory(s):		
				☐ Stem packing leaks:	☐ Hot/cold faucets are not marked
			supply pipes/valves:		☐ Broken waste stop:
				☐ Damaged/cracked sink:	☐ Unit is loose from wall - improperly
			Tub/Shower(s):		
			, ,	☐ Stem packing leaks	☐ Hot/cold faucets are not marked
			supply pipes/valves:	\square Missing tub drain plug:	☐ Broken tub drain plug
				$\hfill\square$ Open joints indicated / re-ca	aulk or re-grout:
			, ,	☐ Damaged tub	$\hfill\Box$ Shower diverter is not operating properly
			Commodes:		
			supply pipes/valves:	\square Shut off valve leaks:	
				\square Tank is loose from Commod	
			anchorage:	\square Commode Base is not secur	red to floor:
			Other:	☐ Toilet runs	
				nsed plumber inspect and repai	ir entire plumbing system as needed.
	√		f. Hall Bath		
			Comments:		
			Lavatory(s):		
				☐ Stem packing leaks:	☐ Hot/cold faucets are not marked
			supply pipes/valves:		☐ Broken waste stop:
				\square Damaged/cracked sink:	\square Unit is loose from wall - improperly
			Tub/Shower(s):		
				☐ Stem packing leaks	☐ Hot/cold faucets are not marked
				☐ Missing tub drain plug:	☐ Broken tub drain plug
				☐ Open joints indicated / re-ca	
				□ Damaged tub	☐ Shower diverter is not operating properly
			Commodes:		
			supply pipes/valves:		de Passe
				☐ Tank is loose from Commod	
			_	☐ Commode Base is not secur	red to floor:
			Other:	☐ Toilet runs	
П	V	П	a Half Bath	nsed plumber inspect and repair	ir entire plumbing system as needed.
ш	ŭ		g. Half Bath		
			Comments:		
			Lavatory(s):	☐ Stem packing leaks:	☐ Hot/cold faucets are not marked
			supply pipes/valves:		☐ Broken waste stop:
				☐ Damaged/cracked sink:	☐ Unit is loose from wall - improperly
			Commodes:	in Damagea/cracked Sink.	- Chicle loose from Wall Improperty
			supply pipes/valves:	☐ Shut off valve leaks:	
				☐ Tank is loose from Commod	de Base:
				☐ Commode Base is not secur	
			Other:	☐ Toilet runs	
					ir entire plumbing system as needed.
			- Accommend lice	noca pianiboi inspect ana repa	ii chare plumbing system as necucu.

Report Identification: 2750 Holly Hall # 1006 Page 13 of 16

Report Number: 203235A Date: November 18, 2020

Alan Harper T.R.E.C. # 21133

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

	1	NI .	NP	D	INSPECTED ITEM
				IV	. PLUMBING SYSTEM (Cont'd)
					Water Supply System And Fixtures (Cont'd)
✓				h.	Other
					Comments:
				Wate	er supply line (s): 🗆 Water leaks indicated:
				0	utside faucet (s): Missing handles:
					☐ Faucet Drips:
					\square Recommend licensed plumber inspect and repair entire plumbing system as needed.
✓			✓	B.	
					Comments:
					Kitchen: Hall Bath:
				La	nundry Room: Drain lines are not physically tested Hall Bath:
				Lc	Master Bath: Half Bath:
					Hall Bath: tub drains extermly slow Wet Bar:
					☑ Recommend licensed plumber inspect and repair entire plumbing system as needed.
		v		C.	
	ш	Ľ		0.	Energy Source: ☐ Gas ☐ Electric Number of units
					Location: ☐ Attic ☐ Garage ☐ Laundry room ☐ Other
					Type: ☐ Tankless ☐ Standard Gallon Tank
					Comments:
					\square Lack of protection from physical damage to unit located in a garage: \square T&P drain line is improperly sized
					\square Electric or Gas Water heater should be raised 18" off of garage \square Drain pan drain line is missing
					☐ Corrosion noted on pipe connections; ☐ Corroded T&P valve
					☐ Temperature & Pressure valve does not turn - inoperable: ☐ Obstructed T&P valve
					☐ Temperature & Pressure valve drain lines runs uphill: ☐ Damaged T&P valve
					☐ Temperature & Pressure valve drain line is missing - Improper: ☐ Leaking T&P valve
					☐ Temperature & Pressure valve drain line should terminate to ☐ Broken or missing parts or controls
					□ Power wire- Romex type wiring should be in conduit □ Damaged drain pan
					☐ Rusted tank case ☐ Missing drain pan
					□ CO/Gas leak detected (TIF 8800) □ Unsafe location
					☐ Improper flexible gas line in use (should be yellow flex) ☐ Inappropriate location ☐ Missing gas shut off value. ☐ Inadequate access and clearances
					 ☐ Missing gas shut off valve: ☐ Gas line is missing drip leg (to catch moisture & sediment) ☐ Inadequate access and clearances ☐ Improper drain line material
					 ☐ Gas line is missing drip leg (to catch moisture & sediment) ☐ Improper drain line material ☐ Lack of a burner shield ☐ Inadequate/improper flame
					☐ Cold water supply valve handle is broken
					☐ Recommend licensed plumber inspect and repair entire water heating system as needed:
					See section C (page 10) for information on water heater vent system
					Water temperature should be max. temperature of 130 degrees
					Temperature and Pressure relief (T&P) valves may or may NOT be tested due to the possibility
					the the valve may not re-seat (causing a water leak). The valve should be tested by the
					home owner annually.
		7		D.	Hydro - Therapy Equipment
					Comments:
					☐ Unit does not operate ☐ Recaulk or regrout around unit
					☐ Vacuum switch does not operate ☐ Access panel is not accessible
					☐ Ports and /or valves do not work properly ☐ Faucet Drips:
					☐ Warning: THIS UNIT IS NOT GFCI PROTECTED. ☐ Inaccessible pump/motor

Report Identification: 2750 Holly Hall # 1006

Page 14 of 16 Report Number: 203235A Date: November 18, 2020

Alan Harper T.R.E.C. # 21133

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

	1	NI	NP D		INSPECTED ITEM	
				۷.	. APPLIANCES	
V			 ✓	a.	Dishwasher	
					Comments:	
					☑ Deficient control panel:	
					photo	Orhora
					☐ Rusted dish racks:	High Heated Staff
					☑ Damaged door springs:	
					☐ Visible leaks indicated:	
_	_	_	_	L	Food Wests Disposal	
V				b.	Food Waste Disposal Comments:	
					☐ Unit is inoperable: ☐ Unusual vibrations or noises:	
					☐ Romex wiring should be in conduit: ☐ Deficient grinding component:	
					☐ Visible leaks indicated: ☐ Damaged exterior casing:	
					☐ Damaged rubber splash guard: ☐ Unit is not properly secured:	
v			V	C.	Range Exhaust Vent	
					Comments: vent terminates into bottom side of cabinet - improper	
					\Box Unit is inoperable: \Box Blower does not operate on all s	speeds::
					☐ Vent pipe does not terminate outside: ☐ Missing/damaged filter:	
					☐ Inadequate vent pipe material: ☐ Unit is not properly secured:	
					☐ Unusual sounds or vibrations: ☐ Deficient switches:	
					☐ Improper/damaged/missing vent pipe: ☐ Light is out:	was a ti a a
_	_	_	_	ч	See section C (page 10) Ducts, Chases, and Vents for more vent info	rmation
V				d.	Range / Cook tops Comments:	
					Range Type:	
					☐ Element on range does not operate properly:	
					\square Indicator lights are inoperable or damaged:	
					☐ Unit is inoperable:	
					☐ Missing Anti-Tip Device	
					☐ Missing gas shut off valve:	
					☐ Control panel/knobs are damaged: Ovens	
					Oven type: ☐ Electric ☐ Gas	
					☐ Door does not open/close properly	
					☐ Light is out	
					☐ Improper flexible gas line in use (should be yellow flex)	
					OVEN TEMPERATURE (see below - unit should be within +/- 25 degrees to be	e operable)
					All units are tested on bake setting at 350 degrees.	
					Single unit 338 degrees Broiler O.K. ☑ Yes □	l No
						l No
					Lower Unit degrees Broiler O.K. Yes] No
					If temperature variance is not within 25 degrees, calibration is recommendation	
V			✓	e.	Microwave Cooking Equipment	
					(Built -in only. Counter top units are NOT tested.)	
					Comments: microwave is extremely low	
					☐ Unit is inoperable: ☐ Handle is broken: ☐ Turn table o	
					-	maged lights /lenses;
_	_	_	_	£	·	properly secured:
		V		f.	Trash Compactor Comments:	
					☐ Unit is inoperable: ☐ Unusual sounds or vibrations:	

Report Identification: 2750 Holly Hall # 1006 Page 15 of 16

Report Number: 203235A Date: November 18, 2020

Alan Harper T.R.E.C. # 21133

I = Inspected NI = Not Inspected NP = Not Present D = Deficient

I	ľ	ΝI	NP D		INSPE	CTED ITE	M	
				٧.	APPLIANCES (cont'd)			
1				g.	Bathroom Exhaust Fans and / or	Heaters		
					Comments:			
					☐ Unit is inoperable			☐ Heat lamp
					\square Exhaust fan vent should terminate to at	mosphere (Not At	tic Area):	☐ Unit is noisy:
					☐ Unit is loose at ceiling or wall:			☐ Missing cover(s):
					\square Individual components do not work: Ve	nt / Light / Heat L	amp	☐ Remove wall unit:
		~		h.	Garage Door Operators			
					Comments:			
					☐ Unit does Not reverse - Recommend Ad			
						Tested □ No	ot Tested	
					☐ Unit is inoperable:			
		√		i	Door Bell and Chimes			
					Comments:			
					☐ Unit does Not operate:			
					☐ Missing cover:			
4				j.	Dryer Vent			
					Comments:			
					☐ Damaged louver cover:		-	vent pipe material:
					☐ Missing louver cover:			outing length of vent pipe
				١/١	☐ Dryer exhaust line should terminate to a	itmospnere:	☐ Damaged Io	uver cover:
				VI	OPTIONAL SYSTEMS			
					An additional fee is charged for the	inspection o		-
		V		A.	Lawn Sprinkler System		Number of	Stations:
					Comments: Home Owner Associati	on's- respons		•
					☐ Surface water leak detected:		_	or freeze sensor:
					☐ Missing shut off valves::			in control panel::
				_	☐ Damaged sprinkler heads	4 Hama O	☐ Unit is inope	
		V		В	Swimming Pools and Equipmen			on's- responsibility
		_	_	_	Comments: If checked - Refer to se	parate POOL REP	ORT (attached):	
		√		C.	Outbuildings	ania raanan	oibility	
					Comments: Home Owner Association ☐ Roof leaks:	_		l•
							ot GFCI protected	
					☐ Compromised structure: Comments:	☐ Heat /cool c	loes not work (if	applicable)
П		V		D.	Outdoor Cooking Equipment			
	ш	Ľ	Ш	٥.	Energy Source:	l gas:	☐ Propane	e: 🗆 Other:
					Comments:	. 900.		
					☐ Unit is inoperable:	☐ Damaged co	ontrols:	
					☐ Pedestal is not secured/damaged:	☐ Unit is ruste		
					Additional Comments			

Attached is a "Liability Limitation Agreement". Please read carefully. Acceptance and reliance upon this inspection report is contingent upon acceptance and understanding of this liability agreement.

Important Inspection and Liability Limitation Agreement

Agreement

We are a general real estate inspection company. We are licensed and regulated by the Texas Real Estate Commission. Our inspection and inspection forms are designed to adhere to guidelines in the 'Rules of the Texas Real Estate Commission' for home inspectors effective January 1,2018 and all subsequent amendments. {This Report complies with the January 1, 2009 requirements from the T.R.E.C.}

(1) What We Do:

We perform a visual inspection of accessible areas and items and report to you the general conditions of inspected areas and/or items. Our inspection is limited to items specifically listed in this report only. We inspect and report to you if an item is performing the function for which it was designed or is deficient. We will explain our report to you or your designated agent. We perform our inspection in a professional and workmanlike manner. Our report of the inspection and its contents are based solely on the condition and appearance existing at the time of inspection. We do not address or comment on the condition or functional abilities of any item past the date and time of inspection. If we report that an item is not functioning or is deficient and is in need of replacement, we urge you to have the item examined by a specialist prior to making the final purchase of the property. We also advise you to re-check the functional ability of systems to insure no defects have occurred after the date of our inspection and prior to closing. If a structure has been unoccupied for an extended period of time, it is not uncommon for defects to occur, particularly in plumbing joints or HVAC systems.

We are not liable for damage or defects which may have been cosmetically masked or altered or are not completely visual and apparent under normal conditions. Weather conditions may affect the Inspector's ability to detect defects. Example: Minor areas of moisture penetration may not be visible at different times of the day or with low levels of humidity.

The information contained in this report is the sole possession of the buyer.

(2) What We Do Not Do:

We do not offer guarantees, warranties or insure the future performance or condition of any item, whether inspected or not. If you desire a guarantee, warranty, insurance policy or certification you must obtain such products and information from a company in that business endeavor. We do not inspect any item we cannot see in a normal manner of inspection.

We do not move furniture, rugs, carpet, paintings or any other furnishings or stored items in the course of our inspection.

We do not enter areas with less than proper clearance space needed, or areas, which in the opinion of the Inspector, is unsafe

We do not walk on wood shake, wood shingle, tile or any roof areas we may damage or any roof area which the Inspector considers unsafe to walk. These areas will be viewed either from the attic or ground or both, whichever is applicable.

We do not dismantle any item or system to check component parts, including gas fired heat exchangers.

We do not inspect for building codes, soil analysis, design adequacy, capacity, efficiency, sizing, value, flood plain location, pollution, environmental hazards or habitability.

We do not inspect for termites or any other insect infestation. We do not inspect security systems.

We do not inspect for, nor comment on, cosmetic damage.

We do not operate equipment or systems outside the parameters of manufacturers recommendations.

We do not re-inspect repair work (all repairs are to be done by licensed professional repair tradesman)

(3) What You Do:

You agree not to allow any third party not associated with the negotiations and consummation of the sale of the inspected property to have access to or rely on information contained in this report. You agree to notify the Inspector within sixty days from the date of this inspection of any items disputed in this report and to allow a re-inspection of the disputed item prior to any repairs. You agree to limit any liabilities incurred by us and/or our associates which pertain to this inspection to the amount of the fee paid for this inspection and release our company and its associates from any further liability. You are to put into writing to our company any disputes. Communications must be consistent in that the party originally accompanying the inspector will be the party resolving the problem.

DISPUTE RESOLUTION: In the event of a dispute between the parties relating to this agreement, the parties or their representatives will meet promptly in an effort to resolve the dispute amicably. Upon the request of any party to this agreement, all unresolved disputes (not limited to breech of contract action), shall be submitted for binding arbitration in accordance with the Better Business Bureau Rules of Arbitration then in effect, and then neither party shall have a right to bring a suit in court. You agree to pay any and all fees incurred by all parties concerned. Any and all litigation, arbitration, or third party dispute resolution of any kind must take place in Galveston county, Texas.

You agree any payment made for inspection services that are subsequently dishonored will result in an additional \$100.00 fee.

RE-INSPECTION FEE \$100.00. (To come back and finish job / due to utilities not on or outside temperature too low for A/C.)

You attest that the inspector performing this inspection has made no oral representation that differ from the contents of this agreement.

You agree to the provisions and limitations of this contract and report by your reliance upon it whether you sign it or not.

You agree to pay a \$75.00 (seventy five dollars) billing fee for inspections not paid for at the time/day of inspection.

These inspections are visual only and structure and equipment is determined operable (unless otherwise indicated) at the time of inspection only. **Any** use of this report constitutes acceptance of the above listed terms and conditions.

No warrantees or guarantees are offered for inspected components.

I HAVE READ THIS AGREEMENT AND I UNDERSTAND AND ACCEPT THESE CONDITIONS:

Address: 2/50 Holly Hall # 1006	Report #	U	Date: November 18, 2020	
Client's Signature			Real Estate Inspector // Professiona	al Inspector