

HOUSTON INSPECTIONS

Houston Home Inspections, PLLC d/b/a Houston Inspections
713.408.1129 Office
www.houstoninspect.com



INSPECTED FOR

**Campbell Roper
4713 Lido Ln
Houston, TX 77092**

March 12, 2021

PROPERTY INSPECTION REPORT

Prepared For: Campbell Roper
(Name of Client)

Concerning: 4713 Lido Ln, Houston, TX 77092
(Address or Other Identification of Inspected Property)

By: Michael Bell, Lic #23723 03/12/2021
(Name and License Number of Inspector) (Date)

Shawn Emerick Lic #4623 
(Name, License Number of Sponsoring Inspector)

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments,

lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods. Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathroom, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as, smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms requires a seller to remedy conditions revealed by an inspection. The

decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

**ADDITIONAL INFORMATION PROVIDED BY INSPECTOR
GENERAL INFORMATION**

Present at Inspection: Buyer, Buyers Agent, Unground Plumbing Inspector

Building Status: Occupied

Weather Conditions: Dry, Cloudy

Ambient Temperature At Time of Inspection: 70 to 80

Wind Conditions (Approximate Speed): 5 - 12 MPH

How To Interpret This Report:

Building Codes, TREC Standards, Installation Standards or Safety Issues= Blue Text

Items that do not comply with current building codes, TREC Standards, other standards (manufacturer, trade associations, etc.), or that are safety issues.

Items Damaged, Non-Functional, or Operating Improperly= Red Text

Items in need of repairs either because they are broken, not functioning, or damaged.

General Comments & Specific Limitations= Black Text

These are general information, limitations, or notices.

NOTICE

The Client, by accepting this Property Inspection Report or relying upon it in any way, expressly agrees to the SCOPE OF INSPECTION, GENERAL & SPECIFIC LIMITATIONS, and the INSPECTION AGREEMENT included in this inspection report. This report is not valid without the signed inspection agreement, and the report is not transferable.

This inspection report is made for the sole purpose of assisting the purchaser to determine his and/or her own opinion of feasibility of purchasing the inspected property and does not warrant or guarantee all defects to be found. If you have any questions or are unclear regarding our findings, please call our office prior to the expiration of any time limitations such as option periods. The Client is advised of the following:

- When recommendations have been made for repairs and/or service, we recommend that you contact a qualified tradesman prior to closing so actual costs involved can be anticipated.
- Future performance and/or life expectancy of items listed in this report is beyond the scope of this inspection and cannot be predicated.
- All repairs, alterations and recommended work within this report should be done by a licensed (where necessary) and qualified tradesperson in accordance with state and local codes.
- If an error message is received when downloading this report or the boxes with check marks on the left side of each section is not shown when this report is printed please contact our office so that a hard copy can be sent to the client.
- When the word damage is used in this report, it can be referring to the following: wood rot, decay, moisture damage, etc.
- The digital pictures in this report are a sample of the damages in place and should not be considered to show all of the damages and/or deficiencies found. There will be some damage and/or deficiencies not represented with digital imaging.

- Check marks in boxes adjacent to comments indicate the condition or item is present at this property.
- This report contains technical information. If you were not present during this inspection, please call the office to arrange for a consultation with your inspector. If you choose not to consult with the inspector, this inspection company cannot be held liable for your understanding or misunderstanding of the reports content.
- No environmental inspection of any kind were performed during this inspection. Even if comments are made regarding certain aspects or issues, inspections and / or any determination of the presence or possible dangers of materials organisms or microbial organisms including, but not limited o Chinese drywall, asbestos, lead, formaldehyde, mildew, mold, fungi, etc. are specifically excluded from the inspection and from this report. **No indoor air quality test were performed. If deficiencies are found during inspection, i.e. water penetrations, evidence of previous water penetrations, discolorations, staining, microbial growth, etc. or you have concerns about the presence of microbial growths, you should, as part of your due diligence, have environmental inspections of your choice, i.e. mold inspection, lead testing, etc. performed on this property prior to closing.**
- Underground items (such as utilities), gas lines, fuel quality, environmental items (such as fuel tanks), telephone systems, televisions and / or satellite systems, elevators, bulkheads / docks and piers, fences / yard enclosures, intercoms, sound systems, security, and playground equipment are specifically excluded from this report.
- The client should understand that we do not inspect the fencing if present, i.e. wood fences, iron fencing, gates, etc.. We have not formal training on fencing and this is beyond the scope of this inspection.
- This is not a pest inspection. We are not licensed to inspect for insect infestations, rodent activity, or animal infestations. If this is a concern a pest control company should be contacted to further evaluate this property. The wood destroying insect report does not address nuisance insect, rodents or other animals.

ADDITIONAL NOTES SPECIFIC TO THIS PROPERTY

An infrared camera was used during the inspection of the property specified above. This is a high tech camera that sees what the human eye does not and is a very useful tool used by your inspector. Most tradesmen / contractors are not familiar and / or not qualified to understand the capabilities of the infrared camera or its findings. Therefore, the client is urged to retain a tradesman that can properly evaluate the problems found, determine the needed repairs, and correct the problems found.

Optional items not listed on this report including but not limited to built-in refrigerators, wine coolers, gate operators, instant water heaters below individual sinks, water softeners and filters, elevators, fire sprinkler systems, etc. are beyond the scope of this inspection and are not inspected. If the property being inspected has components installed or that are a part of the transaction (washers, dryers, audio equipment, etc.) the client should contact a third party to perform an inspection to determine if these components are functioning properly. Furthermore, all excluded items may not be listed above and if you have any questions about whether certain components are within the scope of the inspection the client should contact the inspector for clarification.



The inspection of this property was limited due to the fact that it is currently occupied. The inspection of doors, windows, floors, walls, electrical components (receptacles & switches), and some plumbing fixtures was restricted due to stored items and furniture.

Due to the age of the property being inspected, there will be a larger than normal amount of deficiencies found in regards to current building standards and codes. Many of these codes and standards were not in existence when this property was built. Items such as safety glass, ground fault protection, smoke detectors, and other safety components were not in existence when this property was built. While these newer safety standards are important, the buyer should understand that many of these problems will be found in other properties of this age, unless updating has occurred.

Insect activity was noted around the property (fire ants, yellow jackets, etc.). Recommend treating for insects.

The property inspected has one or more gas-fired appliances installed on the interior of the property (water heater or furnaces in closets, laundry rooms, etc). During the inspection, I did not notice a carbon monoxide detector installed. The U.S. Consumer Product Safety Commission (CPSC) recommends that consumers purchase and install carbon monoxide detectors with labels showing they meet the requirements of the new Underwriters Laboratories, Inc. (UL) voluntary standard (UL 2034). The UL standard, published in April 1992, requires detectors to sound an alarm when exposure to carbon monoxide reaches potentially hazardous levels over a period of time. Detectors that meet the requirements of UL 2034 provide a greater safety margin than previously-manufactured detectors.

About 200 people die each year from carbon monoxide poisoning associated with home fuel-burning heating equipment. Carbon monoxide is a colorless, odorless gas that is produced when any fuel is incompletely burned. Symptoms of carbon monoxide poisoning are similar to flu-like illnesses and include dizziness, fatigue, headaches, nausea, and irregular breathing. Carbon monoxide can leak from faulty furnaces or fuel-fired heaters or can be trapped inside by a blocked chimney or flue. Burning charcoal inside the house or running an automobile engine in an attached garage also will produce carbon monoxide in the home.

The first line of defense against carbon monoxide is to make sure that all fuel-burning appliances operate properly. Consumers should have their home heating systems (including chimneys and flues) inspected each year for proper operations and leakage. Inspectors should check all heating appliances and their electrical and mechanical components, thermostat controls, and automatic safety devices.

Properly working carbon monoxide detectors can provide an early warning to consumers before the deadly gas builds up to a dangerous level. Exposure to a low concentration over several hours can be as dangerous as exposure to high carbon monoxide levels for a few minutes - the new detectors will detect both conditions. Most of the devices cost under \$100. Each home should have at least one carbon monoxide detector in the area outside individual bedrooms. CPSC believes that carbon monoxide detectors are as important to home safety as smoke detectors are.

GENERAL LIMITATIONS

The inspector is not required to:

(A) inspect:

- (i) items other than those listed herein;
- (ii) elevators;
- (iii) detached buildings, decks, docks, **fences**, or waterfront structures or equipment;
- (iv) anything buried, hidden, latent, or concealed;
- (v) sub-surface drainage systems; or
- (vi) automated or programmable control systems, automatic shut-off, photoelectric sensors, timers, clocks, metering devices, signal lights, lightning arrestor system, remote controls, security or data distribution systems, or solar panels;
- (vii) concrete flatwork such as; driveways, sidewalls, walkways, paving stones or patios

(B) report:

- (i) past repairs that appear to be effective and workmanlike except as specifically required by these standards;
- (ii) cosmetic or aesthetic conditions; or
- (iii) wear and tear from ordinary use;

- (C) determine:
 - (i) insurability, warrantability, suitability, adequacy, compatibility, capacity, reliability, marketability, operating costs, recalls, counterfeit products, product lawsuits, life expectancy, age, energy efficiency, vapor barriers, thermostatic performance, compliance with any code, listing, testing or protocol authority, utility sources, or manufacturer or regulatory requirements except as specifically required by these standards;
 - (ii) the presence or absence of pests, termites, or other wood-destroying insects or organisms;
 - (iii) the presence, absence, or risk of asbestos, lead-based paint, mold, mildew, corrosive gypsum board "Chinese Drywall" or any other environmental hazard, environmental pathogen, carcinogen, toxin, mycotoxin, pollutant, fungal presence or activity, or poison;
 - (iv) types of wood or preservative treatment and fastener compatibility; or
 - (v) the cause or source of a conditions;
- (D) anticipate future events or conditions, including but not limited to:
 - (i) decay, deterioration, or damage that may occur after the inspection;
 - (ii) deficiencies from abuse, misuse or lack of use;
 - (iii) changes in performance of any part, component, or system due to changes in use or occupancy;
 - (iv) the consequences of the inspection or its effects on current or future buyers and sellers;
 - (v) common accidents, personal injury, or death;
 - (vi) the presence of water penetrations; or
 - (vii) future performance of any item;
- (E) operate shut-off, safety, stop, pressure or pressure-regulating valves or items requiring the use of codes, keys, combinations, or similar devices;
- (F) designate conditions as safe;
- (G) recommend or provide engineering, architectural, appraisal, mitigation, physical surveying, realty, or other specialist services;
- (H) review historical records, installation instructions, repair plans, cost estimates, disclosure documents, or other reports;
- (I) verify sizing, efficiency, or adequacy of the ground surface drainage system;
- (J) verify sizing, efficiency, or adequacy of the gutter and downspout system;
- (H) operate recirculation or sump pumps;
- (L) remedy conditions preventing inspection of any item;
- (M) apply open flame or light a pilot to operate any appliance;
- (N) turn on decommissioned equipment, systems or utility services; or
- (O) provide repair cost estimates, recommendations, or re-inspection services.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

I. STRUCTURAL SYSTEMS

A. Foundations

Comments:

Type of Foundation(s): Slab on Grade Concrete

Foundation Performance Opinion(s):

At the time of the inspection, evidence was found that indicated that the foundation may not be performing its intended function. It is recommended that further inspection be made by a Registered Professional Engineer to determine if there has been a loss of structural integrity and if repairs are needed.

Note: The foundation performance opinion stated above neither in any way addresses future foundation movement or settlement, nor does it certify the floors to be level. Weather conditions, drainage, leakage, and other adverse factors are able to affect structures, and differential movements are likely to occur due to the expansive nature of the soils in the Houston and surrounding areas. The inspector's opinion is based on visual observations of accessible and unobstructed areas of the structure at the time of the inspection. In most cases, floor coverings and/or stored articles prevent recognition of signs of settlement - cracking in all but the most severe cases. It is important to note that specialized testing done of any sub-slab plumbing systems was not performed during this limited visual inspection, as these are specialized processes. Future performance of the structure cannot be predicted or warranted. Should you have present or future concerns regarding the foundation's condition, you are strongly advised to consult with a licensed Professional Engineer for further evaluation.

SUGGESTED FOUNDATION MAINTENANCE & CARE - Due to the expansive nature of the soil in the Houston area, a frequent foundation-watering program is recommended. Consistent watering at the entire perimeter of the slab can help prevent further and/or future settlement and damage. Drainage must be directed away from all sides of the foundation with grade slopes.

Signs of Structural Movement or Settling:

- Wall, floor, or ceiling cracks
- Doors out of adjustment, i.e. sticking, not latching, etc. as evident of settlement.
- Cracked Window Glass



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Shrinkage cracks were observed at various visible locations on the foundation / concrete floors. Cracking is a normal property of concrete as it dries and shrinks during the curing process. Additional shrinkage cracks may be present under the floor coverings in the structure.



Note: The signs of structural movement or settling noted above can be indicative of repairs needed or normal settlement in relation to the foundation. The performance opinion and the additional repairs sections of the foundation comments should be consulted to determine what repairs are needed.

Items Damaged, Non-Functional, or Operating Improperly

A small portion of the rear corner of the foundation has separated.



Exposed steel reinforcing bars (rebar) was noted in the garage. Recommend repairs to prevent ongoing corrosion and deterioration of the steel.



I=Inspected

NI=Not Inspected


NP=Not Present

D=Deficient

I NI NP D

General Comments

The below graph reflects measurements taken during the inspection to assist with determining the performance of the foundation. The outline / drawing is not to scale and does not accurately reflect every detail of the foundation walls.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

B. Grading and Drainage

Comments:

[Building Codes, TREC Standards, Installation Standards or Safety Issues](#)

Grading does not slope away from the structure(s) as required (6" in first 10').

Splash blocks not installed at the base of gutter downspouts

General Comments

During heavy rains, the accumulation of unforeseen water on this lot may occur. The client is advised to keep soil levels 4"-8" from the top of the slab and graded away to promote positive drainage and prevent water from ponding around the foundation. High soil levels are a conducive condition to wood-destroying insects. The installation of gutters and other mechanisms of collecting rain water from the roof runoff and discharging it away from the structure should be considered.

Specific Limitations

Yard drains, patio drains, and other underground drainage systems are beyond the scope of the inspection and were not inspected.

C. Roof Covering Materials

Comments:

Type of Roof: Combination

Roof Covering Material(s):Composition Shingles

Viewed From:Ground, Accessible Attic Areas, Walked on Roof

Performance Opinion

The roof covering is in need of repairs. Problems found during the inspection of the roof covering are listed in the section(s) below. It is recommended that a qualified tradesman be consulted to evaluate the roof covering and perform all necessary repairs to insure the roof is watertight.

[Building Codes, TREC Standards, Installation Standards or Safety Issues](#)

Slope of roof is improper for type of shingles installed. The low pitch roof will be vulnerable for water penetrations.

Kickout or diverter flashing is not installed at the required locations. This creates a possibility of water penetrations if not corrected.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Items Damaged, Non-Functional, or Operating Improperly

Evidence of previous roof leaks were noted during the inspection as evident by staining on the roof decking, repairs at roof penetrations, or other signs. The current owner(s) should be consulted to verify that the leaks have been repaired properly and that no water penetrations exist.



Raised shingles were found at the sections of the roof covering.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Leaves and other debris were found at sections of the roof covering. Due to the trees around the structure, this will require ongoing maintenance. The buildup of leaves will slow the flow of rainwater from the roof, making the roof vulnerable to water penetrations. Recommend removal of the debris on the roof covering.



The debris should be cleaned from the gutters to allow proper drainage of rainwater from the roof covering.



Specific Limitations

Roof inspections are limited to visual observations of accessible surfaces and components. The roof is inspected from the roof level, only if it can be done safely and without damaging the roof. Certain types of damage and / or poor workmanship (e.g., improper fastening, manufacturer defects, etc.) may not be apparent during a visual inspection. As such, the inspector cannot guarantee that the roof will be free of leaks, nor can the inspector determine the remaining service life of the roof covering.

Roof maintenance is an ongoing process and includes keeping the roof free of tree debris, replacing any loose, damaged, or missing shingles, and sealing any gaps at flashing materials. This report does not address future roof leaks. If defects are reported and/or you have concerns about remaining life expectancy, insurability or potential for future problems, we recommend consulting with a qualified roofing specialist.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

D. Roof Structures and Attics

Comments:

Viewed From: Entered Attic, Most Areas Obstructed / Inaccessible for Inspection

Approximate Average Depth of Horizontal Insulation: 0-8"

Accessibility of Attic: Partial

Performance Opinion

The roof structure is performing its intended function (supporting the roof covering) at the time of the inspection. No signs of sagging or broken structural members were observed at the time of the inspection. It should be noted that some of the structural members dimensions do not comply with current building codes, i.e. purlins, ridge braces, etc.

Description of Roof Structure & Framing: Rafter Assembly

Roof Structure

Building Codes, TREC Standards, Installation Standards or Safety Issues

- Missing "H" / plywood clips at roof decking
- Ridge board is not properly sized (Does not support full face of rafters)
- Purlin braces are spaced improperly according to current codes (maximum of 4' apart).
- Purlin braces are improperly sized (required to be the same size as rafter they support).

Items Damaged, Non-Functional, or Operating Improperly

Damaged and / or stained roof decking was found in the attic due to water penetrations (active or previous). Recommend further evaluation and repairs if needed by a qualified tradesman. (See Roof Covering Materials section for pictures)

Attic Access, Ladders, and Service Walks

Building Codes, TREC Standards, Installation Standards or Safety Issues

- Attic door casings not constructed properly (joists at opening should be doubled on all four sides and secured with joist hangers).
- Missing weather-stripping at attic door.
- Missing attic stairway landing - Safety Hazard
- Walkway is not installed properly leading to mechanical systems in attic. - Safety Hazard
The walkway has not been installed properly leading to the mechanical system(s) in the attic. Building codes require a walkway that 24" in width, unobstructed, and a minimum of 1/2" thick to be installed leading to all mechanical systems installed in attics.
- Work platform(s) not installed or not sized properly at mechanical system(s) (3' x 3').

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Items Damaged, Non-Functional, or Operating Improperly

The attic door does not close completely. The door should be adjusted.



Evidence of rodent activity was noted in the attic as evident by nesting materials, holes, etc.



Attic Insulation

Items Damaged, Non-Functional, or Operating Improperly

Missing insulation was found at sections of the ceiling / attic while using a infrared camera and while inspecting the attic.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Attic Ventilation & Screening: Ridge Vents, Soffit

General Comments

An addition to the home is evident in the attic due to the old roof structure still being present in the attic area.



Evidence of previous structural repairs were found in the attic as evident by new lumber at several locations.



Old / out of service mechanical equipment (water heater, heater, a/c, etc) was found in the attic that was not removed when the equipment was replaced in the past.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

Specific Limitations

The inspector will not enter an attic where he reasonably determines that conditions or materials to be unsafe. Insulation covering structural, plumbing, mechanical, or electrical components may preclude inspection of these items. Some areas of the attic are not accessible or visible for inspection due to the size of the crawl space and other obstructions (stored items, structural components, ducts, insulation, etc.).

E. Walls (Interior and Exterior)

Comments:

Exterior Cladding's: Brick Veneer, Cement Board, Wood

Interior Cladding's: Drywall, Tile, Wood

Building Codes, TREC Standards, Installation Standards or Safety Issues

Brick / Masonry Veneer

Vertical expansion joints are missing at the brick veneers (25' Foot Run of Wall).


Cement Board Siding, Trim, Fascia, Etc.

Hardi Installation Problems Found:

- 2" clearance from roof line
- 4" x 4" Kickout Flashing not installed
- 2" clearance from slabs, path, steps to siding

Flashing Details

Kickout / diverter flashing is not installed at the wall & roof Intersections. This creates a opening that could allow moisture to enter the wall cavity and create damage.



General

- Improper clearance of the exterior veneers from flatwork (2").
- Improper clearance of the exterior veneers from the grade (8").
- Improper clearance of the exterior siding from the roof.
- Closet rods are not secured at the wall hangers.
- Missing sealant found at exterior penetrations.
- Backer rod missing at openings / sealant.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Items Damaged, Non-Functional, or Operating Improperly
Exterior Walls

Damaged and / or missing items were found on the exterior of the property. Recommend repairs / replacement of the affected areas. In addition, areas where decay is present should be removed, exposing underlying materials for inspection prior to repair by a qualified tradesman.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

All exterior wall penetrations (electrical panels, electrical disconnects, light fixtures, etc.) and openings (expansion joints, windows, door thresholds, etc.) should be sealed with an approved material to prevent water penetrations into the wall cavities. Properly sealed exterior veneers help provide a barrier against the weather, insects, and enable environmental control of the interior spaces.



Brick / mortar cracks were found on the exterior of the structure as evidence of settlement of the structure.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Interior Walls

Damage wood and other veneers were found in the garage, bathroom tub access, and attic. The damage appears to have been caused by wood-destroying insects. All visible and underlying damage should be removed and repaired. In addition, the wood-destroying insects, if active, should be treated by a licensed pest control company.



Staining and discoloration was found at the windowsills in several rooms.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Evidence of previous water penetrations were found during the inspection at the following locations:

1. garage
2. garage workshop
3. tub access

No signs of active leaks were found during the inspection, i.e. moisture readings were within normal ranges, no abnormalities found with the infrared camera, etc. The current owner of the property should be consulted to determine if they are aware of previous leaks and any repairs that have previously taken place.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Damaged / discolored drywall was found in the front bedroom closet during the inspection. No abnormalities were found at this area with the infrared camera and no elevated moisture readings were observed when inspected with a pinless (non invasive) moisture meter. Recommend further evaluation to determine the needed repairs.



Hardware has not been installed at the kitchen cabinets making them difficult to open.



Missing insulation was found at some of the exterior walls in the front bedroom. This problem was found using an infrared camera.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

General Comments

During the inspection of the walls on the interior of the structure with a infrared camera abnormalities were noted.

Specific Limitations

The inspector cannot determine the condition of wood or structural components hidden within wall cavities. No opinion as to the condition of the wood, structural members, vapor barriers, insulation, or other components in hidden areas is implied or intended by this report. **This report does not address environmental hazards of any kind such as mold, lead based paint, asbestos, etc.** If the client has concerns about these issues, a qualified licensed tradesman should be consulted to perform these inspections. The inspector will not determine the cosmetic condition of paints, stains, or other surface coatings. Stored items, wall coverings, furniture will limit the ability to inspect some of the wall components.

-
-
-
-

F. Ceilings and Floors

Comments:

Items Damaged, Non-Functional, or Operating Improperly
Ceilings

Damaged / discolored drywall was found in the garage during the inspection. No abnormalities were found at this area with the infrared camera and no elevated moisture readings were observed when inspected with a pinless (non invasive) moisture meter. Recommend further evaluation to determine the needed repairs.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Cracking was noted on the interior ceiling of the property as evidence of settlement.



Floors

The wood floors are showing signs of wear and tear (ding's, scratches, etc.).



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Damaged and missing grout was found at the floor tiles in the kitchen and bathroom.



General Comments

Evidence of patching was found at several sections of the ceilings in the home.



The ceiling has been removed in the garage workshop area.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

Specific Limitations

The inspector cannot determine the condition of structural components in hidden ceilings or floor cavities. No opinion as to the condition of the wood, structural members, or other components in hidden areas is implied or intended by this report. Carpet is not pulled back revealing tack strips and other concealed items. Environmental issues related to water penetrations are not addressed in this report. This **report does not address environmental hazards of any kind such as mold, lead based paint, asbestos, etc.** No comments or representation is made on the condition of thin sets, mortars, etc. Hollow spots or voids are not always noticeable or detectable while doing a general inspection. If the clients suspects poor workmanship or other flooring concerns a flooring specialists should be consulted to further evaluate.

-
-
-
-

G. Doors (Interior and Exterior)

Comments:

Building Codes, TREC Standards, Installation Standards or Safety Issues

- Safety glass missing or the labels not legible at the exterior doors.
- Door leading from garage to the Interior of the property does not appear to be a solid core or is not labeled for this Installation.

The door leading from the interior of the garage into the property appears to not be a solid core door. Current codes require this door to be solid wood (minimum of 1 3/8" thick or 20 minute fire rating) for proper fire separation.

- Sill pan not visible at exterior doors. This could lead to moisture penetrations.
- Self-closing device not installed at the garage door leading into dwelling unit.

Items Damaged, Non-Functional, or Operating Improperly

Scratches and other surface imperfections were found at some of the doors.

The finish at some of the door handles and other door hardware is worn.

Loose door handles were found at various doors.

Moisture damage was found at the garage closet door. Recommend replacement of any damage and improvements to correct this problem from reoccurring.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Voids were found at the weather stripping at the garage workshop exterior door. .



Door(s) were found in the following locations that are in need of adjustments (do not latch, stick when closed, etc).:

1. front bedroom
2. rear bedroom
3. rear door

All doors at the property should be adjusted to operate properly.

General Comments

It is recommended all locks on home be changed before moving in. After new locks have been installed, ensure that the jambs at the striker plates are cut deep enough to allow new deadbolt locks to fully engage and lock. Deadbolt locks are not locked unless bolt is fully thrown.

Specific Limitations

If the property is occupied, only accessible doors were operated.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

-
-
-
-

H. Windows

Comments:

Style: Single Pane

Items Damaged, Non-Functional, or Operating Improperly

Cracked glass was found in the formal living room.



Chipped glass was found in the front bedroom.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Loose and disconnected springs were found at the windows. This is a common problem found with this style of window. The problem can lead to the windows being difficult to open and not staying open when operated.



Damaged window screens were found at various windows.

Specific limitations

The inspector does not inspect or comment on the presence or condition of storm windows, awnings, shutters, or other security devices or systems. Failed thermal seals in insulated windows are not always detectable, depending upon atmospheric conditions or if they are particularly dirty or otherwise obstructed. Furniture and stored items being present in an occupied property can restrict the inspection of some windows. Water testing or other invasive test are not performed during our inspection. Window leaks are not always visible or detectable during our limited inspection.

I. Stairways (Interior and Exterior)

Comments:

J. Fireplaces and Chimneys

Comments:

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

-

K. Porches, Balconies, Decks, and Carports

Comments:

Items Damaged, Non-Functional, or Operating Improperly

Cracked, uneven, and damaged patio flatwork was found around the property.



The patio appears to slope toward the structure. Evidence of standing water was found at this area. Flatwork should slope away from the dwelling.



Specific Limitations

The inspection of balconies are limited to the visible components. The underlying flashing and other water proofing that is not visible could not be inspected.

-

L. Other

Comments:

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

II. ELECTRICAL SYSTEMS

A. Service Entrance and Panels


Comments:

Main Panel

Type of Service: Overhead **Main Service Size:** 125

Wire Type: Copper **Service Conductors:** Unable to Identify

Location of Main Electrical Panel: Exterior



Type of Visible Grounding / Bonding: Ground Rod Connection/Water Pipe Connection

Sub Panel

Type of Service: Overhead **Main Service Size:** 125

Wire Type: Copper **Service Conductors:** Unable to Identify

Location of Main Electrical Panel: Garage workshop



Building Codes, TREC Standards, Installation Standards or Safety Issues

- Grounding clamp improper style for rod Installations
- Wires not secured to the panel openings and / or run through common holes
- Bonding not present / visible at gas lines

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---


Arc fault protection not installed at all required locations. Current codes require AFCI protection to be installed in kitchens, family rooms, dining rooms, parlors, libraries, dens, bedrooms, sunroom's, rec rooms, closets, hallways, and laundry rooms.

Double lugged conductors (Neutral Wires at Bars)

Items Damaged, Non-Functional, or Operating Improperly

Missing screws were found at the dead front cover located at the main service panel. Approved screws should be installed at the dead front to properly secure the cover.

A neutral conductor is connected to the ground bar in the sub panel. Recommend further evaluation by a licensed electrician.



Abnormalities were found during the inspection of the electrical panel with a infrared camera. Recommend further evaluation and repairs by a licensed electrician.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

The tree limbs in contact with the overhead electrical conductors should be removed.



Access was made in the wall behind the sub panel. This is a safety hazard and the access should be sealed to prevent shock hazard.



The electrical panel should be relabeled as the original markings are beginning to fade.



General Comments

It is a general recommendation that all circuit breakers be tripped off and on at least once a year to ensure that they are still physically able to trip off. Occasionally, the points on a breaker will fuse to the main bus in the panel, preventing the breaker from tripping off, even if there is an overload on the circuit.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

During the inspection of the electrical panel with a infrared camera significant abnormalities were noted.

Specific Limitations

The inspector is not required to determine the service capacity, amperage, voltage or the capacity of the electrical system relative to present or future use or requirements. We are not required to and do not conduct voltage drop calculations, determine the insurability of the property; or determine the accuracy of breaker labeling. With the exception of the main breaker panel no other equipment or component covers are removed or opened to check electrical wiring, except if aluminum branch wiring is found. Arc fault circuit interrupting devices are not tested when the property is occupied or when in the opinion of the inspector, damage to personal property may result. In addition, overcurrent devices are not operated.

B. Branch Circuits, Connected Devices, and Fixtures

Comments:

Type of Wiring: Copper

**GFCI Safety Protection Present in Following Locations:
Bathrooms/Kitchen (Partial)**

Reset Locations for GFCI's:

Exterior: Not Present - GFCI Needed

Garage: Not Present - GFCI Needed

Kitchen: Kitchen

Bathrooms: Master Bathroom

Laundry Room: Not Present - GFCI Needed

Smoke Detector Locations: Vicinity of Sleeping Rooms

Carbon Monoxide Detectors Present at Property: None Found / Present

Building Codes, TREC Standards, Installation Standards or Safety Issues

Conductors close to attic door

Conduit missing at sections of the distribution wiring

Receptacles not approved for use on the exterior present

Electrical disconnects missing

GFCI's not installed at all required locations

The installation of a ground fault circuit interrupter (GFCI) is currently recommended at all kitchen receptacles (countertops, dishwasher, disposal, etc.), all bathroom receptacles (including receptacles within 6' of tub and shower enclosures), all receptacles in the laundry room (including washer & dryer), all receptacles in the garage (including the ceiling), and all receptacles on the exterior of the property. A ground fault circuit interrupter (GFCI) offers protection from shock or electrocution. The installation of this safety device is recommended at the areas noted above lacking GFCI protection.

Smoke detectors not installed according to current codes

The smoke detectors in the property do not comply with current building codes (i.e. hard wired, battery back ups, interlinked, locations, etc.). Current building codes require smoke detectors to be located inside and outside each sleeping room.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Carbon monoxide detectors were not found / are not present in the property being inspected. Current codes require carbon monoxide detectors to be installed in properties that have fueled fired appliances (gas water heaters, furnaces, etc.) and attached garages.

Tamper resistant receptacles not installed

Tamper resistant receptacles have not been installed as required under current codes.

Conductors not secured properly

Box extender's not present at receptacles

Un-grounded receptacles and / or switches found at property

Items Damaged, Non-Functional, or Operating Improperly

Portions of this property have been wired with two-strand wiring. It has no (bare) grounding wire. At the time this property was built, this type of wiring was acceptable. However, it does not meet current applicable codes. Many of the receptacles were not designed for use with a two-wire system. Receptacles were found in the following locations that were not intended to be used with this type of system:

1. throughout the home

Only approved & compatible receptacles & switches should be used. A licensed electrician should be consulted to further investigate the electrical system and perform all necessary repairs.



A ground fault circuit interrupter (GFCI) receptacle in the exterior did not respond correctly to testing during the inspection. Recommend repairs.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---


Missing / loose receptacle and switch plates were found at various locations at the property being inspected. All cover plates should be installed.



Damaged cover plates were found in the kitchen and attic. Recommend replacement of the plates.



Two receptacles in the garage are not functioning. Recommend further investigation and repairs by a licensed electrician.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Inoperative lights were found during the inspection of the property in various areas. All lights should be repaired prior to closing to insure it is a bulb problem rather than a circuit or fixture problem.



A low hanging wire was noted in the backyard. It is unknown if it is a high voltage or low voltage wire. This is a safety hazard. The wire needs to be properly secured so it is out of the way.



I=Inspected


NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

Exposed electrical connections were noted in the attic. Improper electrical connections should be improved. All electrical connections should be made inside junction boxes fitted with cover plates.



The door bell is inoperative.

General Comments

GFCI's (Ground Fault Circuit Interrupters) are modern electrical devices, either a receptacle or a circuit breaker, which are designed to protect people from electric shock. GFCI's are now required in wet or damp environments. In the event of a fault in an appliance that you are touching, the GFCI would detect the current that passes through your body to ground, and shut the circuit off, protecting you from a potentially fatal shock. We strongly recommend that all receptacles located on kitchen countertops, bathrooms countertops, garages, at hydro-therapy motors, hot tubs, fountains, pools, crawl spaces, outdoors, and other damp locations be upgraded to the ground fault circuit interrupter type.

Smoke detector batteries should be changed when moving into the home. It is recommended that the batteries be changed every six months. Smoke Detectors are tested using the test button present on the unit.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Two prong un-grounded receptacles were found at various locations in the property.



The three-prong receptacle installed in the laundry room is an older style outlet. If a newer electric dryer will be used, this receptacle will have to be replaced by a newer four prong outlet.



Specific Limitations

The inspector will evaluate only accessible receptacles during the inspection. We cannot move furniture to access hidden or blocked receptacles or switches. Only visible electrical components which are interior to or attached to the exterior walls of the property were inspected. Wiring and all associated components underground, interior to walls, floors and ceilings, not attached to the property or not readily visible in the attic, or otherwise inaccessible or hidden from view, could not be observed by the inspector and are excluded from this inspection. Attic insulation and shrouds/covers are not removed to determine if fans are correctly installed. Discrepancies related to the electrical system should be considered as safety hazards. The GFCI receptacles in an occupied property are not tested. A GFCI that is tested from a remote location in an occupied property could result in damage to the current owner's property or create other problems if the reset button cannot be located. Yard lights, intercom systems, speaker wiring, and other low voltage are beyond the scope of this inspection and were not inspected.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS

A. Heating Equipment

Comments:

Unit #1


Type of System: Forced Air

Energy Source: Electric

Location: Attic

Performance Opinion(s)

The electric heater appears to be performing its intended function at the time of the inspection as evident by the supply air temperature (119 degrees). Yearly inspections of the heater should be performed by a licensed HVAC technician to keep the system in good working order.



Building Codes, TREC Standards, Installation Standards or Safety Issues

Electrical disconnect not present

General Comments

If the system does not have a documented history of regular cleaning and maintenance, servicing by a licensed HVAC technician will be required. Recommend annual cleaning and servicing by a licensed HVAC technician.

Specific Limitations

The system fan, burner, and heat exchanger are not readily available for inspection without disassembly of the unit. Because we do not disassemble equipment, the condition of the system interior is unknown. The future performance and/or life expectancy of this system is beyond the scope of this inspection. If any problems are found/reported on this report, a licensed HVAC contractor should be hired to fully evaluate the heater. This inspection is limited, and we cannot predict the extent of repairs needed once the unit is fully evaluated.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

-
-
-
-

B. Cooling Equipment

Comments:

Type of System(s): Split System Electric

Unit #1

Approximate System Size: 3 Ton

Approximate Manufactured Date: 2010 exterior / interior unknown

Approximate Seer Rating: 13

Today's Temperature Differential (Delta T): 20

Location: Exterior and Attic

Performance Opinion

The temperature differential measurements between the return and supply air were within normal ranges at the time of the inspection. This is a limited diagnostic test to determine if the a/c is cooling properly. If other visible problems were found, a licensed HVAC contractor should be consulted to perform the necessary repairs. The client should understand that, as with any mechanical system, future performance and breakdowns cannot be predicted. Yearly inspections by an HVAC technician are recommended to keep the system in good working condition.

Primary Drain Line(s) Point of Termination(s):Un-Trapped Plumbing Vent

Secondary Drain Line(s) Point of Termination(s):Unable to Locate

Building Codes, TREC Standards, Installation Standards or Safety Issues

- Electrical disconnect(s) missing
- Primary drain line not insulated properly
- Missing electrical conduit

Items Damaged, Non-Functional, or Operating Improperly

The primary drain line terminates in a plumbing vent in the attic. Recommend improvements.



I=Inspected

NI=Not Inspected

NP=Not Present


D=Deficient

I	NI	NP	D
---	----	----	---

What appears to be microbial growth was noted on the exterior of the HVAC components located in the attic. Recommend further evaluation to determine if repairs are needed.



Damage was noted at the primary drain line, it appears to have been damaged by rodents. The primary drain line is also disconnected in the attic. Recommend repairs.



Damaged and missing insulation on the visible portions of the refrigerant lines should be repaired/replaced.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Rust and corrosion was noted at the exterior of unit(s) # 1.



General Comments

Temperature differential readings are a fundamental standard for testing the proper operation of the cooling system. Unusual conditions such as excessive humidity, low outdoor temperatures, and restricted airflow may indicate abnormal operation even though the equipment is functioning basically as designed and occasionally may indicate normal operation in spite of an equipment malfunction. If the system does not have a documented history of regular cleaning and maintenance, cleaning and service by a licensed HVAC technician is required. Recommend annual cleaning and servicing by a licensed HVAC technician.

Float switch(es) have been installed at the emergency drain pan(s) located below the evaporator coil(s) in the attic. This is a feature that turns off the outside unit in the event water collects in the drain pan.

Specific Limitations

The model, age, size, and seer rating information included in this report are estimations from information gathered from the data plate on the equipment and the accuracy cannot be guaranteed. The system fan and evaporator coil are not readily accessible for inspection without disassembly of the unit. Because we do not disassemble equipment, the condition of the system interior is unknown. The inspector will not pressure test the system coolant, determine the presence of leaks, or operate setback features on thermostats or controls. Because this is a limited visual inspection any problems noted on the report should be fully evaluated by a licensed HVAC contractor to determine all necessary repairs. We cannot predict the life expectancy of the equipment nor accurately estimate the cost of repairs.

While we will inspect the visible portions of the secondary and primary drain lines installed at the HVAC systems / drain pans. It is impossible for us to visually evaluate lines that are buried or concealed within insulation, wall spaces, etc. Furthermore, we do not perform functional testing of these lines.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

-

C. Duct Systems, Chases, and Vents

Comments:

[Building Codes, TREC Standards, Installation Standards or Safety Issues](#)

- Ducts not supported properly in attic

Items Damaged, Non-Functional, or Operating Improperly

Damaged ductwork was noted in the attic.



General Comments

Terminated ductwork was noted in the home.



Specific Limitations

The inspector will not determine the efficiency, adequacy, or capacity of the systems. Nor will the inspector determine the uniformity of the supply ducts or determine types of materials contained in insulation, wrapping of pipes and ducts, jackets, boilers, and wiring. Ductwork, chases, and other components associated with ducts and vents that are concealed and/or not visible were not inspected. In addition, electronic air filters, humidifiers, and germ-killing equipment were not inspected. **If dirt, debris, discoloration, microbial growth, or others problems are noted on the inspection report that could be related to mold problems the client is advised to contact a mold inspector to have these problems further evaluated. A mold inspection was not performed and all environmental concerns are specifically excluded from this report, i.e. mold in ducts, mold on registers, microbial growth at any location, etc..**

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

IV. PLUMBING SYSTEM

A. Plumbing Supply, Distribution Systems and Fixtures

Comments:

Location of Water Meter: Front of Property

Locations of Main Water Supply Shut Off Valve: Front Exterior



Static Water Pressure Reading: 60 psi

Type of Water Supply Piping: Galvanized / Steel - This property has been plumbed with galvanized/steel piping. The older steel piping is subject to corrosion on the interior of the pipe. This corrosion leads to two different problems. The first problem relates to water pressure. As corrosion builds up, the inside diameter of the pipe becomes constricted, resulting in a loss of water pressure. This piping is typically replaced when the loss of pressure can no longer be tolerated. The second problem can more costly. Depending on the mineral makeup of your water supply, the piping can deteriorate to the point the pin hole leaks develop throughout the supply piping. Both of these problems are difficult to detect during a limited visual inspection. A licensed plumber can further evaluate the piping and make recommendations in regard to repairs and provide estimates. Predicting future performance of the piping is beyond the scope of this inspection.; CPVC; PEX



Gas Valve Present In Laundry Room For Use with Dryer: Yes No Not Visible

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Building Codes, TREC Standards, Installation Standards or Safety Issues

- Anti-siphon devices not installed at all hose bibs
- Dielectric unions not found or visible at unions
- Hot & cold valves not labeled at washing machine connections
- Un-insulated piping in attic / crawl space / exterior
- Piping not supported / secured properly

Items Damaged, Non-Functional, or Operating Improperly
Exterior

The supply piping on the exterior of the building / structure should be insulated to protect from freezing.



The rear hose bib faucet handle is damaged.



Bathroom

Low water pressure was noted during operation of the sink. Recommend further investigation and improvements if needed.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Discolored water was noted while operating the supply plumbing. The source of the this discoloration could not be determined. A licensed plumber should determine the source and make the needed repairs.



Surface stains/discolorations were found at the tub.



The toilet tank is loose. Recommend securing.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Attic

Corrosion was found at the supply piping at the following location: attic. No active leaks were found during the inspection, but these can develop at any time. A licensed plumber should correct this problem.



Specific Limitations

The inspector will not operate any main, branch, or shut-off valves; inspect any system that has been shut down or otherwise secured; inspect any components that are not visible or accessible; inspect any fire sprinkler systems; inspect the quality or the volume of the water; determine the portability of any water system; inspect water conditioning equipment; inspect solar water heaters, determine the effectiveness of anti siphon device, operate free-standing appliances; inspect the gas supply system for leaks. Portions of the plumbing system concealed by finishes and/or storage (below sinks, etc.), below the structure, and beneath the yard were not inspected. The inspection of the washing machine connections are limited to a visual inspection of the valve and visible / accessible piping. The washing machine valves are not operated and the washer is not operated. Water filtration systems and/or softeners installed are beyond the scope of this inspection are were not inspected.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

-
-
-
-

B. Drains, Wastes, and Vents

Comments:

Type of Waste Piping: Cast Iron / Metal - Portions of the waste piping are older. It may be prone to unexpected problems. Improvement is recommended on an as needed basis. Under ground / under slab plumbing lines are beyond the scope of this inspection and were not inspected. The integrity of the below grade plumbing lines was not determined during this inspection. If this type of inspection is desired, a licensed plumber should be consulted to perform this specialized testing., Plastic

Main Sewer Cleanout Location: Rear of Property



Building Codes, TREC Standards, Installation Standards or Safety Issues

- PVC piping exposed on exterior not painted to protect from UV rays



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

Specific Limitations

While some water was run down the drains, this cannot simulate the waste flows characteristic of full occupancy. Therefore hidden or inaccessible leaks could be present during the inspection and not be visible to the inspector at the time of the inspection. There may be partial blockage of the sanitary drain lines buried in the yard, from broken pipes or tree roots. Examination of such partial blockage is beyond the scope of this inspection. If drain stoppages occur, you should consult a licensed plumber immediately. Portions of the plumbing system concealed by finishes and/or storage (below sinks, etc.), below the structure, and beneath the yard were not inspected. Floor drains are not inspected.

C. Water Heating Equipment

Comments:

Energy Source: Gas with Flex / Black Iron


Capacity: 40 Gallons

Location of Water Heater(s): Garage

Manufactured Date: 2019

Performance Opinion:

The hot water heater was functional at the time of inspection. The unit should be drained and flushed periodically to eliminate chemical deposit buildup. Adjust temperature to a maximum of 120 degrees to prevent scalding. The water heater was set to "vacation" mode at the temperature control.



Building Codes, TREC Standards, Installation Standards or Safety Issues

Improper clearance of flue pipe from combustibles

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Items Damaged, Non-Functional, or Operating Improperly

Discoloration was noted at the water heater flue pipe possibly due to the improper clearance at the pipe. Recommend improvements.



General Comments

It is recommended that water heater tanks be drained and flushed yearly to reduce mineral deposits and extend the life of the unit. Homes left vacant for extended periods of time may have a buildup of hydrogen sulfide gas inside the water heater tank. This gas causes an unpleasant "rotten eggs" odor. Generally, flushing the unit a few times will alleviate this problem. If the problem persists, contact a licensed plumber for further evaluation of the water heater.

No gas leaks were detected by our gas detector during the inspection of the accessible gas lines and components at this fixture.



Specific Limitations

Temperature & Pressure Relief valves are not operated due to the likelihood of leaks at this valve after testing and the potential to cause damage on the interior of the residence during testing.

While we will inspect the visible portions of the emergency drain and T & P drain lines installed at the water heater(s) / drain pan(s). It is impossible for us to visually evaluate lines that are buried or concealed within insulation, wall spaces, etc. Furthermore, we do not perform functional testing of these lines.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

D. Hydro-Massage Therapy Equipment

Comments:

E. Other

Comments:

[Building Codes, TREC Standards, Installation Standards or Safety Issues](#)

Improper Gas Line Materials - Copper



Gas Supply Systems Notifications / Specific Limitations

Only readily accessible and visible gas connections at the point of use are inspected. If you wish to have a more exhaustive test performed, i.e pressure test contact a licensed plumber or other specialized gas professionals for a more exhaustive check of the gas line connections inside walls and at other inaccessible areas. As a general recommendation pressure testing is recommended to be performed on older properties.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

V. APPLIANCES

A. Dishwashers

Comments:

Type of Back Flow Prevention: Airgap / Line Looped

Rust / Corrosion Present at Following Components: Racks

Disconnect Location: Wall Switch - A switch / electrical disconnect has been installed for the dishwasher. This switch has to be in the on position for the dishwasher to operate.

Items Damaged, Non-Functional, or Operating Improperly

Observed rust on the dishwasher components. Recommend repair with approved materials.



B. Food Waste Disposers

Comments:

C. Range Hood and Exhaust Systems

Comments:

Range Hood Type: Recirculate

D. Ranges, Cooktops, and Ovens

Comments:

Type of Range: Electric

Type of Oven: Electric

Oven Temperature Measured When Set at 350 Degrees F = 335

Building Codes, TREC Standards, Installation Standards or Safety Issues

Missing anti-tip device

An anti-tip device has not been installed at the range/oven as required by code. This is a safety issue that should be corrected.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Items Damaged, Non-Functional, or Operating Improperly
Damage was found at sections of the surface on the oven/stovetop.



-
-
-
-

E. Microwave Ovens

Comments:

-
-
-
-

F. Mechanical Exhaust Vents and Bathroom Heaters

Comments:

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

G. Garage Door Operators

Comments:

[Building Codes, TREC Standards, Installation Standards or Safety Issues](#)

Electronic eyes installed improperly - >6"

Items Damaged, Non-Functional, or Operating Improperly

The light is not functioning at the garage door operator.

Specific Limitations

Due to the likelihood of causing damage to the garage door or door operator, the auto reverse mechanisms are not tested. As a general rule, the garage door operator pressure switch and / or auto reverse mechanism should be adjusted prior to moving in. These safety devices should be routinely adjusted. In addition, the garage door operator remotes are not tested.

H. Dryer Exhaust Systems

Comments:


Dryer Vents To: Exterior Wall

[Building Codes, TREC Standards, Installation Standards or Safety Issues](#)

Dryer vent material improper

Items Damaged, Non-Functional, or Operating Improperly

The dryer vent is in need of cleaning as evident by the build up of lint at the dryer opening.



General

The dryer duct and vent hood should be cleaned every 6 months or sooner if necessary. Dirty ducts and lint build up can become fire hazards and reduce the efficiency of the dryer.

I. Other

Comments:

INSPECTION AGREEMENT

PLEASE READ THIS AGREEMENT CAREFULLY BEFORE SIGNING

I. Scope of Services

A. In exchange for the Inspection Fee paid by Client, the Inspector agrees to provide the Client with an Inspection Report setting out the Inspector's professional opinions concerning the condition of certain observable systems and items of the Property. The inspection will be performed in accordance with the Standards of Practice promulgated by the Texas Real Estate Commission. Inspector will attempt to identify major defects and problems with the Property. However, Client acknowledges that the Inspection Report may not identify all defects or problems.

B. The inspection is limited to those items which can be seen, easily accessed and/or operated by the Inspector at the time of the inspection as set out in the Inspection Report. Inspector will not remove walls, floors, wall coverings, floor coverings and other obstructions in order to inspect concealed items. Systems and conditions which are not specifically addressed in the Inspection Report are excluded.

C. The Inspector may indicate one of the following opinions of the Inspector regarding a particular item:

1. The item is performing its intended function at the time of the inspection;
2. The item is in need of repair; or
3. Further evaluation by an expert is recommended.

D. Exclusions. Unless otherwise agreed to in writing, the scope of the inspection will not include the following:

1. the presence or risk of environmental conditions such as asbestos, lead-based paint, formaldehyde, fungi, MOLD*, mildew, corrosive or contaminated drywall or any other environmental hazard or condition
2. indoor air quality tests;
3. the presence or absence of pests, termites, or other wood-destroying insects or organisms;
4. compliance with any codes, ordinances, statutes or restrictions;
5. items or components that require the use of specialized equipment to inspect;
6. anticipated future life or changes in performance of any item inspected; and
7. other items specifically excluded from the scope of an inspection under the Standards of Practice promulgated by the Texas Real Estate Commission.

*Client may wish to have a licensed mold assessor perform a mold assessment/analysis. A list of licensed mold assessors can be found at <https://www.dshs.texas.gov/mold/profession.shtm>. If deficiencies are found during the inspection, *i.e.* water penetrations, evidence of previous water penetrations, discolorations, staining, microbial growth, etc., you should always, as part of your due diligence, have a mold assessment performed prior to closing.

II. Inspection Report

A. The Inspection Report provided by the Inspector will contain the Inspector's professional, good-faith opinions concerning the need for repair or replacement of certain observable items. All statements in the report are the Inspector's opinions and should not be construed as statements of fact or factual representations concerning the Property. **By signing this Agreement, the Client understands that the services provided by the Inspector fall within the Professional Services Exemption of the Texas Deceptive Trade Practices Act ("DTPA") and agrees that no cause of action exists under the DTPA related to the services provided.**

B. The Inspection Report is not a substitute for disclosures by sellers and real estate agents. Client should obtain as much information concerning the history of the property from the sellers as possible. The seller's disclosure notice should be reviewed in detail for any disclosures that may influence or affect the desirability and/or market value of the Property.

C. As noted above, the Inspection Report may state that further evaluation of certain items is needed by an expert in the field of the item inspected. By signing this Agreement, Client acknowledges that qualified experts may be needed to further evaluate such items as structural systems, foundations, grading, drainage, roofing, plumbing, electrical systems, HVAC, appliances, sprinkler systems, fire/smoke detection systems, septic systems and other observable items as noted in the report.

D. Client understands and agrees that the Inspection Report will not be provided to Client until the Inspection Fee has been paid.

III Disclaimer of Warranties

The Inspector makes no guarantee, warranty or promise, express or implied, as to any of the following:

1. That all defects have been found or that the Inspector will pay for repair of undisclosed defects;
2. That any of the items inspected are designed or constructed in a good and workmanlike manner;
3. That any of the items inspected will continue to perform in the future as they are performing at time of the inspection; and
4. That any of the items inspected are merchantable or fit for any particular purpose.

IV. LIMITATION OF LIABILITY

IT IS UNDERSTOOD THE INSPECTION COMPANY IS NOT AN INSURER AND THAT THE INSPECTION AND REPORT SHALL NOT BE CONSTRUED AS A GUARANTEE OR WARRANTY OF ANY KIND. BY SIGNING THIS AGREEMENT, CLIENT ACKNOWLEDGES THAT THE INSPECTION FEE PAID TO THE INSPECTION COMPANY IS NOMINAL GIVEN THE RISK OF LIABILITY ASSOCIATED WITH PERFORMING MOLD INSPECTIONS IF LIABILITY COULD NOT BE LIMITED. CLIENT ACKNOWLEDGES THAT WITHOUT THE ABILITY TO LIMIT LIABILITY, THE INSPECTION COMPANY WOULD BE FORCED TO CHARGE CLIENT MUCH MORE THAN THE INSPECTION FEE FOR THE INSPECTOR'S SERVICES. CLIENT ACKNOWLEDGES BEING GIVEN THE OPPORTUNITY TO HAVE THIS AGREEMENT REVIEWED BY COUNSEL OF HIS OR HER OWN CHOOSING AND FURTHER ACKNOWLEDGES THE OPPORTUNITY OF HIRING A DIFFERENT INSPECTOR TO PERFORM THE INSPECTION. BY SIGNING THIS AGREEMENT, CLIENT AGREES TO LIABILITY BEING LIMITED TO THE AMOUNT OF THE INSPECTION FEE PAID BY THE CLIENT OR \$300.00, WHICHEVER IS GREATER. THE CLIENT AGREES TO HOLD THE INSPECTION COMPANY AND ITS RESPECTIVE OFFICERS, AGENTS AND EMPLOYEES HARMLESS FROM AND AGAINST ANY AND ALL LIABILITIES, DEMANDS, CLAIMS, AND EXPENSES INCIDENT THERETO FOR INJURIES TO PERSONS AND FOR LOSS OF, DAMAGE TO, DESTRUCTION OF PROPERTY, COST OF REPAIRING OR REPLACING, OR CONSEQUENTIAL DAMAGE ARISING OUT OF OR IN CONNECTION WITH THIS INSPECTION.

V. Fees or Other Valuable Consideration Disclosure

In connection with this inspection, Houston Home Inspections, PLLC d/b/a Houston Inspections may accept or pay referral fees and/or give or receive valuable consideration to and from third parties. By signing below the client is acknowledging being informed of this arrangement between the company and the third party, and hereby consents to these arrangements. Your inspector may have an affiliation with a third-party service provider ("TPSP") in order to offer you additional value-added services. Houston Home Inspections, PLLC, dba Houston Inspections is not liable for work performed by third party contractors.

VI. Dispute Resolution

In the event a dispute arises regarding an inspection that has been performed under this agreement, the Client agrees to notify the Inspector within ten (10) days of the date the Client discovers the basis for the dispute so as to give the Inspector a reasonable opportunity to re-inspect the property. Client agrees to allow re-inspection before any corrective action is taken. Client agrees not to disturb or repair or have repaired anything which might constitute evidence relating to a complaint against the Inspector. Client further agrees that the Inspector can either conduct the re-inspection himself or can employ others (at Inspector's expense) to re-inspect the property, or both. **In the event a dispute cannot be resolved by the Client and the Inspector, the parties agree that any dispute or controversy shall be resolved by mandatory and binding arbitration administered by the American Arbitration Association ("AAA") pursuant to Chapter 171 of the Texas Civil Practice & Remedies Code and in accordance with this arbitration agreement and the commercial arbitration rules of the AAA.**

VII. Attorney's Fees

The Inspector and the Client agree that in the event any dispute or controversy arises as a result of this Agreement, and the services provided hereunder, the prevailing party in that dispute shall be entitled to recover all of the prevailing party's reasonable and necessary attorneys' fees and costs incurred by that party.

VIII. Exclusivity

The report is intended for the sole, confidential and exclusive use and benefit of the CLIENT and the INSPECTION COMPANY has no obligation or duty to any other party. INSPECTION COMPANY accepts no responsibility for use by third parties. There are no third party beneficiaries to this Agreement. This Agreement is not transferable or assignable. Client gives permission for the Inspector to discuss report findings with real estate agents, specialists, or repair persons for the sake of clarification.

TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

Rule §7.176 Requires this department prescribed form to be used for real estate transactions in Texas regarding the visible presence or absence of wood destroying insects and conditions conducive to infestations of wood destroying insects.

4713 Lido Ln

Inspected Address

Houston

City

77092

Zip Code

SCOPE OF INSPECTION

- A. This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guest houses or any other structure will not be included in this inspection report unless specifically noted in Section 5 of this report.
- B. This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). **Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work.**
- C. Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. **The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment, has rendered the pest(s) inactive.**
- D. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is present.
- E. If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified expert.
- F. **THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS.**
- G. If termite treatment (including pesticides, baits or other methods) has been recommended, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticides to be used and complete details of warranty (if any). At a minimum, the warranty must specify which areas of the structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party.
- H. There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and renewal options.
- I. There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure, (2) there is visible evidence of a previous infestation with no evidence of a prior treatment.
- J. If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture.

4713 Lido Ln Houston 77092
Inspected Address City Zip Code

1A. Marathon Pest Control, LLC 1B. 0734966
Name of Inspection Company SPCS Business License Number

1C. 32222 Tamina Rd., A-5 Magnolia TX 77354 832-934-7378
Address of Inspection Company City State Zip Telephone No.

1D. Michael Bell 1E. Certified Applicator [] (check one)
Name of Inspector (Please Print) Technician [x]

1F. Friday, March 12, 2021
Inspection Date

2. Campbell Roper Seller [] Agent [] Buyer [x] Management Co. [] Other []
Name of Person Purchasing Inspection

3. Owner of Record
Owner/Seller

4. REPORT FORWARDED TO: Title Company or Mortgagee [] Purchaser of Service [x] Seller [] Agent [x] Buyer [x]
(Under the Structural Pest Control regulations only the purchaser of the service is required to receive a copy)

The structure(s) listed below were inspected in accordance with the official inspection procedures adopted by the Texas Structural Pest Control Service. This report is made subject to the conditions listed under the Scope of Inspection. A diagram must be attached including all structures inspected.

5A. single story home with garage
List structure(s) inspected that may include residence, detached garages and other structures on the property. (Refer to Part A, Scope of Inspection)

5B. Type of Construction:
Foundation: Slab [x] Pier and Beam [] Pier Type: _____ Basement [] Other: _____
Siding: Wood [x] Hardie Plank [x] Brick [x] Stone [] Stucco [] Other: _____
Roof: Composition [x] Wood Shingle [] Metal [] Tile [] Other _____

6A. This company has treated or is treating the structure for the following wood destroying insects: No Treatment Performed / Inspection Only

If treating for subterranean termites, the treatment was: Partial [] Spot [] Bait [] Other []
If treating for drywood termites or related insets, the treatment was: Full [] Limited []

6B. None n/a n/a
Date of Treatment by Inspecting Company Common Name of Insect Name of Pesticide, Bait or Other Method

This company has a contract or warranty in effect for control of the following wood destroying insects:
Yes [] No [x] List Insects: Marathon Pest Control, LLC carries no warranty on this property expressed or implied.
If "Yes", copy(ies) of warranty and treatment diagram must be attached.

Neither I nor the company for which I am acting have had, presently have, or contemplate having any interest in the purchase of sale of this property. I do further state that neither I nor the company for which I am acting is associate in any way with any party to this real estate transaction.

Signatures:
7A. [Signature] #0816352
Inspector (Technician or Certified Applicator Name and License Number)

Others Present:
7B. None
Apprentices, Technicians, or Certified Applicators (Names) and Registration/License Number(s)

Notice of Inspection Was Posted At or Near:
8A. Electric Breaker Box [] 8B. Date Posted: Friday, March 12, 2021
Water Heater Closet []
Beneath the Kitchen Sink [x]

9A. Were any areas of the property obstructed or inaccessible? Yes [x] No []
(Refer to Part B & C, Scope of Inspection) If "Yes" specify in 9B.

9B. The obstructed or inaccessible areas include but are not limited to the following:
Attic [x] Insulated area of attic [x] Plumbing Areas [x] Planter box abutting structure [x]
Deck [] Sub Floors [] Slab Joints [x] Crawl Space []
Soil Grade Too High [x] Heavy Foliage [] Eaves [x] Weepholes []
Other [x] Specify: Some areas at the property being inspected were inaccessible or access was restricted due to stored items and / or furniture. The foundation wall(s) are not visible at several locations due to patio flatwork that has been installed.

4713 Lido Ln
Inspected Address

Houston
City

77092
Zip Code

10A. Conditions conducive to wood destroying insect infestation?
(Refer to Part J, Scope of Inspection) If "Yes" specify in 10B.

Yes No

10B. Conducive Conditions include but are not limited to:

Wood to Ground Contact (G) Formboards left in place (I) Excessive Moisture (J)
Debris under or around structure (K) Footing too low or soil line too high (L) Wood Rot (M) Heavy Foliage (N)
Planter box abutting structure (O) Wood Pile in Contact with Structure (Q) Wooden Fence in Contact with the Structure (R)
Insufficient ventilation (T) Other (C) Specify: _____

11. Inspection Reveals Visible Evidence in or on the structure:

	Active Infestation		Previous Infestation		Previous Treatment	
11A. Subterranean Termites	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
11B. Drywood Termites	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
11C. Formosan Termites	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
11D. Carpenter Ants	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
11E. Other Wood Destroying Insects	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>

Specify: _____

11F. Explanation of signs of previous treatment (including pesticides, baits, existing treatment stickers or other methods) identified:

drill marks and sellers disclosure

11G. Visible evidence of: Previous subterranean termites has been observed in the following areas: garage workshop, attic, and tub drain area

If there is visible evidence of active or previous infestation, it must be noted. The type of insect(s) must be listed on the first blank and all identified infested areas of the property inspected must be noted in the second blank. (Refer to Part D, E & F, Scope of Inspection)

12A. Corrective treatment recommended for active infestation or evidence of previous infestation with no prior treatment

as identified in Section 11. (Refer to Part G, H and I, Scope of Inspection)

Yes No

12B. A preventive treatment and/or correction of conducive conditions as identified in 10A & 10B is recommended as follows:

Yes No

Specify reason: Refer to graph and comments below.

Refer to Scope of Inspection Part J

Diagram of Structure(s) Inspected

The inspector must draw a diagram including approximate perimeter measurements and indicate active or previous infestation and type of insect by using the following codes: E-Evidence of infestation; A-Active; P-Previous; D-Drywood Termites; S-Subterranean Termites; F-Formosan Termites; C-Conducive Conditions; B-Wood Boring Beetles; H-Carpenter Ants; Other(s) - Specify _____

FW-Flat Work Covering Foundation Wall


x-Drill Mark (Previous Treatment)

L-Footing too Low or Soil Line too High

M-Wood Rot

O-Planter's Box Abutting Structure

PS-Previous Subterranean Termites



Additional Comments Evidence of previous infestation of wood destroying insects were found during the inspection as reflected on this report / graph. Evidence was found that this property (portions or all) has been treated for wood destroying insects in the past. Final determination of structurally significant damage to wood members (if any) cannot be determined without removal of wall coverings. Recommend client obtain additional information from seller regarding extent and location of previous infestation, chemical and company used, warranty if applicable, etc.. Marathon Pest Control, LLC specifically excludes hidden / latent damage if present (we cannot see thru walls). Conducive conditions were found during the inspection of the property, which could conceal insect activity or promote future insect activity or conceal damage. DUE TO THE CONDUCTIVE CONDITIONS FOUND WE CANNOT GUARANTEE THE ABSENCE OF WOOD DESTROYING INSECTS. The conducive conditions should be corrected. After the conducive conditions have been corrected it is recommended that the property be re-inspected for wood destroying insects. The client should take into consideration the cost of associated with correcting the conducive and / or performing a treatment and plan accordingly. Notice to Client(s): There is always a possibility of the presence of undetectable activity of wood destroying insects. If evidence of active or previous infestation(s) of listed wood destroying insects is reported, it should be assumed that some degree of damage is present, wether visible or non-visible.

4713 Lido Ln
Inspected Address

Houston
City

77092
Zip Code

Statement of Purchaser

I have received the original or a legible copy of this form. I have read and understand any recommendations made. I have also read and understand the "Scope of Inspection." I understand that my inspector may provide additional information as an addendum to this report.

If additional information is attached, list number of pages: **2 Page(s)**

Signature of Purchaser of Property or their Designee

Date

Refer to Signed Inspection Agreement

Customer or Designee not Present

Buyers Initials _____

Additional Information / Notices

Was a seller's disclosure available for review?: Yes (if no we recommend you review the seller's disclosure prior to closing to determine if disclosures have been made in regards to wood destroying insects; signs of previous termite treatments are not always visible or easily observed. If evidence is produced in regards to previous wood destroying insects please contact us so we may have a opportunity to review the evidence and perform a re-inspection if needed.

Wood Destroying Report Addendum / Photos

The digital pictures within his report are a representative sample and should not be considered to show all. There will be items not represented with digital imaging.

Inspection Sticker from Today's Inspection: Below Kitchen Sink

Conducive Conditions Present: Yes (Sample Pictures Below)



Inaccessible Areas Present:



Evidence of Previous Treatment Present: Yes Drills Marks, Yes Seller's Disclosure



Wood Destroying Insect Activity or Evidence: Yes (Sample Pictures Below)

