TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

Page 1 of 3

1707 Gano Street	Houston	TX	77009			
INSPECTED ADDRESS	CITY	STATE	ZIP			

SCOPE OF INSPECTION

A This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guesthouses or any other structure will not be Included in this inspection report unless specifically noted in Section 5 of this report.

B. This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall covers, floor coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work.

C. Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure(s) being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment; has rendered the pest(s) inactive.

D. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is present.

- E. If visible damage is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified expert.
- F. THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS.

G. If termite treatment (including pesticides, baits or other methods) has been recommend, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticide to be used and complete details of warranty (if any). At a minimum, the warranty must specify which areas of the structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party.

- H. There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranted, treatment techniques and renewal options.
- I. There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is visible evidence of a previous infestation with no evidence of a prior treatment.
- J. If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture.

I have read and understand the above <u>SCOPE OF INSPECTION</u>. Buyer's signature:

1A. BPG Inspection LLC				1B. 687176		
Name of Inspection Company				SPCS Bus	iness License Number	
1C. 6610 Cove Lake Dr Katy		ТХ	77449	800-285	5-3001	
Address of Inspection Company	City/State		Zip	Phone	e Number	
1D. Steve Fusselman		1E	. 🗷 Certi	fied Applicator	(check one)	
Name of Inspector (Please Print)			□Techr	nician		
2.		3.	6/11/2	2018		
Case Number (VA/FHA/ Other)			Inspecti	ion Date		
4A. Bailey Furgeson		Seller	Agent	Buyer 🗵	Management Co. 🔲	
Name of Person Purchasing Inspection		Other 🗌			-	
4B						
Owner/Seller						
4C. Report forwarded to: Title Company or Mortgagee Purchaser of service Seller Agent Buyer Buyer (Under the Structural Pest Control regulations only the purchaser of the service is required to receive a copy)						

The structure(s) listed below were inspected in accordance with the official inspection procedures adopted by the Texas Department of Agriculture Structural Pest Control Service. This report is made subject to the conditions listed under the Scope of Inspection. A diagram must be attached including all structures inspected.

5. Home structure Only

List structure(s) inspected that may include residence, detached garages and other structures on the property. (Refer to Part A, Scope of Inspection)

Licensed and Regulated by the Texas Department of Agriculture, Structural Pest Control Service, P.O. Box 12847, Austin, Texas 78767 - 2847

SPCS/T-4 (Rev. 9/01/07)


(866) 918-4481

Buyers Initials:

TEXAS OFFICIAL WOOD DEST	ROYING INSECT REPO	RI Page 2 of 3
 6A. Were any areas of the property obstructed or inaccessible? Ye ☐ (Refer to Part B & C, Scope of Inspection) If "yes" specify in 6E 6B. The obstructed or inaccessible areas include but are not limited Attic (Parts of) Insulated area of attic Insulated area of atti	3.	Planter box abutting structure Crawl Space (Parts of) Weepholes
 (Refer to Part I, Scope of Inspection) If 'yes" specify in 7B. 7B. Conducive Conditions include but are not limited to: Wood to Ground Contact (G) Formboards left in place (I) 	es ☐ No ⊠ ☐ Excessive Moisture (J) ☐ ☐ Heavy Foliage (N) ☐ h the Structure (R) ☐	Debris under or around Structure (K) Planter Box Abutting Structure (O) Insufficient Ventilation (T)
8A.Subterranean TermitesY8B.Drywood TermitesY8C.Formosan TermitesY8D.Carpenter AntsY	es □ No ⊠ Yes □ N es □ No ⊠ Yes □ N	
 8F. Explanation of signs of previous treatment identified: 8G. Visible evidence of: Previous subterreanean termite damage has been observed in the following areas: multiple areas of there is visible evidence of active or previous infestation, it must be all identified infested areas of the property inspected must be noted i (Refer to Part D, E & F, Scope of inspection.) 	of exterior e noted. The type of insects(s)	must be listed in the first blank and
 The conditions conducive to insect infestation reported in 7A & 7B: 9. Will be or has been mechanically corrected by the inspecting lf yes, specify corrections: 		Yes 🗌 No 🗵
 9A. Corrective treatment recommended for active infestation or event treatment as identified in Section 8. (Refer to Part G, H, and I, Score 9B. Preventive treatment and/or correction of conducive condition as follows: Specify reason:	ope of inspection)	ommended Yes 🗌 No 🗵
10A. This company has treated or is treating the structure for the foll If treating for subterranean termites, the treatment was: If treating for drywood termites or related insects, the treatment was 10B. Date of Original Treatment by Inspecting Company	Partial Spo	t 🔲 Bait 🗌 Other 🗌
Common Name of Insect Nam This company has a contract or warranty in effect for control of the for Yes No List Insects:		
If "Yes", copy(s) of warranty and treatment diagram must be atta		
1707 Gano Street	Houston	<u> </u>
INSPECTED ADDRESS	CITY	STATE ZIP
SPCS/T-4 (Rev. 9/01/07)		Buyers Initials:

TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

The inspector must draw a diagram including approximate perimeter measurements and indicate active or previous infestation and type of insect by the following codes: **E**-Evidence of Infestation: **A** (active), **P** (previous); **D**-Drywood Termite; **S**-Subterranean Termite; **F**-Formosan termite; **C**-Conducive Conditions; **B**- Wood boring Beetles; **H**-Carpenter Ants; Other(s): <u>PS- Previous subterreanean termite damage</u>



Additional Comments:

Neither I nor the company for which I am acting have had, presently have, or contemplate having any interest in the property. I do further state that neither I nor the company for which I am acting is associated in any way with any party to this transaction.

Signatures:	12A	Notice of Inspection Was Posted At or Near:
11-19-15		Electric Breaker Box:
11A.		Water Heater Closet
Inspector		Beneath Kitchen Sink:
Approved:		
11B. 0687176	12B.	Date Posted: June 11, 2018
Certified Applicator and Certified Applicator License Number		

Statement of Purchaser

I have received the original or a legible copy of this form. I have read and understand any recommendations made. I have also read and understand the "Scope of Inspection." I understand that my inspector may provide additional information as an addendum to this report. If additional information is attached, list number of pages: _____