

BRYAN & BRYAN INSPECTIONS

(281) 484-8318 office@inspectorteam.com https://www.inspectorteam.com/



NEW CONSTRUCTION FINAL INSPECTION REPORT

1118 Modesto Dr Rosharon TX 77583

Cynthia Chambers MARCH 29, 2021



Inspector
Rene Guajardo
TREC #5945
(281) 484-8318
office@inspectorteam.com



Agent Jamale Nagi Keller Williams Hou Preferred (281) 886-3057 jamale@kw.com



PROPERTY INSPECTION REPORT

Prepared For: Cynthia Chambers
(Name of Client)

Concerning: 1118 Modesto Dr, Rosharon TX 77583

(Address or Other Identification of Inspected Property)

By: Rene Guajardo - TREC #5945

03/29/2021 9:00 am

(Name and License Number of Inspector)

(Date)

Greg Bryan TREC#3608

(Name, License Number of Sponsoring Inspector)

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. This inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. If is recommended that you obtain as much information as is available about this property, including seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for and by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods.

REI 7-5 (5/4/2015) 1 of 14

Promulgated by the Texas Real Estate Commission (TREC) P.O. Box 12188, Austin, TX 78711-2188 (http://www.trec.texas.gov)

(512) 936-3000

REI 7-5 (5/4/2015) 2 of 14

Report Identification: <u>1118 Modesto Dr, Rosharon TX 77583</u>

Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathrooms, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate license holders also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms require a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Type of Building: Single Family Access provided by:: Builder In Attendance: Buyer

Weather Conditions: Clear

Temperature (approximate): 60 Fahrenheit (F)

REI 7-5 (5/4/2015) 3 of 14

Report Identification: <u>1118 Modesto Dr.</u>, Rosharon TX 77583

Thank you for choosing Bryan & Bryan Inspections

Please review the inspection report and let us know if you have any further questions.

The Phase 3 (New Construction Final) Inspection is the evaluation of a newly built home that is substantially complete. This report has been prepared for our client in accordance with their requirements, and addresses the condition of the site, structure, and progress of work up to the point of the inspection.

This report should be presented to the builder for review, who may determine that a particular item listed as deficient in the report does in fact comply with specifications set forth in the construction documents.

The browser-based version uses advanced web features to allow for easier navigation and expanded photographs. The PDF menu on this webpage includes a PDF version of the full report on the Texas Real Estate Commission's promulgated form, as well as a summary, which may warrant further investigation by the builder. Please review all documents and attachments that were sent to you by the inspector.

REI 7-5 (5/4/2015) 4 of 14

I = Inspected NI = Not Inspected NP = Not Prese

I NI NP D

NP = Not Present D = Deficient

I. STRUCTURAL SYSTEMS

General Photos of Structure:







General Photos of Roof Covering:









X		A. Foundations
تت	 	A. Puullualiuli

Type of Foundation(s): Slab on Grade

Comments:

Foundation Inspected with Digital Level:

This foundation was measured with the use of an electronic digital measurement tool. Multiple elevation points were registered on the foundation throughout the property to determine if there were elevation variations that indicated excessive movement of the foundation. At the time of this inspection the measured areas did not indicate any variations that, in this inspector's OPINION, indicated any need for invasive repairs to the foundation.

☑ ☐ ☐ B. Grading and Drainage Comments:

 $oxed{\boxtimes}$ $oxed{\Box}$ $oxed{\Box}$ C. Roof Covering Materials

Types of Roof Covering: Composition Shingles

Report Identification: 1118 Modesto Dr, Rosharon TX 77583

NI = Not Inspected NP = Not Present I = Inspected

NI NP D

D = Deficient

Viewed From: Walking the roof surface

Roof fastening not verified:

The roof fastening method was not verified as determining this may have caused damage to the roofing

material.

□ □ □ D. Roof Structure and Attic

Viewed From: Decked areas of attic

Approximate Average Depth of Insulation: 10 Inches

Comments:

Attic Access Method: Pull down ladder(s), Access Hatch

Type of Attic/Roof Ventillation: None found Type of Insulation Material: Spray Foam

Only accessible areas were entered:

Note: Only accessible areas of the attic are inspected. The inspector does not crawl/walk over areas that may be unsafe or not easily accessible.

Foam Barrier is present:

Note: A spray foam barrier was installed on the roof decking. This may conceal possible evidence of water penetration and limit evaluation of the decking material.

☑ ☐ ☑ E. Walls (Interior and Exterior)

Comments:

Fresh Paint:

Fresh paint and new finishes can hide defects from the inspector.

1: Exterior- Masonry: Mortar "Point Ups"

Recommendation

Insufficient mortar was used in some areas of the exterior masonry. Evaluate and remedy as needed.

Recommendation: Contact your builder.



2: Exterior- Siding: Damage

Recommendation

Front Exterior

There was damage to exterior siding.

Recommendation: Contact your builder.

NI = Not Inspected I = Inspected **NP** = **Not Present** D = Deficient

NI NP D



3: Exterior- Siding: Siding Gap

Recommendation

Rear Walls

There is a gap siding noted at one or more areas of the house. Remedy as needed.

Recommendation: Contact your builder.



4: Exterior: Trim missing, loose, or damaged

Recommendation

Various areas of ceilings and soffits

Sections of exterior trim were either missing, loose, or damaged. Remedy as needed.

Recommendation: Contact your builder.



5: Cosmetic Deficiencies in New Home

Recommendation

Cosmetic deficiencies (dings, dents, missing paint, holes, missing tile, etc.) were observed at various locations around the home. Consult with the builder to ensure cosmetics are addressed at the walkthrough.

Recommendation: Contact your builder.

I = Inspected NI = Not Inspected

NP = **Not Present**

D = Deficient

I NI NP D





6: Exposed building materials

Recommendation

Exposed building materials were observed at various areas of exterior. Remedy as needed

Recommendation: Contact a qualified professional.



X		F. Ceilings and Floors
		Comments:

☐ ☐ ☐ ☐ G. Doors (Interior and Exterior)

Comments:



1: Interior Door: Sticks/Difficult to Operate

Recommendation

Front Left Bedroom Closet

Door sticks and is tough to open. Remedy as needed.

Recommendation: Contact your builder.

2: Garage Vehicle Door: Needs Adjustment

Recommendation

Garage

Binding -

A garage door contractor should evaluate and make any needed adjustments.

Recommendation: Contact your builder.

NI = Not Inspected

NP = **Not Present**

D = Deficient

NI NP D

3: Not square

Recommendation
For Example: Garage

Various doors are not square or plumb in frame. Remedy as needed

Recommendation: Contact a qualified professional.



\times			H. Windows Comments:
	\boxtimes		I. Stairways (Interior and Exterior) Comments:
	X		J. Fireplaces and Chimneys Comments:
	X		K. Porches, Balconies, Decks, and Carports Comments:
X		X	L. Other Comments:

1: Gate not secure

Recommendation

Left gate is not secure and does not latch. Remedy as needed

Recommendation: Contact a qualified professional.



2: Damaged picket

Recommendation

Damaged picket observed in backyard

Recommendation: Contact a qualified professional.

I = Inspected NI

NI = Not Inspected NP = Not Present

Present D = Deficient

NI NP D




II. ELECTRICAL SYSTEMS

General Photos of Distribution Panels:



General Infrared Photos of Distribution Panel(s):



\boxtimes \square	☐ A. Service Entrance and Panels
	Comments: Main disconnect/service box type and location: Breakers - garage
	Service entrance cable location: Underground (cable material type not visible)
	Service size: 150 Amps
	Grounding Rod not Visible:
\boxtimes \square	☐ B. Branch Circuits, Connected Devices, and Fixtures
	Type of Wiring: Copper
	Comments:

III. HEATING, VENTILATION & AIR CONDITIONING SYSTEMS

NI = Not Inspected **NP** = **Not Present** D = Deficient

NI NP D

General Photos of HVAC Equipment:







X		A. Heating Equipment
		Type of System: Furnace
		Energy Source: Electric
		Comments:

1: Heating System Issues Require Further Evaluation

Recommendation

System inoperative -

Due to multiple deficiencies identified with the Heating system, a full evaluation by a licensed HVAC contractor is recommended.

Recommendation: Contact your builder.

□ □ □ B. Cooling Equipment

Type of System: Central Air Conditioner

Comments:

1: Cooling System Issues Require Further Evaluation

Recommendation

System inoperative -

Due to multiple deficiencies identified with the cooling system, a full evaluation by a licensed HVAC contractor is recommended.

Recommendation: Contact your builder.

 $oxed{\boxtimes}$ $oxed{\Box}$ $oxed{\Box}$ C. Duct System, Chases, and Vents

Comments:

Media filter: Media filter is located at the HVAC cabinet. This filter should be replaced every 6-12 months.

IV. PLUMBING SYSTEMS

General Photos of Water Heating Equipment:

11 of 14

NI = Not Inspected

NP = **Not Present**

D = Deficient

I NI NP D






 $oxed{oxed}$ $oxed{\Box}$ $oxed{\Box}$ A. Plumbing Supply, Distribution Systems, and Fixtures

Location of water meter: Front yard near street
Location of main water supply valve: Interior Wall - Front Left Closet



Static water pressure reading: 50-55 psi, 65 psi



Comments:

B. Drains, Wastes, & Vents

Comments:

C. Water Heating Equipment

Energy Source: Gas

Capacity: Tankless

Comments:

Location: Garage

☐ ☐ ☑ ☐ D. Hydro-Massage Therapy Equipment

Comments:

V. APPLIANCES

NI = Not Inspected

NP = **Not Present**

D = **D**eficient

NI NP D

General Photos of Microwave Oven(s):



\boxtimes			A. Dishwashers Comments:
	\boxtimes		B. Food Waste Disposers Comments:
			1: No Conduit Recommendation Romex wiring was not installed under the kitchen sink at the disposal. Recommendation: Contact a qualified professional.
\boxtimes		X	C. Range Hood and Exhaust Systems Comments: Exhaust Hood Type: Vented
			1: Disconnected Vent Pipe Recommendation The exhaust fan vent pipe was disconnected. Securing or reconnecting the vent pipe is recommended to ensure proper ventilation to the exterior of the home.

Recommendation: Contact a qualified professional.



	\boxtimes		D. Ranges, Cooktops, and Ovens Comments: Range/Oven Energy Source: Gas, Electric
\boxtimes			E. Microwave Ovens Comments:
\boxtimes			F. Mechanical Exhaust Vents and Bathroom Heater Comments:
\times		\boxtimes	G. Garage Door Operators Comments:
			1: Binds During Opeartion

REI 7-5 (5/4/2015)

13 of 14

H. Dryer Exhaust Systems

Comments:

REI 7-5 (5/4/2015) 14 of 14