Rayal mist

Tom Ball

77377

SCOPE OF INSPECTION

A B

This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guest houses or any other structure will not be included in this inspection report unless specifically noted in Section 5 of this report.

This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work.

Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment; has rendered the pest(s) inactive.

If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of demand in C

D. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is

If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified

THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS. G

If termite treatment (including pesticides, baits or other methods) has been recommended, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticides to be used and complete details of warranty (if any). At a minimum, the warranty must specify which areas of the structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party.

There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and renewal options. Н

treatment techniques and renewal options. ١.

There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure, (2) there is visible evidence of a previous infestation with no

J.

recommended if (1) there is visible evidence of an active infestation in or on the structure, (2) there is visible evidence of a previous infestation with no evidence of a prior treatment.

If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture. Service of the Texas Department of Agriculture.

1A. K.C Pest Control	1B. 9890 OS48834
Name of Inspection Company	SPCS Business License Number
10. 5314 LACREK Spri	~9 1x 77379 Z81379-6723
Address of Inspection Company	City State Zip Telephone No.
10. Relton Casey	1E. Certified Applicator Check one)
Name of Inspector (Please Print)	Technician
· Na	3 1-15-20
Case Number (VA/FHA/Other)	Inspection Date
4A. Whotney King.	Seller
Name of Person/Purchasing Inspection	
4B	_
Owner/Seller	
4C.REPORT FORWARDED TO: Title Company or Mortgagee Purcha (Under the Structural Pest Control regulations only the purchaser of	ser of Service Seller Agent Buyer the service is required to receive a copy)
The structure(s) listed below were inspected in accordance with the official insp	ection procedures adopted by the Texas Department of Agriculture Structural Pest Control Service.
This report is made subject to the conditions listed under the Scope of Inspection	on. A diagram must be attached including all structures inspected.
5. Houset 4	
List structure(s) inspected that may include residence, detached garages and o	ther structules on the property. (Refer to Part A, Scope of Inspection)
6A. Were any areas of the property obstructed or inaccessible? Yes (Refer to Part B & C, Scope of Inspection) If "Yes" specify in 6B.	No □
6B.The obstructed or inaccessible areas include but are not limited to the follow	ing:
Attic Insulated area of attic Plumbing Deck Sub Floors Slab Join	
Soil Grade Too High Heavy Foliage Eaves	Weepholes
Other	
7A.Conditions conducive to wood destroying insect infestation: Yes (Refer to Part J, Scope of Inspection) If "Yes" specify in 7B.	No □
7B.Conducive Conditions include but are not limited to:	
Wood to Ground Contact (G) Debris under or around structure (K) □ Wood to Ground Contact (G) Footing too low or soil line too h	Formboards left in place (I) Excessive Moisture (J) Heavy Foliage (N)
Planter box abutting structure (O) Wood Pile in Contact with Structure	eture (Q) Wooden Fence in Contact with the Structure (R)
Insufficient ventilation (T)	□ Specify:
8.Inspection Reveals Visible Evidence in or on the structure:	Active Infestation Previous Infestation Previous Treatment
8A.Subterranean Termites	Yes No Yes No Yes No Yes
8B.Drywood Termites 8C.Formosan Termites	Yes No Ye
8D.Carpenter Ants	Yes No Yes No Yes No Yes No
8E.Other Wood Destroying Insects	Yes No Yes No Yes No Yes
Specify:	ng treatment stickers or other methods) identified
or .Explanation or signs or previous treatment (including pesticides, baits, existing	ng nauman anatora ar anta manataa) taantiinaa
8G.Visible evidence of:has been observed i	n the following areas:
If there is visible evidence of active or previous infestation, it must be noted. The inspected must be noted in the second blank. (Refer to Part D, E & F, Scope of	he type of insect(s) must be listed in the first blank and all identified infested areas of the property of Inspection)

onditions conducive to insect infestation reported in 7A & 7B:	OOD DESTROYING INSECT REPORT Page 2 of
be or has been mechanically corrected by inspecting company: 'es," specify corrections:	Yes ☐ No ☐
prrective treatment recommended for active infestation or evidence of p	evious infestation with no prior treatment
as identified in Section 8. (Refer to Part G, H, and I, Scope of Inspec	on): Yes□ No
oreventive treatment and/or correction of conflucive conditions as iden ecify reason: confluence of Inspection Part J	Gond, trans
his company has treated or is treating the structure for the following w	od destroving insects:
ting for subterranean termites, the treatment was: Partial ring for drywood termites or related insects, the treatment was: Full	Spot D Bait D Other D
Date of Treatment by Inspecting Company	Common Name of Insect Name of Pesticide, Bait or Other Method
ompany has a contract or warranty in effect for control of the following Yes No List Insects:	vood destroying insects:
If "Yes", copy(ies) of warranty and treatment diagram r	
spector must draw a diagram including approximate perimeter measur	of Structure(s) Inspected ments and indicate active or previous infestation and type of insect by using the following code
penter Ants; Other(s) – Specify	erranean Termites; F-Formosan Termites; C-Conducive Conditions; B-Wood Boring Beetles;
((&)	
	m) ya
1 5	
	52
12-	Change
	7) 10