



---

New Invoice

**\$135.31**

Due on May 20, 2022

[Pay Invoice](#)

---

**Invoice #000102**

May 20, 2022

**Customer**

Douglass Fontaine

[douglass.fontaine3@gmail.com](mailto:douglass.fontaine3@gmail.com)

228-219-4328

**Additional Recipients**

[homeplateinspections@yahoo.com](mailto:homeplateinspections@yahoo.com)

---

**Message**

We appreciate your business!

TACLA113096C

**Invoice summary**

**Ac inspection** **\$125.00**

*29234 Legends Beam Drive*

*Older Rheem condenser and cased box coil.*

*Gauges show that unit is low on R410A.*

*Temp gauge shows a DeltaT @ 10\* split from return to supply which verifies the unit is not running efficiently.*

*Condenser needs armor flex insulation on suction line.*

*Box coil needs to be resealed with tape and mastic sealant.*

*Drain pan should be replaced and a float switch needs to be added to the pan and wired into the low voltage wiring to prevent ceiling damage.*

---

Subtotal **\$125.00**

Sales Tax **\$10.31**

---

**Total Due** **\$135.31**

Note: AC evaporator and coils were replaced August 2023 with new American Standard unit. Installed by different contractor, Houston West Services. 1 year labor warranty and 10 year manufacturer warranty.