

FW: TERMITE PAPERWORK

1 message

libbymitchellrealtor@gmail.com <libbymitchellrealtor@gmail.com> To: Regency Real Estate Pros <soldbyregency@gmail.com> Wed, Feb 7, 2024 at 11:24 AM

From: Becky Coats

bcoats@billclarkbugsperts.com>

Date: Tue, Feb 6, 2024 at 1:15 PM

To: ARTURO.0.2666@GMAIL.COM <ARTURO.0.2666@gmail.com>

Hello,

I've attached your current termite service agreement, the paperwork for the service done and last 2 inspection reports. The service is current thru April, 12 2024 and is transferrable to a new homeowner. Have them call us once they have closed and we can transfer it to them.

Thank you,

Becky Coats

(409) 898-1113

bcoats@billclarkbugsperts.com

billclarkbugsperts.com

From: Art Turner <arturo.o.2666@gmail.com> Date: Tue, Feb 6, 2024 at 5:43 PM

Termites were found in flower bed during inspection and treated all around the outside of the house by digging a trench and treating it with chemicals. I replaced one baseboard inside where they were located on the outside, just out of abundance of caution. All clear ever since.

TERMITE PAPERWORK.pdf

got pests?	2975 N. 11 TH ST. • P.O. BO	985-5700 727-7575 384	$\frac{4 - 12 - 22}{-8855}$
We've Got The Answers	Eastern (<i>R</i> Formosan (<i>Coptotern</i> ONE YEAR SERVICE AGRI		
Name Ant Terner		Service Location (if different from main	iling address)
Address 1328 Gucker City, State, Zio Code	las 77632		ngreement (see graph for treatment areas): met in Seil To blab
Phone: H: C: <u>409-920-2666</u>	W: O:	Home & Darage = Paris Montacti, Includes joints,	r efterior expansion
E:mail:		7	

In accordance with your request, we are pleased to submit, herewith, our proposal including the Work Order, Pesticide Label, Treatment Disclosure, Graph, Consumer Information Sheet, Treatment Specifications, Inspection Report, Post-Treatment Swarming, Know Your Termites, Facts You Should Know About Hidden Termite Damage, any other related documents and this AGREEMENT to service structure(s) as identified above seeking the control of and/or protection against Eastern (*Reticulitermes* spp.) and Formosan (*Coptotermes* spp.) Subterranean Termites.

A. SERVICE AGREEMENT <u>ONLY</u>: Bill Clark Pest Control, Inc. (the Company) agrees to service identified structure(s) in compliance with all applicable federal, state and local laws and applicable recommendations on use of designated termiticide(s) by manufacturer. In addition to the initial service, further service as needed and as determined by the Company will be rendered at no additional charge so long as this Agreement remains in effect. The exception would be the tenure since treatment addressed in paragraph D. The Company agrees to make an annual inspection while the Agreement is in effect and timely payment is made by Client of the annual renewal fee. Further "no charge" inspections may be made in between these annual inspections should the Client observe a matter of concern and report said concerns to the Company. As this is a Service Agreement only, it DOES NOT INCLUDE DAMAGE REPAIR (See paragraph J).

CLIENT'S PAYMENT OBLIGATION: As consideration for the Company providing the first annual services stated herein, the Client agrees to pay an amount of $\$ \frac{6 \frac{4}{3} \frac{2^{\circ}}{2^{\circ}}}{(\text{plus any applicable sales tax})}$ for a total of $\$ \frac{6 \frac{6}{2^{\circ}} \frac{2^{\circ}}{2^{\circ}}}{(\text{plus any applicable sales tax})}$. At the end of the initial one year period, if the Agreement is not cancelled by the Company, this Agreement may, by mutual agreement of Client and Company, be renewed for one additional year at an annual fee of $\$ \frac{175^{\circ}}{2^{\circ}}$ (plus any applicable sales tax) for a total of $\$ \frac{189 \frac{44}{2^{\circ}}}{(\text{plus any applicable})}$. Any further renewals shall be at a fee mutually agreed upon by Client and Company. This Agreement can only be renewed nine (9) times for one year Each time (See paragraph L). Failure to pay said fees in full on or before the anniversary date shall, in the sole discretion of the Company, result in cancellation of this Agreement in its entirety, upon which event the Company will be discharged of any and all future liabilities and responsibilities.

B. OTHER WOOD DESTROYING INSECTS (WDI): This Agreement covers the area's two most common WDI, the Eastern (*Reticulitermes* spp.) and the Formosan (*Coptotermes* spp.) Subterranean Termites. If, during the course of this Agreement another form of WDI is found in the structure(s) (i.e., Drywood Termites, Beetles, Carpenter Ants, Carpenter Bees or other(s)), appropriate recommendations will be made concerning such infestation. Such recommendations may include but are not limited to fumigation, infested area removal, or structural modifications. Any actions taken on the acommendations shall be solely at the Client's expense. This expense would be additional to the sums paid under this Agreement.

C. MOLD, MILDEW OR OTHER FUNGI DISCLAIMER: Moisture is a condition found in varying degrees in most structures. Moisture conditions in and around structures can be conducive to a variety of household pests and wood destroying insects, and moisture conditions can also provide an environment favorable to the growth of mold, mildew, and other fungi. The Company does not possess the knowledge or expertise to identify mold, mildew, or other fungi. The Company also does not possess the knowledge or expertise necessary to give opinion on or offer remediation of the effects of mold, mildew or other fungi, including decay and non-decay fungi, on structures or on air quality. Moisture conditions, mold, mildew, and other fungi-related conditions should be identified, evaluated, and corrected by a professional trade with expertise in this field. The Company is not responsible for any property damage resulting from the presence of mold, mildew, and other fungi. The Company is not responsible for personal or property damage resulting from the disruption or dispersal of mold spores during inspection.

The Company also is not qualified to and does not render an opinion regarding potential human health risks or effects on the body that may result from exposure to mold, mildew, or other fungi. Human exposure to mold, mildew, or other fungi can be enhanced anytime structural components are disturbed through remediation of pest-related problems, simple repairs, remodeling, renovation, rehabilitation, etc. Questions concerning health-related issues, the presence of mold, the release of mold spores, or indoor air quality should be directed to a qualified professional.

By executing this work authorization Service Agreement, client acknowledges that he or she has been advised of the forgoing and has had the opportunity to consult with a qualified professional.

Licensed and regulated by the Texas Department of Agriculture P.O. Box 12847, Austin, TX 78711-2847 • 866-918-4481 • FAX 888-232-2567 X Client's Initial Page 1 of 3

D. LIMITED EFFECTIVE RESIDUAL OF TERMITICIDES: According to research data, as well as our own experience, applied liquid termiticides begin a deterioration process. Though variable, depending on a multitude of circumstances, eventually this deterioration results in a less than effective barrier. Thusly, we will eventually recommend substantial supplemental or even retreatment. Failure to allow such appropriate retreatment and payment accordingly may be cause for termination of this Agreement.

E. CLIENT UNDERSTANDING OF TREATMENT: The Client understands that while the Company will work to control or prevent Eastern (*Reticulitermes* spp.) and Formosan (*Coptotermes* spp.) Subterranean Termites, the complete elimination or prevention of termites may not be possible due to known or unknown structural flaws in and/or conducive conditions on the Client's property. See Paragraph F for list of conducive conditions.

F. CLIENT COMMITMENT AS TO CONDITIONS CONDUCIVE TO INFESTATION: The Client warrants full cooperation with the Company throughout the term of this Agreement and agrees to maintain structure(s) and the property surrounding the covered structure(s) free of conducive conditions to the extent possible such as, but not limited to: cracks in the slab (s), loose wood, trash, lumber, direct wood-to-soil contact; high soil, excessive standing water beneath and/or around structures and/or other poor drainage; and agrees to maintain the covered structure(s) free of decayed wood, faulty plumbing, condensation problems, roof leaks, faulty gutters, faulty downspouts, unsealed exterior building materials, misdirected sprinkler systems, and any other moisture conditions which could contribute to Eastern (*Reticulitermes* spp.), Formosan (*Coptotermes* spp.) Subterranean Termites or other wood destroying insect infestations. Furthermore client agrees to adhere to recommendations of making areas accessible for inspection or treatments such as removal of specific areas to expose any possible hidden conducive conditions, moisture problems, carton nests or damaged structural members. Removal and replacement of suggested structural materials will be solely at client's expense. Any sustained or periodic above ground moisture can support termite colonies above ground (known as "suspended colonies") - a condition for which the Company is not responsible. Failure to promptly correct any conducive condition(s) may be cause for immediate termination of this Agreement.

G. ACCESS TO PROPERTY: So long as Agreement is in effect, Client shall provide Company prompt access to property for any necessary services, re-servicing and any necessary inspections. Failure to allow the Company prompt property access may be cause for immediate termination of this Agreement.

H. ADDITIONS, ALTERATIONS AND OTHER CHANGES: This Agreement covers the structure(s) identified herein as of the date of enactment of this Agreement. The Client will immediately notify the Company prior to (1) the structure(s) being structurally modified, altered, added on to or otherwise changed; or (2) the foundation being modified in any manner; or (3) soil and/or plantings within three feet of structure foundation being removed, replaced, added to or modified in any manner. Additional services required by the Company because of any such actions shall be solely at the Client's expense and may require an adjustment in the annual renewal fee. Failure of such notification to the Company by the Client or failure by Client to permit needed additional services may cause immediate termination of this Agreement.

I. WORKMANSHIP: While performing any work under this Agreement, the Company will exercise due care to avoid damaging any part of Client's property or plants. To better access certain structures for appropriate service, the Client may have to remove, temporarily or permanently, soil, plants, vines, equipment, or piping. Client further agrees to inform the Company in advance, of any known structural piping, cables, conduit, or other physical conditions or circumstances in, on, around or beneath areas of the property to be treated. The Company is not responsible for damage during treatment, re-treatments, or inspections to the above listed items if the item was known and not previously brought to the Company's attention. Repair for such damaged items will be solely at Client's expense.

J. RELEASE AND INDEMNITY: THE CLIENT EXPRESSLY RELEASES AND INDEMNIFIES THE COMPANY FROM ANY CLAIM OR LOSS RESULTING FROM THE CLIENT'S FAILURE TO PROVIDE ADVANCE NOTICE OF OR REMOVE THE CONDITIONS OUTLINED IN PARAGRAPH E and H.

UNDER NO CIRCUMSTANCES SHALL THE COMPANY BE LIABLE FOR, AND THE CLIENT EXPRESSLY RELEASES THE COMPANY FROM OBLIGATIONS TO REPAIR ANY PAST, PRESENT, OR FUTURE DAMAGES CAUSED BY TERMITES, OTHER WOOD DESTROYING INSECTS, DECAY, OR ANY INCIDENTAL DAMAGES OR CONSEQUENTIAL DAMAGES, INCLUDING LOSS OF INCOME, LOSS OF TIME, LOST SALES, LIABILITY TO THIRD PARTIES, OR ANY OTHER ECONOMIC LOSS, OR ANY OTHER COSTS OR EXPENSES, INCURRED BY THE CLIENT AS A RESULT OF SUCH DAMAGE.

K. **PROPERTY OWNERSHIP SALE/TRANSFER:** In the event the property subject to this Agreement is sold or ownership transferred, the following applies:

- (1) This Agreement shall immediately terminate.
- (2) Any interest by new owner in negotiating an Agreement would be solely at the discretion of the Company.
- (3) Any prepaid service fees shall not be reimbursed.

L. CAUSES FOR CANCELLATION DURING AGREEMENT TERM: The Company reserves the right to cancel this Agreement without notice during the Agreement term for any of the following reasons:

- (1) Failure to timely pay annual renewal fee (paragraph A).
- (2) Failure to allow needed prompt access to property (paragraph G).
- (3) Failure to correct conducive conditions (paragraph F).
- (4) Failure to timely notify the Company of additions, alterations or other changes (paragraph H).
- (5) Failure to comply with additional retreatment recommendations (paragraph D).
- (6) Transfer of ownership (paragraph K).

NOTE: For any "Cause for Cancellation" as outlined above, there would be no reimbursement of any prepaid service fees.

X Client's Initial: Page 2 of 3

M. RENEWAL: This one year Agreement can be renewed annually up to (9) times after the expiration of the initial one year period by mutual consent of the Client and Company. Under no circumstances will this current Agreement extend past the initial one year period plus nine (9) consecutive annual renewals.

N. CANCELLATION AT RENEWAL: Both the Client and the Company shall have the option to cancel Agreement without cause at the end of the initial one year period or the end of any one year renewal period.

O. ORAL STATEMENTS: The oral statements of employees, representatives, or agents of the Company do not constitute warranties. The employees, representatives, or agents of the Company are not authorized to make warranties concerning the services described in this Agreement. Any such oral statements shall not be relied upon by the Client and are not part of this Agreement.

P. REMEDY/DISCLAIMER OF WARRANTIES: The Company's sole responsibility is to furnish the services, described above and to exercise due care in providing those services. If a problem or defect arises with the service, the Client's sole remedy is retreatment during the Agreement period. THE COMPANY DISCLAIMS ANY OTHER WARRANTY OR GUARANTEE, EXPRESSED OR IMPLIED, WITH RESPECT TO THE SERVICES TO BE FURNISHED UNDER THIS AGREEMENT.

Q. DISPUTE SOLVING: It is agreed between the Client and the Company that any controversy or dispute arising between the parties shall earnestly be dealt with by Client and Company for resolution.

R. CHEMICAL SENSITIVITY: If Client or other occupants of the structure(s) or adjacent buildings believe they are or may be sensitive to pesticides/termiticides or their odors, Client must notify Company in writing, in advance of treatment, including whether Client or other occupants have consulted with a medical doctor or other healthcare provider regarding such sensitivity. Company reserves the right, upon receipt of such notification, to deny or terminate service. Failure to provide notification represents Client's assumption of risk and waiver of any claims against Company in connection with such sensitivity.

S. AUTHORITY OF UNDERSIGNED PARTIES: If the Client is not an individual, the person signing below is an authorized representative of the Client and executes this Agreement on behalf of the Client. The Client warrants that the Client is the owner of the property. The person executing this Agreement on behalf of the Company is signing on behalf of the Company.

T. WRITTEN AGREEMENT: This document contains the entire Agreement between the Client and the Company. Its terms are contractual, not mere recitals. It may not be amended, altered, modified or changed in any way except by agreement in writing by the Company and the Client. If any provision of the Agreement is or may be held by a court of competent jurisdiction to be invalid, void, or unenforceable, the remaining portions shall nevertheless survive and continue in full force and effect without being impaired or invalidated in any way.

I HAVE COMPLETELY READ THIS AGREEMENT. BILL CLARK PEST CONTROL, INC. HAS ANSWERED ALL MY QUESTIONS ABOUT THIS AGREEMENT.

X Client: (or Authorized Representative)

Company: <u>Sull</u>

Date: 4-12-

Date: 3-16-2022

THIS REPORT IS NOT VALID FOR USE IN REAL ESTATE TRANSACTIONS

got pests?		WORK ORDER	
BULL CLARK UGSPERTS SINCE 1957	BEAUMONT OR (409) 898-3224 886	. P.O. BOX 5511 BEAUMONT, TEXAS 77 ANGE PORT ARTHUR NEDERLAND 6-2828 985-5700 727-7575 800-924-7072 FAX: (409) 899-5454	726-5511 JASPER 384-8855 BBB.
We've Got The Answers	I Contraction of the second		ACCREDITED BUSINESS
CEDVICE ADDRESS /28	o Austin ha		4 - 2
SERVICE ADDRESS 73 2	<u>Street</u>	m <u>brange</u> City vner's Phone #'s <u>409- 960-24</u>	<u>746.36</u> Zip Code
Owner's Name <u><i>Urt Tari</i></u>	NEM OV	vner's Phone #'s <u>409-920-24</u>	.66
Owner's Mailing Address			
Contact's Name	Street Co	City City	Zip Code
	allow Bill Clark Pest Co	□ Termistops at slab penetrations □ Termin □ Wood treatments □ Soil treatment of perimeter before any	eatments with termiticides
POST TREATMENT: The fo	llowing checked box rej	present the type of service that is to be perform	ned.
PARTIAL TREATMENT	F —Treatment of the foll	lowing area(s): <u>Perimeter Soil</u>	to slab Contacts.
One-vear DETDEATMEN	NT ONT V SERVICE A	GREEMENTrenewable annually.	
□ PARTIAL LIMITED TR	EATMENT—By client	t request, only the following areas will be treat	ted:
annually. There may be ad	ljacent area(s) susceptibl	EATMENT ONLY and ONLY for the area(s) le to termite infestations which are not treated the following area(s) of less than 10 linear or	
There may be adjacent area	(c) succentible to termit	. NO GUARANTEE IS GIVEN	FOR A SPOT TREATMENT.
	-	TION—One year Service Agreement—renev	vahle annually
			-
\Box LIQUID TREATMENT V	WITH TARPAULIN F	UMIGATION —One year Service Agreemen	t—renewable annually.
ANY OTHER W	OOD DESTROYING	IDE FOR THE REPAIR OF DAMAGE CA INSECT.	AUSED BY TERMITES OR
TREATMENT FO			
nitial 📃 🗹 Subterranean	•		· · · · · · · · · · · · · · · · · · ·
nitial 📃 🗹 Subterranean	ermites (Coptotermes spp	D.)	· · · · · · · · · · · · · · · · · · ·
nitial Subterranean	ermites (<i>Coptotermes</i> spp	D.)	· · · · · · · · · · · · · · · · · · ·
re-Construction Treatment	sermites (<i>Coptotermes</i> spp	D.)	· · · · · · · · · · · · · · · · · · ·
nitial Z Subterranean E Formosan Ter re-Construction Treatment	srmites (<i>Coptotermes</i> spp <u> <u> </u> <u> </u></u>	 D.) Beetles/Borers, (Specify) TREATMENT COST Method of Payment Inspection Date	· · · · · · · · · · · · · · · · · · ·
nitial Subterranean Formosan Ter re-Construction Treatment	strmites (Coptotermes spp $\frac{5}{64325}$ 5325	 D.) Beetles/Borers, (Specify) TREATMENT COST Method of Payment Inspection Date Service Scheduled Date 	· · · · · · · · · · · · · · · · · · ·
nitial Subterranean Pre-Construction Treatment	semites (Coptotermes spp $\frac{643}{53}$ $\frac{53}{696}$ $\frac{53}{696}$ $\frac{53}{696}$	 D.) Beetles/Borers, (Specify) TREATMENT COST Method of Payment Inspection Date Service Scheduled Date Annual Renewal Fee	$\frac{145 \circ^2}{(\text{Plus Tax})}$
Initial Subterranean Formosan Ter Pre-Construction Treatment	semites (Coptotermes spp $\frac{5}{643}$ $\frac{5}{53}$ $\frac{5}{696}$ $\frac{5}{696}$ $\frac{5}{10.768}$ $\frac{5}{10.768}$	 D.) Beetles/Borers, (Specify) TREATMENT COST Method of Payment <u>olloct</u> Inspection Date Service Scheduled Date Annual Renewal Fee 	\$ 1750°

P.O. Box 12847 • AUSTIN, TEXAS 78711-2847 Phone: 866-918-4481 • Fax: 888-232-2567 

THIS REPORT IS NOT VALID FOR USE IN REAL ESTATE TRANSACTIONS

Subterranean Termite Post-Construction Treatment Disclosure

(Mold, Mildew or other Fungi are not covered by this treatment)

WARRANTY information provided includes the complete details any warranty provided and the following:

- Time Period of the Warranty
- Renewal Options and Cost
- ♦ Obligations of the Contracting Parties
- Conditions that could develop which void the warranty.
- ♦ Name of the pest control company responsible for the warranty.

If the warranty does not include the entire structure treated, the areas included in the warranty are: (specify)

A label of Termicolor 80 WG (s) is enclosed.
The concentration of the termiticide(s) to be applied at this location is $D_{\circ}D6\overline{2}6$
Areas of Present Termite Activity
Areas to be treated, drilled, rodded, trenched or baited Soil Parimeter.
Type of Construction Type of Treatment
Type of treatment [] Pier & Beam [/ Partial [] Baits [] Physical Barriers
(Refer to Definition of Treatment) [] Slab [] Spot [] Other (specify)
Approximate Measurements of the Structure(s) to be treated $\frac{1872.F}{1872.F}$
Name: Mat Turner
Address: 1328 Buckingham
City: Orange State: Terfac Zip: 77632
I have received a copy of this disclosure statement along with the graph consumer information sheet and the pesticide label.
Biller Martin 0560768 Filly J. Martin 3-16-22
Signature of Certified Applicator I.D./C.A. # Printed Name Date
or Technician Completing Estimate Bill Clark Pest Control Inc. #166 X / 11-1 / 12-22
Name of Pest Control Company TPCL. No. Chent or Authorized Person Date

NOTICE OF CANCELLATION

You may cancel this transaction, without any penalty or obligation, within three business days from the transaction date.

If you cancel, any payments made by you under the contract or sale, and any negotiable instrument executed by you will be returned within 10 days following receipt by the seller of your cancellation notice.

To cancel this transaction, mail or deliver a signed and dated copy of this cancellation notice or any other written notice, or send a telegram.

TO: Bill Clark Pest Control, Inc. P.O. Box 5511 Beaumont, Texas 77726-5511

not later than midnight of

I hereby cancel this transaction:

Date

Client or Authorized Person

	Occupant	Date <u>3-16-86</u>
iting Address <u>1388 Guck</u>	ingham City Orange	Date <u>3 -16-88</u> State <u>Types</u> Zip <u>7763</u> Inspected By DUSH'n Boone
ne Phone 920-2666	_ Business Phone	Inspected By Dustin Boonc
□ Active □ Previous □ Drywood Termite □ Subterranean Termite nary Use: v Residence □ Co e of Construction: □ Crawl S e of Foundation: ☑ Concrete e of Siding: ☑ Brick □ Wood	A Uvood Boring Beetle P Specify D Carpenter Ants Carpenter Ants Number of Carpenter Ants D Visible Damage mmercial D Public Bldg. D Other pace Monolithic Slab D Floating Hollow Block D Brick D Stor Stone D Metal D Viny! D O	B □ Excessive MoistureM H □ Cracks in Slab

5/13



BILLCLARKBUGSPERTS.COM

2975 N. 11 TH ST. · P.O. BOX 5511 · BEAUMONT, TEXAS 77726-5511 BEAUMONT ORANGE PORT ARTHUR NEDERLAND JASPER (409) 898-3224 886-2828 985-5700 727-7575 384-8855 OTHER AREAS: 1-800-924-7072 FAX: (409) 899-5454 TPCL#166

INSPECTION REPORT

This Is Not A Structural Damage Report, Not A Mold, Mildew Or Other Fungi Inspection Report, Nor A Warranty As To The Absence Of Wood Destroying Insects

CLIENT NAME: Art Turner

SERVICE ADDRESS: 1328 Buckingham Dr Orange, TX 77632 United States

This inspection report covers only the structure(s) listed below:

Home and garage

A. Scope of Inspection:

- (1) This report is based on our visual findings at the time of this inspection and may vary from other periodic reports due to weather, moisture, drought and other variable conditions.
- (2) Due to the characteristics and behavior of various wood destroying insects, it may not be possible to determine the presence of infestation or damage without defacing or removing parts of the structure being inspected.
- (3) Due to the habits of some wood destroying insects and the fact that most slab foundations will eventually have some cracks, all structures in our area are conducive to infestations and may require alternative treatment methods.
- (4) Damage that has been concealed or that has been repaired (partially or completely) may not be visible except by defacing the surface appearance.
- (5) If visible evidence of active or previous infestation of any wood destroying insects is reported, it should be assumed that some degree of damage has occurred.
- (6) If visible evidence of wood destroying insect damage is reported, it does not necessarily imply that the damage should be repaired or replaced. Our inspectors are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified person.
- (7) This property is not inspected for the presence or absence of health related mold, mildew or other fungi. We are neither qualified, authorized nor licensed to inspect for health related mold, mildew or other fungi. If you desire information about the presence or absence of health related mold, mildew or other fungi, you should contact an industrial hygienist specializing in this field.

B. Bath Trap Door(s):

N/A	# present	# not present	2	# accessible	# not accessible	2	(Refer to C. #30 and any references.)

C. Conducive Conditions:

Conducive conditions to wood destroying insect infestation(s) observed at the time of this inspection include but are not limited to the following (Refer to A. #1 above.):

- (1) [] Planter box abutting structure(s) () No recommendations at this time
 - () Remove plants and soil from inside planter. () Remove planter box: Location_
- (2) [] Wooden deck against structure(s) () No recommendations at this time
- () Need at least 1 in. from structure
- (3) [] Wooden fence in contact with structure(s) () No recommendations at this time
- () Need at least 2 in. from structure
- (4) [] Dirt filled porch/steps () No recommendations at this time
- () Remove soil from beneath
- (5) [] Debris under or within 3 ft. of structure(s)
 - () Remove debris from structure: Location_
- (6) [] Wood to ground contact
- () Remove wood to ground contact: Location_

(7) [] Bark mulch in flower beds within 1 ft. of structure(s) () No recommendations at this time
 () Remove away from structure at least 1 ft.: Location______

- (8) [] Woodpile, stumps, etc. within 3 ft. of structure(s) () No recommendations at this time
- () Remove wood pile, stump, etc.: Location
- (9) [] Heavy foliage within 1 ft. of structure(s) () No recommendations at this time
- () Remove and/or trim back from structure at least 1 ft.: Location_
- (10) [] Form boards or grade stakes left in place () No recommendations at this time
 - () Remove formboard, grade stakes, etc.: Location____

Licensed and regulated by: Texas Department of Agriculture P.O. Box 12847, Austin, TX 78711-2847 Phone (866) 918-4481 FAX (888) 232-2567

X Client's Initials:

Date: 04/12/2022

() Remove poor or set post on concrete pade: Location (2) I Wood flooring over slab: Location (3) XC cract(s) in slab(s) (QN No recommendations at this time (4) XC construction/expansion joint(s) in slab(s) (14) XC construction/expansion joint(s) in slab(s) (15) I TERIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location (16) I Soil grade too high on slab () No recommendations at this time (17) I Coort below grade () No recommendations at this time (18) I Cortor below grade () No recommendations at this time (19) I Coortor below grade () No recommendations at this time (10) Location: (17) I Excessive moisture () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location Location (18) I Unsealed exterior building materials () No recommendations at this time () Repair, replace and/or seal: Location/Area Location (19) I Condensation problems () Repair, replace and/or seal: Location/Area Location () Repair, replace and structure(s) () No recommendations at this time Repair, replace and structure(s) () No recommendations a	(11)	[]	Wood post or girder in or through slab () No recommendations at this time
 () Remove wood over slab: Jocation (13) XCrack(s) in slab(s) (y) No recommendations at this time () Repair crack or slab: Location () No treated, recommend treatment: Location () INTERIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location () INTERIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location () EXTERIOR () Previously treated, no recommendation at this time () Lover soil to expose at least 2 in. of slab and/or place a barrier 6 in. from structure to retain the soil. Also may refer to C-20. Location; (16) [) Footer below grade () No recommendations at this time () Lover soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location (17) [] Excessive moisture () Repair/Correct: Cause () Repair/replace; Cause () Repair/replace; Cause () Repair/replace; Cause () Location () Repair/replace; Cause () No recommendations at this time () Repair/replace; Cause () Location () Repair/replace; Cause () Location () Poor drainage around structure(s) () No recommendations at this time () Repair/replace; Cause () Location () Repair, replace on structure(s) () Repair, replace or instal at least 2 ft. extensions: Location () Repair, replace or instal at least 2 ft. of structure(s) () Repair or place; Location/Area () Repair or place; Location/Area () Repair or place; Location (Area () Repair or replace instal at least 2 ft. of structure(s) () Repair oreplace; Location (Area () Repair or replace; Loc		()	Remove post or set post on concrete pad: Location
 (13) K. Crack(s) in slab(s) (X) No recommendations at this time (Repair crack or slab: Location (14) K. Construction/expansion joint(s) in slab(s) (15) I. Soil grade too high on slab () No recommendation. () Not treated, recommend treatment: Location (15) I. Soil grade too high on slab () No recommendations at this time (16) Lower soil to expose at least 2 in, of slab and/or place a barrier 6 in. from structure to retain the soil. Also may refer to C-20. Location: (16) I. Footer below grade () No recommendations at this time (17) I. Excessive moisture (18) Lower soil to expose 2 in of foundation and maintain this level. Also refer to C-20. Location (19) I. Excessive moisture (10) Repair/Correct: Cause (10) No recommendations at this time (11) Unsealed exterior building materials () No recommendations at this time (18) I. Unsealed exterior building materials () No recommendations at this time (19) I. Condensation problems (19) Repair/Correct: Cause (20) I. Poor drainage around structure(s) () No recommendations at this time (21) I. Poor drainage around structure(s) () No recommendations at this time (22) I. Faulty gutters on structure(s) (23) I. Faulty gutters to action (24) I. Repair, replace or install gutters: Location (25) I. Repair, replace or install at least 2 f. extensions: Location (23) I. Faulty downspoulds on structure(s) (24) I. Mustification structure(s) (25) I. Insufficient ventilation in crawl space(s) (24) I. Mustification structure(s) (25) I. Insufficient ventilation in crawl space(s) (26) Repair or replace: Location (27) I. Leaky price systems within 3 f. of structure(s) (28) I. Replace or install at least 2 f. extensions: Location (27) I. Leaky price systems within 3 f. of structure(s) (28) I. Replace or replace	(12)	[]	Wood flooring over slab () No recommendations at this time
 (14) X Construction/expansion joint(s) in slab(s) (15) INTERIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location		()	Remove wood over slab: Location
 (14) X Construction/expansion joint(s) in slab(s) (15) INTERIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location	(13)		Crack(s) in slab(s) (χ) No recommendations at this time
 (14) X Construction/expansion joint(s) in slab(s) NTERIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location (15) X ETERIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location (16) X ETERIOR () Previously treated, no recommendations at this time () Lower soil to expose at least 2 in. of slab and/or place a barrier 6 in. from structure to retain the soil. Also may refer to C-20. Location (16) I Footer below grade () No recommendations at this time () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location (17) I Excessive moisture () Repair/Correct: Cause () Location (18) I Unsealed exterior building materials () No recommendations at this time () Repair/Correct: Cause () Repair/Correct: Cause () Door drainage around structure(s) () No recommendations at this time () Drain water away from structure(s) () No recommendations at this time () Drain water away from structure(s) () Drain water from beneath and away from structure () Drain water from beneath and away from structure () Repair, replace: adorize or install gatters: Location () Repair, replace: clocation () Repair, replace: clocation/area () Repair preplace: Location/area () Repair preplace: Location/area () Repair preplace: Location/area () Repair or replace: Location/area () Repair preplace: Location/area () Repair preplace: Location/Area () Replace or replace: Location/Area () Replace or replace: Location/Area () Replace or replace: Location/Area () Replace or rep		$\left(\right)$	Repair crack or slab: Location
NTFRIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location (N) EXTERIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location (15) I Soil grade too high on slab () No recommendations at this time () Lower soil to expose at least 2 in. of slab and/or place a barrier 6 in. from structure to retain the soil. Also may refer to C-20. Location (16) I 7) I Excessive moisture () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location (17) I Excessive moisture () Repair/Correct: Cause Location (18) I Unscaled exterior building materials () No recommendations at this time () Repair/replace: Cause Location (20) I Poor drainage around structure(s) () No recommendations at this time () Drain water away from structure: Location (21) I Faulty gutters on structure(s) () Drain water from beneath and away from structure(s) () Drain water from beneath and away from structure(s) () Repair, replace or install a least 2 ft. extensions: Location (21) I Faulty gutters on structure(s)	(14)	ĪVĪ	
(X) EXTERIOR № Previously treated, no recommendation. () Not treated, recommend treatment: Location (15) [1] Soil grade too high on slab () No recommendations at this time (16) [1] Footer below grade () No recommendations at this time (16) [1] Footer below grade () No recommendations at this time (16) [1] Footer below grade () No recommendations at this time (17) [1] Excessive moisture (18) [1] Unsealed exterior building materials () No recommendations at this time (18) [1] Unsealed exterior building materials () No recommendations at this time (18) [1] Unsealed exterior building materials () No recommendations at this time (19) [1] Condensation problems Location (19) [1] Condensation and structure(s) () No recommendations at this time Poor drainage around structure(s) (20) [1] Poor drainage around structure(s) [1] Poor drainage around structure(s) (21) [1] Fourty gutters on structure(s) [2] [2] (22) [1] Fourty gutters on structure(s) [2] [2] (23) [1] Fourty g		(
 (15) [1] Soil grade too high on slab () No recommendations at this time () Lower soil to expose at least 2 in. of slab and/or place a barrier 6 in. from structure to retain the soil. Also may refer to C-20. Location: (16) [1] Footer below grade () No recommendations at this time () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location (17) [1] Excessive moisture () Repair/Correct: Cause Location (18) [1] Unsealed exterior building materials () No recommendations at this time () Repair/replace and/or seal: Location/Area (19) [1] Condensation problems () Repair/replace: Cause Location/Area (20) [1] Poor drainage around structure(s) () No recommendations at this time () Drain water away from structure(s) () Drain water from beneath and away from structure () Tain water from beneath and away from structure () Repair, replace or install gutters: Location (21) [1] Faulty gutters on structure(s) () Repair, replace or install gutters: Location (22) [1] Faulty gutters on structure(s) () Repair, replace or install gutters: Location (23) [1] Faulty gutters: Location/Area (24) [1] Wood decay () No recommendations at this time () Repair, replace co install at least 2 ft. extensions: Location (24) [1] Mudirected sprisher systems within 3 ft. of structure(s) () Add/move openings oversts: Location (26) [1] Insufficient ventilation in crawl space(s) () Add/move openings oversts: Location (27) [1] Leaky pipe system () Use no more than necessary. Turn off 3 three days prior to a treatment. (28) [1] Roof leaks () Repair replace: Location/Area () No recommendations at this time () Repair or replace: Location/Area () Use no more than necessary. Turn off 3 three days prior to a treatment. () Replace or replace: Location/Area () Replace or		()	
 (15) [1] Soil grade too high on slab () No recommendations at this time () Lower soil to expose at least 2 in. of slab and/or place a barrier 6 in. from structure to retain the soil. Also may refer to C-20. Location: (16) [1 Footer below grade () No recommendations at this time () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location (17) [1 Excessive moisture () Repair/Correct: Cause Location (18) [1 Unsealed exterior building materials () No recommendations at this time () Repair/replace: Cause Location/Area (19) [1 Condensation problems () Repair/replace: Cause Location/Area (20) [1 Poor drainage around structure(s) () No recommendations at this time () Drain water away from structure(s) () Drain water away from structure(s) () Repair, replace or install gutters: Location. (21) [1 Faulty gutters on structure(s) () Repair, replace or install at least 2 ft. extensions: Location. (22) [1 Faulty gutters: Location/Area (23) [1 Faulty gutters: Location/Area (24) [1 Wood decay () No recommendations at this time () Repair, replace ci notisul at least 2 ft. extensions: Location. (23) [24) [25] [26] [26] [26] [26] [26] [26] [26] [26			EVTEDIOD AA Deviewele tereted as assume addies () Net tereted assume address to entry
 Lower soil to expose at least 2 in. of slab and/or place a barrier 6 in. from structure to retain the soil. Also may refer to C-20. Location: [1] Footer below grade () No recommendations at this time () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location [1] Excessive moisture () Repair/Correct: Cause [2] Location problems () Repair/replace and/or seal: Location/Area [2] [Condensation problems () Repair/replace: Cause [2] Location [2] Poor drainage around structure(s) () No recommendations at this time () Repair/replace: Cause [3] [Vater beneath and/or around structure(s) () Naver away from structure: Location [4] [Water beneath and/or around structure(s) () Repair, replace or install guitters: Location [5] [Faulty downspouts on structure(s) () Repair, replace or install guitters: Location [6] [Faulty downspouts on structure(s) () Repair, replace or install guitters: Location [7] [Wood decay () No recommendations at this time () Repair, replace or install guitters: Location [8] [] Faulty downspouts on structure(s) () Repair, replace or install structure(s) () Repair, replace: Location/Area [2] [] Faulty downspouts on structure: Location [2] [] Redirect water away from structure: Location [2] [] Readifier expression () Redirect water away from structure: Location [2] [Redirect water away from structure: Location [2] [Really plumbing () No recommendations at this time () Redirect water away from structure: Location [2] [Really plumbing () No recommendations at this time () Repair or		Ŵ	EXTERIOR (X) Previously realed, no recommendation. () Not realed, recommend realment. Location
 Lower soil to expose at least 2 in. of slab and/or place a barrier 6 in. from structure to retain the soil. Also may refer to C-20. Location: [1] Footer below grade () No recommendations at this time () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location [1] Excessive moisture () Repair/Correct: Cause [2] Location problems () Repair/replace and/or seal: Location/Area [2] [Condensation problems () Repair/replace: Cause [2] Location [2] Poor drainage around structure(s) () No recommendations at this time () Repair/replace: Cause [3] [Vater beneath and/or around structure(s) () Naver away from structure: Location [4] [Water beneath and/or around structure(s) () Repair, replace or install guitters: Location [5] [Faulty downspouts on structure(s) () Repair, replace or install guitters: Location [6] [Faulty downspouts on structure(s) () Repair, replace or install guitters: Location [7] [Wood decay () No recommendations at this time () Repair, replace or install guitters: Location [8] [] Faulty downspouts on structure(s) () Repair, replace or install structure(s) () Repair, replace: Location/Area [2] [] Faulty downspouts on structure: Location [2] [] Redirect water away from structure: Location [2] [] Readifier expression () Redirect water away from structure: Location [2] [Redirect water away from structure: Location [2] [Really plumbing () No recommendations at this time () Redirect water away from structure: Location [2] [Really plumbing () No recommendations at this time () Repair or	(15)	r ı	Soil grade too high on slab () No recommendations at this time
Location: (16) I Footer below grade () No recommendations at this time () Lower soil to expose 2 in of foundation and maintain this level. Also refer to C-20. Location (17) I Excessive moisture () () Repair/Correct: Cause Location () Repair, replace and/or seal: Location/Area	(13)		
 (16) [] Footer below grade () No recommendations at this time () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location () Repair/Correct. Cause Location () No recommendations at this time () Repair/replace and/or seal: Location/Area () Repair/replace: Cause Location () Repair/replace: Cause Location () Repair/replace: Cause Location () Repair/replace: Cause Location () Poor drainage around structure(s) () No recommendations at this time () Drain water away from structure(s) () No recommendations at this time () Drain water from beneath and away from structure () Drain water from beneath and away from structure () Drain water from beneath and away from structure () Drain water from beneath and away from structure () Drain water from beneath and away from structure () Drain water foro monut structure(s) () Paulty gutters on structure(s) () Repair, replace or install gutters: Location (23) [] Faulty downspouts on structure(s) () Repair, replace or install gutters: Location (24) [] Wood decay () No recommendations: Location () Repair, replace or install at least 2 ft. extensions: Location () Repair or replace: Location/Area () Add/move openings or vents: Location () Add/move openings or vents: Location () Add/move openings or vents: Location () Redirect water away from structure: Location () Redirect water away from structure: Location () Redirect water away from structure: Location () Leaky pipe system () Leaky pipe system () Use no more than necessary. Turn off 3 three days prior to a treatment. () Repair or replace: Location/Area<td></td><td>()</td><td></td>		()	
 () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location	(10)	гı	
Location (17) Excessive moisture (18) Expair/Correct: Cause	(10)		
(17) [] Excessive moisture (18) [] Unsealed exterior building materials () No recommendations at this time (18) [] Unsealed exterior building materials () No recommendations at this time (19) [] Condensation problems (19) [] Condensation problems (19) [] Condensation problems (20) [] Poor drainage around structure(s) () No recommendations at this time (20) [] Poor drainage around structure(s) () No recommendations at this time (10) Drain water from beneath and away from structure (21) [] Faulty gutters on structure(s) (10) Drain water from beneath and away from structure (22) [] Faulty downspouts on structure(s) (11) Water beneath and or around structure (23) [] Faulty downspouts on structure(s) (11) Water beneath and away from structure (22) [] Faulty downspouts on structure(s) (23) [] Faulty downspouts on structure(s) (11) Wood decay () No recommendations at this time (23) [] Insufficient		()	
 Repair/Correct: CauseLocation Unsealed exterior building materials () No recommendations at this time Repair, replace and/or seal: Location/Area Condensation problems Repair/replace: CauseLocation Poor drainage around structure(s) () No recommendations at this time Drain water away from structure: Location Drain water from beneath and away from structure Braulty gutters on structure(s) Repair, replace or install gutters: Location Repair, replace or install gutters: Location Repair, replace or install gutters: Location Repair or replace: Location/Area	(17)	г 1	
(18) [1] Unsealed exterior building materials () No recommendations at this time (19) [1] Condensation problems (19) [1] Condensation problems (10) [1] Poor drainage around structure(s) () No recommendations at this time (20) [1] Poor drainage around structure(s) () No recommendations at this time (21) [1] Water beneath and/or around structure(s) (22) [1] Faulty gutters on structure(s) (23) [1] Faulty downspouts on structure(s) (23) [1] Faulty downspouts on structure(s) (23) [1] Faulty downspouts on structure(s) (24) [1] Wood decay () No recommendations at this time (25) [1] Insufficient ventilation in crawl space(s) (26) [1] Insufficient ventilation in crawl space(s) (27) [1] Leaky pipe system (28) [1] Insufficient ventilation in crawl space(s) (27) [1] Leaky pipe system (28) [1] Iselficient ventilation in crawl space(s) (29) [1] Kedirect water away from structure: Location	(17)	ĮĮ	
 () Repair, replace and/or seal: Location/Area	(10)	()	
(19) [] Condensation problems (1) Repair/replace: Cause Location (20) [] Poor drainage around structure(s) () No recommendations at this time (21) [] Water beneath and/or around structure(s) (1) Drain water from beneath and away from structure (22) [] Faulty gutters on structure(s) (23) [] Faulty downspouts on structure(s) (24) [] Kood decay () No recommendations: Location (23) [] Faulty downspouts on structure(s) () Repair, replace or install at least 2 ft. extensions: Location (24) [] Wood decay () No recommendations at this time () Repair or replace: Location/Area () Repair or replace: Location () Redirect water away from structure: Location () Redirect water aw	(18)	ĻŢ	
 () Repair/replace: CauseLocation	(1.0)	()	
 (20) [] Poor drainage around structure(s) () No recommendations at this time () Drain water away from structure: Location	(19)	ΙĮ	
 () Drain water away from structure: Location		()	
 (21) [] Water beneath and/or around structure(s) () Drain water from beneath and away from structure (22) [] Faulty gutters on structure(s) () Repair, replace or install gutters: Location	(20)	[]	
 () Drain water from beneath and away from structure (22) [] Faulty gutters on structure(s) () Repair, replace or install gutters: Location		()	
 (22) [] Faulty gutters on structure(s) () Repair, replace or install gutters: Location (23) [] Faulty downspouts on structure(s) () Repair, replace or install at least 2 ft. extensions: Location (24) [] Wood decay () No recommendations at this time () Repair or replace: Location/Area (25) [] Insufficient ventilation in crawl space(s) () Add/move openings or vents: Location (26) [] Misdirected sprinkler systems within 3 ft. of structure(s) () Redirect water away from structure: Location (27) [] Leaky pipe system () Use no more than necessary. Turn off 3 three days prior to a treatment. (28) [] Faulty plumbing () No recommendations at this time () Replace or repair: Location/Area (29) [] Roof leaks () Repair or replace: Location () Repair or replace: Location (29) [] Bath trap area(s) (Refer to B. above) () Need to install inspection door(s). How many: Location(s) () Need to make access by removing items: Location 	(21)	[]	
 () Repair, replace or install gutters: Location		()	
 (23) [] Faulty downspouts on structure(s) () Repair, replace or install at least 2 ft. extensions: Location	(22)	[]	Faulty gutters on structure(s)
 () Repair, replace or install at least 2 ft. extensions: Location		()	Repair, replace or install gutters: Location
 (24) [] Wood decay () No recommendations at this time () Repair or replace: Location/Area	(23)	[]	
 () Repair or replace: Location/Area		()	Repair, replace or install at least 2 ft. extensions: Location
 (25) [] Insufficient ventilation in crawl space(s) () Add/move openings or vents: Location (26) [] Misdirected sprinkler systems within 3 ft. of structure(s) () Redirect water away from structure: Location	(24)	[]	Wood decay () No recommendations at this time
 () Add/move openings or vents: Location		()	Repair or replace: Location/Area
 (26) [] Misdirected sprinkler systems within 3 ft. of structure(s) () Redirect water away from structure: Location	(25)	[]	Insufficient ventilation in crawl space(s)
 () Redirect water away from structure: Location		()	Add/move openings or vents: Location
 (27) [] Leaky pipe system () Use no more than necessary. Turn off 3 three days prior to a treatment. (28) [] Faulty plumbing () No recommendations at this time () Replace or repair: Location/Area	(26)	[]	Misdirected sprinkler systems within 3 ft. of structure(s)
 () Use no more than necessary. Turn off 3 three days prior to a treatment. (28) [] Faulty plumbing () No recommendations at this time () Replace or repair: Location/Area		()	Redirect water away from structure: Location
 () Use no more than necessary. Turn off 3 three days prior to a treatment. (28) [] Faulty plumbing () No recommendations at this time () Replace or repair: Location/Area	(27)	[]]	Leaky pipe system
 (28) [] Faulty plumbing () No recommendations at this time () Replace or repair: Location/Area		()	Use no more than necessary. Turn off 3 three days prior to a treatment.
 () Replace or repair: Location/Area	(28)	ÌÌ	
 (29) [] Roof leaks () Repair or replace: Location (30) [] Bath trap area(s) (Refer to B. above) () Need to install inspection door(s). How many: Location(s) () Need to make access by removing items: Location 		()	Replace or repair: Location/Area
 (i) Repair or replace: Location	(29)	ÌÌ	
 (30) [] Bath trap area(s) (Refer to B. above) () Need to install inspection door(s). How many: Location(s) () Need to make access by removing items: Location 		()	Denois or replace: Location
 () Need to install inspection door(s). How many: Location(s) () Need to make access by removing items: Location 	(30)	ìí	
() Need to make access by removing items: Location	(- •)	(Need to install inspection door(s). How many: Location(s)
		$\dot{()}$	
	(31)	ìì	
 (i) Need to repair (i) No recommendations at this time: Location(s): 	()	()	

(32) [] Wall voids () It is imperative that client or authorized person exposes wall void(s) in specified areas to identify possible hidden pest damage and or to facilitate treatment and removal of any unknown conducive conditions. Repair/reconstruction of any defaced areas of the property are not the responsibility of BCPC. Location(s):

(33)	ĺχ	This report discloses conditions that may be conducive to the growth of mold, mildew or other fungi. (Refer to A#7 o SCOPE OF INSPECTION).)f
(34)[]	Dther:	

() See Page(s)_____

X Client's Initials:

Page 2 of 3 01/18

Date: 04/12/2022

D. Recommendations for Correction(s) of Conducive Condition(s):

This may include structural modification, soil modification, treatment, no action or a combination thereof. Recommendations may be made by the Company to correct infestation(s), conducive condition(s) and/or inaccessible area(s) which may not be possible to do under existing condition(s). Some conducive conditions can not be corrected without creating other conducive conditions. Therefore, the Company accepts no responsibility for recommendation(s) made. It is the Client's sole decision for enactment. Any action(s) taken on the recommendations shall be solely at the Client's expense. Client should contact a qualified person(s) for corrections of conducive conditions.

E. Client Commitment As to Conditions Conducive To Infestations:

The Client agrees to cooperate with the Company throughout the term of the Agreement and agrees to maintain structure(s) and the property surrounding the covered structure(s) free of conducive conditions to the extent possible which could contribute to Subterranean Termites or other wood destroying insect infestations. Any sustained or periodic above ground moisture can support termite colonies above ground (known as "suspended colonies") - a condition for which the Company is not responsible. Failure to promptly correct any conducive condition(s) may be cause for immediate termination of this Agreement.

F. Obstructed And/Or Inaccessible Areas:

This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to areas concealed by wall coverings, furniture, equipment, stored articles and any portion of the structure in which inspection would necessitate removing or defacing any part of the structue(s) (including the surface appearance of the structure). Our inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work. Obstructed or inaccessible areas include but are not limited to the following:

(1) [] Attic (no access)	(9) [] Behind deck against structure(s)	(17) Slab(s) joint(s)
(2) [] Insulated area(s) of attic	(10) [] Behind planter box(s) abutting structure(s)	(18) Plumbing area(s)
(3) Eaves	(11) [] Foliage against structure(s)	(19) Bath trap area(s) (Refer to B.)
(4) Wall voids	(12) X Behind veneer	(20) Crawl space (no access)
(5) Beneath floor coverings	(13) Beneath thresholds	(21) [] Insufficient crawl space
(6) Soil grade too high	(14) Beneath or behind porches	(22) [] Sub floor beneath structure(s)
(7) [] Footer below grade	(15) [] Beneath or behind steps	(23) [] Voids in brick piers/fireplace(s)
(8) [] Weep holes in brick	(16) $[\mathbf{X}]$ Crack(s) in slab(s)	(24) [] Other (Specify below)
	A	
Specify (other):		() See Page(s)

Specify (other):

G. Inspection reveals visible evidence of wood destroying insects in or on the structure(s):

The structure(s) was specifically inspected for wood destroying insect(s) checked below:	Active Infestation A	Previous Infestation B	Insect Damage C	Treatment Recommended D
(1) X Subterranean Termites (Reticulitermes spp.)	Yes [] No X]	Yes [] No X]	Yes [] No X]	Yes [] No 🗶]
(2) X Formosan Termites (Copotermes spp.)	Yes [] No X]	Yes [] No X]	Yes [] No X]	Yes [] No 🙀]
(3) [] Drywood Termites	Yes [] No []	Yes [] No []	Yes [] No []	Yes [] No []
(4) [] Carpenter Ants	Yes [] No []	Yes [] No []	Yes [] No []	Yes [] No []
(5) [] Other Wood Destroying Insects (Specify below)	Yes [] No []	Yes [] No []	Yes [] No []	Yes [] No []
Specify (other):				

Description, location(s) and comments:

) See Page(s)

I have received a legible copy of this form and any referenced material which I have read and understand.

THIS REPORT IS NOT VALID FOR USE IN REAL ESTATE **TRANSACTIONS**

04/12/2022 Date

spector's Signature

04/12/2022

Page 3 of 3 01/18

OFFICE



BILLCLARKBUGSPERTS.COM

2975 N. 11 TH ST. · P.O. BOX 5511 · BEAUMONT, TEXAS 77726-5511 BEAUMONT ORANGE PORT ARTHUR NEDERLAND JASPER (409) 898-3224 886-2828 985-5700 727-7575 384-8855 OTHER AREAS: 1-800-924-7072 FAX: (409) 899-5454 TPCL#166

INSPECTION REPORT

This Is Not A Structural Damage Report, Not A Mold, Mildew Or Other Fungi Inspection Report, Nor A Warranty As To The Absence Of Wood Destroying Insects

CLIENT NAME: Art Turner

SERVICE ADDRESS: 1328 Buckingham Dr Orange, TX 77632 United States

This inspection report covers only the structure(s) listed below:

Home and garage

A. Scope of Inspection:

- (1) This report is based on our visual findings at the time of this inspection and may vary from other periodic reports due to weather, moisture, drought and other variable conditions.
- (2) Due to the characteristics and behavior of various wood destroying insects, it may not be possible to determine the presence of infestation or damage without defacing or removing parts of the structure being inspected.
- (3) Due to the habits of some wood destroying insects and the fact that most slab foundations will eventually have some cracks, all structures in our area are conducive to infestations and may require alternative treatment methods.
- (4) Damage that has been concealed or that has been repaired (partially or completely) may not be visible except by defacing the surface appearance.
- (5) If visible evidence of active or previous infestation of any wood destroying insects is reported, it should be assumed that some degree of damage has occurred.
- (6) If visible evidence of wood destroying insect damage is reported, it does not necessarily imply that the damage should be repaired or replaced. Our inspectors are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified person.
- (7) This property is not inspected for the presence or absence of health related mold, mildew or other fungi. We are neither qualified, authorized nor licensed to inspect for health related mold, mildew or other fungi. If you desire information about the presence or absence of health related mold, mildew or other fungi, you should contact an industrial hygienist specializing in this field.

B. Bath Trap Door(s):

N/A	# present	# not present	2	# accessible	# not accessible	2	(Refer to C. #30 and any references.)
-----	-----------	---------------	---	--------------	------------------	---	---------------------------------------

C. Conducive Conditions:

Conducive conditions to wood destroying insect infestation(s) observed at the time of this inspection include but are not limited to the following (Refer to A. #1 above.):

- (1) [] Planter box abutting structure(s) () No recommendations at this time
 - () Remove plants and soil from inside planter. () Remove planter box: Location_
- (2) [] Wooden deck against structure(s) () No recommendations at this time
- () Need at least 1 in. from structure
- (3) [] Wooden fence in contact with structure(s) () No recommendations at this time
- () Need at least 2 in. from structure
- (4) [] Dirt filled porch/steps () No recommendations at this time
- () Remove soil from beneath
- (5) [] Debris under or within 3 ft. of structure(s)
 - () Remove debris from structure: Location_
- (6) [] Wood to ground contact
- () Remove wood to ground contact: Location_

(7) [] Bark mulch in flower beds within 1 ft. of structure(s) () No recommendations at this time
 () Remove away from structure at least 1 ft.: Location_____

- (8) [] Woodpile, stumps, etc. within 3 ft. of structure(s) () No recommendations at this time
- () Remove wood pile, stump, etc.: Location
- (9) [] Heavy foliage within 1 ft. of structure(s) () No recommendations at this time
- () Remove and/or trim back from structure at least 1 ft.: Location_
- (10) [] Form boards or grade stakes left in place () No recommendations at this time
 - () Remove formboard, grade stakes, etc.: Location____

Licensed and regulated by: Texas Department of Agriculture P.O. Box 12847, Austin, TX 78711-2847 Phone (866) 918-4481 FAX (888) 232-2567

X Client's Initials:

Date:04/17/2023

() Remove poor or set post on concrete pade: Location (2) I Wood flooring over slab: Location (3) XC cract(s) in slab(s) (QN No recommendations at this time (4) XC construction/expansion joint(s) in slab(s) (14) XC construction/expansion joint(s) in slab(s) (15) I TERIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location (16) I Soil grade too high on slab () No recommendations at this time (17) I Coort below grade () No recommendations at this time (18) I Cortor below grade () No recommendations at this time (19) I Coortor below grade () No recommendations at this time (10) Location: (17) I Excessive moisture () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location Location (18) I Unsealed exterior building materials () No recommendations at this time () Repair, replace and/or seal: Location/Area Location (19) I Condensation problems () Repair, replace and/or seal: Location/Area Location () Repair, replace and structure(s) () No recommendations at this time Repair, replace and structure(s) () No recommendations a	(11)	[]	Wood post or girder in or through slab () No recommendations at this time
 () Remove wood over slab: Jocation (13) XCrack(s) in slab(s) (y) No recommendations at this time () Repair crack or slab: Location () No treated, recommend treatment: Location () INTERIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location () INTERIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location () EXTERIOR () Previously treated, no recommendation at this time () Lover soil to expose at least 2 in. of slab and/or place a barrier 6 in. from structure to retain the soil. Also may refer to C-20. Location; (16) [) Footer below grade () No recommendations at this time () Lover soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location (17) [] Excessive moisture () Repair/Correct: Cause () Repair/replace; Cause () Repair/replace; Cause () Repair/replace; Cause () Location () Repair/replace; Cause () No recommendations at this time () Repair/replace; Cause () Location () Repair/replace; Cause () Location () Poor drainage around structure(s) () No recommendations at this time () Repair/replace; Cause () Repair, replace and/or scal: Location () Poor drainage around structure(s) () No recommendations at this time () Repair, replace on instal gutters: Location () Repair, replace on instal gutters: Location () Repair, replace on instal gutters: Location () Repair, replace or instal at least 2 ft. extensions: Location () Repair, replace or instal at least 2 ft. extensions: Location () Repair or replace: Location/Area () Repair or replace: Location/Area () Repair or replace: Location/Area () Repair or replace: Location (Area Area) () Replate or replace: Location (Area) () R		()	Remove post or set post on concrete pad: Location
 (13) K. Crack(s) in slab(s) (X) No recommendations at this time (Repair crack or slab: Location (14) K. Construction/expansion joint(s) in slab(s) (15) I. Soil grade too high on slab () No recommendation. () Not treated, recommend treatment: Location (15) I. Soil grade too high on slab () No recommendations at this time (16) Lower soil to expose at least 2 in, of slab and/or place a barrier 6 in. from structure to retain the soil. Also may refer to C-20. Location: (16) I. Footer below grade () No recommendations at this time (17) I. Excessive moisture (18) Lower soil to expose 2 in of foundation and maintain this level. Also refer to C-20. Location (19) I. Excessive moisture (10) Repair/Correct: Cause (10) No recommendations at this time (11) Unsealed exterior building materials () No recommendations at this time (18) I. Unsealed exterior building materials () No recommendations at this time (19) I. Condensation problems (19) Repair/Correct: Cause (20) I. Poor drainage around structure(s) () No recommendations at this time (21) I. Poor drainage around structure(s) () No recommendations at this time (22) I. Faulty gutters on structure(s) (23) I. Faulty gutters to a structure(s) (24) I. Repair, replace or install and away from structure (25) I. Insufficient ventilation in crawl space(s) (24) I. Mustification structure(s) (25) I. Insufficient ventilation in crawl space(s) (24) I. Mustification space(s) (25) I. Insufficient ventilation in crawl space(s) (26) Repair, replace or install a least 2 f. extensions: Location (23) I. Faulty downspopulation structure(s) (24) I. Mustification space(s) (25) I. Insufficient ventilation in crawl space(s) (26) Repair or replace: Location/Area (27) I. Leaky pipe system (28) I. Faulty plumb	(12)	[]	Wood flooring over slab () No recommendations at this time
 (14) X Construction/expansion joint(s) in slab(s) (15) INTERIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location		()	Remove wood over slab: Location
 (14) X Construction/expansion joint(s) in slab(s) (15) INTERIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location	(13)		Crack(s) in slab(s) (χ) No recommendations at this time
 (14) X Construction/expansion joint(s) in slab(s) NTERIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location (15) X ETERIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location (16) X ETERIOR () Previously treated, no recommendations at this time () Lower soil to expose at least 2 in. of slab and/or place a barrier 6 in. from structure to retain the soil. Also may refer to C-20. Location (16) I Footer below grade () No recommendations at this time () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location (17) I Excessive moisture () Repair/Correct: Cause () Location (18) I Unsealed exterior building materials () No recommendations at this time () Repair/Correct: Cause () Repair/Correct: Cause () Door drainage around structure(s) () No recommendations at this time () Drain water away from structure(s) () No recommendations at this time () Drain water away from structure(s) () Drain water from beneath and away from structure () Drain water from beneath and away from structure () Repair, replace: adorize or install gatters: Location () Repair, replace: clocation () Repair, replace: clocation/area () Repair preplace: Location/area () Repair or replace: Location/Area () Replace or repairs: Location/Area () Replace or repairs: Location/Area () Replace or repair		$\left(\right)$	Repair crack or slab: Location
NTFRIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location (N) EXTERIOR () Previously treated, no recommendation. () Not treated, recommend treatment: Location (15) I Soil grade too high on slab () No recommendations at this time () Lower soil to expose at least 2 in. of slab and/or place a barrier 6 in. from structure to retain the soil. Also may refer to C-20. Location (16) I 7) I Excessive moisture () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location (17) I Excessive moisture () Repair/Correct: Cause Location (18) I Unscaled exterior building materials () No recommendations at this time () Repair/replace: Cause Location (20) I Poor drainage around structure(s) () No recommendations at this time () Drain water away from structure: Location (21) I Faulty gutters on structure(s) () Drain water from beneath and away from structure(s) () Drain water from beneath and away from structure(s) () Repair, replace or install a least 2 ft. extensions: Location (21) I Faulty gutters on structure(s)	(14)	ĪVĪ	
(X) EXTERIOR № Previously treated, no recommendation. () Not treated, recommend treatment: Location (15) [1] Soil grade too high on slab () No recommendations at this time (16) [1] Footer below grade () No recommendations at this time (16) [1] Footer below grade () No recommendations at this time (16) [1] Footer below grade () No recommendations at this time (17) [1] Excessive moisture (18) [1] Unsealed exterior building materials () No recommendations at this time (18) [1] Unsealed exterior building materials () No recommendations at this time (18) [1] Unsealed exterior building materials () No recommendations at this time (19) [1] Condensation problems Location (19) [1] Condensation and structure(s) () No recommendations at this time Poor drainage around structure(s) (20) [1] Poor drainage around structure(s) [1] Poor drainage around structure(s) (21) [1] Fourty gutters on structure(s) [2] [2] (22) [1] Fourty gutters on structure(s) [2] [2] (23) [1] Fourty g		(
 (15) [1] Soil grade too high on slab () No recommendations at this time () Lower soil to expose at least 2 in. of slab and/or place a barrier 6 in. from structure to retain the soil. Also may refer to C-20. Location: (16) [1] Footer below grade () No recommendations at this time () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location (17) [1] Excessive moisture () Repair/Correct: Cause Location (18) [1] Unsealed exterior building materials () No recommendations at this time () Repair/replace and/or seal: Location/Area (19) [1] Condensation problems () Repair/replace: Cause Location/Area (20) [1] Poor drainage around structure(s) () No recommendations at this time () Drain water away from structure(s) () Drain water from beneath and away from structure () Tain water from beneath and away from structure () Repair, replace or install gutters: Location (21) [1] Faulty gutters on structure(s) () Repair, replace or install gutters: Location (22) [1] Faulty gutters on structure(s) () Repair, replace or install gutters: Location (23) [1] Faulty gutters: Location/Area (24) [1] Wood decay () No recommendations at this time () Repair, replace co install at least 2 ft. extensions: Location (24) [1] Mudirected sprisher systems within 3 ft. of structure(s) () Add/move openings oversts: Location (26) [1] Insufficient ventilation in crawl space(s) () Add/move openings oversts: Location (27) [1] Leaky pipe system () Use no more than necessary. Turn off 3 three days prior to a treatment. (28) [1] Roof leaks () Repair replace: Location/Area () No recommendations at this time () Repair or replace: Location/Area () Use no more than necessary. Turn off 3 three days prior to a treatment. () Replace or replace: Location/Area () Replace or		()	
 (15) [1] Soil grade too high on slab () No recommendations at this time () Lower soil to expose at least 2 in. of slab and/or place a barrier 6 in. from structure to retain the soil. Also may refer to C-20. Location: (16) [1 Footer below grade () No recommendations at this time () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location (17) [1 Excessive moisture () Repair/Correct: Cause Location (18) [1 Unsealed exterior building materials () No recommendations at this time () Repair/replace: Cause Location/Area (19) [1 Condensation problems () Repair/replace: Cause Location/Area (20) [1 Poor drainage around structure(s) () No recommendations at this time () Drain water away from structure(s) () Drain water away from structure(s) () Repair, replace or install gutters: Location. (21) [1 Faulty gutters on structure(s) () Repair, replace or install at least 2 ft. extensions: Location. (22) [1 Faulty gutters: Location/Area (23) [1 Faulty gutters: Location/Area (24) [1 Wood decay () No recommendations at this time () Repair, replace ci constall at least 2 ft. extensions: Location. (23) [1 Insufficient ventilation in crawl space(s) () Add/move openings or vents: Location (24) [1 Kudificient ventilation in crawl space(s) () Add/move openings or vents: Location. (27) [1 Leaky pipe system () Use no more than necessary. Turn off 3 three days prior to a treatment. (28) [1 Ruely plumbing () No recommendations at this time () Repair replace: Location/Area (29) [1 Roof leaks () Repair replace: Location/Area () No recommendations at this time () Replace or replace. Location/Area ()			EVTEDIOD AA Deviewele tereted as assume addies () Net tereted assume address to entry
 Lower soil to expose at least 2 in. of slab and/or place a barrier 6 in. from structure to retain the soil. Also may refer to C-20. Location: [1] Footer below grade () No recommendations at this time () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location [1] Excessive moisture () Repair/Correct: Cause [2] Location problems () Repair/replace and/or seal: Location/Area [2] [Condensation problems () Repair/replace: Cause [2] Location [2] Poor drainage around structure(s) () No recommendations at this time () Repair/replace: Cause [3] [Vater beneath and/or around structure(s) () Naver away from structure: Location [4] [Water beneath and/or around structure(s) () Repair, replace or install guitters: Location [5] [Faulty downspouts on structure(s) () Repair, replace or install guitters: Location [6] [Faulty downspouts on structure(s) () Repair, replace or install guitters: Location [7] [Wood decay () No recommendations at this time () Repair, replace or install guitters: Location [8] [] Faulty downspouts on structure(s) () Repair, replace or install structure(s) () Repair, replace: Location/Area [2] [] Faulty downspouts on structure: Location [2] [] Redirect water away from structure: Location [2] [] Readifier expression () Redirect water away from structure: Location [2] [Redirect water away from structure: Location [2] [Really plumbing () No recommendations at this time () Redirect water away from structure: Location [2] [Really plumbing () No recommendations at this time () Repair or		Ŵ	EXTERIOR (X) Previously realed, no recommendation. () Not realed, recommend realment. Location
 Lower soil to expose at least 2 in. of slab and/or place a barrier 6 in. from structure to retain the soil. Also may refer to C-20. Location: [1] Footer below grade () No recommendations at this time () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location [1] Excessive moisture () Repair/Correct: Cause [2] Location problems () Repair/replace and/or seal: Location/Area [2] [Condensation problems () Repair/replace: Cause [2] Location [2] Poor drainage around structure(s) () No recommendations at this time () Repair/replace: Cause [3] [Vater beneath and/or around structure(s) () Naver away from structure: Location [4] [Water beneath and/or around structure(s) () Repair, replace or install guitters: Location [5] [Faulty downspouts on structure(s) () Repair, replace or install guitters: Location [6] [Faulty downspouts on structure(s) () Repair, replace or install guitters: Location [7] [Wood decay () No recommendations at this time () Repair, replace or install guitters: Location [8] [] Faulty downspouts on structure(s) () Repair, replace or install structure(s) () Repair, replace: Location/Area [2] [] Faulty downspouts on structure: Location [2] [] Redirect water away from structure: Location [2] [] Readifier expression () Redirect water away from structure: Location [2] [Redirect water away from structure: Location [2] [Really plumbing () No recommendations at this time () Redirect water away from structure: Location [2] [Really plumbing () No recommendations at this time () Repair or	(15)	r ı	Soil grade too high on slab () No recommendations at this time
Location: (16) I Footer below grade () No recommendations at this time () Lower soil to expose 2 in of foundation and maintain this level. Also refer to C-20. Location (17) I Excessive moisture () () Repair/Correct: Cause Location () Repair, replace and/or seal: Location/Area	(13)		
 (16) [] Footer below grade () No recommendations at this time () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location () Repair/Correct. Cause Location () No recommendations at this time () Repair/replace and/or seal: Location/Area () Repair/replace: Cause Location () Repair/replace: Cause Location () Repair/replace: Cause Location () Repair/replace: Cause Location () Poor drainage around structure(s) () No recommendations at this time () Drain water away from structure(s) () No recommendations at this time () Drain water from beneath and away from structure () Drain water from beneath and away from structure () Drain water from beneath and away from structure () Drain water from beneath and away from structure () Drain water for beneath and away from structure () Drain water for beneath and away from structure () Repair, replace or install guters: Location () Repair or replace: Location/Area () Mod decay () No recommendations at this time () Repair or replace: Location/Area () Add/move openings or vents: Location () Add/move openings or vents: Location () Redirect wary from structure: Location () Redire that awar from structure: Location () Redirect wary from structure: Location		()	
 () Lower soil to expose 2 in. of foundation and maintain this level. Also refer to C-20. Location	(10)	гı	
Location (17) Excessive moisture (18) Expair/Correct: Cause	(10)		
(17) [] Excessive moisture (18) [] Unsealed exterior building materials () No recommendations at this time (18) [] Unsealed exterior building materials () No recommendations at this time (19) [] Condensation problems (19) [] Condensation problems (19) [] Condensation problems (20) [] Poor drainage around structure(s) () No recommendations at this time (20) [] Poor drainage around structure(s) () No recommendations at this time (10) Drain water from beneath and away from structure (21) [] Faulty gutters on structure(s) (10) Drain water from beneath and away from structure (22) [] Faulty downspouts on structure(s) (11) Water beneath and or around structure (23) [] Faulty downspouts on structure(s) (11) Water beneath and away from structure (22) [] Faulty downspouts on structure(s) (23) [] Faulty downspouts on structure(s) (11) Wood decay () No recommendations at this time (23) [] Insufficient		()	
 Repair/Correct: CauseLocation Unsealed exterior building materials () No recommendations at this time Repair, replace and/or seal: Location/Area Condensation problems Repair/replace: CauseLocation Poor drainage around structure(s) () No recommendations at this time Drain water away from structure: Location Drain water from beneath and away from structure Braulty gutters on structure(s) Repair, replace or install gutters: Location Repair, replace or install gutters: Location Repair, replace or install gutters: Location Repair or replace: Location/Area	(17)	г 1	
(18) [1] Unsealed exterior building materials () No recommendations at this time (19) [1] Condensation problems (19) [1] Condensation problems (10) [1] Poor drainage around structure(s) () No recommendations at this time (20) [1] Poor drainage around structure(s) () No recommendations at this time (21) [1] Water beneath and/or around structure(s) (22) [1] Faulty gutters on structure(s) (23) [1] Faulty downspouts on structure(s) (23) [1] Faulty downspouts on structure(s) (23) [1] Faulty downspouts on structure(s) (24) [1] Wood decay () No recommendations at this time (25) [1] Insufficient ventilation in crawl space(s) (26) [1] Insufficient ventilation in crawl space(s) (27) [1] Leaky pipe system (28) [1] Insufficient ventilation in crawl space(s) (27) [1] Leaky pipe system (28) [1] Iselficient ventilation in crawl space(s) (29) [1] Kedirect water away from structure: Location	(17)	ĮĮ	
 () Repair, replace and/or seal: Location/Area	(10)	()	
(19) [] Condensation problems (1) Repair/replace: Cause Location (20) [] Poor drainage around structure(s) () No recommendations at this time (21) [] Water beneath and/or around structure(s) (1) Drain water from beneath and away from structure (22) [] Faulty gutters on structure(s) (23) [] Faulty downspouts on structure(s) (23) [] Faulty downspouts on structure(s) () Repair, replace or install gutters: Location (23) [] Faulty downspouts on structure(s) () Repair, replace or install gutters: Location (24) [] Wood decay () No recommendations at this time () Repair or replace: Location/Area (25) [] Insufficient ventilation in crawl space(s) () Add/move openings or vents: Location (26) [] Misdirected sprinkler systems within 3 ft. of structure(s) () Redirect water away from structure: Location (27) [] Leaky pipe system () Use no more than necessary. Turn off 3 three days prior to a treatment.	(18)	ĻŢ	
 () Repair/replace: CauseLocation	(1.0)	()	
 (20) [] Poor drainage around structure(s) () No recommendations at this time () Drain water away from structure: Location	(19)	ΙĮ	
 () Drain water away from structure: Location		()	
 (21) [] Water beneath and/or around structure(s) () Drain water from beneath and away from structure (22) [] Faulty gutters on structure(s) () Repair, replace or install gutters: Location	(20)	[]	
 () Drain water from beneath and away from structure (22) [] Faulty gutters on structure(s) () Repair, replace or install gutters: Location		()	
 (22) [] Faulty gutters on structure(s) () Repair, replace or install gutters: Location (23) [] Faulty downspouts on structure(s) () Repair, replace or install at least 2 ft. extensions: Location (24) [] Wood decay () No recommendations at this time () Repair or replace: Location/Area (25) [] Insufficient ventilation in crawl space(s) () Add/move openings or vents: Location (26) [] Misdirected sprinkler systems within 3 ft. of structure(s) () Redirect water away from structure: Location (27) [] Leaky pipe system () Use no more than necessary. Turn off 3 three days prior to a treatment. (28) [] Faulty plumbing () No recommendations at this time () Replace or repair: Location/Area (29) [] Roof leaks () Repair or replace: Location () Repair or replace: Location (29) [] Bath trap area(s) (Refer to B. above) () Need to install inspection door(s). How many: Location(s) () Need to make access by removing items: Location 	(21)	[]	
 () Repair, replace or install gutters: Location		()	
 (23) [] Faulty downspouts on structure(s) () Repair, replace or install at least 2 ft. extensions: Location	(22)	[]	Faulty gutters on structure(s)
 () Repair, replace or install at least 2 ft. extensions: Location		()	Repair, replace or install gutters: Location
 (24) [] Wood decay () No recommendations at this time () Repair or replace: Location/Area	(23)	[]	
 () Repair or replace: Location/Area		()	Repair, replace or install at least 2 ft. extensions: Location
 (25) [] Insufficient ventilation in crawl space(s) () Add/move openings or vents: Location (26) [] Misdirected sprinkler systems within 3 ft. of structure(s) () Redirect water away from structure: Location	(24)	[]	Wood decay () No recommendations at this time
 () Add/move openings or vents: Location		()	Repair or replace: Location/Area
 (26) [] Misdirected sprinkler systems within 3 ft. of structure(s) () Redirect water away from structure: Location	(25)	[]	Insufficient ventilation in crawl space(s)
 () Redirect water away from structure: Location		()	Add/move openings or vents: Location
 (27) [] Leaky pipe system () Use no more than necessary. Turn off 3 three days prior to a treatment. (28) [] Faulty plumbing () No recommendations at this time () Replace or repair: Location/Area	(26)	[]	Misdirected sprinkler systems within 3 ft. of structure(s)
 () Use no more than necessary. Turn off 3 three days prior to a treatment. (28) [] Faulty plumbing () No recommendations at this time () Replace or repair: Location/Area		()	Redirect water away from structure: Location
 () Use no more than necessary. Turn off 3 three days prior to a treatment. (28) [] Faulty plumbing () No recommendations at this time () Replace or repair: Location/Area	(27)	[]]	Leaky pipe system
 (28) [] Faulty plumbing () No recommendations at this time () Replace or repair: Location/Area		()	Use no more than necessary. Turn off 3 three days prior to a treatment.
 () Replace or repair: Location/Area	(28)	ÌÌ	
 (29) [] Roof leaks () Repair or replace: Location (30) [] Bath trap area(s) (Refer to B. above) () Need to install inspection door(s). How many: Location(s) () Need to make access by removing items: Location 		()	Replace or repair: Location/Area
 (i) Repair or replace: Location	(29)	ÌÌ	
 (30) [] Bath trap area(s) (Refer to B. above) () Need to install inspection door(s). How many: Location(s) () Need to make access by removing items: Location 		()	Denois or replace: Location
 () Need to install inspection door(s). How many: Location(s) () Need to make access by removing items: Location 	(30)	ìí	
() Need to make access by removing items: Location	(- •)	(Need to install inspection door(s). How many: Location(s)
		$\dot{()}$	
	(31)	ìì	
 (i) Need to repair (i) No recommendations at this time: Location(s): 	()	()	

(32) [] Wall voids () It is imperative that client or authorized person exposes wall void(s) in specified areas to identify possible hidden pest damage and or to facilitate treatment and removal of any unknown conducive conditions. Repair/reconstruction of any defaced areas of the property are not the responsibility of BCPC. Location(s):

(33)	ĺX	This report discloses conditions that may be conducive to the growth of mold, mildew or other fungi. (Refer to A#7 of SCOPE OF INSPECTION).
(34)[]	Other:

() See Page(s)_____

X Client's Initials:

OFFICE

Date: 04/17/2023

D. Recommendations for Correction(s) of Conducive Condition(s):

This may include structural modification, soil modification, treatment, no action or a combination thereof. Recommendations may be made by the Company to correct infestation(s), conducive condition(s) and/or inaccessible area(s) which may not be possible to do under existing condition(s). Some conducive conditions can not be corrected without creating other conducive conditions. Therefore, the Company accepts no responsibility for recommendation(s) made. It is the Client's sole decision for enactment. Any action(s) taken on the recommendations shall be solely at the Client's expense. Client should contact a qualified person(s) for corrections of conducive conditions.

E. Client Commitment As to Conditions Conducive To Infestations:

The Client agrees to cooperate with the Company throughout the term of the Agreement and agrees to maintain structure(s) and the property surrounding the covered structure(s) free of conducive conditions to the extent possible which could contribute to Subterranean Termites or other wood destroying insect infestations. Any sustained or periodic above ground moisture can support termite colonies above ground (known as "suspended colonies") - a condition for which the Company is not responsible. Failure to promptly correct any conducive condition(s) may be cause for immediate termination of this Agreement.

F. Obstructed And/Or Inaccessible Areas:

This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to areas concealed by wall coverings, furniture, equipment, stored articles and any portion of the structure in which inspection would necessitate removing or defacing any part of the structue(s) (including the surface appearance of the structure). Our inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work. Obstructed or inaccessible areas include but are not limited to the following:

(1) [] Attic (no access)	(9) [] Behind deck against structure(s)	(17) $[\mathbf{X}]$ Slab(s) joint(s)
(2) [] Insulated area(s) of attic	(10) [] Behind planter box(s) abutting structure(s)	(18) Plumbing area(s)
(3) X Eaves	(11) [] Foliage against structure(s)	(19) Bath trap area(s) (Refer to B.)
$(4) \bigotimes Wall voids$	(12) X Behind veneer	(20) Crawl space (no access)
(5) \bigotimes Beneath floor coverings	(13) Beneath thresholds	(21) [] Insufficient crawl space
(6) Soil grade too high	(14) Beneath or behind porches	(22) [] Sub floor beneath structure(s)
(7) [] Footer below grade	(15) [] Beneath or behind steps	(23) [] Voids in brick piers/fireplace(s)
(8) [] Weep holes in brick	(16) $[\mathbf{X}]$ Crack(s) in slab(s)	(24) [] Other (Specify below)
	X	
Specify (other):		() See Page(s)

Specify (other):

G. Inspection reveals visible evidence of wood destroying insects in or on the structure(s):

The structure(s) was specifically inspected for wood destroying insect(s) checked below:	Active Infestation A	Previous Infestation B	Insect Damage C	Treatment Recommended D
(1) X Subterranean Termites (Reticulitermes spp.)	Yes [] No X]	Yes [] No X]	Yes [] No X]	Yes [] No X]
(2) X Formosan Termites (Copotermes spp.)	Yes [] No X]	Yes [] No X]	Yes [] No X]	Yes [] No 🏼
(3) [] Drywood Termites	Yes [] No []	Yes [] No []	Yes [] No []	Yes [] No []
(4) [] Carpenter Ants	Yes [] No []	Yes [] No []	Yes [] No []	Yes [] No []
(5) [] Other Wood Destroying Insects (Specify below)	Yes [] No []	Yes [] No []	Yes [] No []	Yes [] No []
Specify (other):				

Description, location(s) and comments:

) See Page(s)

I have received a legible copy of this form and any referenced material which I have read and understand.

THIS REPORT IS NOT VALID FOR USE IN REAL ESTATE **TRANSACTIONS**

	04/17/2023
Client's Signature	Date
6213-	04/17/2023
Inspector's Signature	Date

Page 3 of 3 01/18

OFFICE

X