



Additional support added after wall was removed. Bracing was also resecured with hurricane clips and straps.



Blown-in insulation in ceilings and walls.



Windows in hall were removed and reframed.



Windows in dining room were removed and reframed.



All new kitchen cabinets and granite.



All new custom built showers.

