## DESCRIPTION AND ESTIMATE of the Present Cash Value

Of t	hestory	Asbestos Shingles	roofed	Frame	building
Situ	ated on Lot No. N Pt 7 in	Block No. 14	No1401		L Street
in th	e City of Galveston, owned by	-B. Moore Bill	C D. Palle	150n 76	
۰. ۲	Basement 7: enclosed				
Occupancy	First Floor by	nant owner for	Dwelling		
	Second Floor by				
	Third Floor by				
	·	DESCRIPTION			ocation June 1932
Wh	en built? 1902	Last renaired or	painted? Jun	9 1932 Addn	& Repairs
Ts 'it	on leased grounds?No	When	loes lease expir	mpv 1975	
	at is used for lighting? E1				
	of building? 28x24 12x				
	Plastered			•	
Nun	nber of rooms RXX to ceiled and papered			Bath roo	om1
	Ceiled and painted			nane	
	nber closets?2				
	nber of flues and construction there				
	ablic Fire Hydrant within 500 feet?				
The above described building would cost, at present value of materials and labor					
Making the precent (1) aluation.  S. Blankenship, et al., as independent of John H. Bolton, deceased to J. McLean and wife, all right, distributed in the restates of John distributed in the restates of John distributed in the restates of John distributed in the lot 7 in block, 14, and improve to lot 7 in block, 14, and improve the lot 8 in a					\$ <u></u>
Mak S. Blan	kenship, et al., as independ- under the tast will and tes-	OTTED IMPROVEMEN	ITC	•	\$
of Jo J. M d inte	on H. Bolton, deceased, to clean and wife, all right, rest of the estates of John	OTHER IMPROVEMEN	112		
on and to lot	7 in block 14, and improve	•••••••••••••••••••••••••••••••••••••••		\$	\$
				\$	\$
				\$	\$
				\$	\$
				\$	\$
Ded	uct for depreciation from age, use or	location	per cent	\$	\$
Mak	ing the present Cash Value				\$
REI	MARKS:	new Plansbing Ross 1	Paneled 9	- Painted	- 175
	V .	<i></i>	·		
	, r				
					·
			*****************		INSPECT
Cal	eston, Texas,day of	19:	2		7
Udi!	colori, a compiliation day or				