

Move-in Report

Prepared for Emerson Property Management

5/13/2024



711 Avenue A #4

La Marque TX 77568

2 bed / 1 bath

Technician's comments: None

Smell test performed: No exceptions noted.

KEY ANCILLARY ITEMS


STATUS -

Air Filter	Bedroom 2	Size unknown	INACCESSIBLE _
Smoke Alarm (Wireless)	Bedroom 1	Exp. Feb 2031	PASSED 🗸
Smoke Alarm (Wireless)	Bedroom 2	Exp. Feb 2031	PASSED 🗸
Smoke Alarm	Hallway/Stairway	N/A	MISSING 🔀
Smoke Alarm (Wireless)	Living Room	Exp. Feb 2031	PASSED 📀

⚠ Items that Need Attention Summary

ROOM	ITEM	COMMENTS
Bathroom 1	Floors	Crack in flooring.
	Ceiling	Cracks in ceiling.
	Shower/Fixture	Grout is dicolored/cracking.
Bedroom 1	Floors	Dirty
	Floors	Flooring is scratched.
	Closets	Stains on flooring
Bedroom 2	Floors	Flooring is scratched.
	Floors	Flooring is scratched.
Entry	Floors	Dirty
	Walls/Paint	Cracks in texture
Front Exterior	Walkways	Cracked or uneven
Hallway/Stairway	Floors	Crack in flooring.
	Smoke Alarm (Missing)	Alarm in place
Kitchen	Floors	Crack in flooring.
	Range/Cooktop/Oven	Build up
	Microwave Oven	Build up
Living Room	Floors	Dirty
	Floors	Crack in flooring.
	Light Fixtures	Light did not turn on.
	Walls/Paint	Cracks in texture
	Windows	The window sill is cracking





Bathroom 1 Floors Crack in flooring.



Bathroom 1 Ceiling
Cracks in ceiling.



Bathroom 1 Shower/Fixture Grout is dicolored/cracking.



Bedroom 1 Floors Dirty





Bedroom 1 Floors Flooring is scratched.



Bedroom 1 Closets Stains on flooring






Bedroom 2 Floors Flooring is scratched.



Bedroom 2 Floors Flooring is scratched.





Entry Floors Dirty



Entry Walls/Paint Cracks in texture





Front Exterior Walkways
Cracked or uneven



Hallway/Stairway Floors Crack in flooring.





Hallway/Stairway Smoke Alarm Alarm in place



Kitchen Floors Crack in flooring.



Kitchen Range/Cooktop/Ov Build up



Kitchen Microwave Oven Build up





Living Room *Floors*Dirty




Living Room Floors Crack in flooring.



Living Room
Light Fixtures
Light did not turn



Living Room Walls/Paint Cracks in texture



Living Room Windows The window sill is cracking

	ITEM	RESULT	
1.	Address	24	1 PHOTO
2.	Carport		N/A
3.	Center View	24	1 PHOTO
4.	Downspout/Splash Blocks		N/A
5.	Drainage Issues		N/A
6.	Driveway	24	1 PHOTO
7.	Front Left View	24	1 PHOTO
8.	Front Right View	24	1 PHOTO
9.	Garage Door		N/A
10.	Left Side Yard		N/A
11.	Light Fixtures		N/A
12.	Mail Box	24	1 PHOTO
13.	Other		N/A
14.	Right Side Yard	24	1 PHOTO
15.	Roof/Trim/Gutter	24	1 PHOTO
16.	Satellite Dish	24	1 PHOTO
17.	Trees/Shrubs/Landscaping	24	1 PHOTO
18.	Trees/Touching House		N/A
19.	Walkways		ATTENTION
20.	Walls/Siding/Trim	24	1 PHOTO
21.	Window Screens	24	1 PHOTO
22.	Yard	24	1 PHOTO
	Smell test performed, no exceptions noted.		PASS





Address

Center View





Driveway

Front Left View





Front Right View

Mail Box



5/13/2024 **15** 11:24:43 AM

Right Side Yard

Roof/Trim/Gutter





Satellite Dish

Trees/Shrubs/Landscaping





Walkways

Walkways | Cracked or uneven



Walls/Siding/Trim



Window Screens



Yard

	ITEM	RESULT	
1.	Animal Evidence	0	N/A
2.	BBQ Grill		N/A
3.	Downspout/Splash Blocks		N/A
4.	Drainage Issues		N/A
5.	Electric Meter	24	1 PHOTO
6.	Fence		N/A
7.	House Keys/Qty	24	1 PHOTO
8.	Keyless Deadbolt/Pin Lock	24	1 PHOTO
9.	Left Side Yard	24	1 PHOTO
10.	Light Fixtures		N/A
11.	Other		N/A
12.	Peephole	24	1 PHOTO
13.	Pool		N/A
14.	Pool Fence & Lock		N/A
15.	Porch/Patio/Deck	24	1 PHOTO
16.	Possible Hazard		N/A
17.	Rear Center View	24	1 PHOTO
18.	Rear Door	24	1 PHOTO
19.	Rear Gate		N/A
20.	Right Side Yard		N/A
21.	Roof/Trim/Gutter	24	1 PHOTO
22.	Shed/Storage Building		N/A
23.	Sliding Door Secondary Lock		N/A
24.	Trees/Shrubs/Landscaping		N/A
25.	Trees/Touching House		N/A
26.	Walkways		N/A
27.	Walls/Siding/Trim	24	2 PHOTOS
28.	Window Screens	24	2 PHOTOS
29.	Yard		N/A
	Smell test performed, no exceptions noted.		PASS



Electric Meter



House Keys/Qty



Keyless Deadbolt/Pin Lock



Left Side Yard



Peephole



Porch/Patio/Deck



5/13/2024 18 11:39:09 AM

Rear Center View

Rear Door





Roof/Trim/Gutter

Walls/Siding/Trim





Walls/Siding/Trim


Window Screens



Window Screens

- 1. 360 Images 1 PHOTO
- 2. Blinds/Drapes
- 3. Carbon Monoxide Alarm
- 4. Ceiling OBSERVED
- 5. Ceiling Fan
- 6. Closets N/A
- 7. Door Stop 2 1 PHOTO
- 8. Floors ATTENTION
- 9. Front Door Exterior 1 PHOTO
- 10. Front Door Interior
- 11. Keyless Deadbolt/Pin Lock
- 12. Light Fixtures N/A
- 13. Other
- 14. Outlet/Switch Covers OBSERVED
- 15. Overview (Interior)
- 16. Patio/Porch 2 1 PHOTO
- 17. Peephole 1 PHOTO
- 18. Railings
- 19. Walls/Paint ATTENTION
- 20. Windows N/A
 21. Smoke Alarm N/A
 - Smell test performed, no exceptions noted. PAS

Entry Photos 711 Avenue A #4






360 Image

Door Stop 5/13/2024 10:55:14 AM






Floors

Floors | Dirty





Front Door Exterior

Front Door Interior

Entry Photos 711 Avenue A #4






Keyless Deadbolt/Pin Lock

Overview (Interior)





Patio/Porch

Peephole





Walls/Paint

Walls/Paint | Cracks in texture

ITEM RESULT

- 1. 360 Images
- 2. Blinds/Drapes
- 3. Carbon Monoxide Alarm
- 4. Ceiling
- 5. Ceiling Fan
- 6. Closets
- 7. Door
- 8. Door Stop
- 9. Exterior Door
- 10. Fireplace
- 11. Floors
- 12. Light Fixtures
- 13. Other
- 14. Outlet/Switch Covers
- 15. Overview (Interior)
- 16. Walls/Paint
- 17. Windows
- 18. Wireless Smoke Alarm

Smell test performed, no exceptions noted.

24

1 PHOTO



OBSERVED



N/A



OBSERVED

24

1 PHOTO

0

N/A

0

N/A

0

N/A

0

N/A N/A

^

ATTENTION

^

ATTENTION

4

N/A

OBSERVED

24

1 PHOTO

lack

ATTENTION

A

ATTENTION

PASSED


PASS






360 Image

Ceiling Fan





Floors


Floors | Dirty






Floors | Crack in flooring.


Light Fixtures



Light Fixtures | Light did not turn on. |



Overview (Interior)



Walls/Paint



Walls/Paint | Cracks in texture




Windows



Windows

Living Room Photos



Windows | The window sill is cracking



Wireless Smoke Alarm (mfd 2/2021) | Smoke test: Passed | Alarm in place



Wireless Smoke Alarm (mfd 2/2021) | Smoke test: Passed | Close-up of printed manufacture date | 3.3 years old


ITEM	RESULT

- 1. 360 Images
- 2. Blinds/Drapes
- 3. Cabinet Under Sink
- 4. Carbon Monoxide Alarm
- 5. Ceiling
- 6. Counter Top/Back Splash
- 7. Dishwasher
- 8. Door
- 9. Door Stop
- 10. Electrical Breaker Panel
- 11. Exhaust Fan
- 12. Exterior Door
- 13. Faucet Spray Hose
- 14. Floors
- 15. Garbage Disposal
- 16. Light Fixtures
- 17. Lower Cabinets Exterior
- 18. Lower Cabinets Interior
- 19. Microwave Oven
- 20. Other
- 21. Outlet/Switch Covers
- 22. Overview (Interior)
- 23. Pantry
- 24. Range/Cooktop/Oven
- 25. Refrigerator
- 26. Sink/Faucet
- 27. Upper Cabinets Exterior
- 28. Upper Cabinets Interior
- 29. Walls/Paint
- 30. Windows

Smell test performed, no exceptions noted.

- 1 PHOTO
- 0
- N/A
- 1 PHOTO
- N/A
- ✓ OBSERVE
- 1 PHOTO
- N/A
- N/A
- N/A
- ✓ 1 PHOTO
- 1 PHOTO
- N/A
- 1 PHOTO
- **ATTENTION**
- N/A
- 1 PHOTO
- 1 PHOTO
- 2 PHOTOS
- **A** ATTENTION
- N/A
- ✓ OBSERVED
- 1 PHOTO
- N/A
- ATTENTION
- 3 PHOTOS
- 1 PHOTO
- ∠ 1 PHOTO
- 1 PHOTO
- OBSERVED
- N/A
 - PASS

ITEM RESULT





360 Image

Cabinet Under Sink



Counter Top/Back Splash



Electrical Breaker Panel



Exhaust Fan



Faucet Spray Hose





Floors

Floors | Crack in flooring.







Light Fixtures

Lower Cabinets - Exterior







Lower Cabinets - Interior



Microwave Oven | GE | Exterior



Microwave Oven | GE | Build up



Microwave Oven | GE | Interior



Microwave Oven | GE | Serial #



Overview (Interior)



Range/Cooktop/Oven | GE | Exterior




Range/Cooktop/Oven | GE | Interior



Range/Cooktop/Oven | GE | Interior of Bottom Oven Drawer



Range/Cooktop/Oven | GE | Serial #



Range/Cooktop/Oven | GE | Build up



Refrigerator | GE | Exterior



Refrigerator | GE | Interior





Refrigerator | GE | Serial #

Sink/Faucet







Upper Cabinets - Interior

- 1. 360 Images
- 2. Carbon Monoxide Alarm
- 3. Ceiling
- 4. Closets
- 5. Door Stop
- 6. Floors
- 7. Light Fixtures
- 8. Other
- 9. Outlet/Switch Covers
- 10. Overview (Interior)
- 11. Railings
- 12. Stairs
- 13. Walls/Paint
- 14. Missing Smoke Alarm

Smell test performed, no exceptions noted.

- 24
- 1 PHOTO
- 0
- N/A
- OBSERVED
- 0
- N/A N/A
- 0
- ATTENTION
- 41
- 1 PHOTO
- N/A
- **②**
- OBSERVED
- 24
- 1 PHOTO
- 0
- N/A N/A
- OBSERVED
- lack
- **ATTENTION**

DASS





360 Image

5/13/2024 **6** 11:08:21 AM

Floors | Crack in flooring.



Light Fixtures

Floors



Overview (Interior)



Missing Smoke Alarm | Alarm in place

ITEM	RESULT
I ⊏IVI	RESULT

- 1. 360 Images
- 2. Air Conditioner
- 3. Blinds/Drapes
- 4. Carbon Monoxide Alarm
- 5. Ceiling
- 6. Ceiling Fan
- 7. Closets
- 8. Door
- 9. Door Stop
- 10. Floors
- 11. Light Fixtures
- 12. Other
- 13. Outlet/Switch Covers
- 14. Overview (Interior)
- 15. Walls/Paint
- 16. Windows
- 17. Wireless Smoke Alarm

Smell test performed, no exceptions noted.

- 24
- 1 PHOTO
- 24
- 1 PHOTO
- OBSERVED
- N/A
- OBSERVED
- 24
- 1 PHOTO
- lack
- ATTENTION
- 2.4
- 1 PHOTO
- 1 PHOTO
- lack
- ATTENTION 1 PHOTO
- N/A
- OBSERVED
- 24
- 1 PHOTO
- **OBSERVED**
- 24
- 2 PHOTOS

PASSED

PASS





360 Image

Air Conditioner





Ceiling Fan

Closets






Closets | Stains on flooring

Door






Door Stop Floors





Floors | Dirty



Floors | Flooring is scratched.



Light Fixtures

Overview (Interior)





Windows

Windows



Wireless Smoke Alarm (mfd 2/2021) | Smoke test: Passed | Closeup of printed manufacture date | 3.3 years old



Wireless Smoke Alarm (mfd 2/2021) | Smoke test: Passed | Alarm in place

ITEM RESULT

- 1. 360 Images
- 2. Unknown Air Filter
- 3. Blinds/Drapes
- 4. Carbon Monoxide Alarm
- 5. Ceiling
- 6. Ceiling Fan
- 7. Closets
- 8. Door
- 9. Door Stop
- 10. Floors
- 11. Light Fixtures
- 12. Other
- 13. Outlet/Switch Covers
- 14. Overview (Interior)
- 15. Walls/Paint
- 16. Windows
- 17. Wireless Smoke Alarm

Smell test performed, no exceptions noted.

24

1 PHOTO

7

1 PHOTO

OBSERVED

0

N/A

OBSERVED

977

1 PHOTO

24

1 PHOTO

9.7

1 PHOTO

24

1 PHOTO

 $oldsymbol{\Lambda}$

ATTENTION

4

1 PHOTO

N/A

②

OBSERVED

24

1 PHOTO

OBSERVED

24

1 PHOTO

...

PASSED

DAGG





360 Image

Unknown Air Filter | Front | Window unit





Ceiling Fan


Closets





Door Stop





Floors

Floors | Flooring is scratched.





Floors | Flooring is scratched.

Light Fixtures





Overview (Interior)

Windows



Wireless Smoke Alarm (mfd 2/2021) | Smoke test: Passed | Alarm in place



Wireless Smoke Alarm (mfd 2/2021) | Smoke test: Passed | Close-up of printed manufacture date | 3.3 years old

ITEM	RESULT
1 I L IVI	INLOULI

- 1. 360 Images
- 2. Blinds/Drapes
- 3. Cabinet Under Sink
- 4. Carbon Monoxide Alarm
- 5. Ceiling
- 6. Closets
- 7. Commode
- 8. Door
- 9. Door Stop
- 10. Exhaust Fan
- 11. Floors
- 12. Light Fixtures
- 13. Other
- 14. Outlet/Switch Covers
- 15. Overview (Interior)
- 16. Shower/Fixture
- 17. Sink/Faucet
- 18. Towel Bars
- 19. Tub/Fixture
- 20. Walls/Paint
- 21. Windows

Smell test performed, no exceptions noted.

- 24
- 1 PHOTO
- OBSERVEL
- 24
- 1 PHOTO
- 0
- ^
 - ATTENTION

N/A

- N/A
- 1 PHOTO
- N/A
- 1 PHOTO
- 1 PHOTO
- ATTENTION
- 1 PHOTO
- N/A
- ✓ OBSERVED
- ✓ 1 PHOTO
- **ATTENTION**
- 1 PHOTO
- 1 PHOTO
- 1 PHOTO
- ✓ OBSERVED
- 1 PHOTO

PASS





360 Image

Cabinet Under Sink





Ceiling

Ceiling | Cracks in ceiling.






Commode

Door Stop





Exhaust Fan




Floors



Floors | Crack in flooring.




Light Fixtures



Overview (Interior)

Shower/Fixture



Shower/Fixture | Grout is dicolored/cracking.




Sink/Faucet



Towel Bars



Tub/Fixture | Base of Tub



Windows

	ITEM	RESULT	
1.	Air Filter 2		N/A
2.	Air Filter 3		N/A
3.	Air Handler		N/A
4.	Carbon Monoxide Alarm		N/A
5.	Fire Extinguisher		N/A
6.	Garage Remotes/Qty		N/A
7.	Gas Meter		N/A
8.	Mailbox Keys/Qty		N/A
9.	Pet Evidence		N/A
10.	Propane Tank Gauge		N/A
11.	Security System		N/A
12.	Thermostat		N/A
13.	Tobacco Remains		N/A
14.	Trip Hazards		N/A
15.	Water Heater		N/A