

Move-in Report

Prepared for Emerson Property Management

2/27/2024



7809 Glass St #7809

Houston TX 77016

2 bed / 1 bath

Technician's comments: None

Smell test performed: No exceptions noted.

KEY ANCILLARY ITEMS

STATUS -

Air Filter	Kitchen	12 x 24 x 1	SLIGHTLY DUSTY
Smoke Alarm (Wired)	Bedroom 1	Exp. Aug 2033	PASSED 🗸
Smoke Alarm (Wired)	Bedroom 2	Exp. Sep 2033	PASSED 🗸
Smoke Alarm (Wired)	Hallway/Stairway	Exp. Oct 2032	PASSED 🕢

⚠ Items that Need Attention Summary

ROOM	ITEM	COMMENTS
Bathroom 1	Walls/Paint	Holes in wall.
	Commode	Bolt caps missing
Bedroom 1	Ceiling	Holes
	Walls/Paint	Holes in wall.
	Walls/Paint	Holes in wall.
	Door Stop	Missing- no wall damage noted.
Bedroom 2	Door	Discolored
Entry	Front Door Exterior	Scratches; stains; discoloration or chipping of door casing
	Front Door Interior	Gaps in weather stripping
	Floors	Flooring is stained.
	Floors	Flooring is scratched.
	Walls/Paint	Scratches on the wall
	Other	Insects coming through entry door
Front Exterior	Left Side Yard	Overgrown
	Window Screens	Screen(s) are missing
	Window Screens	Screen(s) are missing
	Walkways	Cracked or uneven
Hallway/Stairway	Floors	Flooring is scratched.
Kitchen	House Keys/Qty	2
	Exterior Door	Gaps in weather stripping
	Exterior Door	Gaps in weather stripping
	Ceiling	The ceiling is discolored.
	Ceiling	The ceiling is discolored.
Laundry Room	Floors	Gap in flooring.
	Floors	Gap in flooring.
Rear Exterior	Window Screens	Screen(s) are missing
	Porch/Patio/Deck	Cracked concrete
	Yard	Patches/dead spots in the grass
	Yard	Patches/dead spots in the grass
	Light Fixtures	Light did not turn on.



Bathroom 1 Walls/Paint Holes in wall.



Bathroom 1 Commode Bolt caps missing





Bedroom 1 Ceiling Holes



Bedroom 1 Walls/Paint Holes in wall.





Bedroom 1 Walls/Paint Holes in wall.




Bedroom 1 Door Stop Missing- no wall damage noted.



Bedroom 2 Door Discolored



EntryFront Door Exterior Scratches; stains; discoloration or chipping of door casing



EntryFront Door Interior
Gaps in weather
stripping



Entry Floors Flooring is stained.



Entry Floors Flooring is scratched.



Entry Walls/Paint Scratches on the wall



Entry Other Insects coming through entry door



Front Exterior Left Side Yard Overgrown



Front Exterior Window Screens Screen(s) are missing



Front Exterior Window Screens Screen(s) are missing




Front Exterior Walkways
Cracked or uneven



Hallway/Stairway Floors Flooring is scratched.






Kitchen House Keys/Qty



Kitchen Exterior Door Gaps in weather stripping



Kitchen Exterior Door Gaps in weather stripping



Kitchen Ceiling
The ceiling is discolored.





Kitchen Ceiling
The ceiling is discolored.



Laundry Room *Floors* Gap in flooring.



Laundry Room *Floors* Gap in flooring.




Rear Exterior Window Screens Screen(s) are missing



Rear Exterior Porch/Patio/Deck Cracked concrete



Rear Exterior Yard Patches/dead spots in the grass



Rear Exterior Yard Patches/dead spots in the grass



Rear Exterior Light Fixtures Light did not turn

ITEM	RESULT

- 1. Address 1 PHOTO
- 2. Carport N/A
- 3. Center View 1 PHOTO
- 4. Downspout/Splash Blocks
- 5. Drainage Issues
- 6. Driveway 1 PHOTO
- 7. Electric Meter 1 PHOTO
- 8. Electrical Breaker Panel PHOTO
- 9. Front Left View 1 PHOTO
- 10. Front Right View 1 PHOTO
- To Trong type view
- 11. Garage Door12. Left Side YardATTENTION
- 13. Light Fixtures 1 PHOTO
- 14. Mail Box
- 15. Other
- 16. Right Side Yard 1 PHOTO
- 17. Roof/Trim/Gutter 1 PHOTO
- 18. Trees/Shrubs/Landscaping 1 PHOTO
- 19. Trees/Touching House
- 20. Walkways ATTENTION
- 21. Walls/Siding/Trim 21. Walls/Siding/Trim 22. 3 PHOTOS
- 22. Water Shut Off 1 PHOTO
- 23. Window Screens ATTENTION
- 24. Yard 1 PHOTO


Smell test performed, no exceptions noted. PASS





Address

Center View





Driveway

Electric Meter





Electrical Breaker Panel

Front Left View



2/27/2024 **12** 3:47:32 PM

Front Right View

Left Side Yard





Left Side Yard | Overgrown

Light Fixtures





Right Side Yard

Roof/Trim/Gutter



Trees/Shrubs/Landscaping



Walkways



Walkways | Cracked or uneven



Walls/Siding/Trim



Walls/Siding/Trim




Walls/Siding/Trim




2/27/2024 23 3:48:04 PM

Water Shut Off

Window Screens



Window Screens | Screen(s) are missing



Window Screens



Window Screens | Screen(s) are missing



Window Screens

Front Exterior Photos



Yard

13. Pool

ITEM RESULT

1.	Air Conditioner	24	1 PHO	T(

- N/A 2. Animal Evidence
- N/A 3. BBQ Grill
- N/A 4. Downspout/Splash Blocks
- 5. Drainage Issues N/A
- 6. Fence 4 PHOTOS
- 7. Gas Meter
- 8. Keyless Deadbolt/Pin Lock 1 PHOTO
- 9. Left Side Yard N/A
- 10. Light Fixtures **ATTENTION**
- 11. Other N/A
- 12. Peephole 1 PHOTO
- 14. Pool Fence & Lock N/A
- 15. Porch/Patio/Deck **ATTENTION**
- 16. Possible Hazard N/A
- 17. Rear Center View 1 PHOTO
- 1 PHOTO 18. Rear Door
- 19. Rear Gate N/A
- 20. Right Side Yard N/A
- 21. Roof/Trim/Gutter 1 PHOTO
- 23. Sliding Door Secondary Lock N/A
- 24. Trees/Shrubs/Landscaping N/A
- 25. Trees/Touching House N/A
- 26. Walkways 1 PHOTO
- 27. Walls/Siding/Trim 2 PHOTOS
- 28. Window Screens
- 29. Yard **ATTENTION** Smell test performed, no exceptions noted.

22. Shed/Storage Building

N/A

N/A





Air Conditioner







Fence



Fence



Gas Meter



2/27/2024 **8** 3:40:56 PM

Gas Meter

Keyless Deadbolt/Pin Lock





Light Fixtures

Light Fixtures | Light did not turn on. |





Peephole

Porch/Patio/Deck




Porch/Patio/Deck | Cracked concrete



Rear Center View



Rear Door



Roof/Trim/Gutter



Walkways



Walls/Siding/Trim



Walls/Siding/Trim



Window Screens




Window Screens | Screen(s) are missing



Yard



Yard | Patches/dead spots in the grass



Yard | Patches/dead spots in the grass

ITEM RESULT

- 1. 360 Images
- 2. Blinds/Drapes
- 3. Carbon Monoxide Alarm
- 4. Ceiling
- 5. Ceiling Fan
- 6. Closets
- 7. Door Stop
- 8. Floors
- 9. Front Door Exterior
- 10. Front Door Interior
- 11. Keyless Deadbolt/Pin Lock
- 12. Light Fixtures
- 13. Other
- 14. Outlet/Switch Covers
- 15. Overview (Interior)
- 16. Patio/Porch
- 17. Peephole
- 18. Railings
- 19. Thermostat
- 20. Walls/Paint
- 21. Windows
- 22. Smoke Alarm

Smell test performed, no exceptions noted.

- 24
- 1 PHOTO
- **OBSERVED**
- 9
- N/A
- OBSERVED
- 0
- N/A
- 0
 - N/A 1 PHOTO
- Λ
- ATTENTION
- lack
- ATTENTION
- $oldsymbol{\Lambda}$
- ATTENTION
- 24
- 1 PHOTO
- 24
- 1 PHOTO
- lack
- ATTENTION
- OBSERVED
- 24
- 1 PHOTO
- 24
- 1 PHOTO
- 24
- 1 PHOTO
- 0
- N/A
- 24
- 1 PHOTO
- Δ
- ATTENTION
- N/A
- PASS

Entry Photos 7809 Glass St #7809






360 Image

2/27/2024 **8** 3:16:19 PM

Door Stop



Floors



Floors | Flooring is stained.



Floors | Flooring is scratched.

Front Door Exterior



Front Door Exterior | Scratches; stains; discoloration or chipping of door casing



Front Door Interior



Front Door Interior | Gaps in weather stripping



Keyless Deadbolt/Pin Lock




Light Fixtures



Other



Other | Insects coming through entry door



Overview (Interior)




Patio/Porch



Peephole



Thermostat



Walls/Paint

Entry Photos 7809 Glass St #7809






Walls/Paint

Walls/Paint | Scratches on the wall





Windows

Windows

ITEM RESULT

- 1. 360 Images
- 2. 12 x 24 x 1 Air Filter
- 3. Blinds/Drapes
- 4. Cabinet Under Sink
- 5. Carbon Monoxide Alarm
- 6. Ceiling
- 7. Counter Top/Back Splash
- 8. Dishwasher
- 9. Door
- 10. Door Stop
- 11. Exhaust Fan
- 12. Exterior Door
- 13. Faucet Spray Hose
- 14. Fire Extinguisher
- 15. Floors
- 16. Garbage Disposal
- 17. House Keys/Qty
- 18. Light Fixtures
- 19. Lower Cabinets Exterior
- 20. Lower Cabinets Interior
- 21. Microwave Oven
- 22. Other
- 23. Outlet/Switch Covers
- 24. Overview (Interior)
- 25. Pantry
- 26. Range/Cooktop/Oven
- 27. Refrigerator
- 28. Sink/Faucet
- 29. Upper Cabinets Exterior
- 30. Upper Cabinets Interior
- 31. Walls/Paint

- 24
- 2 PHOTOS
- 24
- 3 PHO 1 OS
- OBSERVED
- 24
- 1 PHOTO
- N/A
- A
- ATTENTION
- 24
- 2 PHOTOS
- 0
- N/A

N/A

- 0
 -) N/A
- 2.7
- 1 PHOTO
- $oldsymbol{\Lambda}$
- **ATTENTION**
- N/A
- 2 PHOTOS
- ✓ OBSERVED
- N/A
- ATTENTION
- 1 PHOTO
- 2 PHOTOS
- 4 PHOTOS
- N/A
- N/A
- ✓ OBSERVED
- 1 PHOTO
- 1 PHOTO
- 4 PHOTOS
- 3 PHOTOS
- 1 PHOTO
- 2 PHOTOS
- 2 PHOTOS
- ✓ OBSERVEI

ITEM RESULT

32. Windows

24

PHOTOS

Smell test performed, no exceptions noted.

PASS

360 Image






3:25:29 PM

360 Image



12 x 24 x 1 Air Filter | Front



12 x 24 x 1 Air Filter | Back



12 x 24 x 1 Air Filter | Close-up of size/initials/date



Cabinet Under Sink





Ceiling


Ceiling | The ceiling is discolored. |



Ceiling | The ceiling is discolored. |



Counter Top/Back Splash




Counter Top/Back Splash




Exhaust Fan





Exterior Door

Exterior Door | Gaps in weather stripping



Exterior Door | Gaps in weather stripping




Fire Extinguisher



Fire Extinguisher




House Keys/Qty




2/27/2024 18 3:20:42 PM

House Keys/Qty | 2

Light Fixtures



Lower Cabinets - Exterior




Lower Cabinets - Exterior



Lower Cabinets - Interior





Lower Cabinets - Interior





Lower Cabinets - Interior Lower Cabinets - Interior







Pantry



Range/Cooktop/Oven | GE | Exterior



Range/Cooktop/Oven | GE | Interior



Range/Cooktop/Oven | GE | Interior of Bottom Oven Drawer



Range/Cooktop/Oven | GE | Serial #



Refrigerator | GE | Exterior



Refrigerator | GE | Interior



Refrigerator | GE | Serial # | Insects in refrigerator



Sink/Faucet



2/27/2024 29 3:23:21 PM

Upper Cabinets - Exterior

Upper Cabinets - Exterior




2/27/2024 30 3:24:29 PM

Upper Cabinets - Interior

Upper Cabinets - Interior





Windows Windows

ITEM	RESULT

- 1. 360 Images
- 2. Carbon Monoxide Alarm
- 3. Ceiling
- 4. Closets
- 5. Door Stop
- 6. Floors
- 7. Light Fixtures
- 8. Other
- 9. Outlet/Switch Covers
- 10. Overview (Interior)
- 11. Railings
- 12. Stairs
- 13. Walls/Paint
- 14. Electric Water Heater
- 15. Wired Smoke Alarm

Smell test performed, no exceptions noted.

- 24
- 1 PHOTO
- 0
- N/A
- OBSERVED
- 24
- 1 PHOTO
- 9
- N/A
- lack
- **ATTENTION**
- 24
- 1 PHOTO
- 0
- N/A
- **②**
- OBSERVEL
- 24
- 1 PHOTO
- 0
- N/A
- 0
- N/A
- \bigcirc
- 2 PHOTOS
- _
- PASSED

PASS






360 Image


Closets






Floors

Floors | Flooring is scratched.





Light Fixtures

Overview (Interior)

Hallway/Stairway Photos



Electric Water Heater | Rheem | Water heater (with expansion tank if present)



Electric Water Heater | Rheem | Water heater label



Wired Smoke Alarm (mfd 10/2022) | Smoke test: Passed | Alarm in place



Wired Smoke Alarm (mfd 10/2022) | Smoke test: Passed | Close-up of printed manufacture date | 1.4 years old

ITEM RESULT

- 1. 360 Images
- 2. Blinds/Drapes
- 3. Carbon Monoxide Alarm
- 4. Ceiling
- 5. Ceiling Fan
- 6. Closets
- 7. Door
- 8. Door Stop
- 9. Floors
- 10. Light Fixtures
- 11. Other
- 12. Outlet/Switch Covers
- 13. Overview (Interior)
- 14. Walls/Paint
- 15. Windows
- 16. Wired Smoke Alarm

Smell test performed, no exceptions noted.

24

1 PHOTO

OBSERVED

O

N/A

ATTENTION

0

N/A

24

2 PHOTOS

24

1 PHOTO

 $oldsymbol{\Lambda}$

ATTENTION

1 PHOTO

N/A

OBSERVED

24

1 PHOTO

A

ATTENTION

1 PHOTO

PASSED

PASS






360 Image Ceiling





Ceiling | Holes Closets





Closets Door





Door Stop

Door Stop | Missing- no wall damage noted.






Light Fixtures

Overview (Interior)





Walls/Paint

Walls/Paint



Walls/Paint | Holes in wall.



Walls/Paint | Holes in wall.



Windows



Wired Smoke Alarm (mfd 8/2023) | Smoke test: Passed | Alarm in place



Wired Smoke Alarm (mfd 8/2023) | Smoke test: Passed | Close-up of printed manufacture date | .6 years old

ITEM	RESULT

- 1. 360 Images
- 2. Blinds/Drapes
- 3. Carbon Monoxide Alarm
- 4. Ceiling
- 5. Ceiling Fan
- 6. Closets
- 7. Door
- 8. Door Stop
- 9. Floors
- 10. Light Fixtures
- 11. Other
- 12. Outlet/Switch Covers
- 13. Overview (Interior)
- 14. Walls/Paint
- 15. Windows
- 16. Wired Smoke Alarm

Smell test performed, no exceptions noted.

- 24
- 1 PHOTO
- **OBSERVED**
- 0
- N/A
- OBSERVED
- 0
- N/A
- 24
- 2 PHOTOS
- A
- ATTENTION
- 2.7
- 1 PHOTO

- 24
- 1 PHOTO
- N/A
- OBSERVE
- 24
- 1 PHOTO
- **OBSERVED**
- 24
- 1 PHOTO
- PASSED

PASS





360 Image

Closets





Closets

Door





Door | Discolored

Door Stop



Light Fixtures



Overview (Interior)



Windows



Wired Smoke Alarm (mfd 9/2023) | Smoke test: Passed | Alarm in place



Wired Smoke Alarm (mfd 9/2023) | Smoke test: Passed | Close-up of printed manufacture date | .5 years old

	ITEM	RESULT	
1.	360 Images	24	1 PHOTO
2.	Blinds/Drapes		N/A
3.	Cabinet Under Sink	24	1 PHOTO
4.	Carbon Monoxide Alarm		N/A
5.	Ceiling		OBSERVED
6.	Closets		N/A
7.	Commode		ATTENTION
8.	Door	24	1 PHOTO
9.	Door Stop	24	1 PHOTO
10.	Exhaust Fan	24	1 PHOTO
11.	Floors		OBSERVED
12.	Light Fixtures	24	1 PHOTO
13.	Other		N/A
14.	Outlet/Switch Covers		OBSERVED
15.	Overview (Interior)	24	1 PHOTO
16.	Shower/Fixture	24	1 PHOTO
17.	Sink/Faucet	24	1 PHOTO

18. Towel Bars

19. Tub/Fixture

20. Walls/Paint

Smell test performed, no exceptions noted.

21. Windows

1 PHOTO

1 PHOTO

N/A

PASS

ATTENTION





360 Image

Cabinet Under Sink







Commode


Commode | Bolt caps missing





Door Stop





Exhaust Fan

Light Fixtures





Overview (Interior)

Shower/Fixture





Sink/Faucet

Towel Bars




2/27/2024 **20** 3:34:33 PM

Tub/Fixture | Base of Tub

Walls/Paint





Walls/Paint

Walls/Paint | Holes in wall.

- 1. 360 Images 1 PHOTO
- 2. Blinds/Drapes N/A
- 3. Cabinet Under Sink
- 4. Carbon Monoxide Alarm
- 5. Ceiling OBSERVED
- 6. Closets N/A
- 7. Door
- 8. Door Stop
- 9. Dryer
- 10. Floors ATTENTION
- 11. Light Fixtures N/A
- 12. Other
- 13. Outlet/Switch Covers
- 14. Overview (Interior)
- 15. Utility Sink
- 16. Walls/Paint OBSERVED
- 17. Washer Connection18. Washing MachineN/A
- 19. Windows N/A
 - Smell test performed, no exceptions noted. PASS


Laundry Room Photos





360 Image **Floors**








Floors | Gap in flooring. Floors | Gap in flooring.







Washer Connection

	ITEM	RESULT	
1.	Air Filter 2		N/A
2.	Air Filter 3		N/A
3.	Air Handler		N/A
4.	Carbon Monoxide Alarm		N/A
5.	Garage Remotes/Qty		N/A
6.	Mailbox Keys/Qty		N/A
7.	Pet Evidence		N/A
8.	Propane Tank Gauge		N/A
9.	Satellite Dish		N/A
10.	Security System		N/A
11.	Tobacco Remains		N/A
12.	Trip Hazards		N/A