



GF NO. 0301007049 STARTEX TITLE
 ADDRESS: 10006 DEL MONTE DRIVE
 HOUSTON, TEXAS 77042
 BORROWER: GEORGE MIKAL BUGEL AND
 MAUREEN F. BUGEL

LOT 317, BLOCK 11
 BRIARGROVE PARK, SECTION 1

ACCORDING TO THE MAP OR PLAT THEREOF
 RECORDED IN VOLUME 72, PAGE 19 OF THE MAP
 RECORDS OF HARRIS COUNTY, TEXAS



THIS PROPERTY DOES NOT LIE WITHIN THE
 100 YEAR FLOOD PLAIN AS ESTABLISHED
 BY THE U.S. DEPT. OF HOUSING & URBAN
 DEVELOPMENT.
 COMMUNITY/PANEL NO. 48201C 0435 P
 MAP REVISION: 4/20/2000
 ZONE X

RECORD BEARING: VOL. 72, PG. 19, H.C.M.R.

I HEREBY CERTIFY THAT THIS SURVEY WAS MADE
 ON THE GROUND, THAT THIS PLAT CORRECTLY
 REPRESENTS THE FACTS FOUND AT THE
 TIME OF SURVEY AND THAT THERE ARE NO
 ENCROACHMENTS APPARENT ON THE GROUND,
 EXCEPT AS SHOWN HEREON. THIS SURVEY IS
 CERTIFIED FOR THIS TRANSACTION ONLY AND
 ABSTRACTING PROVIDED IN THE ABOVE
 REFERENCED TITLE COMMITMENT WAS RELIED
 UPON IN PREPARATION OF THIS SURVEY.

PRECISION SURVEYORS
 PROFESSIONAL LAND SURVEYORS

1-800-LANDSURVEY 281-96-1286
 1-800-526-3787 FAX 281-96-1287

14825 MEMORIAL DRIVE SUITE 800 HOUSTON, TEXAS 77060

Daniel King
 PROFESSIONAL LAND SURVEYOR
 No. 4764
 DRAWING NO. 01-5877
 AUGUST 8, 2001
 REVISED 8/10/01



DRAWN BY: MM

TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

The conditions conducive to insect infestation reported in 7A & 7B:

9. Will be or has been mechanically corrected by inspecting company:

Yes No

If "Yes," specify corrections:

8A. Corrective treatment recommended for active infestation or avoidance of previous infestation with no prior treatment as identified in Section 8. (Refer to Part G, H, and I, Scope of Inspection):

Yes No

8B. A preventive treatment and/or correction of conducive conditions as identified in 7A & 7B is recommended as follows:

Yes No

Specify reason:
Refer to Scope of Inspection Part J

10A. This company has treated or is treating the structure for the following wood destroying insects:

If treating for subterranean termites, the treatment was: Partial Spot Bait Other 2/17

If treating for drywood termites or related insects, the treatment was: Full Limited N/A

10B. Date of Treatment by Inspecting Company: N/A

Common Name of Insect: N/A


Name of Pesticide, Bait or Other Material: N/A

This company has a contract or warranty in effect for control of the following wood destroying insects:

Yes No If "Yes," copy(ies) of warranty and treatment diagram must be attached.

Diagram of Structure(s) Inspected

The Inspector must draw a diagram including approximate perimeter measurements and indicate active or previous infestation and type of insect by using the following codes: E-Evidence of Infestation, A-Active; P-Previous; D-Drywood Termites; S-Subterranean Termites; F-Fornosan Termites; C-Conducive Conditions; B-Wood Boring Beetles; H-Carpenter Ants; Other(s) - Specify.



Additional Comments: None

Neither I nor the company for which I am acting have had, presently have, or contemplate having any interest in the property. I do further state that neither I nor the company for which I am acting is associated in any way with any party to this transaction.

Signature: Wing M. Rockwell
11A. Inspector

12A. Notice of Inspection Was Posted At or Near:

- Electric Breaker Box
- Water Heater Closet
- Bath Trap Access
- Beneath the Kitchen Sink

Approved: Craig M. Rockwell (46296PT)
11B. Certified Applicator and Certified Applicator License Number

12B. Date Posted: 9/25/09
Date

I have received the original or a legible copy of this form. I have read and understand any recommendations made. I have also read and understand the "Scope of Inspection." I understand that my inspector may provide additional information as an addendum to this report.

If additional information is attached, list number of pages: N/A

Signature of Purchaser of Property or their Designee: [Signature] Date: 9/25/09

[Signature]