

.B.G. Surveying, nc



PROVIDENCE

LEGEND

----OES----OVERHEAD ELECTRIC SERVICE ---OHP--OVERHEAD ELECTRIC POWER COLUMN WOOD FENCE 0.5' WIDE TYPICAL UNDERGROUND ELECTRIC CHAIN LINK TRANSFORMER PAD PE EQUIPMENT AC AIR CONDITIONER EDGE OF ASPHALT CM CONTROLLING MONUMENT EDGE OF GRAVEL DOUBLE SIDED WOOD FENCE OVERHEAD ELECTRIC CONCRETE IRON FENCE POWER POLE FENCE POST FOR CORNER

EXCEPTIONS:

NOTE: PROPERTY SUBJECT TO TERMS, CONDITIONS, AND EASEMENTS CONTAINED IN INSTRUMENT RECORDED IN CAB. R, SHEET 20, 9348561, 2001-099692, 2002-004258, 2004-103117, 2008-024822, 2009116493, 2010026343, 2010085649, 2011076399

EASEMENTS RECORDED IN THE FOLLOWING VOLUMES AND PAGES DO NOT AFFECT THE ABOVE DESCRIBED PROPERTY VOL. 970, PG. 76 CC# 8848234

FLOOD NOTE: According to the F.I.R.M. No. 48339C0515 G, this property does lie in Zone X and does not lie within the 100 year flood zone.

Date:

NOTES:
BEARINGS, EASEMENTS AND BUILDING LINES ARE BY RECORDED PLAT UNLESS OTHERWISE NOTED.

20,

0,

0

20

SCALE:

_;


Accepted

d by: Purchaser

Purchaser

Job No._

1506003



Jewelsford Drive


Being Lot Twenty—Two (22), Block One (1), of The Woodlands Village of Sterling Ridge, Section Thirteen (13), a subdivision in Montgomery County, Texas, according to the map or plat thereof recorded in Cabinet R, Sheet 20, of the Map Records of Montgomery County, Texas.

SURVEYOR'S CERTIFICATE

by the Surveyor, or under his direction; (c) all monuments stown increase actually existed on the date of the survey, and the location, size and type of material thereof are correctly shown; (d) except as shown hereon there are no observable protrusions on to the Property or observable protrusions there from, there are no observable improvements on the Property, there property description set forth hereon were prepared from an actual on—the—ground survey of the real property (26 Jewelsford Drive) described in (Cabinet R, Sheet 20), and shown hereon; (b) such survey was conducted accuracy standards of the State of Texas; (j) the Property is not located in a 100 Year Flood Plain or in an identified "Flood Prone Area" as defined has apparent access to and from a public roadway; (h) recorded easements listed hereon have been labeled and platted hereon; (i) the boundaries, dimensions and other details shown hereon are shown to the appropriate are no observable discrepancies, conflicts, shortages in area or boundary Flood Disaster Protection Act of 1973. from the nearest and setback from the Property lines the distances indicated; line conflicts; (e) by the U. S. Department of Housing and Urban Development (Flood shown hereon, and all are located within inc., and Providence Title Company) that, (a) this plat of survey and the hereby certifies to (Dylan Dahmann and Katherine Dahmann, Quicken Loans Company) in connection with the transaction described in GF# 220001362. nsurance Rate Map Community Panel No. 48339C0515 G) pursuant to the The undersigned This survey is made relying on information provided by (Providence Title Registered Professional Land Surveyor (Josh Connally) intersection street or road is as shown; (g) the Property the size, location and type of improvements, if any, are d all are located within the boundaries of the Property (f) the distance

The surveyor expressly understands and agrees that (Dylan Dahmann and Katherine Dahmann, Quicken Loans Inc., and Providence Title Company) are entitled to rely on this survey as having been performed to the appropriate standards of the current (1999 Edition) Texas Society of Professional Surveyors Standards and Specifications for a Category 1A, Condition II Survey, as set forth by the Texas Board of Professional Land Surveying.

at user's own ris Use of this survey by any other parties and/or for other purposes shall be responsibility of the undersigned. k and any loss resulting from other use shall not be the



Josh Connal Registered Professional Land Surveyor No. 5706

